

28-JAN-2016 12:22 K:\TIPProjects-I\I5788\Structures\Finalplans\250158_plans.dgn tfang

+

REPAIR QUANTITY TABLE						
UNDERSIDE OF DECK REPAIRS						
		ESTIMATE		ACTUAL		
SHOTCRETE REPAIRS	AREA SF	VOLUME CF	AREA SF	VOLUME CF		
UNDERSIDE OF DECK & OVERHANGS						
BENT DIAPHRAGMS	1.2	0.3				
RC DECK GIRDERS	4.2	1.1				
	ESTIMATE		AC	ACTUAL		
EPOXY RESIN INJECTION	3.0 LF					

VALUES IN CHARTS REPRESENT ESTIMATED UNDERSIDE OF DECK REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN.OF 1" BEHIND REBAR AND MIN.1" CLEAR TO SAWCUT. SEE REPAIR DETAILS.

NOTES:

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE. FOR BENT DIAPHRAGM AND RC DECK GIRDER REPAIR DETAILS SEE SHEET S-24. REPAIR CONCRETE BENT DIAPHRAGMS AS DIRECTED BY THE ENGINEER.

PROJECT NO. <u>I-5788</u> <u>CUMBERLAND</u> COUNTY					
BRIDGE NO. 158					
SHEET 2 OF 5 STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH SUPERSTRUCTURE REPAIR SPAN B SBL					
REVISIONS	SHEET NO. S-38				
NO. BY: DATE: NO. BY: DATE: 1 3 4 3 4	TOTAL SHEETS 72				

 16301	A THE MANNER AND A THE
ocuSigned by: Ting H. Jone 72088400977435	-
1/28/2016	i