NOTES REPAIR LOCATIONS AND ESTIMATED QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE AS-BUILT REPAIR QUANTITY TABLE. FOR CAP REPAIRS, SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET. -SPAN B FACE NO REPAIRS NOTED FOR BENT 1 DURING INSPECTION BY STRUCTURES MANAGEMENT UNIT. THE CONTRACTOR AND ENGINEER SHALL INSPECT THE BENT PRIOR TO BEGINNING WORK. └SPAN A FACE TOP OF CAP END VIEW END VIEW SPAN A FACE SPAN B FACE NORTH FACE SOUTH FACE SPAN A FACE SPAN B FACE

AS-BUILT REPAIR QUANTITY TABLE

REPAIRS BENT 1					
SHOTCRETE REPAIRS	REPAIRS BENT 1	QUANTITIES			
SHOTCRETE REPAIRS		ESTIMATE		ACTUAL	
COLUMN	SHOTCRETE REPAIRS				VOLUME CF
EPOXY RESIN INJECTION CAP COLUMN COLUMN EPOXY COATING SO. FT SO. FT SO. FT	CAP	0.0	0.0		
EPOXY RESIN INJECTION FT FT CAP COLUMN COLUMN SO. FT SO. FT FT	COLUMN	0.0	0.0		
EPOXY RESIN INJECTION FT FT CAP COLUMN COLUMN SO. FT SO. FT FT					
EPOXY RESIN INJECTION FT FT CAP COLUMN COLUMN SO. FT SO. FT FT					
COLUMN O.O EPOXY COATING SO. FT SO.	EPOXY RESIN INJECTION				
EPOXY COATING SO. FT. SO. FT.	CAP		0.0		
EPOXT COATING FT FT	COLUMN		0.0		
EPOXT COATING FT FT					
TOP OF BENT CAP 0	EPOXY COATING				
	TOP OF BENT CAP		0		

VALUES IN CHARTS REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1" BEHIND REBAR AND MIN. 1" CLEAR TO SAWCUT.



PROJECT NO. I-5756

HAYWOOD COUNTY

BRIDGE NO. 231

gned by: SHEET 1 OF 2

3/21/2016

DEPARTMENT OF TRANSPORTATION

RALEIGH

SEAL

32492

BENT 1

DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED 2 SHEET NO. BY: DATE: SHEET NO. S-107

REVISIONS SHEET NO. BY: DATE: NO. BY: DATE: S-107

SHEET NO. BY: DATE: NO. BY: DATE: SHEET NO. S-107

1 3 SHEET NO. S-107

1 122

DATE : 11/15 DATE : 12/15

W.O.KEITH

J. YANNACCONE

DRAWN BY : __ CHECKED BY :

UNDERSIDE OF CAP