
NOTES:

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

FOR CAP REPAIR DETAILS, SEE "TYPICAL CAP REPAIR DETAILS" SHEET.

FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS.

FOR "EPOXY RESIN INJECTION", SEE SPECIAL PROVISIONS.



+

+

.

REPAIR QUANTITY TABLE					
REPAIRS BENT 9-S	QUANTITIES ESTIMATE			ACTUAL	
SHOTCRETE REPAIRS	AREA	VOLUME	AREA	VOLUME	
CAP (VERTICAL FACE)	SF 4.1	CF 1.7	SF	CF	
CAP (VERTICAL FACE)	0.0	0.0			
PILE COLLAR (VERT FACE)	0.0	0.0			
PILE COLLAR (HORIZ FACE)	0.0	0.0			
EPOXY RESIN INJECTION		LN.FT.		LN.FT.	
САР		3.0			
EAST FACE		10	8-59 ⁻	36	
PROJECT NO. <u>B-5936</u> <u>TYRRELL</u> COUNTY					
		KELL		OUNTY	
BRI	DGE NO)	7		
STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH BENT 9-S					
					DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED 2

.

.