REPAIR QUANTITY TABLE NOTES: REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE. REPAIRS BENT 13-S ESTIMATE SHOTCRETE REPAIRS CAP (VERTICAL FACE) 19.2 CAP (HORIZONTAL, CORNER) 0.0 FOR CAP REPAIR DETAILS, SEE "TYPICAL CAP REPAIR DETAILS" SHEET. 0.0 PILE COLLAR (VERT FACE) FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS. 0.0 PILE COLLAR (HORIZ FACE) FOR "EPOXY RESIN INJECTION", SEE SPECIAL PROVISIONS. EPOXY RESIN INJECTION VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS. _3.0 ERI _2.0 ERI 4.8 SF ~ 3.0 ERI ¬ 1.0 ERI-3.6 SF (ALL AROUND) 3.6 SF (ALL AROUND) 3.6 SF (ALL AROUND) 3.6 SF (ALL AROUND) 1.0 ERI NORTH FACE WEST FACE SOUTH FACE EAST FACE - SHOTCRETE REPAIR ERI - EPOXY RESIN INJECTION PLAN BOTTOM OF CAP Paul Bryant 8/13656264E6^{B77448...} DATE : <u>4-2016</u> DATE : <u>4-2016</u> P. D. BRYANT DRAWN BY :

B-5936 PROJECT NO. TYRRELL COUNTY 7 BRIDGE NO. STATE OF NORTH CAROLINA
DEPARTMENT OF TRANSPORTATION BENT 13-S REVISIONS DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

QUANTITIES

VOLUME CF

8.0

0.0

0.0

0.0

LN.FT.

10.0

ACTUAL

VOLUME CF

LN.FT.

21-JUN-2016 10:00 Ri\Structures\401_021_B5936_SMU_S9 THRU 399_BT.dgn pbryant

CHECKED BY :