REPAIR QUANTITY TABLE NOTES: REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE. REPAIRS BENT 15-S ESTIMATE SHOTCRETE REPAIRS CAP (VERTICAL FACE) 17.7 CAP (HORIZONTAL, CORNER) 0.0 FOR CAP REPAIR DETAILS, SEE "TYPICAL CAP REPAIR DETAILS" SHEET. 0.0 PILE COLLAR (VERT FACE) FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS. 0.0 PILE COLLAR (HORIZ FACE) FOR "EPOXY RESIN INJECTION", SEE SPECIAL PROVISIONS. EPOXY RESIN INJECTION VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS. \_ 1.3 SF \_ 1.1 SF 0.9 SF-1.0 ERI -(ALL AROUND) (ALL AROUND) (ALL AROUND) NORTH FACE WEST FACE SOUTH FACE EAST FACE - SHOTCRETE REPAIR ERI - EPOXY RESIN INJECTION PLAN BOTTOM OF CAP Paul Bryant P. D. BRYANT DRAWN BY :

CHECKED BY :

~ 2.0 ERI -3.6 SF (ALL AROUND) B-5936 PROJECT NO. TYRRELL COUNTY 7 BRIDGE NO. STATE OF NORTH CAROLINA
DEPARTMENT OF TRANSPORTATION BENT 15-S REVISIONS DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED 3653D2AF1B77448... 8/11/2016 DATE : <u>4-2016</u> DATE : <u>4-2016</u> 21-JUN-2016 10:02 R:\Structures\401\_021\_B5936\_SMU\_S9 THRU 399\_BT.dgn pbryant

QUANTITIES

VOLUME CF

7.4

0.0

0.0

0.0

LN.FT.

3.0

ACTUAL

VOLUME CF

LN.FT.