NOTES: REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE. REPAIRS BENT 21-S SHOTCRETE REPAIRS CAP (VERTICAL FACE) CAP (HORIZONTAL, CORNER) FOR CAP REPAIR DETAILS, SEE "TYPICAL CAP REPAIR DETAILS" SHEET. PILE COLLAR (VERT FACE) FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS. PILE COLLAR (HORIZ FACE) FOR "EPOXY RESIN INJECTION", SEE SPECIAL PROVISIONS. EPOXY RESIN INJECTION -4.0 SF (ALL AROUND) (AĽL AROUND) NORTH FACE WEST FACE SOUTH FACE EAST FACE - SHOTCRETE REPAIR ERI - EPOXY RESIN INJECTION BRIDGE NO. PLAN BOTTOM OF CAP DocuSigned by: Paul Bryant 3653D2AF1B77448.. 8/11/2016 DATE : <u>4-2016</u> DATE : <u>4-2016</u> DRAWN BY : P. D. BRYANT

REPAIR QUANTITY TABLE QUANTITIES ESTIMATE ACTUAL VOLUME CF VOLUME CF AREA SE 8.0 3.3 0.0 0.0 0.0 0.0 0.0 0.0 LN.FT. LN.FT. 0.0 VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS.

B-5936 PROJECT NO. TYRRELL

STATE OF NORTH CAROLINA
DEPARTMENT OF TRANSPORTATION

7

COUNTY

BENT 21-S

REVISIONS DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED S-336

CHECKED BY :