REPAIR QUANTITY TABLE NOTES: REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE. REPAIRS BENT 23-S SHOTCRETE REPAIRS CAP (VERTICAL FACE) CAP (HORIZONTAL, CORNER) FOR CAP REPAIR DETAILS, SEE "TYPICAL CAP REPAIR DETAILS" SHEET. PILE COLLAR (VERT FACE) FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS. PILE COLLAR (HORIZ FACE) FOR "EPOXY RESIN INJECTION", SEE SPECIAL PROVISIONS. 0.5 SF-NORTH FACE WEST FACE SOUTH FACE EAST FACE - SHOTCRETE REPAIR ERI - EPOXY RESIN INJECTION PLAN DocuSigned by: BOTTOM OF CAP Paul Bryant -3653D2AF1B77448.. 8/11/2016 DATE : <u>4-2016</u> DATE : <u>4-2016</u> DRAWN BY : P. D. BRYANT

ESTIMATE ACTUAL VOLUME CF VOLUME CF AREA SE 0.5 0.2 0.0 0.0 0.0 0.0 0.0 0.0 LN.FT. LN.FT. EPOXY RESIN INJECTION 0.0 VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS. B-5936 PROJECT NO. TYRRELL COUNTY 7 BRIDGE NO. STATE OF NORTH CAROLINA
DEPARTMENT OF TRANSPORTATION BENT 23-S REVISIONS DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED S-338

QUANTITIES

CHECKED BY :