REPAIR QUANTITY TABLE NOTES: REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE. REPAIRS BENT 31-S ESTIMATE SHOTCRETE REPAIRS 0.0 CAP (VERTICAL FACE) CAP (HORIZONTAL, CORNER) 0.0 FOR CAP REPAIR DETAILS, SEE "TYPICAL CAP REPAIR DETAILS" SHEET. PILE COLLAR (VERT FACE) 0.0 FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS. 0.0 PILE COLLAR (HORIZ FACE) FOR "EPOXY RESIN INJECTION", SEE SPECIAL PROVISIONS. EPOXY RESIN INJECTION VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS. NORTH FACE WEST FACE SOUTH FACE EAST FACE PROJECT NO. TYRRELL BRIDGE NO. PLAN NO REPAIRS NOTED DURING INSPECTION BY STRUCTURES MANAGEMENT UNIT. THE CONTRACTOR AND ENGINEER SHALL INSPECT THE BENT PRIOR TO BEGINNING WORK. BOTTOM OF CAP Paul Bryant -3653D2AF1B77448.. 8/11/2016

19-JUL-2016 15:06 Ri\Structures\FINAL DGNS\401\_021\_B5936\_SMU\_S38 THRU 380\_BT.dgn pbryant

DATE : <u>4-2016</u> DATE : <u>4-2016</u>

P. D. BRYANT

DRAWN BY : CHECKED BY :

STATE OF NORTH CAROLINA
DEPARTMENT OF TRANSPORTATION

BENT 31-S

B-5936

7

COUNTY

S-346

QUANTITIES

VOLUME CF

0.0

0.0

0.0

0.0

LN.FT.

0.0

ACTUAL

VOLUME CF

LN.FT.

DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

REVISIONS DATE: