NORTH FACE

NOTES:

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.


FOR CAP REPAIR DETAILS, SEE "TYPICAL CAP REPAIR DETAILS" SHEET.

FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS.


FOR "EPOXY RESIN INJECTION", SEE SPECIAL PROVISIONS.

	REPAIR QUANTITY TABLE				
	REPAIRS BENT 44-S	QUANTITIES			
		ESTIMATE		ACTUAL	
	SHOTCRETE REPAIRS	AREA SF	VOLUME CF	AREA SF	VOLUME CF
	CAP (VERTICAL FACE)	0.0	0.0		
	CAP (HORIZONTAL, CORNER)	0.0	0.0		
	PILE COLLAR (VERT FACE)	0.0	0.0		
	PILE COLLAR (HORIZ FACE)	0.0	0.0		
	EPOXY RESIN INJECTION		LN. FT.		LN. FT.
	CAD		0.0		

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS.



SOUTH FACE



EAST FACE

WEST FACE

PLAN BOTTOM OF CAP

NO REPAIRS NOTED DURING INSPECTION BY STRUCTURES MANAGEMENT UNIT. THE CONTRACTOR AND ENGINEER SHALL INSPECT THE BENT PRIOR TO BEGINNING WORK.

Paul Bryant_{8/11/2016}



STATE OF NORTH CAROLINA
DEPARTMENT OF TRANSPORTATION

B-5936

7

_ COUNTY

BENT 44-S

REVISIONS S-359 DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

PROJECT NO.

BRIDGE NO.

TYRRELL

DATE : <u>4-2016</u> DATE : <u>4-2016</u> P. D. BRYANT DRAWN BY : CHECKED BY :

21-JUN-2016 10:39 R:\Structures\401_021_B5936_SMU_S9 THRU 399_BT.dgn pbryant