## NOTES:

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.


FOR CAP REPAIR DETAILS, SEE "TYPICAL CAP REPAIR DETAILS" SHEET.

FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS.

FOR "EPOXY RESIN INJECTION", SEE SPECIAL PROVISIONS.

CAP CAP PILE PILE EP0> САР

VALUES REMOVA MIN.2″



+

+

.

REPAIR QUANTITY TABLE				
DEDATES DENT 54-S QUANTITIES				
REPAIRS BENT 54-S	ESTI	MATE	ACT	UAL
SHOTCRETE REPAIRS	AREA SF	VOLUME CF	AREA SF	VOLUME CF
CAP (VERTICAL FACE)	0.0	0.0	,	
CAP (HORIZONTAL, CORNER)	0.0	0.0		
PILE COLLAR (VERT FACE)	0.0	0.0		
PILE COLLAR (HORIZ FACE)	0.0	0.0		
EPOXY RESIN INJECTION		LN.FT.		LN.FT.
САР		0.0		
EAST FACE				
PROJECT NO. <u>B-5936</u> <u>TYRRELL</u> COUNTY BRIDGE NO. <u>7</u> STATE OF MORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH BENT 54-S				
		REVISIONS		SHEET NO. S-369
DOCUMENT NOT CONSIDERED NO. FINAL UNLESS ALL <b>1</b>	BY: DATE	: NO. BY:	DATE:	TOTAL SHEETS
SIGNATURES COMPLETED		Ą		394

.

.