NOTES:

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.


FOR CAP REPAIR DETAILS, SEE "TYPICAL CAP REPAIR DETAILS" SHEET.

FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS.

FOR "EPOXY RESIN INJECTION", SEE SPECIAL PROVISIONS.

CAP CAP PILE PILE EP0> САР

VALUES REMOVA MIN.2″



+

.

REPAIR QUANTITY TABLE				
QUANTITIES				
REPAIRS BENT 57-S	ESTI	ΜΑΤΕ	ACI	UAL
SHOTCRETE REPAIRS	AREA SF	VOLUME CF	AREA SF	VOLUME CF
CAP (VERTICAL FACE)	0.0	0.0		
CAP (HORIZONTAL, CORNER)	0.0	0.0		
PILE COLLAR (VERT FACE)	0.0	0.0		
PILE COLLAR (HORIZ FACE)	0.0	0.0		
EPOXY RESIN INJECTI	ON	LN.FT.		LN.FT.
САР		0.0		
/ALUES IN CHART REPRESENT EST; REMOVAL OF UNSOUND CONCRETE, M MIN. 2"CL TO SAWCUT. SEE REPAIR	IN, OF 1'BE DETAILS.	HIND REBAR	AND	
EAST FACE				
PRC		10 RELL)	<u>B-593</u> C	
SEAL 23739 SCALE 20.00 SEAL 20.0		STATE OF NORTH (NT OF TR RALEIGH	ANSPORT	ATION
. –	F	REVISIONS		SHEET NO.
DOCUMENT NOT CONSIDERED FINAL UNLESS ALL	BY: DATE	: NO. BY:	DATE:	S-372
FINAL UNLESS ALL 1 SIGNATURES COMPLETED 2		<u>এ</u>		TOTAL SHEETS 394

.

.