



4800 SIX FORKS ROAD SUITE 120
RALEIGH, NC 27609
& ASSOCIATES (919) 882-7839

DRAWN BY: _____AARON J. MCMILLAN DATE: 03-2018
CHECKED BY: ____JACOB H. DUKE DATE: 03-2018
DESIGN ENGINEER OF RECORD: SAMUEL L. CULLUM DATE: 03-2018



CONCRETE REPAIR AREA

NORTH ELEVATION



SHOTCRETE REPAIR AREA



EPOXY RESIN INJECTION (ERI)

EAST ELEVATION

AS-BUILT REPAIR QUANTITY TABLE QUANTITIES BENT 26 ESTIMATE ACTUAL VOLUME CU.FT. VOLUME CU.FT. AREA SQ.FT SHOTCRETE REPAIRS CAP COLUMN/PILE AREA SQ.FT CONCRETE REPAIRS CAP EPOXY RESIN INJECTION LIN.FT. LIN. FT. CAP COLUMN/PILE PILE REPAIR JACKET LIN.FT. LIN.FT

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE. MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2"CLEARANCE TO SAWCUT. FOR REPAIR DETAILS, SEE "CONCRETE RESTORATION DETAILS - SUBSTRUCTURE" SHEET.

16.0

GALVANIC STRUCTURAL C.P. JACKET

NOTES:

REPAIR LOCATIONS AND ESTIMATED QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE AS-BUILT REPAIR QUANTITY TABLE.

FOR PILE CP JACKET REPAIRS, PRIOR TO ORDERING JACKETS, PERFORM A PILE JACKET SURVEY WITH THE ENGINEER AND THE ENGINEER OF RECORD TO DETERMINE PILE JACKET LOCATIONS AND LENGTHS.

CONCRETE COVER FOR EXTERIOR BARS IN THE CAP IS 3"ON THE BOTTOM FACE, 2"ELSEWHERE, AND 3"ON THE COLUMNS PER EXISTING BRIDGE PLANS. ACTUAL CONCRETE COVER SHALL BE DETERMINED BY THE CONTRACTOR AND PRESENTED TO THE ENGINEER PRIOR TO BEGINNING SCARIFICATION.

CURRENT AVERAGE COVER IS EXPECTED TO BE FROM 2"TO 3"ON THE CAP AND FROM $2\frac{1}{2}$ "TO 3"ON THE COLUMNS BASED ON VISUAL INSPECTION.

SEE TITLE SHEET FOR PROJECT CARDINAL DIRECTION DESIGNATION.

FOR CONCRETE AND SHOTCRETE REPAIRS, SEE CONCRETE RESTORATION DETAILS - SUBSTRUCTURE SHEET.

* QUANTITIES OF CONCRETE REPAIR AREAS ARE ANTICIPATED UNDER BEARING AREAS. DUE TO LACK OF INFORMATION, ALL AREAS ARE NOT KNOWN. QUANTITY INCLUDES CONTINGENCIES AND ARE ANTICIPATED TO BE SUFFICIENT FOR ACTUAL QUANTITIES ENCOUNTERED. FOR CONCRETE REPAIRS SEE CONCRETE RESTORATION DETAILS.

ALL DEFECT QUANTITIES ON STRUTS AND COLUMN FOOTINGS ARE LISTED WITH THE QUANTITIES FOR THE CAP.

SHOTCRETE REPAIRS MAY BE REPLACED WITH CONCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

PROJECT NO. 15BPR.25

BRUNSWICK COUNTY

BRIDGE NO. 14



DEPARTMENT OF TRANSPORTATION
RALEIGH

SUBSTRUCTURE CONCRETE REPAIRS BENT 26

REVISIONSSHEET NODOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETEDNO. BY: DATE: NO. BY: DATE: S-6413TOTAL SHEETS24111