

SOUTH ELEVATION

WEST FLEWATION

WEST ELEVATION

THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE AS-BUILT REPAIR QUANTITY TABLE.

FOR PILE CP JACKET REPAIRS, PRIOR TO ORDERING JACKETS, PERFORM A PILE JACKET SURVEY WITH THE ENGINEER AND THE ENGINEER OF RECORD

TO DETERMINE PILE JACKET LOCATIONS AND LENGTHS.

CONCRETE COVER FOR EXTERIOR BARS IN THE CAP IS 3"ON THE BOTTOM FACE, 2"ELSEWHERE, AND 3"ON THE COLUMNS PER EXISTING BRIDGE PLANS. ACTUAL CONCRETE COVER SHALL BE DETERMINED BY

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE. MINIMUM OF 1"BEHIND REBAR

REPAIR LOCATIONS AND ESTIMATED QUANTITIES ARE GIVEN WITH

THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER.

AND MINIMUM 2"CLEARANCE TO SAWCUT. FOR REPAIR DETAILS, SEE "CONCRETE RESTORATION DETAILS - SUBSTRUCTURE" SHEET.

AS-BUILT REPAIR QUANTITY TABLE

AREA SQ.FT

5.3

AREA SQ.FT

0.8

ESTIMATE

VOLUME CU.FT.

2.7

0.4

LIN. FT.

LIN.FT.

5.0

BENT 29

SHOTCRETE REPAIRS

CONCRETE REPAIRS

EPOXY RESIN INJECTION

GALVANIC STRUCTURAL C.P. JACKET

COLUMN/PILE

COLUMN/PILE

BEGINNING SCARIFICATION.

PILE REPAIR JACKET

CAP

CAP

CAP

NOTES:

QUANTITIES

ACTUAL

AREA SQ.FT. VOLUME CU.FT.

LIN.FT

LIN.FT

CURRENT AVERAGE COVER IS EXPECTED TO BE FROM 2"TO 3"ON THE CAP AND FROM 21/2" TO 3"ON THE COLUMNS BASED ON VISUAL INSPECTION.

SEE TITLE SHEET FOR PROJECT CARDINAL DIRECTION DESIGNATION.

THE CONTRACTOR AND PRESENTED TO THE ENGINEER PRIOR TO

FOR CONCRETE AND SHOTCRETE REPAIRS, SEE CONCRETE RESTORATION DETAILS - SUBSTRUCTURE SHEET.

* QUANTITIES OF CONCRETE REPAIR AREAS ARE ANTICIPATED UNDER BEARING AREAS. DUE TO LACK OF INFORMATION, ALL AREAS ARE NOT KNOWN. QUANTITY INCLUDES CONTINGENCIES AND ARE ANTICIPATED TO BE SUFFICIENT FOR ACTUAL QUANTITIES ENCOUNTERED. FOR CONCRETE REPAIRS SEE CONCRETE RESTORATION DETAILS.

ALL DEFECT QUANTITIES ON STRUTS AND COLUMN FOOTINGS ARE LISTED WITH THE QUANTITIES FOR THE CAP.

SHOTCRETE REPAIRS MAY BE REPLACED WITH CONCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

PROJECT NO. 15BPR.25

BRUNSWICK COUNTY

BRIDGE NO. 14

SEAL 043571

Docusigned by: 5 NG INE E 19C97095C75A467... 4/12/2018

DEPARTMENT OF TRANSPORTATION
RALEIGH

SUBSTRUCTURE CONCRETE REPAIRS BENT 29

REVISIONSSHEET NO.DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETEDNO.BY:DATE:NO.BY:DATE:S-6713TOTAL SHEETS24111

5.3 SF — ╎┍╒╌╒╒ ╾┟┪╼┟╅┙ ┧┤╤╤╤╌ ┶┢┢┢ I I I I II I I I I \perp $| \cdot |$ 1111 IIIIII I I I1111 1111 \perp 1111 I I I I I1111 \perp 1111 IIIIII I I I I \perp 1111 I I I I1111 IIIII1111 I I I I II I I I I1111 \perp IIIII \perp \perp IIIII****\.\.\/ \\\\\ **〜〜**/ PILE 4 CP JACKET

NORTH ELEVATION

EAST ELEVATION

1111111111


11 11 11 11

4800 SIX FORKS
RALEIGH, NC 27
KISINGER CAMPO
& ASSOCIATES
(919) 882-7839

4800 SIX FORKS ROAD SUITE 120 RALEIGH, NC 27609

DRAWN BY: AARON J. MCMILLAN DATE: 03-2018
CHECKED BY: JACOB H. DUKE DATE: 03-2018
DESIGN ENGINEER OF RECORD: SAMUEL L. CULLUM DATE: 03-2018

CONCRETE REPAIR AREA



SHOTCRETE REPAIR AREA



EPOXY RESIN INJECTION (ERI)