



NC DEPARTMENT OF TRANSPORTATION
 DIVISION OF HIGHWAYS
 STRUCTURE MANAGEMENT UNIT

ATTENTION: **PAR SUBMITTED
 SIGN NOTICE ISSUED
 CHANGES TO STRUCTURE DATA**

Structure Safety Report

Routine Element Inspection - Contract

INSPECTION DATE: 08/10/2021

DIVISION: 5 COUNTY: WAKE STRUCTURE NUMBER: 910126 FREQUENCY: 24 MONTHS

FACILITY CARRIED: SR2044 MILE POST: _____

LOCATION: 1.2 MI.S.US1A

FEATURE INTERSECTED: SMITHS CREEK

LATITUDE: 35° 55' 44.53" LONGITUDE: 78° 31' 39.86"

SUPERSTRUCTURE: _____

SUBSTRUCTURE: _____

SPANS: 4 SPANS. SEE SPAN PROFILE SHEET FOR SPAN DETAILS

FRACTURE CRITICAL TEMPORARY SHORING SCOUR CRITICAL SCOUR PLAN OF ACTION

GRADES: (Inspector/NBI Coding) DECK 5/5 SUPERSTRUCTURE 3/3 SUBSTRUCTURE 3/3 CULVERT N/N

POSTED SV: 18 POSTED TTST: 23

OTHER SIGNS PRESENT: (4) DELINEATORS



Sign noticed issued for	Number Required
<u>NO</u> WEIGHT LIMIT	<u>0</u>
<u>NO</u> DELINEATORS	<u>0</u>
<u>YES</u> NARROW BRIDGE	<u>2</u>
<u>NO</u> ONE LANE BRIDGE	<u>0</u>
<u>NO</u> LOW CLEARANCE	<u>0</u>

DIRECTION OF INSPECTION S-N

DIRECTION MATCHES PLANS _____

south approach, looking north

INSPECTED BY MICHAEL MEYER	SIGNATURE 	ASSISTED BY SANYAM GURME
-------------------------------	---------------	--------------------------

**BRIDGE INSPECTION
RECORD AND SUMMARY
FOR
SHORED STRUCTURES**

BRIDGE # 910126 COUNTY Wake DATE 07/27/00

THE FOLLOWING S. I. & A. ITEMS ARE TO BE CODED TO REFLECT THE FACT THAT THE STRUCTURE IS SHORED UP:

	<u>CODE</u>	<u>BY</u>
SI & A ITEM 103 - TEMPORARY STRUCTURE DESIGNATION	T	JRJ
SI & A ITEM 59 - SUPERSTRUCTURE	—	
SI & A ITEM 60 - SUBSTRUCTURE	3	JRJ
SI & A ITEM 64 - OPERATING RATING	HS <u>0.0</u> BY <u>CR-01</u>	VPP
SI & A ITEM 64 - INVENTORY RATING	HS <u>0.0</u> BY <u>CR-01</u>	VPP

COMMENTS:

(steel) crutch bent added at each side of
beams #1, 2 and 3.

RETAIN TEMP-TMS DA/13/16

NATIONAL BRIDGE INVENTORY ----- STRUCTURE INVENTORY AND APPRAISAL

09/29/2021

IDENTIFICATION

(1) STATE NAME NORTH CAROLINA BRIDGE 910126
 (8) STRUCTURE NUMBER (FEDERAL) 1830126
 (5) INVENTORY ROUTE (ON/UNDER) ON 131020440
 (2) STATE HIGHWAY DEPARTMENT DISTRICT 5
 (3) COUNTY CODE (FEDERAL) 183 (4) PLACE CODE 70540
 (6) FEATURE INTERSECTED SMITHS CREEK
 (7) FACILITY CARRIED SR2044
 (9) LOCATION 1.2 MI.S.US1A
 (11) MILEPOINT 0.0
 (12) BASE HIGHWAY NETWORK 0
 (13) LRS INVENTORY ROUTE & SUBROUTE
 (16) LATITUDE 35° 55' 44.53" (17) LONGITUDE 78° 31' 39.86"
 (98) BORDER BRIDGE STATE CODE PERCENT SHARED
 (99) BORDER BRIDGE STRUCTURE NUMBER

SUFFICIENCY RATING 11.46
 STATUS = Structurally Deficient

CLASSIFICATION

CODE

(112) NBIS BRIDGE SYSTEM YES
 (104) HIGHWAY SYSTEM Inventory Route not on NHS 0
 (26) FUNCTIONAL CLASS Urban Collector 17
 (100) STRAHNET HIGHWAY Not a STRAHNET Route 0
 (101) PARALLEL STRUCTURE No parallel structure exists N
 (102) DIRECTION OF TRAFFIC 2-way traffic 2
 (103) TEMPORARY STRUCTURE Temporary Structure or Conditions T
 (110) DESIGNATED NATIONAL NETWORK - on national network for trucks 0
 (20) TOLL On Free Road 3
 (21) MAINT - 01
 (22) OWNER - 01
 (37) HISTORICAL SIGNIFICANCE - 5

STRUCTURE TYPE AND MATERIAL

(43) STRUCTURE TYPE MAIN Prestressed Concrete
 TYPE Channel beam CODE 522
 (44) STRUCTURE TYPE APPROACH
 TYPE CODE
 (45) NUMBER OF SPANS IN MAIN UNIT 4
 (46) NUMBER OF SPANS IN APPROACH 0
 (107) DECK STRUCTURE TYPE CODE 2
 (108) WEARING SURFACE/PROTECTIVE SYSTEM
 (A) TYPE OF WEARING SURFACE CODE 6
 (B) TYPE OF MEMBRANE CODE 0
 (C) TYPE OF DECK PROTECTION CODE 0

CONDITION

CODE

(58) DECK 5
 (59) SUPERSTRUCTURE 3
 (60) SUBSTRUCTURE 3
 (61) CHANNEL & CHANNEL PROTECTION 6
 (62) CULVERTS N

LOAD RATING AND POSTING

CODE

(31) DESIGN LOAD HS 15 3
 (63) OPERATING RATING METHOD - Load Factor 1
 (64) OPERATING RATING - HS-16 29
 (65) INVENTORY RATING METHOD - 1
 (66) INVENTORY RATING HS-9 16
 (70) BRIDGE POSTING Posting Required 0
 (41) STRUCTURE OPEN, POSTED, OR CLOSED
 DESCRIPTION Posted for Load P

AGE AND SERVICE

(27) YEAR BUILT 1967
 (106) YEAR RECONSTRUCTED 0
 (42) TYPE OF SERVICE ON - Highway
 OFF - Waterway CODE 15
 (28) LANES ON STRUCTURE 2 LANES UNDER STRUCTURE 0
 (29) AVERAGE DAILY TRAFFIC 2000
 (30) YEAR OF ADT 2017 (109) TRUCK ADT PCT 7
 (19) BYPASS OR DETOUR LENGTH 6.0

APPRAISAL

CODE

(67) STRUCTURAL EVALUATION 3
 (68) DECK GEOMETRY 4
 (69) UNDERCLEARANCES, VERT & HORIZ N
 (71) WATERWAY ADEQUACY 3
 (72) APPROACH ROADWAY ALIGNMENT 4
 (36) TRAFFIC SAFETY FEATURES 0000
 (113) SCOUR CRITICAL BRIDGES 8

GEOMETRIC DATA

(48) LENGTH OF MAXIMUM SPAN 29.0
 (49) STRUCTURE LENGTH 121.0
 (50) CURB OR SIDEWALK: LEFT 0.4 RIGHT 0.4
 (51) BRIDGE ROADWAY WIDTH, CURB TO CURB 24.1
 (52) DECK WIDTH OUT TO OUT 25.5
 (32) APPROACH ROADWAY WITH (W/ SHOULDERS) 26.0
 (33) BRIDGE MEDIAN No median CODE 0
 (34) SKEW 0 (35) STRUCTURE FLARED 0
 (10) INVENTORY ROUTE MIN VERT CLEAR 999.9
 (47) INVENTORY ROUTE TOTAL HORIZ CLEAR 24.1
 (53) MIN VERT CLEAR OVER BRIDGE RDWY 999.9
 (54) MIN VERT UNDERCLEAR: REFERENCE 0.0
 (55) MIN LAT UNDERCLEARANCE RT: REFERENCE N 0.0
 (56) MIN LAT UNDERCLEARANCE LT: 0.0

PROPOSED IMPROVEMENTS

CODE

(75) TYPE OF WORK
 (76) LENGTH OF STRUCTURE IMPROVEMENT
 (94) BRIDGE IMPROVEMENT COST
 (95) ROADWAY IMPROVEMENT COST
 (96) TOTAL PROJECT COST
 (97) YEAR OF IMPROVEMENT COST ESTIMATE
 (114) FUTURE ADT 4,000 YEAR OF FUTURE ADT 2040

NAVIGATION DATA

(38) NAVIGATION CONTROL - CODE 0
 (111) PIER PROTECTION CODE
 (39) NAVIGATION VERTICAL CLEARANCE 0.0
 (116) VERT - LIFT BRIDGE NAV MIN VERT CLEAR 0.0
 (40) NAVIGATION HORIZONTAL CLEARANCE 0.0

INSPECTION

(90) INSPECTION DATE 08/21 (91) FREQUENCY 24
 (92) CRITICAL FEATURE INSPECTION (93) CFI DATE
 A) FRACTURE CRIT DETAIL A)
 B) UNDERWATER INSP B)
 C) OTHER SPECIAL INSP C)
 SCOUR

Superstructure Build Details

Span Number 1

Span Length 30.4170

Skew 90.0000

Number of Items	Type of Component	Element Name	Quantity	Protective System Applied	Quantity (Sq Ft)
1	Asphalt Wearing Surface	Wearing Surface	733 Square Feet		
10	Prestressed Concrete Channel	Prestressed Concrete Top Flange	780 Square Feet		
2	Concrete and Metal Railing	Other Bridge Railing	62 Feet	Galvanized Protective System	98
10	Prestressed Concrete Channel	Prestressed Concrete Open Girder/Beam	310 Feet		

Span Number 2

Span Length 30.0000

Skew 90.0000

Number of Items	Type of Component	Element Name	Quantity	Protective System Applied	Quantity (Sq Ft)
10	Prestressed Concrete Channel	Prestressed Concrete Open Girder/Beam	300 Feet		
10	Prestressed Concrete Channel	Prestressed Concrete Top Flange	770 Square Feet		
2	Concrete and Metal Railing	Other Bridge Railing	60 Feet	Galvanized Protective System	96
1	Asphalt Wearing Surface	Wearing Surface	723 Square Feet		

Span Number 3

Span Length 30.0000

Skew 90.0000

Number of Items	Type of Component	Element Name	Quantity	Protective System Applied	Quantity (Sq Ft)
2	Concrete and Metal Railing	Other Bridge Railing	60 Feet	Galvanized Protective System	96
10	Prestressed Concrete Channel	Prestressed Concrete Top Flange	770 Square Feet		
1	Asphalt Wearing Surface	Wearing Surface	723 Square Feet		
10	Prestressed Concrete Channel	Prestressed Concrete Open Girder/Beam	300 Feet		

Span Number 4

Span Length 30.4170

Skew 90.0000

Number of Items	Type of Component	Element Name	Quantity	Protective System Applied	Quantity (Sq Ft)
10	Prestressed Concrete Channel	Prestressed Concrete Open Girder/Beam	310 Feet		
2	Concrete and Metal Railing	Other Bridge Railing	62 Feet	Galvanized Protective System	80
1	Asphalt Wearing Surface	Wearing Surface	733 Square Feet		
10	Prestressed Concrete Channel	Prestressed Concrete Top Flange	780 Square Feet		

Superstructure Build Details



Structure Element Scoring

Structure Number: **910126**

Inspection Date **8/10/2021**

Element Number	Parent Number	Element Name	Location	Total Quantity	Level 1 Quantity	Level 2 Quantity	Level 3 Quantity	Level 4 Quantity
15	0	Prestressed Concrete Top Flange	Beam	3100	3098	1	1	0
109	0	Prestressed Concrete Open Girder/Beam	Beam	1220	1003	47	98	72
216	0	Timber Abutment	Abutments	72	0	49	23	0
225	0	Steel Pile	Piles and Columns	13	1	12	0	0
515	225	Steel Protective Coating	Piles and Columns	216	132	0	84	0
228	0	Timber Pile	Piles and Columns	28	18	6	4	0
231	0	Steel Pier Cap	Caps	204	65	139	0	0
515	231	Steel Protective Coating	Caps	1902	1425	321	0	156
233	0	Prestressed Concrete Pier Cap	Caps	130	118	11	1	0
333	0	Other Bridge Railing	Bridge Rail	244	0	224	19	1
515	333	Steel Protective Coating	Bridge Rail	370	0	0	0	370
510	0	Wearing Surface	Wearing Surfaces	2912	2191	0	721	0

Summary of Maintenance Needs

Maintenance By Defect

Structure Number: **910126**

Inspection Date: **08/10/2021**

MMS Code	Element Name	Defect Name	Recommended Quantity
3326	Prestressed Concrete Top Flange	Delamination/Spall	1 Square Feet
3306	Prestressed Concrete Open Girder/Bear	Delamination/Spall	174 Feet
3306	Prestressed Concrete Open Girder/Bear	Exposed Prestressing	38 Feet
3306	Prestressed Concrete Open Girder/Bear	Cracking (PSC)	7 Feet
3306	Prestressed Concrete Open Girder/Bear	Patched Area	2 Feet
3346	Timber Abutment	Scour	10 Feet
3346	Timber Abutment	Decay/Section Loss	13 Feet
3346	Timber Abutment	Check/Shake	49 Feet
3344	Timber Pile	Decay/Section Loss	4 Each
3344	Timber Pile	Scour	1 Each
3344	Timber Pile	Check/Shake	7 Each
3348	Prestressed Concrete Pier Cap	Delamination/Spall	1 Feet
3348	Prestressed Concrete Pier Cap	Cracking (PSC)	11 Feet
3318	Other Bridge Railing	Connection	1 Feet
3318	Other Bridge Railing	Damage	11 Feet
3318	Other Bridge Railing	Delamination/Spall	19 Feet
2816	Wearing Surface	Patched Area/Pothole (Wearing Surface)	22 Square Feet
2816	Wearing Surface	Crack (Wearing Surface)	699 Square Feet
3342	Steel Protective Coating	Effectiveness (Steel Protective Coatings)	370 Square Feet
3342	Steel Protective Coating	Effectiveness (Steel Protective Coatings)	561 Square Feet

Element Structure Maintenance Quantities

Structure Number: **910126**

Inspection Date **08/10/2021**

Location	MMS Code	Description	Maint Quantity	Total Quantity	Severe Quantity	Poor Quantity	Fair Quantity	Good Quantity
Abutments	3346	Maintenance of Timber Bulkheads or Wingwalls	72	72	0	23	49	0
Beam	3306	Maintenance Concrete Superstructure Components	221	1220	72	98	47	1003
Beam	3326	Maintenance of Concrete Deck	1	3100	0	1	1	3098
Bridge Rail	3318	Maintenance of Concrete Bridge Rail	31	244	1	19	224	0
Bridge Rail	3342	Clean and Paint Steel	370	370	370	0	0	0
Caps	3342	Clean and Paint Steel	477	1902	156	0	321	1425
Caps	3348	Maintenance of Concrete Substructure	12	130	0	1	11	118
Caps	3354	Maintenance of Steel Substructure Components	0	204	0	0	139	65
Piles and Columns	3342	Clean and Paint Steel	84	216	0	84	0	132
Piles and Columns	3344	Maintenance To Timber Substrcutre	12	28	0	4	6	18
Piles and Columns	3354	Maintenance of Steel Substructure Components	0	13	0	0	12	1
Wearing Surfaces	2816	Asphalt Surface Repair	721	2912	0	721	0	2191

Priority Actions Request

Structure Number 910126

Span1

3306	Slab 1	Prestressed Concrete Channel	
Priority Level	Defect Type	Quantity	Defect Description
2	Delamination/Spall	1	Span 1 Slab 1: (PAR) left and right leg at bent 1, four [4] spalls/delaminations [up to 12in x 5in x 1in deep] with loss of bearing area
3306	Slab 2	Prestressed Concrete Channel	
Priority Level	Defect Type	Quantity	Defect Description
2	Delamination/Spall	2	Span 1 Slab 2: (PAR) left and right leg at bent 1, three [3] spalls/delaminations [up to 10in x 6in x 1in deep] channel legs crushing and bottom of channel legs sits below top of crutch bent cap
2	Exposed Prestressing	2	Span 1 Slab 2: [PAR] left leg near midspan, spall [16in x 5in x full width] with exposed strand that exhibits section loss [up to 25%]
3306	Slab 3	Prestressed Concrete Channel	
Priority Level	Defect Type	Quantity	Defect Description
2	Delamination/Spall	2	Span 1 Slab 3: (PAR) left and right leg at bent 1, two [2] spalls [up to 12in x 6in x 1in deep] with exposed strand, channel legs crushing and bottom of channel legs sits below top of crutch bent cap
3306	Slab 4	Prestressed Concrete Channel	
Priority Level	Defect Type	Quantity	Defect Description
2	Patched Area	1	Span 1 Slab 4: (PAR) right leg at bent 1, spalled patched area [12in x full width x 5in high] with exposed strands
3306	Slab 5	Prestressed Concrete Channel	
Priority Level	Defect Type	Quantity	Defect Description
2	Exposed Prestressing	4	Span 1 Slab 5: (PAR) right leg at midspan, spall (40in x 3in deep) with exposed strand (25% section loss)
3306	Slab 10	Prestressed Concrete Channel	
Priority Level	Defect Type	Quantity	Defect Description
2	Delamination/Spall	11	Span 1 Slab 10: [PAR] left leg at midspan, spall/delamination, [11ft x full width of leg x 11in high] with four [4] exposed prestressed strands, three [3] of the exposed strands have failed with remaining one [1] strand exhibiting section loss [up to 40%]

Span2

3306 Slab 2 Prestressed Concrete Channel

? Priority Action Request (PAR)
 1 Assigned Routine Maintenance
 2 Assigned Priority Maintenance
 3 Assigned Critical Find

Priority Actions Request

Structure Number 910126

Priority Level	Defect Type	Quantity	Defect Description
2	Delamination/Spall	3	Span 2 Slab 2: [PAR] left and right leg at bent 2, two [2] spalls/delaminations [up to 36in x 6in x full width], with two [2] exposed stirrups [no section loss noted] and exposed strand [section loss up to 20%]

3306 Slab 5 Prestressed Concrete Channel

Priority Level	Defect Type	Quantity	Defect Description
2	Delamination/Spall	1	Span 2 Slab 5: (PAR) left and right leg at bent 1, two [2] spalls [up to 12in x 8in x up to full width], with exposed stirrup [no section loss noted] channel legs crushing and bottom of channel legs sits below top of crutch bent cap

3306 Slab 7 Prestressed Concrete Channel

Priority Level	Defect Type	Quantity	Defect Description
2	Delamination/Spall	3	Span 2 Slab 7: [PAR] left leg near midspan, spall/delamination [30in x 4in x full width], with exposed strand [section loss up to 30%]

3306 Slab 9 Prestressed Concrete Channel

Priority Level	Defect Type	Quantity	Defect Description
2	Delamination/Spall	6	Span 2 Slab 9: [PAR] right leg 12ft from bent 1, spall/delamination [6ft x 3in x full width] with exposed strand (25% section loss)
2	Delamination/Spall	5	Span 2 Slab 9: [PAR] right leg at bent 1, spall/delamination [52in x 8in x up to full width] with one exposed strand (50% section loss on strand)

Span3

3306 Slab 2 Prestressed Concrete Channel

Priority Level	Defect Type	Quantity	Defect Description
2	Exposed Prestressing	6	Span 3 Slab 2: [PAR] left leg at bent 3, spall [6ft x full width x 5in], with exposed strand (40% section loss)
2	Exposed Prestressing	2	Span 3 Slab 2: (PAR) right leg at midspan, spall (20in x 5in x3/4in)

3306 Slab 5 Prestressed Concrete Channel

Priority Level	Defect Type	Quantity	Defect Description
2	Delamination/Spall	1	Span 3 Slab 5: (PAR) right leg at bent 3, spall [6in x 4in x full width], with exposed strand

3306 Slab 6 Prestressed Concrete Channel

Priority Level	Defect Type	Quantity	Defect Description
2	Delamination/Spall	2	Span 3 Slab 6: [PAR] left leg at far third, spall [2ft x 5in] with exposed strand

? Priority Action Request (PAR)
 1 Assigned Routine Maintenance
 2 Assigned Priority Maintenance
 3 Assigned Critical Find

Priority Actions Request

Structure Number 910126

Span4

Priority Level	Defect Type	Quantity	Defect Description
3318 Left Bridge Rail Concrete and Metal Railing			
2	Connection	1	Span 4 Left Bridge Rail: [PAR] rail post 6 is missing
2	Delamination/Spall	9	Span 4 Left Bridge Rail: (PAR) at rail posts 3,4 & 5, delamination/spall [up to 3ft x 11in x 3in deep] allowing excessive deflection of rail
3306 Slab 4 Prestressed Concrete Channel			
2	Delamination/Spall	1	Span 4 Slab 4: (PAR) at far end of both legs, three [3] spalls/delaminations [6in x 6in x 1-1/2in deep] with one exposed strand [section loss up to 10%]
3306 Slab 8 Prestressed Concrete Channel			
2	Delamination/Spall	1	Span 4 Slab 8: (PAR) left leg at far third, spall/delamination [36in x 3in x 2in deep] with exposed rusted strand
2	Exposed Prestressing	4	Span 4 Slab 8: [PAR] right leg at far third, spall [4ft x 3in x full width] with exposed strand
3306 Slab 10 Prestressed Concrete Channel			
2	Exposed Prestressing	20	Span 4 Slab 10: [PAR] 5 TOTAL AREAS OF AREAS IN LEFT LEG OF FULL WIDTH X UP TO 6" HIGH SPALLS WITH EXPOSED STRANDS FOR 20' TOTAL (20% SECTION LOSS) (PHOTO 4 OF 4)

Bent 1

Priority Level	Defect Type	Quantity	Defect Description
3346 Abutment Timber Abutment			
2	Decay/Section Loss	10	End Bent 1 Abutment: [PAR] between piles 3 and 5 second bulkhead board below cap, decay [10ft x up to full height x full width] with fill exposed
3344 Pile 1 Timber Pile			
2	Decay/Section Loss	1	End Bent 1 Pile 1: (PAR) along height of exposed pile, multiple checks [full height x up to 1/8in], pile sounds hollow when hammered

Priority Actions Request

Structure Number 910126

3344	Pile 3	Timber Pile	
Priority Level	Defect Type	Quantity	Defect Description
2	Decay/Section Loss	1	End Bent 1 Pile 3: (PAR) at base of pile, multiple checks [full height x up to 1/4in wide x up to 2in deep], decay [14in x 10in x 3in deep]

3344	Pile 5	Timber Pile	
Priority Level	Defect Type	Quantity	Defect Description
2	Scour	1	End Bent 1 Pile 5: (PAR) concrete collar is undermined (60%)

Bent 2

3346	Abutment	Timber Abutment	
Priority Level	Defect Type	Quantity	Defect Description
2	Decay/Section Loss	3	End Bent 2 Abutment: [PAR] between piles 1 and 2, lower board decay [3ft x 4in x full width] with exposed/missing backfill material

Other Ground Mounted Signs

3250	Other Ground Mounted Signs	Other Ground Mounted Signs	
Priority Level	Defect Type	Quantity	Defect Description
2		2	(PAR) clear roadway of bridge between 18ft-25ft; approach roadway (25.6ft) wider than clear roadway of bridge (24.083ft)
2		2	(PAR) northeast delineator covered by vegetation (southwest delineator similar)
2		1	(PAR) southeast corner of bridge adjacent to roadway, erosion hole (3ft long x 2.5ft wide x up to 4ft deep) up to 1ft of undermining of roadway

Element Condition and Maintenance Data

Structure Number: 910126

Inspection Date: 08/10/2021

Span 1 Wearing Surface

Asphalt Wearing Surface

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
510	Wearing Surface	733	557	0	176	0	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
510	Crack (Wearing Surface)	along edges of channels, (5) longitudinal cracks (full length x 1/16in)	3	150	150	Square Feet
510	Crack (Wearing Surface)	over end bent 1, transverse crack (full width x up to 1/8in)	3	24	24	Square Feet
510	Patched Area/Pothole (Wearing Surface)	northbound lane at bent 1, pothole (6in x 20in x up to 1-1/2in deep)	3	2	2	Square Feet

General Comments

Span 1 Left Bridge Rail

Concrete and Metal Railing

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
333	Other Bridge Railing	31	0	31	0	0	Feet
515	Steel Protective Coating	49	0	0	0	49	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
333	Corrosion	along length of rail, active corrosion with no section loss noted	2	25		Feet
333	Cracking (RC and Other)	along length of curb, multiple vertical cracks [6in x 0.02in] some wrap around to top face	2	6		Feet
515	Effectiveness (Steel Protective Coatings)	coating failure with active corrosion	4	49	49	Square Feet

General Comments

Span 1 Right Bridge Rail

Concrete and Metal Railing

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
333	Other Bridge Railing	31	0	23	8	0	Feet
515	Steel Protective Coating	49	0	0	0	49	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
333	Delamination/Spall	at rail post 1, spall [2ft x 10in x 3in deep]	3	2	2	Feet
333	Delamination/Spall	at rail post 2, spall [3ft x 10in x 3in deep]	3	3	3	Feet
333	Delamination/Spall	at rail post 4, spall [3ft x 10in x 3in deep]	3	3	3	Feet
333	Corrosion	along length of rail, active corrosion with no section loss noted	2	16		Feet
333	Cracking (RC and Other)	along length of curb, multiple vertical cracks [6in x 0.02in] some wrap around to top face	2	2		Feet
333	Patched Area	at rail post 3 outside face of concrete curb, patched area (5ft x full height)	2	5		Feet
515	Effectiveness (Steel Protective Coatings)	coating failure with active corrosion	4	49	49	Square Feet

General Comments

Span 1**Slab 1****Prestressed Concrete Channel**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
15	Prestressed Concrete Top Flange	78	78	0	0	0 Square Feet
109	Prestressed Concrete Open Girder/Beam	31	25	5	0	1 Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
109	Delamination/Spall	(PAR) left and right leg at bent 1, four [4] spalls/delaminations [up to 12in x 5in x 1in deep] with loss of bearing area	4	1	1 Feet
109	Delamination/Spall	exterior face at far end, spall [5.5in x 1.5in]	3		1 Feet
109	Delamination/Spall	left and right leg near midspan, multiple spalls/delaminations [up to 5in x 4in x 3/4in deep] with two exposed stirrups [no section loss noted]	2	4	4 Feet
109	Delamination/Spall	right leg at near end, spall [3in x 3in x 3/4in] with exposed rusted reinforcing [no loss noted]	2	1	1 Feet

General Comments

West face at grout pocket 3, missing grout with exposed tendon with surface rust [no section loss noted]

Span 1**Slab 2****Prestressed Concrete Channel**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
15	Prestressed Concrete Top Flange	78	78	0	0	0 Square Feet
109	Prestressed Concrete Open Girder/Beam	31	22	5	0	4 Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
109	Delamination/Spall	(PAR) left and right leg at bent 1, three [3] spalls/delaminations [up to 10in x 6in x 1in deep] channel legs crushing and bottom of channel legs sits below top of crutch bent cap	4	2	2 Feet
109	Exposed Prestressing	[PAR] left leg near midspan, spall [16in x 5in x full width] with exposed strand that exhibits section loss [up to 25%]	4	2	2 Feet
109	Delamination/Spall	left leg at far third, four [4] spalls/delaminations [up to 6in x 3in x 3/4in deep] with four [4] exposed stirrups [no section loss noted]	2	4	4 Feet
109	Delamination/Spall	right leg at near end, spall [3in x 3in x 3/4in] with exposed rusted reinforcing [no loss noted]	2	1	1 Feet

General Comments**Span 1****Slab 3****Prestressed Concrete Channel**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
15	Prestressed Concrete Top Flange	78	78	0	0	0 Square Feet
109	Prestressed Concrete Open Girder/Beam	31	22	7	0	2 Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
109	Delamination/Spall	(PAR) left and right leg at bent 1, two [2] spalls [up to 12in x 6in x 1in deep] with exposed strand, channel legs crushing and bottom of channel legs sits below top of crutch bent cap	4	2	2 Feet
109	Delamination/Spall	left and right leg at far half, multiple spalls/delaminations [up to 6in x 4in x 1/2in deep] with six [6] exposed stirrup ends [no section loss noted]	2	5	5 Feet

109	Delamination/Spall	right leg at end bent 1, two [2] spalls [up to 6in x 4in x 1/2in deep] with exposed stirrup [no section loss noted]	2	1	1	Feet
109	Delamination/Spall	right leg at near end, three [3] spalls [6in x 4in x 1in] with exposed rusted reinforcing [no loss noted]	2	1	1	Feet

General Comments**Span 1 Slab 4****Prestressed Concrete Channel**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
15	Prestressed Concrete Top Flange	78	78	0	0	0 Square Feet
109	Prestressed Concrete Open Girder/Beam	31	28	2	1	0 Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
109	Delamination/Spall	left leg at bent 1, two [2] spalls [up to 12in x 4in x 1in deep]	3		2 Feet
109	Patched Area	(PAR) right leg at bent 1, spalled patched area [12in x full width x 5in high] with exposed strands	3	1	1 Feet
109	Delamination/Spall	left leg near midspan, delamination [6in x 2in] with exposed stirrup end [no section loss noted]	2	1	1 Feet
109	Delamination/Spall	underside at far third, spall [3in x 3in x 1/2in] with exposed rebar [no section loss noted]	2	1	1 Feet

General Comments**Span 1 Slab 5****Prestressed Concrete Channel**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
15	Prestressed Concrete Top Flange	78	78	0	0	0 Square Feet
109	Prestressed Concrete Open Girder/Beam	31	20	0	7	4 Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
109	Exposed Prestressing	(PAR) right leg at midspan, spall (40in x 3in deep) with exposed strand (25% section loss)	4	4	4 Feet
109	Delamination/Spall	left and right legs at far end, four [4] spalls/delaminations [up to 9in x 4in x 1/4in]	3	1	1 Feet
109	Delamination/Spall	right leg at middle third, six spalls/delaminations [up to 8in x 4in x 1/2in deep]	3	6	6 Feet

General Comments**Span 1 Slab 6****Prestressed Concrete Channel**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
15	Prestressed Concrete Top Flange	78	76	1	1	0 Square Feet
109	Prestressed Concrete Open Girder/Beam	31	27	2	2	0 Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
15	Delamination/Spall	underside at near third, honeycomb [12in x 12in x up to 2in deep]	3	1	1 Square Feet
15	Patched Area	underside near midspan, sound patch (12in diameter)	2	1	Square Feet
109	Delamination/Spall	right leg at end bent 1, spall [20in x 6in x 1/2in deep] with two [2] exposed stirrups [no section loss noted]	3	2	3 Feet
109	Delamination/Spall	left leg 7ft from bent 1, spall [4in x 4in x 1/4in deep] with exposed stirrup that exhibits surface corrosion [no section loss noted]	2	1	1 Feet

109	Delamination/Spall	left leg at far end, spall [3in x 4in x 1/4in deep]	2	1	1 Feet
-----	--------------------	---	---	---	--------

General Comments**Span 1****Slab 7****Prestressed Concrete Channel**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
15	Prestressed Concrete Top Flange	78	78	0	0	0 Square Feet
109	Prestressed Concrete Open Girder/Beam	31	28	0	3	0 Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
109	Delamination/Spall	left and right leg at far end, three [3] spalls/delamination [up to 10in x up to full width x 5-1/2in high]	3	3	3 Feet

General Comments**Span 1****Slab 8****Prestressed Concrete Channel**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
15	Prestressed Concrete Top Flange	78	78	0	0	0 Square Feet
109	Prestressed Concrete Open Girder/Beam	31	30	0	1	0 Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
109	Patched Area	right leg at far end, one [1] unsound patch [9in x 4in]	3	1	1 Feet

General Comments**Span 1****Slab 9****Prestressed Concrete Channel**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
15	Prestressed Concrete Top Flange	78	78	0	0	0 Square Feet
109	Prestressed Concrete Open Girder/Beam	31	26	2	3	0 Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
109	Delamination/Spall	right leg at far end, three [3] spalls/delaminations [up to 9in long x 11in high x 1/2in deep] with two [2] exposed stirrups [loss < 1/16in]	3	3	3 Feet
109	Delamination/Spall	left leg at end bent 1, delamination [4in x 4in]	2	1	1 Feet
109	Delamination/Spall	left leg at far end, two [2] spalls [up to 4in diameter x 1in deep] with one [1] exposed stirrup [loss < 1/16in]	2	1	1 Feet

General Comments**Span 1****Slab 10****Prestressed Concrete Channel**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
15	Prestressed Concrete Top Flange	78	78	0	0	0 Square Feet
109	Prestressed Concrete Open Girder/Beam	31	16	1	3	11 Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
----------------	-------------	--------------------	----	--------	-----------

Structure Number: **910126**Inspection Date: **08/10/2021**

109	Delamination/Spall	[PAR] left leg at midspan, spall/delamination, [11ft x full width of leg x 11in high] with four [4] exposed prestressed strands, three [3] of the exposed strands have failed with remaining one [1] strand exhibiting section loss [up to 40%]	4	11	11	Feet
109	Delamination/Spall	left leg at end bent 1, spall/delamination [10in x 7in x 1/2in deep] with two [2] exposed stirrups [no section loss noted]	3	1	1	Feet
109	Delamination/Spall	right leg at far end over bearing, spall [18in x 9in x 1/2in deep]	3	2	2	Feet
109	Delamination/Spall	left leg at far end, delamination [5in x 3in]	2	1	1	Feet

General Comments

East face at grout pocket 3, missing grout with exposed tendon with surface rust [no section loss noted]

Span 2 Wearing Surface**Asphalt Wearing Surface**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
510	Wearing Surface	723	548	0	175	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
510	Crack (Wearing Surface)	along edges of channels, (5) longitudinal cracks (full length x 1/16in)	3	150	150 Square Feet
510	Crack (Wearing Surface)	UP TO 1/8" TRANSVERSE CRACKING OVER BENT 1	3	25	25 Square Feet

General Comments**Span 2 Left Bridge Rail****Concrete and Metal Railing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
333	Other Bridge Railing	30	0	30	0	0 Feet
515	Steel Protective Coating	48	0	0	0	48 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
333	Corrosion	along length of rail, active corrosion with no section loss noted	2	25	Feet
333	Cracking (RC and Other)	along length of curb, multiple vertical cracks [6in x 0.02in] some wrap around to top face	2	5	Feet
515	Effectiveness (Steel Protective Coatings)	coating failure with active corrosion	4	48	48 Square Feet

General Comments**Span 2 Right Bridge Rail****Concrete and Metal Railing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
333	Other Bridge Railing	30	0	28	2	0 Feet
515	Steel Protective Coating	48	0	0	0	48 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
333	Delamination/Spall	at rail post 5, delamination/spall [2ft x 8in x 3in deep]	3	2	2 Feet
333	Corrosion	along length of rail, active corrosion with no section loss noted	2	18	Feet
333	Cracking (RC and Other)	along length of curb, multiple vertical cracks [6in x 0.02in] some wrap around to top face	2	7	Feet

333	Damage	top of rail near midspan, impact damage [6ft x 2in]	2	3	3	Feet
515	Effectiveness (Steel Protective Coatings)	coating failure with active corrosion	4	48	48	Square Feet

General Comments**Span 2 Slab 1****Prestressed Concrete Channel**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
15	Prestressed Concrete Top Flange	77	77	0	0	0 Square Feet
109	Prestressed Concrete Open Girder/Beam	30	25	2	3	0 Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
109	Delamination/Spall	right leg 6ft from bent 2, spall (30in x 3in x 3/4in) with exposed rusted rebar	3	3	3 Feet
109	Delamination/Spall	right leg at near third, two [2] spalls [up to 6in x 3in x 3/4in deep]	2	2	2 Feet

General Comments

West face at grout pocket 1, missing grout with exposed tendon with surface rust [no section loss noted]

Span 2 Slab 2**Prestressed Concrete Channel**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
15	Prestressed Concrete Top Flange	77	77	0	0	0 Square Feet
109	Prestressed Concrete Open Girder/Beam	30	25	0	2	3 Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
109	Delamination/Spall	[PAR] left and right leg at bent 2, two [2] spalls/delaminations [up to 36in x 6in x full width], with two [2] exposed stirrups [no section loss noted] and exposed strand [section loss up to 20%]	4	3	3 Feet
109	Delamination/Spall	left leg at bent 1, spall [16in x 8in x 3/4in deep] with two [2] exposed stirrups [no section loss noted]	3	2	2 Feet

General Comments**Span 2 Slab 3****Prestressed Concrete Channel**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
15	Prestressed Concrete Top Flange	77	77	0	0	0 Square Feet
109	Prestressed Concrete Open Girder/Beam	30	28	0	2	0 Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
109	Delamination/Spall	left leg at bent 1, delamination [14in x 4in]	3	2	2 Feet

General Comments

Span 2**Slab 4****Prestressed Concrete Channel**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
15	Prestressed Concrete Top Flange	77	77	0	0	0 Square Feet
109	Prestressed Concrete Open Girder/Beam	30	28	0	2	0 Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
109	Delamination/Spall	left and right leg at bent 1, three [3] spalls [up to 8in x 5in x 1/2in deep], with exposed stirrup [no section loss noted]	3	2	2 Feet

General Comments

Span 2**Slab 5****Prestressed Concrete Channel**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
15	Prestressed Concrete Top Flange	77	77	0	0	0 Square Feet
109	Prestressed Concrete Open Girder/Beam	30	28	1	0	1 Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
109	Delamination/Spall	(PAR) left and right leg at bent 1, two [2] spalls [up to 12in x 8in x up to full width], with exposed stirrup [no section loss noted] channel legs crushing and bottom of channel legs sits below top of crutch bent cap	4	1	1 Feet
109	Delamination/Spall	left leg at far end, spall [3in x 4in x 1/2in deep]	2	1	1 Feet

General Comments

Span 2**Slab 6****Prestressed Concrete Channel**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
15	Prestressed Concrete Top Flange	77	77	0	0	0 Square Feet
109	Prestressed Concrete Open Girder/Beam	30	24	1	5	0 Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
109	Delamination/Spall	left and right leg at bent 1, four [4] spalls [up to 6.5in x 5.5in x 1/2in deep], with four [4] exposed stirrups [no section loss noted]	3	4	4 Feet
109	Delamination/Spall	left leg at 15ft from bent 1, spall (8in x 2in x 1/2in)	3	1	1 Feet
109	Delamination/Spall	right leg at 15ft from bent 2, spall (5in x 1-1/2in x 1/2in)	2	1	1 Feet

General Comments

Span 2**Slab 7****Prestressed Concrete Channel**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
15	Prestressed Concrete Top Flange	77	77	0	0	0 Square Feet
109	Prestressed Concrete Open Girder/Beam	30	23	0	4	3 Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
----------------	-------------	--------------------	----	--------	-----------

109	Delamination/Spall	[PAR] left leg near midspan, spall/delamination [30in x 4in x full width], with exposed strand [section loss up to 30%]	4	3	3	Feet
109	Delamination/Spall	left and right leg at bent 1, four [4] spalls [up to 8in x 3in x 1/2in], with three [3] exposed stirrups [no section loss noted]	3	4	4	Feet

General Comments**Span 2 Slab 8****Prestressed Concrete Channel**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
15	Prestressed Concrete Top Flange	77	77	0	0	0 Square Feet
109	Prestressed Concrete Open Girder/Beam	30	21	0	9	0 Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
109	Delamination/Spall	left and right leg along full length, nine [9] spalls [up to 8in x 4in x up to 1in], with five [5] exposed stirrups [no section loss noted]	3	9	9 Feet

General Comments**Span 2 Slab 9****Prestressed Concrete Channel**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
15	Prestressed Concrete Top Flange	77	77	0	0	0 Square Feet
109	Prestressed Concrete Open Girder/Beam	30	16	0	3	11 Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
109	Delamination/Spall	[PAR] right leg 12ft from bent 1, spall/delamination [6ft x 3in x full width] with exposed strand (25% section loss)	4	6	6 Feet
109	Delamination/Spall	[PAR] right leg at bent 1, spall/delamination [52in x 8in x up to full width] with one exposed strand (50% section loss on strand)	4	5	5 Feet
109	Delamination/Spall	left and right leg at bent 2, three [3] spalls/delaminations [up to 10in x 5in x 1/2in deep], with exposed stirrup [no section loss noted]	3	2	2 Feet
109	Delamination/Spall	left leg at bent 1, spall/delamination [8in x 5in x 1/2in] with exposed stirrup [no section loss noted]	3	1	1 Feet

General Comments**Span 2 Slab 10****Prestressed Concrete Channel**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
15	Prestressed Concrete Top Flange	77	77	0	0	0 Square Feet
109	Prestressed Concrete Open Girder/Beam	30	20	1	9	0 Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
109	Delamination/Spall	left and right leg at bent 1, four [4] spalls [up to 18in x 6in x 1/2in]	3	5	5 Feet
109	Delamination/Spall	left leg at midspan, delamination (4ft x 2in high) with longitudinal crack (up to 1/8in)	3	4	4 Feet
109	Delamination/Spall	left leg at bent 2, spall [up to 5in x 4in x 1/4in deep]	2	1	1 Feet

General Comments

East face at grout pocket 1, missing grout with exposed tendon with surface rust [no section loss noted]

Span 3 Wearing Surface**Asphalt Wearing Surface**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
510	Wearing Surface	723	548	0	175	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
510	Crack (Wearing Surface)	1/8" TRANSVERSE CRACK OVER BENT 2	3	25	25 Square Feet
510	Crack (Wearing Surface)	along edges of channels, (5) longitudinal cracks (full length x 1/16in)	3	150	150 Square Feet

General Comments

Span 3 Left Bridge Rail**Concrete and Metal Railing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
333	Other Bridge Railing	30	0	30	0	0 Feet
515	Steel Protective Coating	48	0	0	0	48 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
333	Corrosion	along length of rail, active corrosion with no section loss noted	2	20	Feet
333	Cracking (RC and Other)	along length of curb, multiple vertical cracks [6in x 0.02in] some wrap around to top face	2	10	Feet
515	Effectiveness (Steel Protective Coatings)	coating failure with active corrosion	4	48	48 Square Feet

General Comments

Span 3 Right Bridge Rail**Concrete and Metal Railing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
333	Other Bridge Railing	30	0	30	0	0 Feet
515	Steel Protective Coating	48	0	0	0	48 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
333	Corrosion	along length of rail, active corrosion with no section loss noted	2	16	Feet
333	Cracking (RC and Other)	along length of curb, multiple vertical cracks [full height x 0.02in] some wrap around to top face	2	6	Feet
333	Damage	along length of rail at top, three [3] areas of impact damage [up to 3ft x 3in]	2	8	8 Feet
515	Effectiveness (Steel Protective Coatings)	coating failure with active corrosion	4	48	48 Square Feet

General Comments

Span 3**Slab 1****Prestressed Concrete Channel**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
15	Prestressed Concrete Top Flange	77	77	0	0	0 Square Feet
109	Prestressed Concrete Open Girder/Beam	30	29	0	1	0 Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
109	Delamination/Spall	right leg at bent 2, spall [11in x 6in x 1in], with exposed rusted reinforcing [no section loss noted]	3	1	1 Feet

General Comments

Span 3**Slab 2****Prestressed Concrete Channel**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
15	Prestressed Concrete Top Flange	77	77	0	0	0 Square Feet
109	Prestressed Concrete Open Girder/Beam	30	17	0	7	6 Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
109	Exposed Prestressing	[PAR] left leg at bent 3, spall [6ft x full width x 5in], with exposed strand (40% section loss)	4	6	6 Feet
109	Cracking (PSC)	left leg at bent 2, longitudinal crack (4ft x 1/32in)	3	4	4 Feet
109	Delamination/Spall	left right leg at bent 2, two [2] spalls/delaminations [8in x 5in x 1in deep], with exposed stirrup [no section loss noted]	3	1	1 Feet
109	Exposed Prestressing	(PAR) right leg at midspan, spall (20in x 5in x 3/4in) with exposed rusted strand	3	2	2 Feet

General Comments

Span 3**Slab 3****Prestressed Concrete Channel**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
15	Prestressed Concrete Top Flange	77	77	0	0	0 Square Feet
109	Prestressed Concrete Open Girder/Beam	30	29	1	0	0 Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
109	Delamination/Spall	left leg at bent 2, delamination [5in x 5in]	2	1	1 Feet

General Comments

Span 3**Slab 5****Prestressed Concrete Channel**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
15	Prestressed Concrete Top Flange	77	77	0	0	0 Square Feet
109	Prestressed Concrete Open Girder/Beam	30	23	0	7	0 Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
109	Delamination/Spall	(PAR) right leg at bent 3, spall [6in x 4in x full width], with exposed strand	3	1	1 Feet

109	Delamination/Spall	left and right legs along length of slab, six [6] spalls/delaminations [up to 8in x 6in x 1/2in deep], with six [6] exposed stirrups [no section loss noted]	3	6	6	Feet
-----	--------------------	--	---	---	---	------

General Comments

Span 3 Slab 6**Prestressed Concrete Channel**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
15	Prestressed Concrete Top Flange	77	77	0	0	0 Square Feet
109	Prestressed Concrete Open Girder/Beam	30	23	4	3	0 Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
109	Delamination/Spall	[PAR] left leg at far third, spall [2ft x 5in] with exposed strand	3	2	2 Feet
109	Delamination/Spall	right leg at bent 3, spall [10in x 4in x 1/2in deep]	3	1	1 Feet
109	Delamination/Spall	left and right leg along length of slab, four [4] spalls/delaminations [2in x 4in x 1/2in deep], with three [3] exposed stirrups [no section loss noted]	2	4	4 Feet

General Comments

Span 3 Slab 7**Prestressed Concrete Channel**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
15	Prestressed Concrete Top Flange	77	77	0	0	0 Square Feet
109	Prestressed Concrete Open Girder/Beam	30	29	1	0	0 Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
109	Delamination/Spall	left leg at bent 3, spall [6in x 2in x 1/4in deep]	2	1	1 Feet

General Comments

Span 3 Slab 8**Prestressed Concrete Channel**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
15	Prestressed Concrete Top Flange	77	77	0	0	0 Square Feet
109	Prestressed Concrete Open Girder/Beam	30	27	0	3	0 Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
109	Cracking (PSC)	right leg at far third, longitudinal crack (16in x 1/32in)	3	2	2 Feet
109	Delamination/Spall	left and right leg at bent 3, two [2] spalls/delaminations [up to 9in x 2in x 1in deep], with exposed strand [no section loss noted]	3	1	1 Feet

General Comments

Span 3**Slab 9****Prestressed Concrete Channel**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
15	Prestressed Concrete Top Flange	77	77	0	0	0	Square Feet
109	Prestressed Concrete Open Girder/Beam	30	28	1	1	0	Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
109	Delamination/Spall	left leg at 6ft from bent 2, spall (6in x 2in x 1/2in)	3	1	1	Feet
109	Delamination/Spall	left leg at bent 3, spall [3in x 2in x 1/4in deep]	2	1	1	Feet

General Comments

Span 3**Slab 10****Prestressed Concrete Channel**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
15	Prestressed Concrete Top Flange	77	77	0	0	0	Square Feet
109	Prestressed Concrete Open Girder/Beam	30	28	0	2	0	Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
109	Delamination/Spall	right leg at bent 2, spall [22in x 15in x 2in], with exposed stirrup [no section loss noted]	3	2	2	Feet

General Comments

Span 4**Wearing Surface****Asphalt Wearing Surface**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
510	Wearing Surface	733	538	0	195	0	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
510	Crack (Wearing Surface)	along edges of channels, (5) longitudinal cracks (full length x 1/8in)	3	150	150	Square Feet
510	Crack (Wearing Surface)	over end bent 2, transverse crack (full width x up to 1/8in)	3	25	25	Square Feet
510	Patched Area/Pothole (Wearing Surface)	northbound lane along edge of channels 8 and 9, pothole (20ft x 3in x 1in)	3	20	20	Square Feet

General Comments

Span 4**Left Bridge Rail****Concrete and Metal Railing**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
333	Other Bridge Railing	31	0	21	9	1	Feet
515	Steel Protective Coating	49	0	0	0	49	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
333	Connection	[PAR] rail post 6 is missing	4	1	1	Feet
333	Delamination/Spall	(PAR) at rail posts 3,4 & 5, delamination/spall [up to 3ft x 11in x 3in deep] allowing excessive deflection of rail	3	9	9	Feet
333	Corrosion	along length of rail, active corrosion with no section loss noted	2	11		Feet

Structure Number: **910126**Inspection Date: **08/10/2021**

333	Cracking (RC and Other)	along length of curb, multiple vertical cracks [full height x 0.02in] some wrap around to top face	2	10	Feet
515	Effectiveness (Steel Protective Coatings)	coating failure with active corrosion	4	49	49 Square Feet

General Comments

Span 4 Right Bridge Rail

Concrete and Metal Railing

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
333	Other Bridge Railing	31	0	31	0	0 Feet
515	Steel Protective Coating	31	0	0	0	31 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
333	Corrosion	along length of rail, active corrosion with no section loss noted	2	25	Feet
333	Cracking (RC and Other)	along length of curb, multiple vertical cracks [6in x 0.02in] some wrap around to top face	2	6	Feet
515	Effectiveness (Steel Protective Coatings)	coating failure with active corrosion	4	31	31 Square Feet

General Comments

Span 4 Slab 1

Prestressed Concrete Channel

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
15	Prestressed Concrete Top Flange	78	78	0	0	0 Square Feet
109	Prestressed Concrete Open Girder/Beam	31	25	1	5	0 Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
109	Delamination/Spall	right leg at bent 3, two [2] spalls [up to 8in x 3in] with exposed stirrup [no section loss noted]	3	2	2 Feet
109	Delamination/Spall	right leg at near third, spall [14in x 3in x full width] with exposed stirrup [no section loss noted]	3	2	2 Feet
109	Delamination/Spall	right leg near midspan, spall [12in x 8in x 3/4in] with exposed stirrup [no section loss noted]	3	1	1 Feet
109	Delamination/Spall	at far end of right leg, spall [3in x 2in x 1/4in deep]	2	1	1 Feet

General Comments

Span 4 Slab 2

Prestressed Concrete Channel

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
15	Prestressed Concrete Top Flange	78	78	0	0	0 Square Feet
109	Prestressed Concrete Open Girder/Beam	31	29	2	0	0 Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
109	Delamination/Spall	at far end of left leg, spall [2in x 2in x 1/4in deep] with one exposed stirrup [no section loss noted]	2	1	1 Feet
109	Delamination/Spall	left leg at bent 3, spall [6in x 6in x 1/2in deep]	2	1	1 Feet

General Comments

Span 4**Slab 3****Prestressed Concrete Channel**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
15	Prestressed Concrete Top Flange	78	78	0	0	0 Square Feet
109	Prestressed Concrete Open Girder/Beam	31	30	1	0	0 Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
109	Delamination/Spall	at far end of both legs, spall [4in x 2in x 1/4in deep] with two exposed stirrups [no section loss noted]	2	1	1 Feet

General Comments

Span 4**Slab 4****Prestressed Concrete Channel**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
15	Prestressed Concrete Top Flange	78	78	0	0	0 Square Feet
109	Prestressed Concrete Open Girder/Beam	31	30	0	0	1 Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
109	Delamination/Spall	(PAR) at far end of both legs, three [3] spalls/delaminations [6in x 6in x 1-1/2in deep] with one exposed strand [section loss up to 10%]	4	1	1 Feet

General Comments

Span 4**Slab 5****Prestressed Concrete Channel**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
15	Prestressed Concrete Top Flange	78	78	0	0	0 Square Feet
109	Prestressed Concrete Open Girder/Beam	31	28	1	2	0 Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
109	Delamination/Spall	right leg at bent 3, spall/delamination [18in x 5in x 1/2in] with two [2] exposed stirrups [no section loss noted]	3	2	2 Feet
109	Delamination/Spall	at far end of right leg, spall [3in x 2in x 1/4in deep] with one exposed stirrup [no section loss noted]	2	1	1 Feet

General Comments

Span 4**Slab 6****Prestressed Concrete Channel**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
15	Prestressed Concrete Top Flange	78	78	0	0	0 Square Feet
109	Prestressed Concrete Open Girder/Beam	31	29	2	0	0 Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
109	Delamination/Spall	at far end of left leg, two [2] spalls/delaminations [6in x 5in x 1/2in deep] with two exposed stirrups [no section loss noted]	2	1	1 Feet
109	Delamination/Spall	left leg at bent 3, spall [6in x 3in x 1/2in]	2	1	1 Feet

General Comments

Span 4 Slab 7**Prestressed Concrete Channel**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
15	Prestressed Concrete Top Flange	78	78	0	0	0 Square Feet
109	Prestressed Concrete Open Girder/Beam	31	30	1	0	0 Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
109	Delamination/Spall	at far end of both legs, three [3] spalls/delaminations [6in x 6in x 1/2in deep] with two exposed stirrups [no section loss noted]	2	1	1 Feet

General Comments

Span 4 Slab 8**Prestressed Concrete Channel**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
15	Prestressed Concrete Top Flange	78	78	0	0	0 Square Feet
109	Prestressed Concrete Open Girder/Beam	31	18	2	6	5 Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
109	Delamination/Spall	(PAR) left leg at far third, spall/delamination [36in x 3in x 2in deep] with exposed rusted strand	4	1	1 Feet
109	Exposed Prestressing	[PAR] right leg at far third, spall [4ft x 3in x full width] with exposed strand	4	4	4 Feet
109	Cracking (PSC)	right leg at near third, longitudinal crack (1ft x 1/32in)	3	1	1 Feet
109	Delamination/Spall	right leg at near third, five [5] spalls/delaminations [up to 8in x 3in x 1/2in deep] with four [4] exposed stirrups [no section loss noted]	3	5	5 Feet
109	Delamination/Spall	at far end of both legs, two [2] spalls/delaminations [8in x 3in x 1/2in deep] with two exposed stirrups [no section loss noted]	2	1	1 Feet
109	Delamination/Spall	left leg at bent 3, spall [4in x 4in x 1/4in deep]	2	1	1 Feet

General Comments

Span 4 Slab 9**Prestressed Concrete Channel**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
15	Prestressed Concrete Top Flange	78	78	0	0	0 Square Feet
109	Prestressed Concrete Open Girder/Beam	31	30	0	1	0 Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
109	Delamination/Spall	at far end of right leg, spall [8in x 4in x 1in deep] with one exposed stirrup [no section loss noted]	3	1	1 Feet

General Comments

Span 4**Slab 10****Prestressed Concrete Channel**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
15	Prestressed Concrete Top Flange	78	78	0	0	0	Square Feet
109	Prestressed Concrete Open Girder/Beam	31	9	1	1	20	Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
109	Exposed Prestressing	[PAR] 5 TOTAL AREAS OF AREAS IN LEFT LEG OF FULL WIDTH X UP TO 6" HIGH SPALLS WITH EXPOSED STRANDS FOR 20' TOTAL (20% SECTION LOSS)	4	20	20	Feet
109	Delamination/Spall	right leg at bent 3, spall [10in x 4in x 3/4in deep]	3	1	1	Feet
109	Delamination/Spall	at far end of left leg, spall [3in x 2in x 1/4in deep] with one exposed stirrup [no section loss noted]	2	1	1	Feet

General Comments**End Bent 1****Abutment****Timber Abutment**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
216	Timber Abutment	36	0	26	10	0	Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
216	Decay/Section Loss	[PAR] between piles 3 and 5 second bulkhead board below cap, decay [10ft x up to full height x full width] with fill exposed	3	10	10	Feet
216	Check/Shake	along length of backwall, checks/shakes [up to 1ft x up to 1/8in], with surface decay [up to 1/2in]	2	26	26	Feet

General Comments**End Bent 1****Pile 1****Timber Pile**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
228	Timber Pile	1	0	0	1	0	Each

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
228	Decay/Section Loss	(PAR) along height of exposed pile, multiple checks [full height x up to 1/8in], pile sounds hollow when hammered	3	1	1	Each

General Comments**End Bent 1****Pile 2****Timber Pile**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
228	Timber Pile	1	0	1	0	0	Each

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
228	Check/Shake	along height of exposed pile, multiple checks [full height x up to 1/8in]	2	1	1	Each

General Comments

Replaced pile section with concrete collar

End Bent 1**Pile 3****Timber Pile**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
228	Timber Pile	1	0	0	1	0 Each

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
228	Decay/Section Loss	(PAR) at base of pile, multiple checks [full height x up to 1/4in wide x up to 2in deep], decay [14in x 10in x 3in deep]	3	1	1 Each

General Comments**End Bent 1****Pile 4****Timber Pile**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
228	Timber Pile	1	0	1	0	0 Each

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
228	Check/Shake	along height of exposed pile, multiple checks [full height x up to 1/8in]	2	1	1 Each

General Comments

replaced pile section with concrete collar

End Bent 1**Pile 5****Timber Pile**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
228	Timber Pile	1	0	0	1	0 Each

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
228	Scour	(PAR) concrete collar is undermined (60%)	3	1	1 Each
228	Check/Shake	along height of exposed pile, multiple checks [full height x up to 1/16in]	2		1 Each

General Commentsreplaced pile section with concrete collar
concrete collar is undermined, [full width x 1ft high]**End Bent 1****End Bent Cap 1****Prestressed Concrete Pier Cap**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
233	Prestressed Concrete Pier Cap	26	25	0	1	0 Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
233	Delamination/Spall	over pile 3, spall/delamination [8in x 5in x 1/4in deep]	3	1	1 Feet

General Comments

End Bent 2 Abutment
Timber Abutment

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
216	Timber Abutment	36	0	23	13	0 Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
216	Decay/Section Loss	[PAR] between piles 1 and 2, lower board decay [3ft x 4in x full width] with exposed/missing backfill material	3	3	3 Feet
216	Scour	between piles 1 & 3, erosion [10ft long x 7ft x 18in deep] also gap [up to 2in] at cap/backwall junction	3	10	10 Feet
216	Check/Shake	along length of abutment, checks [up to 1/16in]	2	23	23 Feet

General Comments

End Bent 2 Pile 1
Timber Pile

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
228	Timber Pile	1	0	1	0	0 Each

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
228	Check/Shake	along height of pile, multiple checks [up to 1/16in]	2		Each
228	Decay/Section Loss	South face a midheight, section loss [4in high x 4-1/4in wide x 3/4in deep]	2	1	1 Each

General Comments

End Bent 2 Pile 2
Timber Pile

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
228	Timber Pile	1	0	1	0	0 Each

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
228	Check/Shake	along height of pile, multiple checks [up to 1/16in]	2	1	1 Each

General Comments

End Bent 2 Pile 3
Timber Pile

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
228	Timber Pile	1	0	0	1	0 Each

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
228	Decay/Section Loss	at base of pile, decay (8in x 1in x 1-1/2in deep)	3	1	1 Each
228	Check/Shake	along height of pile, multiple checks [up to 1/8in]	2		1 Each
228	Decay/Section Loss	South face a midheight, section loss [3-1/2in high x 3-1/4in wide x 1in deep]	2		Each

General Comments

End Bent 2**Pile 5****Timber Pile**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
228	Timber Pile	1	0	1	0	0 Each

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
228	Check/Shake	along height of pile, multiple checks [up to 1/16in]	2	1	1 Each

General Comments

replacement pile for pile 4

End Bent 2**Pile 6****Timber Pile**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
228	Timber Pile	1	0	1	0	0 Each

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
228	Check/Shake	along height of pile, multiple checks [up to 1/16in]	2	1	1 Each

General Comments

replacement pile for pile 7

End Bent 2**End Bent 2 Cap****Prestressed Concrete Pier Cap**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
233	Prestressed Concrete Pier Cap	26	15	11	0	0 Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
233	Cracking (PSC)	at multiple locations along cap, longitudinal crack [up to 5ft x 0.009in]	2	11	11 Feet

General Comments**Crutch Bent 1 Span 1****Cap 1****Steel Pier Cap**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
231	Steel Pier Cap	34	6	28	0	0 Feet
515	Steel Protective Coating	317	234	52	0	31 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
231	Corrosion	along length of cap at lower web and top flange, corrosion with section loss [<1/16in] with adjacent spot rust	2	28	Feet
515	Effectiveness (Steel Protective Coatings)	along length of lower web, top flange, paint failure with active corrosion with section loss	4	31	31 Square Feet
515	Effectiveness (Steel Protective Coatings)	along length of cap at random locations, paint failure with active spot rust	2	52	52 Square Feet

General Comments

Crutch Bent 1 Span 1**Pile 1****Steel Cross Cap Crutch Pile**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
225	Steel Pile	1	0	1	0	0	Each
515	Steel Protective Coating	18	11	0	7	0	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
225	Corrosion	at pile cap, surface corrosion [no section loss noted] with adjacent spot rust	2	1		Each
515	Effectiveness (Steel Protective Coatings)	at pile cap and random locations along the height of pile, active surface corrosion	3	7	7	Square Feet

General Comments

Crutch Bent 1 Span 1**Pile 2****Steel Cross Cap Crutch Pile**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
225	Steel Pile	1	0	1	0	0	Each
515	Steel Protective Coating	18	11	0	7	0	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
225	Corrosion	at pile cap, surface corrosion [no section loss noted] with adjacent spot rust	2	1		Each
515	Effectiveness (Steel Protective Coatings)	at pile cap and random locations along the height of pile, active surface corrosion	3	7	7	Square Feet

General Comments

Crutch Bent 1 Span 2**Cap 1****Steel Pier Cap**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
231	Steel Pier Cap	34	7	27	0	0	Feet
515	Steel Protective Coating	317	232	54	0	31	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
231	Corrosion	along length of cap at lower web and top flange, corrosion with section loss [<1/16in] with adjacent spot rust	2	27		Feet
515	Effectiveness (Steel Protective Coatings)	along length of lower web, top flange, paint failure with active corrosion with section loss	4	31	31	Square Feet
515	Effectiveness (Steel Protective Coatings)	along length of cap at random locations, paint failure with active spot rust	2	54	54	Square Feet

General Comments

Crutch Bent 1 Span 2**Pile 1****Steel Cross Cap Crutch Pile**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
225	Steel Pile	1	0	1	0	0	Each
515	Steel Protective Coating	18	12	0	6	0	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
----------------	-------------	--------------------	----	--------	-----------	--

225	Corrosion	at pile cap, surface corrosion [no section loss noted] with adjacent spot rust	2	1	Each
515	Effectiveness (Steel Protective Coatings)	at pile cap and random locations along the height of pile, active surface corrosion	3	6	6 Square Feet

General Comments

Crutch Bent 1 Span 2**Pile 2****Steel Cross Cap Crutch Pile**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
225	Steel Pile	1	0	1	0	0 Each
515	Steel Protective Coating	18	11	0	7	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
225	Corrosion	at pile cap, surface corrosion [no section loss noted] with adjacent spot rust	2	1	Each
515	Effectiveness (Steel Protective Coatings)	at pile cap and random locations along the height of pile, active surface corrosion	3	7	7 Square Feet

General Comments

Crutch Bent 2 Span 2**Cap 1****Steel Pier Cap**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
231	Steel Pier Cap	34	13	21	0	0 Feet
515	Steel Protective Coating	317	242	51	0	24 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
231	Corrosion	along length of cap at lower web and top flange, corrosion with section loss [$<1/16$ in] with adjacent spot rust	2	21	Feet
515	Effectiveness (Steel Protective Coatings)	along length of lower web, top flange, paint failure with active corrosion with section loss	4	24	24 Square Feet
515	Effectiveness (Steel Protective Coatings)	along length of cap at random locations, paint failure with active spot rust	2	51	51 Square Feet

General Comments

Crutch Bent 2 Span 2**Pile 1****Steel Cross Cap Crutch Pile**

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
225	Steel Pile	1	0	1	0	0 Each
515	Steel Protective Coating	18	10	0	8	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
225	Corrosion	at pile cap, surface corrosion [no section loss noted] with adjacent spot rust	2	1	Each
515	Effectiveness (Steel Protective Coatings)	at pile cap and random locations along the height of pile, active surface corrosion	3	8	8 Square Feet

General Comments

Crutch Bent 2 Span 2 Pile 2
Steel Cross Cap Crutch Pile

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
225	Steel Pile	1	0	1	0	0	Each
515	Steel Protective Coating	18	11	0	7	0	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
225	Corrosion	at pile cap, surface corrosion [no section loss noted] with adjacent spot rust	2	1		Each
515	Effectiveness (Steel Protective Coatings)	at pile cap and random locations along the height of pile, active surface corrosion	3	7	7	Square Feet

General Comments

Crutch Bent 1 Span 3 Cap 1
Steel Pier Cap

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
231	Steel Pier Cap	34	18	16	0	0	Feet
515	Steel Protective Coating	317	243	56	0	18	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
231	Corrosion	along length of cap at lower web and top flange, corrosion with section loss [$<1/16$ in] with adjacent spot rust	2	16		Feet
515	Effectiveness (Steel Protective Coatings)	along length of lower web, top flange, paint failure with active corrosion with section loss	4	18	18	Square Feet
515	Effectiveness (Steel Protective Coatings)	along length of cap at random locations, paint failure with active spot rust	2	56	56	Square Feet

General Comments

Crutch Bent 1 Span 3 Pile 1
Steel Cross Cap Crutch Pile

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
225	Steel Pile	1	0	1	0	0	Each
515	Steel Protective Coating	18	11	0	7	0	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
225	Corrosion	at pile cap, surface corrosion [no section loss noted] with adjacent spot rust	2	1		Each
515	Effectiveness (Steel Protective Coatings)	at pile cap and random locations along the height of pile, active surface corrosion	3	7	7	Square Feet

General Comments

Crutch Bent 1 Span 3 Pile 2
Steel Cross Cap Crutch Pile

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty	
225	Steel Pile	1	0	1	0	0	Each
515	Steel Protective Coating	18	12	0	6	0	Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty	
----------------	-------------	--------------------	----	--------	-----------	--

Structure Number: 910126

Inspection Date: 08/10/2021

225	Corrosion	at pile cap, surface corrosion [no section loss noted] with adjacent spot rust	2	1	Each
515	Effectiveness (Steel Protective Coatings)	at pile cap and random locations along the height of pile, active surface corrosion	3	6	6 Square Feet

General Comments

Crutch Bent 2 Span 3 Cap 1

Steel Pier Cap

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
231	Steel Pier Cap	34	12	22	0	0 Feet
515	Steel Protective Coating	317	240	53	0	24 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
231	Corrosion	along length of cap at lower web and top flange, corrosion with section loss [$<1/16$ in] with adjacent spot rust	2	22	Feet
515	Effectiveness (Steel Protective Coatings)	along length of lower web, top flange, paint failure with active corrosion with section loss	4	24	24 Square Feet
515	Effectiveness (Steel Protective Coatings)	along length of cap at random locations, paint failure with active spot rust	2	53	53 Square Feet

General Comments

Crutch Bent 2 Span 3 Pile 1

Steel Cross Cap Crutch Pile

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
225	Steel Pile	1	0	1	0	0 Each
515	Steel Protective Coating	18	10	0	8	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
225	Corrosion	at pile cap, surface corrosion [no section loss noted] with adjacent spot rust	2	1	Each
515	Effectiveness (Steel Protective Coatings)	at pile cap and random locations along the height of pile, active surface corrosion	3	8	8 Square Feet

General Comments

Crutch Bent 2 Span 3 Pile 2

Steel Cross Cap Crutch Pile

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
225	Steel Pile	1	0	1	0	0 Each
515	Steel Protective Coating	18	12	0	6	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
225	Corrosion	at pile cap, surface corrosion [no section loss noted] with adjacent spot rust	2	1	Each
515	Effectiveness (Steel Protective Coatings)	at pile cap and random locations along the height of pile, active surface corrosion	3	6	6 Square Feet

General Comments

Crutch Bent 1 Span 4 Cap 1
Steel Pier Cap

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
231	Steel Pier Cap	34	9	25	0	0 Feet
515	Steel Protective Coating	317	234	55	0	28 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
231	Corrosion	along length of cap at lower web and top flange, corrosion with section loss [$<1/16$ in] with adjacent spot rust	2	25	Feet
515	Effectiveness (Steel Protective Coatings)	along length of lower web, top flange, paint failure with active corrosion with section loss	4	28	28 Square Feet
515	Effectiveness (Steel Protective Coatings)	along length of cap at random locations, paint failure with active spot rust	2	55	55 Square Feet

General Comments

Crutch Bent 1 Span 4 Pile 1
Steel Cross Cap Crutch Pile

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
225	Steel Pile	1	0	1	0	0 Each
515	Steel Protective Coating	18	10	0	8	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
225	Corrosion	at pile cap, surface corrosion [no section loss noted] with adjacent spot rust	2	1	Each
515	Effectiveness (Steel Protective Coatings)	at pile cap and random locations along the height of pile, active surface corrosion	3	8	8 Square Feet

General Comments

Crutch Bent 1 Span 4 Pile 2
Steel Cross Cap Crutch Pile

Element Number	Element Name	Total Qty	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
225	Steel Pile	1	0	1	0	0 Each
515	Steel Protective Coating	18	11	0	7	0 Square Feet

Element Number	Defect Type	Defect Description	CS	CS Qty	Maint Qty
225	Corrosion	at pile cap, surface corrosion [no section loss noted] with adjacent spot rust	2	1	Each
515	Effectiveness (Steel Protective Coatings)	at pile cap and random locations along the height of pile, active surface corrosion	3	7	7 Square Feet

General Comments

Elements Verified

Location	Name	Component	Element Name	Amount
Span 1	Slab 1	Prestressed Concrete Channel	Prestressed Concrete Open Girder/Beam	31
Span 1	Slab 1	Prestressed Concrete Channel	Prestressed Concrete Top Flange	78
Span 1	Slab 2	Prestressed Concrete Channel	Prestressed Concrete Open Girder/Beam	31
Span 1	Slab 2	Prestressed Concrete Channel	Prestressed Concrete Top Flange	78
Span 1	Slab 3	Prestressed Concrete Channel	Prestressed Concrete Open Girder/Beam	31
Span 1	Slab 3	Prestressed Concrete Channel	Prestressed Concrete Top Flange	78
Span 1	Slab 4	Prestressed Concrete Channel	Prestressed Concrete Open Girder/Beam	31
Span 1	Slab 4	Prestressed Concrete Channel	Prestressed Concrete Top Flange	78
Span 1	Slab 5	Prestressed Concrete Channel	Prestressed Concrete Open Girder/Beam	31
Span 1	Slab 5	Prestressed Concrete Channel	Prestressed Concrete Top Flange	78
Span 1	Slab 6	Prestressed Concrete Channel	Prestressed Concrete Open Girder/Beam	31
Span 1	Slab 6	Prestressed Concrete Channel	Prestressed Concrete Top Flange	78
Span 1	Slab 7	Prestressed Concrete Channel	Prestressed Concrete Open Girder/Beam	31
Span 1	Slab 7	Prestressed Concrete Channel	Prestressed Concrete Top Flange	78
Span 1	Slab 8	Prestressed Concrete Channel	Prestressed Concrete Open Girder/Beam	31
Span 1	Slab 8	Prestressed Concrete Channel	Prestressed Concrete Top Flange	78
Span 1	Slab 9	Prestressed Concrete Channel	Prestressed Concrete Open Girder/Beam	31
Span 1	Slab 9	Prestressed Concrete Channel	Prestressed Concrete Top Flange	78
Span 1	Slab 10	Prestressed Concrete Channel	Prestressed Concrete Open Girder/Beam	31
Span 1	Slab 10	Prestressed Concrete Channel	Prestressed Concrete Top Flange	78
Span 1	Left Bridge Rail	Concrete and Metal Railing	Other Bridge Railing	31
Span 1	Right Bridge Rail	Concrete and Metal Railing	Other Bridge Railing	31
Span 1	Wearing Surface	Asphalt Wearing Surface	Wearing Surface	733
Span 2	Slab 1	Prestressed Concrete Channel	Prestressed Concrete Open Girder/Beam	30
Span 2	Slab 1	Prestressed Concrete Channel	Prestressed Concrete Top Flange	77
Span 2	Slab 2	Prestressed Concrete Channel	Prestressed Concrete Open Girder/Beam	30
Span 2	Slab 2	Prestressed Concrete Channel	Prestressed Concrete Top Flange	77
Span 2	Slab 3	Prestressed Concrete Channel	Prestressed Concrete Open Girder/Beam	30
Span 2	Slab 3	Prestressed Concrete Channel	Prestressed Concrete Top Flange	77
Span 2	Slab 4	Prestressed Concrete Channel	Prestressed Concrete Open Girder/Beam	30
Span 2	Slab 4	Prestressed Concrete Channel	Prestressed Concrete Top Flange	77
Span 2	Slab 5	Prestressed Concrete Channel	Prestressed Concrete Open Girder/Beam	30
Span 2	Slab 5	Prestressed Concrete Channel	Prestressed Concrete Top Flange	77
Span 2	Slab 6	Prestressed Concrete Channel	Prestressed Concrete Open Girder/Beam	30
Span 2	Slab 6	Prestressed Concrete Channel	Prestressed Concrete Top Flange	77
Span 2	Slab 7	Prestressed Concrete Channel	Prestressed Concrete Open Girder/Beam	30
Span 2	Slab 7	Prestressed Concrete Channel	Prestressed Concrete Top Flange	77
Span 2	Slab 8	Prestressed Concrete Channel	Prestressed Concrete Open Girder/Beam	30
Span 2	Slab 8	Prestressed Concrete Channel	Prestressed Concrete Top Flange	77
Span 2	Slab 9	Prestressed Concrete Channel	Prestressed Concrete Open Girder/Beam	30
Span 2	Slab 9	Prestressed Concrete Channel	Prestressed Concrete Top Flange	77
Span 2	Slab 10	Prestressed Concrete Channel	Prestressed Concrete Open Girder/Beam	30
Span 2	Slab 10	Prestressed Concrete Channel	Prestressed Concrete Top Flange	77
Span 2	Left Bridge Rail	Concrete and Metal Railing	Other Bridge Railing	30
Span 2	Right Bridge Rail	Concrete and Metal Railing	Other Bridge Railing	30

Elements Verified

Location	Name	Component	Element Name	Amount
Span 2	Wearing Surface	Asphalt Wearing Surface	Wearing Surface	723
Span 3	Slab 1	Prestressed Concrete Channel	Prestressed Concrete Open Girder/Beam	30
Span 3	Slab 1	Prestressed Concrete Channel	Prestressed Concrete Top Flange	77
Span 3	Slab 2	Prestressed Concrete Channel	Prestressed Concrete Open Girder/Beam	30
Span 3	Slab 2	Prestressed Concrete Channel	Prestressed Concrete Top Flange	77
Span 3	Slab 3	Prestressed Concrete Channel	Prestressed Concrete Open Girder/Beam	30
Span 3	Slab 3	Prestressed Concrete Channel	Prestressed Concrete Top Flange	77
Span 3	Slab 4	Prestressed Concrete Channel	Prestressed Concrete Open Girder/Beam	30
Span 3	Slab 4	Prestressed Concrete Channel	Prestressed Concrete Top Flange	77
Span 3	Slab 5	Prestressed Concrete Channel	Prestressed Concrete Open Girder/Beam	30
Span 3	Slab 5	Prestressed Concrete Channel	Prestressed Concrete Top Flange	77
Span 3	Slab 6	Prestressed Concrete Channel	Prestressed Concrete Open Girder/Beam	30
Span 3	Slab 6	Prestressed Concrete Channel	Prestressed Concrete Top Flange	77
Span 3	Slab 7	Prestressed Concrete Channel	Prestressed Concrete Open Girder/Beam	30
Span 3	Slab 7	Prestressed Concrete Channel	Prestressed Concrete Top Flange	77
Span 3	Slab 8	Prestressed Concrete Channel	Prestressed Concrete Open Girder/Beam	30
Span 3	Slab 8	Prestressed Concrete Channel	Prestressed Concrete Top Flange	77
Span 3	Slab 9	Prestressed Concrete Channel	Prestressed Concrete Open Girder/Beam	30
Span 3	Slab 9	Prestressed Concrete Channel	Prestressed Concrete Top Flange	77
Span 3	Slab 10	Prestressed Concrete Channel	Prestressed Concrete Open Girder/Beam	30
Span 3	Slab 10	Prestressed Concrete Channel	Prestressed Concrete Top Flange	77
Span 3	Left Bridge Rail	Concrete and Metal Railing	Other Bridge Railing	30
Span 3	Right Bridge Rail	Concrete and Metal Railing	Other Bridge Railing	30
Span 3	Wearing Surface	Asphalt Wearing Surface	Wearing Surface	723
Span 4	Slab 1	Prestressed Concrete Channel	Prestressed Concrete Open Girder/Beam	31
Span 4	Slab 1	Prestressed Concrete Channel	Prestressed Concrete Top Flange	78
Span 4	Slab 2	Prestressed Concrete Channel	Prestressed Concrete Open Girder/Beam	31
Span 4	Slab 2	Prestressed Concrete Channel	Prestressed Concrete Top Flange	78
Span 4	Slab 3	Prestressed Concrete Channel	Prestressed Concrete Open Girder/Beam	31
Span 4	Slab 3	Prestressed Concrete Channel	Prestressed Concrete Top Flange	78
Span 4	Slab 4	Prestressed Concrete Channel	Prestressed Concrete Open Girder/Beam	31
Span 4	Slab 4	Prestressed Concrete Channel	Prestressed Concrete Top Flange	78
Span 4	Slab 5	Prestressed Concrete Channel	Prestressed Concrete Open Girder/Beam	31
Span 4	Slab 5	Prestressed Concrete Channel	Prestressed Concrete Top Flange	78
Span 4	Slab 6	Prestressed Concrete Channel	Prestressed Concrete Open Girder/Beam	31
Span 4	Slab 6	Prestressed Concrete Channel	Prestressed Concrete Top Flange	78
Span 4	Slab 7	Prestressed Concrete Channel	Prestressed Concrete Open Girder/Beam	31
Span 4	Slab 7	Prestressed Concrete Channel	Prestressed Concrete Top Flange	78
Span 4	Slab 8	Prestressed Concrete Channel	Prestressed Concrete Open Girder/Beam	31
Span 4	Slab 8	Prestressed Concrete Channel	Prestressed Concrete Top Flange	78
Span 4	Slab 9	Prestressed Concrete Channel	Prestressed Concrete Open Girder/Beam	31
Span 4	Slab 9	Prestressed Concrete Channel	Prestressed Concrete Top Flange	78
Span 4	Slab 10	Prestressed Concrete Channel	Prestressed Concrete Open Girder/Beam	31
Span 4	Slab 10	Prestressed Concrete Channel	Prestressed Concrete Top Flange	78
Span 4	Left Bridge Rail	Concrete and Metal Railing	Other Bridge Railing	31

Elements Verified

Location	Name	Component	Element Name	Amount
Span 4	Right Bridge Rail	Concrete and Metal Railing	Other Bridge Railing	31
Span 4	Wearing Surface	Asphalt Wearing Surface	Wearing Surface	733
Bent 1	Bent 1 Cap	Prestressed Concrete Pier Cap	Prestressed Concrete Pier Cap	26
Bent 1	Pile 1	Timber Pile	Timber Pile	1
Bent 1	Pile 2	Timber Pile	Timber Pile	1
Bent 1	Pile 3	Timber Pile	Timber Pile	1
Bent 1	Pile 4	Timber Pile	Timber Pile	1
Bent 1	Pile 5	Timber Pile	Timber Pile	1
Bent 1	Pile 6	Timber Pile	Timber Pile	1
Bent 1	Pile 7	Timber Pile	Timber Pile	1
End Bent 1	End Bent Cap 1	Prestressed Concrete Pier Cap	Prestressed Concrete Pier Cap	26
End Bent 1	Pile 1	Timber Pile	Timber Pile	1
End Bent 1	Pile 2	Timber Pile	Timber Pile	1
End Bent 1	Pile 3	Timber Pile	Timber Pile	1
End Bent 1	Pile 4	Timber Pile	Timber Pile	1
End Bent 1	Pile 5	Timber Pile	Timber Pile	1
End Bent 1	Abutment	Timber Abutment	Timber Abutment	36
Bent 2	Bent 2 Cap	Prestressed Concrete Pier Cap	Prestressed Concrete Pier Cap	26
Bent 2	Pile 1	Timber Pile	Timber Pile	1
Bent 2	Pile 2	Steel Pile	Steel Pile	1
Bent 2	Pile 3	Timber Pile	Timber Pile	1
Bent 2	Pile 4	Timber Pile	Timber Pile	1
Bent 2	Pile 5	Timber Pile	Timber Pile	1
End Bent 2	End Bent 2 Cap	Prestressed Concrete Pier Cap	Prestressed Concrete Pier Cap	26
End Bent 2	Pile 1	Timber Pile	Timber Pile	1
End Bent 2	Pile 2	Timber Pile	Timber Pile	1
End Bent 2	Pile 3	Timber Pile	Timber Pile	1
End Bent 2	Pile 4	Timber Pile	Timber Pile	1
End Bent 2	Pile 5	Timber Pile	Timber Pile	1
End Bent 2	Pile 6	Timber Pile	Timber Pile	1
End Bent 2	Pile 7	Timber Pile	Timber Pile	1
End Bent 2	Abutment	Timber Abutment	Timber Abutment	36
Bent 3	Bent 3 Cap	Prestressed Concrete Pier Cap	Prestressed Concrete Pier Cap	26
Bent 3	Pile 1	Timber Pile	Timber Pile	1
Bent 3	Pile 2	Timber Pile	Timber Pile	1
Bent 3	Pile 3	Timber Pile	Timber Pile	1
Bent 3	Pile 4	Timber Pile	Timber Pile	1
Bent 3	Pile 5	Timber Pile	Timber Pile	1
Crutch Bent 1 Span 1	Cap 1	Steel Pier Cap	Steel Pier Cap	34
Crutch Bent 1 Span 1	Pile 1	Steel Cross Cap Crutch Pile	Steel Pile	1
Crutch Bent 1 Span 1	Pile 2	Steel Cross Cap Crutch Pile	Steel Pile	1
Crutch Bent 1 Span 2	Cap 1	Steel Pier Cap	Steel Pier Cap	34
Crutch Bent 1 Span 2	Pile 1	Steel Cross Cap Crutch Pile	Steel Pile	1

Elements Verified

Location	Name	Component	Element Name	Amount
Crutch Bent 1 Span 2	Pile 2	Steel Cross Cap Crutch Pile	Steel Pile	1
Crutch Bent 2 Span 2	Cap 1	Steel Pier Cap	Steel Pier Cap	34
Crutch Bent 2 Span 2	Pile 1	Steel Cross Cap Crutch Pile	Steel Pile	1
Crutch Bent 2 Span 2	Pile 2	Steel Cross Cap Crutch Pile	Steel Pile	1
Crutch Bent 1 Span 3	Cap 1	Steel Pier Cap	Steel Pier Cap	34
Crutch Bent 1 Span 3	Pile 1	Steel Cross Cap Crutch Pile	Steel Pile	1
Crutch Bent 1 Span 3	Pile 2	Steel Cross Cap Crutch Pile	Steel Pile	1
Crutch Bent 2 Span 3	Cap 1	Steel Pier Cap	Steel Pier Cap	34
Crutch Bent 2 Span 3	Pile 1	Steel Cross Cap Crutch Pile	Steel Pile	1
Crutch Bent 2 Span 3	Pile 2	Steel Cross Cap Crutch Pile	Steel Pile	1
Crutch Bent 1 Span 4	Cap 1	Steel Pier Cap	Steel Pier Cap	34
Crutch Bent 1 Span 4	Pile 1	Steel Cross Cap Crutch Pile	Steel Pile	1
Crutch Bent 1 Span 4	Pile 2	Steel Cross Cap Crutch Pile	Steel Pile	1

General Inspection Notes

Bent 1 Pile 1
pile is no longer in use and has been replaced by crutch bent

Bent 1 Pile 2
pile is no longer in use and has been replaced by crutch bent

Bent 1 Pile 3
pile is no longer in use and has been replaced by crutch bent

Bent 1 Pile 4
pile is no longer in use and has been replaced by crutch bent

Bent 1 Pile 5
pile is no longer in use and has been replaced by crutch bent

Bent 1 Pile 6
pile is no longer in use and has been replaced by crutch bent

Bent 1 Pile 7
pile is no longer in use and has been replaced by crutch bent

Bent 2 Pile 4
pile has been replaced with adjacent pile 5

Bent 2 Pile 5
pile is no longer in use and has been replaced by crutch bent

Bent 2 Pile 7
pile has been replaced with adjacent pile 6

Bent 3 Pile 2
pile is no longer in use and has been replaced by crutch bent

Bent 3 Pile 3
pile is no longer in use and has been replaced by crutch bent

Bent 3 Pile 4
pile is no longer in use and has been replaced by crutch bent

Bent 3 Pile 5
pile is no longer in use and has been replaced by crutch bent

National Bridge and NC Inspection Items

Structure Number: 910126

Inspection Date: 08/10/2021

National Bridge Inventory Items

Item	Grade Scale	Grade
Item 58: Deck	0 - 9, N	5
Item 59: Superstructure	0 - 9, N	3
Item 60: Substructure	0 - 9, N	3
Item 61: Channel and Channel Protection	0 - 9, N	6
Item 62: Culvert	0 - 9, N	N
Item 71: Waterway Adequacy	0 - 9, N	5
Item 72: Approach Roadway Alignment	0 - 9, N	6

Note: If NBI Inspection Item is not present, code NBI item with "N"

NC SMU Inspection Items

Item	Grade Scale	Grade	Maint. Qty.	Maint. Code
Deck Debris	G, F, P, or C	F	3082	3376
Drainage System	G, F, P, or C	F	242	3332
Utilities	G, F, P, or C	P		
Slope Protection	G, F, P, or C			
Scour	G, F, P, or C	F		
Wingwall	G, F, P, or C		0	3350
Field Scour Evaluation		U		
Drift	G, F, P, or C	G	0	3366
Fender System	G, F, P, or C			
Movable Span Machinery	G, F, P, or C			
Response to Live Load	G, F, P, or C	F		
Superstructure Paint Code				

Note: If NC SMU Inspection Item is not present, leave NC SMU item blank

Inspection Information

Item	Grade Scale	Grade
Sign Noticed Issued	YES/NO	Y
Priority Maintenance Request Submitted	YES/NO	Y
Inspection Time	Hours	10
Traffic Control Time	Hours	
Snooper Time	Hours	
Ladder Used	YES/NO	N
Bucket Truck Used	YES/NO	N
Boat Used	YES/NO	N
Other Equipment Used	YES/NO	N
Portion of Structure in > 3' of water	YES/NO	N

National Bridge and NC SMU Inspection Item Details

Structure Number: 910126

Inspection Date: 08/10/2021

Item	Superstructure - Item 59	Grade	3	Maint Code		Qty.	0
Details	multiple channels with exposed and deteriorated strands. 1 strand has failed (span 1 channel 10 at midspan)						
Item	Substructure - Item 60	Grade	3	Maint Code		Qty.	0
Details	Decay with fill loss and erosion at abutments and decay on end bent piles Temporary shoring - original interior bents are no longer in service; channels are only resting on crutch bents.						
Item	Channel and Channel Protection - Item 61	Grade	6	Maint Code		Qty.	0
Details	streambank near bent 1, vertical cuts (30ft x 3ft)						
Item	Waterway Adequacy - Item 71	Grade	5	Maint Code		Qty.	0
Details	drift found on top of caps at crutch bents, evidence that bridge might overtop						
Item	Approach Roadway Alignment - Item 72	Grade	6	Maint Code		Qty.	0
Details	roadway curves at both ends of structure and narrows at bridge causing a reduction in speed						
Item	Sign Notice Issued	Grade	Y	Maint Code		Qty.	0
Details	(PAR) clear roadway of bridge between 18ft-25ft; approach roadway (25.6ft) wider than clear roadway of bridge (24.083ft)						
Item	Deck Debris	Grade	F	Maint Code	3376	Qty.	3082
Details	along both curbs, debris and vegetation growth (full length x 1ft x up to 3in deep)						
Item	Drainage System	Grade	F	Maint Code	3332	Qty.	242
Details	vegetation growth throughout gutterlines affecting drainage						
Item	Utilities	Grade	P	Maint Code		Qty.	0
Details	utility broken at multiple locations throughout structure						
Item	Scour	Grade	F	Maint Code		Qty.	0
Details	undermining of End Bent 1 pile concrete collars						
Item	Response to live load	Grade	F	Maint Code		Qty.	0
Details	some vibrations under live load						
Item	General Comments and Misc Items	Grade		Maint Code		Qty.	0
Details	(PAR) southeast corner of bridge adjacent to roadway, erosion hole (3ft long x 2.5ft wide x up to 4ft deep) up to 1ft of undermining of roadway (PAR) northeast delineator covered by vegetation (southwest delineator similar)						



General Comments and Misc. Items: (PAR) southeast corner of bridge adjacent to roadway, erosion hole (3ft long x 2.5ft wide x up to 4ft deep) up to 1ft of undermining of roadway



Span 1 Wearing Surface: over end bent 1, transverse crack (full width x up to 1/8in)



Span 1 Wearing Surface: along edges of channels, (5) longitudinal cracks (full length x 1/16in)



Span 1 Left Bridge Rail: along length of rail, active corrosion with no section loss noted



Span 2 Wearing Surface: UP TO 1/8" TRANSVERSE CRACKING OVER BENT 1



Deck Debris: along both curbs, debris and vegetation (full length x 1ft x up to 3in deep)



Span 1 Right Bridge Rail: at rail post 2, spall [3ft x 10in x 3in deep]



Span 1 Wearing Surface: northbound lane at bent 1, pothole (6in x 20in x up to 1-1/2in deep)



Span 2 Right Bridge Rail: at rail post 5, delamination/spall [2ft x 8in x 3in deep]



Span 3 Right Bridge Rail: along length of rail at top, three [3] areas of impact damage [up to 3ft x 3in]



Span 4 Wearing Surface: northbound lane along edge of channels 8 and 9, pothole (20ft x 3in x 1in)



Span 4 Left Bridge Rail: [PAR] rail post 6 is missing



Span 4 Left Bridge Rail: (PAR) at rail posts 3,4 & 5, delamination/spall [up to 3ft x 11in x 3in deep] allowing excessive deflection of rail



General Comments and Misc. Items: (PAR) northeast delineator covered by vegetation



End Bent 1 Cap 1: over pile 3, spall/delamination [8in x 5in x 1/4in deep]



End Bent 1 Pile 3: (PAR) at base of pile, multiple checks [full height x up to 1/4in wide x up to 2in deep], decay [14in x 10in x 3in deep]



End Bent 1 Abutment: [PAR] between piles 3 and 5 second bulkhead board below cap, decay [10ft x up to full height x full width] with fill exposed



End Bent 1 Pile 1: (PAR) along height of exposed pile, multiple checks [full height x up to 1/8in], pile sounds hollow when hammered



End Bent 1 Pile 5: (PAR) concrete collar is undermined (60%)



Span 1 Slab 1: left and right leg near midspan, multiple spalls/delaminations [up to 5in x 4in x 3/4in deep] with two exposed stirrups [no section loss noted]



Span 1 Slab 1: (PAR) left and right leg at bent 1, four [4] spalls/delaminations [up to 12in x 5in x 1in deep] with loss of bearing area



Span 1 Slab 2: [PAR] left leg near midspan, spall [16in x 5in x full width] with exposed strand that exhibits section loss [up to 25%]



Span 1 Slab 2: (PAR) left and right leg at bent 1, three [3] spalls/delaminations [up to 10in x 6in x 1in deep] channel legs crushing and bottom of channel legs sits below top of crutch bent cap



Span 1 Slab 3: (PAR) left and right leg at bent 1, two [2] spalls [up to 12in x 6in x 1in deep] with exposed strand, channel legs crushing and bottom of channel legs sits below top of crutch bent cap



Span 1 Slab 4: (PAR) right leg at bent 1, spalled patched area [12in x full width x 5in high] with exposed strands



Span 1 Slab 4: left leg at bent 1, two [2] spalls [up to 12in x 4in x 1in deep]



Span 1 Slab 5: (PAR) right leg at midspan, spall (40in x 3in deep) with exposed strand (25% section loss)



Span 1 Slab 9: left leg at far end, two [2] spalls [up to 4in diameter x 1in deep] with one [1] exposed stirrup [loss < 1/16in]



Span 1 Slab 10: [PAR] left leg at midspan, spall/delamination, [11ft x full width of leg x 11in high] with four [4] exposed prestressed strands, three [3] of the exposed strands have failed with remaining one [1] strand exhibiting section loss [up to 40%] (photo 1 of 2)



Span 1 Slab 10: [PAR] left leg at midspan, spall/delamination, [11ft x full width of leg x 11in high] with four [4] exposed prestressed strands, three [3] of the exposed strands have failed with remaining one [1] strand exhibiting section loss [up to 40%] (photo 2 of 2)



Span 1 Slab 10: right leg at far end over bearing, spall [18in x 9in x 1/2in deep]



Span 1 Crutch Bent 1 Cap 1: along length of cap at lower web and top flange, corrosion with section loss [$<1/16$ in] with adjacent spot rust



Span 2 Slab 1: right leg 6ft from bent 2, spall (30in x 3in x 3/4in) with exposed rusted rebar



Span 2 Slab 2: [PAR] left and right leg at bent 2, two [2] spalls/delaminations [up to 36in x 6in x full width], with two [2] exposed stirrups [no section loss noted] and exposed strand [section loss up to 20%]



Span 2 Slab 5: (PAR) left and right leg at bent 1, two [2] spalls [up to 12in x 8in x up to full width], with exposed stirrup [no section loss noted] channel legs crushing and bottom of channel legs sits below top of crutch bent cap (photo 1 of 2)



Span 2 Slab 5: (PAR) left and right leg at bent 1, two [2] spalls [up to 12in x 8in x up to full width], with exposed stirrup [no section loss noted] channel legs crushing and bottom of channel legs sits below top of crutch bent cap (photo 2 of 2)



Span 2 Slab 7: [PAR] left leg near midspan, spall/delamination [30in x 4in x full width], with exposed strand [section loss up to 30%]



Span 2 Slab 9: [PAR] right leg at bent 1, spall/delamination [52in x 8in x up to full width] with one exposed strand (50% section loss on strand)



Span 2 Slab 9: [PAR] right leg 12ft from bent 1, spall/delamination [6ft x 3in x full width] with exposed strand (25% section loss)



Span 2 Slab 10: left and right leg at bent 1, four [4] spalls [up to 18in x 6in x 1/2in]



Span 2 Slab 10: left leg at midspan, delamination (4ft x 2in high) with longitudinal crack crack (up to 1/8in)



Span 3 Slab 2: [PAR] left leg at bent 3, spall [6ft x full width x 5in], with exposed strand (40% section loss)



Span 3 Slab 2: (PAR) right leg at midspan, spall (20in x 5in x 3/4in) with exposed rusted strand



Span 3 Slab 5: (PAR) right leg at bent 3, spall [6in x 4in x full width], with exposed strand



Span 3 Slab 6: [PAR] left leg at far third, spall [2ft x 5in] with exposed strand



Span 4 Slab 1: right leg near midspan, spall [12in x 8in x 3/4in] with exposed stirrup [no section loss noted]



Span 4 Slab 2: left leg at bent 3, spall [6in x 6in x 1/2in deep]



Span 4 Slab 4: (PAR) at far end of both legs, three [3] spalls/delaminations [6in x 6in x 1-1/2in deep] with one exposed strand [section loss up to 10%]



Span 4 Slab 8: [PAR] right leg at far third, spall [4ft x 3in x full width] with exposed strand



Span 4 Slab 8: (PAR) left leg at far third, spall/delamination [36in x 3in x 2in deep] with exposed rusted strand



Span 4 Slab 10: [PAR] 5 TOTAL AREAS OF AREAS IN LEFT LEG OF FULL WIDTH X UP TO 6" HIGH SPALLS WITH EXPOSED STRANDS FOR 20' TOTAL (20% SECTION LOSS) (PHOTO 1 OF 4)



Span 4 Slab 10: [PAR] 5 TOTAL AREAS OF AREAS IN LEFT LEG OF FULL WIDTH X UP TO 6" HIGH SPALLS WITH EXPOSED STRANDS FOR 20' TOTAL (20% SECTION LOSS) (PHOTO 2 OF 4)



Span 4 Slab 10: [PAR] 5 TOTAL AREAS OF AREAS IN LEFT LEG OF FULL WIDTH X UP TO 6" HIGH SPALLS WITH EXPOSED STRANDS FOR 20' TOTAL (20% SECTION LOSS) (PHOTO 3 OF 4)



Span 4 Slab 10: [PAR] 5 TOTAL AREAS OF AREAS IN LEFT LEG OF FULL WIDTH X UP TO 6" HIGH SPALLS WITH EXPOSED STRANDS FOR 20' TOTAL (20% SECTION LOSS) (PHOTO 4 OF 4)



Span 4 Slab 10: right leg at bent 3, spall [10in x 4in x 3/4in deep]



End Bent 2 Abutment: [PAR] between piles 1 and 2, lower board decay [3ft x 4in x full width] with exposed/missing backfill material



End Bent 2 Pile 3: at base of pile, decay (8in x 1in x 1-1/2in deep)

Stream Bed Soundings

(Profile diagram on following sheet)

County **WAKE**

Structure Number: **910126**

Inspection Date **08/10/2021**

Sounding recorded from: **Top of Bridge Rail**

Highwater Mark Distance **4.33**

Location of Highwater Mark **top of crutch bent cap**


Distance (Station) ft.	Downstream Sounding ft.	Upstream Sounding ft.	Description
0.000	2.500	0.000	fill face
0.250	2.500	0.000	top of bulkhead
0.260	4.800	0.000	top of cap
1.250	4.800	0.000	top of cap
1.260	6.400	8.300	ground at cap
12.800	9.000	0.000	ground
17.000	11.500	0.000	ground
29.070	11.500	11.500	span 1 crutch bent 1
30.400	11.700	11.400	bent 1
31.730	11.700	11.400	span 2 crutch bent 1
35.400	12.000	0.000	ground
36.000	14.000	0.000	water surface water edge (wswe)
51.500	16.000	0.000	streambed
59.470	16.000	13.000	span 2 crutch bent 2
60.800	16.000	13.300	bent 2
62.130	16.000	13.300	span 3 crutch bent 1
74.700	14.000	0.000	streambed
88.770	14.700	13.300	span 3 crutch bent 2
90.100	14.700	13.300	bent 3
91.000	13.800	0.000	water surface water edge (wswe)
91.430	13.500	13.300	span 4 crutch bent 1
98.000	8.900	0.000	ground
119.574	6.000	7.400	ground at cap
119.584	4.800	0.000	top of cap
120.574	4.800	0.000	top of cap
120.584	2.500	0.000	top of bulkhead
120.834	2.500	0.000	fill face

Structure Data Worksheet

Span Profile

County: **WAKE**

Structure Number: **910126**



A: SPAN LENGTH
 B: BEARING TO BEARING
 C: DISTANCE FROM NEAR BEARING
 D: DISTANCE TO FAR BEARING

Span Number	Span Length	Bearing to Bearing	Crutch/ Helper Bent	Distance to Near Bearing	Distance to Far Bearing
1	30.417	28.670			
			1	27.500	1.167
2	30.000	28.670			
			1	1.167	27.500
			2	27.500	1.167
3	30.000	28.670			
			1	1.167	27.500
			2	27.500	1.167
4	30.417	28.670			
			1	1.167	27.500



posting sign northwest corner



south approach, looking north



posting sign southeast corner



asphalt wearing surface over end bent 1



east bridge rail



west bridge rail



asphalt wearing surface over bent 1



asphalt wearing surface over bent 2



looking upstream, east



asphalt wearing surface over bent 3



south approach, looking south (backstation)



north approach, looking north (upstation)



asphalt wearing surface over end bent 2



north approach, looking south



asphalt wearing surface



looking downstream, west



underside of channels (span 2)



end bent 1



bent 1



bent 2



bent 3



upstream profile, looking west



stream under view looking downstream, west (span 2)



channels on bent 2



end bent 2



stream under view looking upstream, east (spans 2 and 3)



downstream profile, looking east



channels on bent 1



channels on bent 3











BRIDGE INSPECTOR'S RECOMMENDATION FOR MAINTENANCE REPAIRS

Bridge: 910126

County WAKE

Date:

These Repairs Should Be Made Within Twelve Months From Date Of This Inspection

MMS Code	Description of Function	Unit	Quantity	Remarks	Est. Cost
 3102	Removal of Hazard	EA	1	(PAR) southeast corner of bridge adjacent to roadway, erosion hole (3ft long x 2.5ft wide x up to 4ft deep) up to 1ft of undermining of roadway	
 3102	Removal of Hazard	EA	2	(PAR) northeast delineator covered by vegetation (southwest delineator similar)	
 3250	Install or Replace Ground Mounted Signs	SF	2	(PAR) clear roadway of bridge between 18ft-25ft; approach roadway (25.6ft) wider than clear roadway of bridge (24.083ft)	
 3306	Maintain Concrete Superstructure Components	SF	1	Span 1 Slab 1: (PAR) left and right leg at bent 1, four [4] spalls/delaminations [up to 12in x 5in x 1in deep] with loss of bearing area	
 3306	Maintain Concrete Superstructure Components	SF	2	Span 1 Slab 2: [PAR] left leg near midspan, spall [16in x 5in x full width] with exposed strand that exhibits section loss [up to 25%]	
 3306	Maintain Concrete Superstructure Components	SF	2	Span 1 Slab 3: (PAR) left and right leg at bent 1, two [2] spalls [up to 12in x 6in x 1in deep] with exposed strand, channel legs crushing and bottom of channel legs sits below top of crutch bent cap	
 3306	Maintain Concrete Superstructure Components	SF	1	Span 1 Slab 4: (PAR) right leg at bent 1, spalled patched area [12in x full width x 5in high] with exposed strands	
 3306	Maintain Concrete Superstructure Components	SF	4	Span 1 Slab 5: (PAR) right leg at midspan, spall (40in x 3in deep) with exposed strand (25% section loss)	
 3306	Maintain Concrete Superstructure Components	SF	11	Span 1 Slab 10: [PAR] left leg at midspan, spall/delamination, [11ft x full width of leg x 11in high] with four [4] exposed prestressed strands, three [3] of the exposed strands have failed with remaining one [1] strand exhibiting section loss [up to 40%]	
 3306	Maintain Concrete Superstructure Components	SF	3	Span 2 Slab 2: [PAR] left and right leg at bent 2, two [2] spalls/delaminations [up to 36in x 6in x full width], with two [2] exposed stirrups [no section loss noted] and exposed strand [section loss up to 20%]	

Key

 Priority Maintenance Item

 Critical Finding Item

 Priority Maintenance Level Not Determined











BRIDGE INSPECTOR'S RECOMMENDATION FOR MAINTENANCE REPAIRS

Bridge: 910126

County WAKE

Date:

These Repairs Should Be Made Within Twelve Months From Date Of This Inspection

MMS Code	Description of Function	Unit	Quantity	Remarks	Est. Cost
 3306	Maintain Concrete Superstructure Components	SF	1	Span 2 Slab 5: (PAR) left and right leg at bent 1, two [2] spalls [up to 12in x 8in x up to full width], with exposed stirrup [no section loss noted] channel legs crushing and bottom of channel legs sits below top of crutch bent cap	
 3306	Maintain Concrete Superstructure Components	SF	3	Span 2 Slab 7: [PAR] left leg near midspan, spall/delamination [30in x 4in x full width], with exposed strand [section loss up to 30%]	
 3306	Maintain Concrete Superstructure Components	SF	5	Span 2 Slab 9: [PAR] right leg at bent 1, spall/delamination [52in x 8in x up to full width] with one exposed strand (50% section loss on strand)	
 3306	Maintain Concrete Superstructure Components	SF	6	Span 2 Slab 9: [PAR] right leg 12ft from bent 1, spall/delamination [6ft x 3in x full width] with exposed strand (25% section loss)	
 3306	Maintain Concrete Superstructure Components	SF	6	Span 3 Slab 2: [PAR] left leg at bent 3, spall [6ft x full width x 5in], with exposed strand (40% section loss)	
 3306	Maintain Concrete Superstructure Components	SF	2	Span 3 Slab 2: (PAR) right leg at midspan, spall (20in x 5in x 3/4in)	
 3306	Maintain Concrete Superstructure Components	SF	1	Span 3 Slab 5: (PAR) right leg at bent 3, spall [6in x 4in x full width], with exposed strand	
 3306	Maintain Concrete Superstructure Components	SF	2	Span 3 Slab 6: [PAR] left leg at far third, spall [2ft x 5in] with exposed strand	
 3306	Maintain Concrete Superstructure Components	SF	4	Span 4 Slab 8: [PAR] right leg at far third, spall [4ft x 3in x full width] with exposed strand	
 3306	Maintain Concrete Superstructure Components	SF	20	Span 4 Slab 10: [PAR] 5 TOTAL AREAS OF AREAS IN LEFT LEG OF FULL WIDTH X UP TO 6" HIGH SPALLS WITH EXPOSED STRANDS FOR 20' TOTAL (20% SECTION LOSS) (PHOTO 4 OF 4)	

Key

 Priority Maintenance Item

 Critical Finding Item

 Priority Maintenance Level Not Determined











BRIDGE INSPECTOR'S RECOMMENDATION FOR MAINTENANCE REPAIRS

Bridge: 910126

County WAKE

Date:

These Repairs Should Be Made Within Twelve Months From Date Of This Inspection

MMS Code	Description of Function	Unit	Quantity	Remarks	Est. Cost
 3306	Maintain Concrete Superstructure Components	SF	2	Span 1 Slab 2: (PAR) left and right leg at bent 1, three [3] spalls/delaminations [up to 10in x 6in x 1in deep] channel legs crushing and bottom of channel legs sits below top of crutch bent cap	
 3306	Maintain Concrete Superstructure Components	SF	1	Span 4 Slab 4: (PAR) at far end of both legs, three [3] spalls/delaminations [6in x 6in x 1-1/2in deep] with one exposed strand [section loss up to 10%]	
 3306	Maintain Concrete Superstructure Components	SF	1	Span 4 Slab 8: (PAR) left leg at far third, spall/delamination [36in x 3in x 2in deep] with exposed rusted strand	
 3318	Maint to Concrete Handrail	LF	9	Span 4 Left Bridge Rail: (PAR) at rail posts 3,4 & 5, delamination/spall [up to 3ft x 11in x 3in deep] allowing excessive deflection of rail	
 3318	Maint to Concrete Handrail	LF	1	Span 4 Left Bridge Rail: [PAR] rail post 6 is missing	
 3344	Repair / Replace Timber Substructure Components	LF	1	End Bent 1 Pile 3: (PAR) at base of pile, multiple checks [full height x up to 1/4in wide x up to 2in deep], decay [14in x 10in x 3in deep]	
 3344	Repair / Replace Timber Substructure Components	LF	1	End Bent 1 Pile 1: (PAR) along height of exposed pile, multiple checks [full height x up to 1/8in], pile sounds hollow when hammered	
 3344	Repair / Replace Timber Substructure Components	LF	1	End Bent 1 Pile 5: (PAR) concrete collar is undermined (60%)	
 3346	Repair / Maintain Timber Wings & Blkhds	SF	10	End Bent 1 Abutment: [PAR] between piles 3 and 5 second bulkhead board below cap, decay [10ft x up to full height x full width] with fill exposed	
 3346	Repair / Maintain Timber Wings & Blkhds	SF	3	End Bent 2 Abutment: [PAR] between piles 1 and 2, lower board decay [3ft x 4in x full width] with exposed/missing backfill material	

Key

 Priority Maintenance Item

 Critical Finding Item

 Priority Maintenance Level Not Determined

BRIDGE INSPECTOR'S RECOMMENDATION FOR PRIORITY MAINTENANCE REPAIRS

Bridge: 910126 County WAKE

THE FOLLOWING MAINTENANCE ITEMS HAVE BEEN SUBMITTED IN CONJUNCTION WITH A PRIORITY MAINTENANCE REQUEST

MMS Code	MMS Description	Quantity
3102	Removal of Hazard	1 EA
Location:		
Bent/Span No.		
Priority Level	Status	
Priority Maintenance	Division Bridge Maintenance Notification	
Submitted Date:	Submitted By:	Assisted By:
08/11/2021	MICHAEL MEYER	
Details		
(PAR) southeast corner of bridge adjacent to roadway, erosion hole (3ft long x 2.5ft wide x up to 4ft deep) up to 1ft of undermining of roadway		

MMS Code	MMS Description	Quantity
3102	Removal of Hazard	2 EA
Location:		
Bent/Span No.		
Priority Level	Status	
Priority Maintenance	Division Bridge Maintenance Notification	
Submitted Date:	Submitted By:	Assisted By:
08/17/2021	MICHAEL MEYER	
Details		
(PAR) northeast delineator covered by vegetation (southwest delineator similar)		

BRIDGE INSPECTOR'S RECOMMENDATION FOR PRIORITY MAINTENANCE REPAIRS

Bridge: 910126

County WAKE

THE FOLLOWING MAINTENANCE ITEMS HAVE BEEN SUBMITTED IN CONJUNCTION WITH A PRIORITY MAINTENANCE REQUEST

MMS Code	MMS Description	Quantity
3250	Install or Replace Ground Mounted Signs	2 SF
Location:		
Bent/Span No.		
Priority Level	Status	
Priority Maintenance	Division Bridge Maintenance Notification	
Submitted Date:	Submitted By:	Assisted By:
08/17/2021	MICHAEL MEYER	
Details		
(PAR) clear roadway of bridge between 18ft-25ft; approach roadway (25.6ft) wider than clear roadway of bridge (24.083ft)		

MMS Code	MMS Description	Quantity
3306	Maintain Concrete Superstructure Components	1 SF
Location:		
Bent/Span No.		
Priority Level	Status	
Priority Maintenance	Division Bridge Maintenance Notification	
Submitted Date:	Submitted By:	Assisted By:
08/11/2021	MICHAEL MEYER	
Details		
Span 1 Slab 1: (PAR) left and right leg at bent 1, four [4] spalls/delaminations [up to 12in x 5in x 1in deep] with loss of bearing area		

BRIDGE INSPECTOR'S RECOMMENDATION FOR PRIORITY MAINTENANCE REPAIRS

Bridge: 910126

County WAKE

THE FOLLOWING MAINTENANCE ITEMS HAVE BEEN SUBMITTED IN CONJUNCTION WITH A PRIORITY MAINTENANCE REQUEST

MMS Code	MMS Description	Quantity
3306	Maintain Concrete Superstructure Components	2 SF
Location:		
Bent/Span No.		
Priority Level	Status	
Priority Maintenance	Division Bridge Maintenance Notification	
Submitted Date:	Submitted By:	Assisted By:
08/11/2021	MICHAEL MEYER	
Details		
Span 1 Slab 2: [PAR] left leg near midspan, spall [16in x 5in x full width] with exposed strand that exhibits section loss [up to 25%]		

MMS Code	MMS Description	Quantity
3306	Maintain Concrete Superstructure Components	2 SF
Location:		
Bent/Span No.		
Priority Level	Status	
Priority Maintenance	Division Bridge Maintenance Notification	
Submitted Date:	Submitted By:	Assisted By:
08/11/2021	MICHAEL MEYER	
Details		
Span 1 Slab 3: (PAR) left and right leg at bent 1, two [2] spalls [up to 12in x 6in x 1in deep] with exposed strand, channel legs crushing and bottom of channel legs sits below top of crutch bent cap		

BRIDGE INSPECTOR'S RECOMMENDATION FOR PRIORITY MAINTENANCE REPAIRS

Bridge: 910126

County WAKE

THE FOLLOWING MAINTENANCE ITEMS HAVE BEEN SUBMITTED IN CONJUNCTION WITH A PRIORITY MAINTENANCE REQUEST

MMS Code	MMS Description	Quantity
3306	Maintain Concrete Superstructure Components	1 SF
Location:		
Bent/Span No.		
Priority Level	Status	
Priority Maintenance	Division Bridge Maintenance Notification	
Submitted Date:	Submitted By:	Assisted By:
08/11/2021	MICHAEL MEYER	
Details		
Span 1 Slab 4: (PAR) right leg at bent 1, spalled patched area [12in x full width x 5in high] with exposed strands		

MMS Code	MMS Description	Quantity
3306	Maintain Concrete Superstructure Components	4 SF
Location:		
Bent/Span No.		
Priority Level	Status	
Priority Maintenance	Division Bridge Maintenance Notification	
Submitted Date:	Submitted By:	Assisted By:
08/11/2021	MICHAEL MEYER	
Details		
Span 1 Slab 5: (PAR) right leg at midspan, spall (40in x 3in deep) with exposed strand (25% section loss)		

BRIDGE INSPECTOR'S RECOMMENDATION FOR PRIORITY MAINTENANCE REPAIRS

Bridge: 910126

County WAKE

THE FOLLOWING MAINTENANCE ITEMS HAVE BEEN SUBMITTED IN CONJUNCTION WITH A PRIORITY MAINTENANCE REQUEST

MMS Code	MMS Description	Quantity
3306	Maintain Concrete Superstructure Components	11 SF
Location:		
Bent/Span No.		
Priority Level	Status	
Priority Maintenance	Division Bridge Maintenance Notification	
Submitted Date:	Submitted By:	Assisted By:
08/11/2021	MICHAEL MEYER	
Details		
<p>Span 1 Slab 10: [PAR] left leg at midspan, spall/delamination, [11ft x full width of leg x 11in high] with four [4] exposed prestressed strands, three [3] of the exposed strands have failed with remaining one [1] strand exhibiting section loss [up to 40%]</p>		

MMS Code	MMS Description	Quantity
3306	Maintain Concrete Superstructure Components	3 SF
Location:		
Bent/Span No.		
Priority Level	Status	
Priority Maintenance	Division Bridge Maintenance Notification	
Submitted Date:	Submitted By:	Assisted By:
08/11/2021	MICHAEL MEYER	
Details		
<p>Span 2 Slab 2: [PAR] left and right leg at bent 2, two [2] spalls/delaminations [up to 36in x 6in x full width], with two [2] exposed stirrups [no section loss noted] and exposed strand [section loss up to 20%]</p>		

BRIDGE INSPECTOR'S RECOMMENDATION FOR PRIORITY MAINTENANCE REPAIRS

Bridge: 910126

County WAKE

THE FOLLOWING MAINTENANCE ITEMS HAVE BEEN SUBMITTED IN CONJUNCTION WITH A PRIORITY MAINTENANCE REQUEST

MMS Code	MMS Description	Quantity
3306	Maintain Concrete Superstructure Components	1 SF
Location:		
Bent/Span No.		
Priority Level	Status	
Priority Maintenance	Division Bridge Maintenance Notification	
Submitted Date:	Submitted By:	Assisted By:
08/11/2021	MICHAEL MEYER	
Details		
Span 2 Slab 5: (PAR) left and right leg at bent 1, two [2] spalls [up to 12in x 8in x up to full width], with exposed stirrup [no section loss noted] channel legs crushing and bottom of channel legs sits below top of crutch bent cap		

MMS Code	MMS Description	Quantity
3306	Maintain Concrete Superstructure Components	3 SF
Location:		
Bent/Span No.		
Priority Level	Status	
Priority Maintenance	Division Bridge Maintenance Notification	
Submitted Date:	Submitted By:	Assisted By:
08/11/2021	MICHAEL MEYER	
Details		
Span 2 Slab 7: [PAR] left leg near midspan, spall/delamination [30in x 4in x full width], with exposed strand [section loss up to 30%]		

BRIDGE INSPECTOR'S RECOMMENDATION FOR PRIORITY MAINTENANCE REPAIRS

Bridge: 910126

County WAKE

THE FOLLOWING MAINTENANCE ITEMS HAVE BEEN SUBMITTED IN CONJUNCTION WITH A PRIORITY MAINTENANCE REQUEST

MMS Code	MMS Description	Quantity
3306	Maintain Concrete Superstructure Components	5 SF
Location:		
Bent/Span No.		
Priority Level	Status	
Priority Maintenance	Division Bridge Maintenance Notification	
Submitted Date:	Submitted By:	Assisted By:
08/11/2021	MICHAEL MEYER	
Details		
Span 2 Slab 9: [PAR] right leg at bent 1, spall/delamination [52in x 8in x up to full width] with one exposed strand (50% section loss on strand)		

MMS Code	MMS Description	Quantity
3306	Maintain Concrete Superstructure Components	6 SF
Location:		
Bent/Span No.		
Priority Level	Status	
Priority Maintenance	Division Bridge Maintenance Notification	
Submitted Date:	Submitted By:	Assisted By:
08/11/2021	MICHAEL MEYER	
Details		
Span 2 Slab 9: [PAR] right leg 12ft from bent 1, spall/delamination [6ft x 3in x full width] with exposed strand (25% section loss)		

BRIDGE INSPECTOR'S RECOMMENDATION FOR PRIORITY MAINTENANCE REPAIRS

Bridge: 910126

County WAKE

THE FOLLOWING MAINTENANCE ITEMS HAVE BEEN SUBMITTED IN CONJUNCTION WITH A PRIORITY MAINTENANCE REQUEST

MMS Code	MMS Description	Quantity
3306	Maintain Concrete Superstructure Components	6 SF
Location:		
Bent/Span No.		
Priority Level	Status	
Priority Maintenance	Division Bridge Maintenance Notification	
Submitted Date:	Submitted By:	Assisted By:
08/11/2021	MICHAEL MEYER	
Details		
Span 3 Slab 2: [PAR] left leg at bent 3, spall [6ft x full width x 5in], with exposed strand (40% section loss)		

MMS Code	MMS Description	Quantity
3306	Maintain Concrete Superstructure Components	2 SF
Location:		
Bent/Span No.		
Priority Level	Status	
Priority Maintenance	Division Bridge Maintenance Notification	
Submitted Date:	Submitted By:	Assisted By:
08/11/2021	MICHAEL MEYER	
Details		
Span 3 Slab 2: (PAR) right leg at midspan, spall (20in x 5in x3/4in)		

BRIDGE INSPECTOR'S RECOMMENDATION FOR PRIORITY MAINTENANCE REPAIRS

Bridge: 910126 County WAKE

THE FOLLOWING MAINTENANCE ITEMS HAVE BEEN SUBMITTED IN CONJUNCTION WITH A PRIORITY MAINTENANCE REQUEST

MMS Code	MMS Description	Quantity
3306	Maintain Concrete Superstructure Components	1 SF
Location:		
Bent/Span No.		
Priority Level	Status	
Priority Maintenance	Division Bridge Maintenance Notification	
Submitted Date:	Submitted By:	Assisted By:
08/11/2021	MICHAEL MEYER	
Details		
Span 3 Slab 5: (PAR) right leg at bent 3, spall [6in x 4in x full width], with exposed strand		

MMS Code	MMS Description	Quantity
3306	Maintain Concrete Superstructure Components	2 SF
Location:		
Bent/Span No.		
Priority Level	Status	
Priority Maintenance	Division Bridge Maintenance Notification	
Submitted Date:	Submitted By:	Assisted By:
08/11/2021	MICHAEL MEYER	
Details		
Span 3 Slab 6: [PAR] left leg at far third, spall [2ft x 5in] with exposed strand		

BRIDGE INSPECTOR'S RECOMMENDATION FOR PRIORITY MAINTENANCE REPAIRS

Bridge: 910126

County WAKE

THE FOLLOWING MAINTENANCE ITEMS HAVE BEEN SUBMITTED IN CONJUNCTION WITH A PRIORITY MAINTENANCE REQUEST

MMS Code	MMS Description	Quantity
3306	Maintain Concrete Superstructure Components	4 SF
Location:		
Bent/Span No.		
Priority Level	Status	
Priority Maintenance	Division Bridge Maintenance Notification	
Submitted Date:	Submitted By:	Assisted By:
08/11/2021	MICHAEL MEYER	
Details		
Span 4 Slab 8: [PAR] right leg at far third, spall [4ft x 3in x full width] with exposed strand		

MMS Code	MMS Description	Quantity
3306	Maintain Concrete Superstructure Components	20 SF
Location:		
Bent/Span No.		
Priority Level	Status	
Priority Maintenance	Division Bridge Maintenance Notification	
Submitted Date:	Submitted By:	Assisted By:
08/11/2021	MICHAEL MEYER	
Details		
Span 4 Slab 10: [PAR] 5 TOTAL AREAS OF AREAS IN LEFT LEG OF FULL WIDTH X UP TO 6" HIGH SPALLS WITH EXPOSED STRANDS FOR 20' TOTAL (20% SECTION LOSS) (PHOTO 4 OF 4)		

BRIDGE INSPECTOR'S RECOMMENDATION FOR PRIORITY MAINTENANCE REPAIRS

Bridge: 910126

County WAKE

THE FOLLOWING MAINTENANCE ITEMS HAVE BEEN SUBMITTED IN CONJUNCTION WITH A PRIORITY MAINTENANCE REQUEST

MMS Code	MMS Description	Quantity
3306	Maintain Concrete Superstructure Components	2 SF
Location:		
Bent/Span No.		
Priority Level	Status	
Priority Maintenance	Division Bridge Maintenance Notification	
Submitted Date:	Submitted By:	Assisted By:
08/17/2021	MICHAEL MEYER	
Details		
<p>Span 1 Slab 2: (PAR) left and right leg at bent 1, three [3] spalls/delaminations [up to 10in x 6in x 1in deep] channel legs crushing and bottom of channel legs sits below top of crutch bent cap</p>		

MMS Code	MMS Description	Quantity
3306	Maintain Concrete Superstructure Components	1 SF
Location:		
Bent/Span No.		
Priority Level	Status	
Priority Maintenance	Division Bridge Maintenance Notification	
Submitted Date:	Submitted By:	Assisted By:
08/17/2021	MICHAEL MEYER	
Details		
<p>Span 4 Slab 4: (PAR) at far end of both legs, three [3] spalls/delaminations [6in x 6in x 1-1/2in deep] with one exposed strand [section loss up to 10%]</p>		

BRIDGE INSPECTOR'S RECOMMENDATION FOR PRIORITY MAINTENANCE REPAIRS

Bridge: 910126

County WAKE

THE FOLLOWING MAINTENANCE ITEMS HAVE BEEN SUBMITTED IN CONJUNCTION WITH A PRIORITY MAINTENANCE REQUEST

MMS Code	MMS Description	Quantity
3306	Maintain Concrete Superstructure Components	1 SF
Location:		
Bent/Span No.		
Priority Level	Status	
Priority Maintenance	Division Bridge Maintenance Notification	
Submitted Date:	Submitted By:	Assisted By:
08/17/2021	MICHAEL MEYER	
Details		
Span 4 Slab 8: (PAR) left leg at far third, spall/delamination [36in x 3in x 2in deep] with exposed rusted strand		

MMS Code	MMS Description	Quantity
3318	Maint to Concrete Handrail	9 LF
Location:		
Bent/Span No.		
Priority Level	Status	
Priority Maintenance	Division Bridge Maintenance Notification	
Submitted Date:	Submitted By:	Assisted By:
08/11/2021	MICHAEL MEYER	
Details		
Span 4 Left Bridge Rail: (PAR) at rail posts 3,4 & 5, delamination/spall [up to 3ft x 11in x 3in deep] allowing excessive deflection of rail		

BRIDGE INSPECTOR'S RECOMMENDATION FOR PRIORITY MAINTENANCE REPAIRS

Bridge: 910126 County WAKE

THE FOLLOWING MAINTENANCE ITEMS HAVE BEEN SUBMITTED IN CONJUNCTION WITH A PRIORITY MAINTENANCE REQUEST

MMS Code	MMS Description	Quantity
3318	Maint to Concrete Handrail	1 LF
Location:		
Bent/Span No.		
Priority Level	Status	
Priority Maintenance	Division Bridge Maintenance Notification	
Submitted Date:	Submitted By:	Assisted By:
08/11/2021	MICHAEL MEYER	
Details		
Span 4 Left Bridge Rail: [PAR] rail post 6 is missing		

MMS Code	MMS Description	Quantity
3344	Repair / Replace Timber Substructure Components	1 LF
Location:		
Bent/Span No.		
Priority Level	Status	
Priority Maintenance	Division Bridge Maintenance Notification	
Submitted Date:	Submitted By:	Assisted By:
08/17/2021	MICHAEL MEYER	
Details		
End Bent 1 Pile 3: (PAR) at base of pile, multiple checks [full height x up to 1/4in wide x up to 2in deep], decay [14in x 10in x 3in deep]		

BRIDGE INSPECTOR'S RECOMMENDATION FOR PRIORITY MAINTENANCE REPAIRS

Bridge: 910126

County WAKE

THE FOLLOWING MAINTENANCE ITEMS HAVE BEEN SUBMITTED IN CONJUNCTION WITH A PRIORITY MAINTENANCE REQUEST

MMS Code	MMS Description	Quantity
3344	Repair / Replace Timber Substructure Components	1 LF
Location:		
Bent/Span No.		
Priority Level	Status	
Priority Maintenance	Division Bridge Maintenance Notification	
Submitted Date:	Submitted By:	Assisted By:
08/17/2021	MICHAEL MEYER	
Details		
End Bent 1 Pile 1: (PAR) along height of exposed pile, multiple checks [full height x up to 1/8in], pile sounds hollow when hammered		

MMS Code	MMS Description	Quantity
3344	Repair / Replace Timber Substructure Components	1 LF
Location:		
Bent/Span No.		
Priority Level	Status	
Priority Maintenance	Division Bridge Maintenance Notification	
Submitted Date:	Submitted By:	Assisted By:
08/17/2021	MICHAEL MEYER	
Details		
End Bent 1 Pile 5: (PAR) concrete collar is undermined (60%)		

BRIDGE INSPECTOR'S RECOMMENDATION FOR PRIORITY MAINTENANCE REPAIRS

Bridge: 910126

County WAKE

THE FOLLOWING MAINTENANCE ITEMS HAVE BEEN SUBMITTED IN CONJUNCTION WITH A PRIORITY MAINTENANCE REQUEST

MMS Code	MMS Description	Quantity
3346	Repair / Maintain Timber Wings & Blkhdrs	10 SF
Location:		
Bent/Span No.		
Priority Level	Status	
Priority Maintenance	Division Bridge Maintenance Notification	
Submitted Date:	Submitted By:	Assisted By:
08/17/2021	MICHAEL MEYER	
Details		
End Bent 1 Abutment: [PAR] between piles 3 and 5 second bulkhead board below cap, decay [10ft x up to full height x full width] with fill exposed		

MMS Code	MMS Description	Quantity
3346	Repair / Maintain Timber Wings & Blkhdrs	3 SF
Location:		
Bent/Span No.		
Priority Level	Status	
Priority Maintenance	Division Bridge Maintenance Notification	
Submitted Date:	Submitted By:	Assisted By:
08/17/2021	MICHAEL MEYER	
Details		
End Bent 2 Abutment: [PAR] between piles 1 and 2, lower board decay [3ft x 4in x full width] with exposed/missing backfill material		

Bridge Inspection Field Sketch



Roadway	21.7ft Wide	2 Paved Lanes	Looking North
Left Shoulder	6.2ft Wide	2.7ft Paved	3.5ft Unpaved
Right Shoulder	4.9ft Wide	1.2ft Paved	3.7ft Unpaved
Left Guardrail			
Right Guardrail			

MEASUREMENTS TAKEN APPROXIMATELY 25FT SOUTH OF END BENT 1

VERIFIED BY: S. GURME 8/10/2021

Title

Approach Roadway Sketch

Description

Data Worksheet

Bridge No: 910126


Drawn By: VWW

Date: 11/23/2005

File Name: S0010000292

Bridge Inspection Field Sketch


Deck Width/Out to Out	25.5ft	Between Rails	24.917ft
Clear Roadway	24.083ft	Wearing Surface	0.333ft
Median Width		Median Height	
Curb Height		Left	0.583ft
		Right	0.583ft
Sidewalk Width		Left	
		Right	
Clear Roadway (Rail to Median)		Left	
		Right	
Guardrail Width		Left	0.67ft
		Right	0.67ft
Top of Rail to Deck/Wearing Surface		Left	2.67ft
		Right	2.67ft
Bridge Rail		Left	Type 23
		Right	Type 23



Measurements for Span #	1	ALL SPANS SIMILAR	
Deck Thickness	0.417ft	Left Overhang	0ft
Top of Rail to Bottom of Beam	4.333ft	Right Overhang	0ft

Number of Channels	10
Leg Width	0.208ft
Leg Height	1ft
Leg to Leg (Centers)	2ft
Channel Width	2.542ft
Channel Height	1.417ft
Comments	

TYPICAL CHANNEL SKETCH



VERIFIED BY: S. GURME 8/10/2021

Title

Typical Section Sketch

Description

Data Worksheet


Bridge No: 910126

Drawn By: VWW

Date: 11/23/2005

File Name: S0010000293


Bridge Inspection Field Sketch



Cap Information			Material Precast Concrete							
Length	Width	Height	Left Overhang	Right Overhang	Left Beam to End of Cap.	Right Beam to End of Cap.				
26.000 ft.	1.333 ft.	1.000 ft.	1.500 ft.	1.500 ft.	.250 ft.	.250 ft.				
Subcap Information			Material							
Length	Width	Height	Left Overhang	Right Overhang	Left Pile to Splice.					
Sill Information			Material							
Length	Width	Height								
Pile #	Material	Spacing	Width/Dia.	Height	Length	Orientation	Driven?	Replacement?	Removed?	Collar?
1	Timber	5.75 ft.	1 ft.			Vertical	Yes	No	No	No
2	Timber	5.75 ft.	1 ft.			Vertical	Yes	No	No	Yes
3	Timber	5.75 ft.	1 ft.			Vertical	Yes	No	No	No
4	Timber	5.75 ft.	1 ft.			Vertical	Yes	No	No	Yes
5	Timber		1 ft.			Vertical	Yes	No	No	Yes
VERIFIED BY: S. GURME 8/10/2021										
Bent/Abutment #: 1			Similar Bents:							

Title End Bent 1 Sketch		Description Data Worksheet			
Bridge No: 910126	Drawn By: ado	Date: 04/03/2008	File Name: S0214000042		

Bridge Inspection Field Sketch



Concrete Collar
 Width = 24.0in
 Height = 9.0in
 Depth = 21.5in

Cap Information			Material Precast Concrete							
Length	Width	Height	Left Overhang	Right Overhang	Left Beam to End of Cap.	Right Beam to End of Cap.				
26.000 ft.	1.333 ft.	1.000 ft.	1.500 ft.	1.500 ft.	.250 ft.	.250 ft.				
Subcap Information			Material							
Length	Width	Height	Left Overhang	Right Overhang	Left Pile to Splice.					
Sill Information			Material							
Length	Width	Height								
Pile #	Material	Spacing	Width/Dia.	Height	Length	Orientation	Driven?	Replacement?	Removed?	Collar?
1	Timber	5.75 ft.	1 ft.			Vertical	Yes	No	No	No
2	Timber	5.75 ft.	1 ft.			Vertical	Yes	No	No	Yes
3	Timber	5.75 ft.	1 ft.			Vertical	Yes	No	No	No
4	Timber	1 ft.	1 ft.			Vertical	Yes	No	No	No
5	Timber	3.75 ft.	1 ft.			Vertical	*No	Yes	No	No
6	Timber	1 ft.	1 ft.			Vertical	*No	Yes	No	No
7	Timber		1 ft.			Vertical	Yes	No	No	No
*REVISED BY: S. GURME 8/10/2021										
Bent/Abutment #: 2			Similar Bents:							

Title
End Bent 2 Sketch

Description
Data Worksheet


Bridge No: 910126

Drawn By:

Date: 02/22/2005

File Name: S0010000294

Bridge Inspection Field Sketch




Cap Information			Material Precast Concrete							
Length	Width	Height	Left Overhang	Right Overhang	Left Beam to End of Cap.	Right Beam to End of Cap.				
*26.000 ft.	1.333 ft.	1.000 ft.	1.500 ft.	1.500 ft.	*.250 ft.	*.250 ft.				
Subcap Information			Material							
Length	Width	Height	Left Overhang	Right Overhang	Left Pile to Splice.					
Sill Information			Material							
Length	Width	Height								
Pile #	Material	Spacing	Width/Dia.	Height	Length	Orientation	Driven?	Replacement?	Removed?	Collar?
1	Timber	5.750 ft.	0.833 ft.			Vertical	Yes	No	No	No
2	Timber	5.750 ft.	1.000 ft.			Vertical	Yes	No	No	No
3	Timber	5.750 ft.	1.000 ft.			Vertical	Yes	No	No	No
4	Timber	1.000 ft.	1.000 ft.			Vertical	Yes	No	No	No
5	Timber	*3.750 ft.	1.000 ft.			Vertical	*No	Yes	No	No
6	Timber	1.000 ft.	1.000 ft.			Vertical	*No	Yes	No	No
7	Timber		1.000 ft.			Vertical	Yes	No	No	No
NON-BEARING BENT										
*REVISED BY: S.GURME 8/10/2021										
Bent/Abutment #: 1			Similar Bents:							

Title Interior Bent 1 Sketch	Description Data Worksheet
--	--------------------------------------

Bridge No: 910126	Drawn By: MRM	Date: 8/12/2015	File Name: S0454000201
-------------------	---------------	-----------------	------------------------


Bridge Inspection Field Sketch



Cap Information			Material Precast Concrete							
Length	Width	Height	Left Overhang	Right Overhang	Left Beam to End of Cap.	Right Beam to End of Cap.				
26.000ft.	1.333 ft.	1.000 ft.	1.400 ft.	1.400 ft.	*.250 ft.	*.250 ft.				
Subcap Information			Material							
Length	Width	Height	Left Overhang	Right Overhang	Left Pile to Splice.					
Sill Information			Material							
Length	Width	Height								
Pile #	Material	Spacing	Width/Dia.	Height	Length	Orientation	Driven?	Replacement?	Removed?	Collar?
1	Timber	6.167 ft.	*1.000 ft.			Vertical	Yes	No	No	No
2	Steel/Timber	5.500 ft.	*1.000 ft.	*1.000 ft.		Vertical	Yes	Yes	No	Yes
3	Timber	5.750 ft.	*1.000 ft.			Vertical	Yes	No	No	No
4	Timber	5.750 ft.	*1.000 ft.			Vertical	Yes	No	No	No
5	Timber		*1.000 ft.			Vertical	Yes	No	No	No
NON-BEARING BENT										
*REVISED BY: S. GURME 8/10/2021										
Bent/Abutment #: 2			Similar Bents:							

Title Interior Bent 2 Sketch		Description Data Worksheet			
Bridge No: 910126	Drawn By: VWW	Date: 11/23/2005	File Name: S0214000043		


Bridge Inspection Field Sketch



Cap Information			Material Precast Concrete							
Length	Width	Height	Left Overhang	Right Overhang	Left Beam to End of Cap.	Right Beam to End of Cap.				
26.000 ft.	1.333 ft.	1.000 ft.	1.300 ft.	1.300 ft.	*.250 ft.	*.250 ft.				
Subcap Information			Material							
Length	Width	Height	Left Overhang	Right Overhang	Left Pile to Splice.					
Sill Information			Material							
Length	Width	Height								
Pile #	Material	Spacing	Width/Dia.	Height	Length	Orientation	Driven?	Replacement?	Removed?	Collar?
1	Timber	6.000 ft.	*1.000 ft.			Vertical	Yes	No	No	Yes
2	Timber	5.750 ft.	*1.000 ft.			Vertical	Yes	No	No	No
3	Timber	5.670 ft.	*1.000 ft.			Vertical	Yes	No	No	No
4	Timber	6.000 ft.	*1.000 ft.			Vertical	Yes	No	No	No
5	Timber		*1.000 ft.			Vertical	Yes	No	No	No
<p>*REVISED BY: S. GURME 8/10/2021</p>										
Bent/Abutment #: 3			Similar Bents:							

Title Interior Bent 3 Sketch			Description Data Worksheet		
Bridge No: 910126	Drawn By: VWW	Date: 11/23/2005	File Name: S0214000044		

Bridge Inspection Field Sketch



Interior Bent 3 Crutch Bent (Interior 1 and 2 Crutch Bents Similar)

VERIFIED BY: S. GURME 8/10/2021

Title

Crutch Bent Sketch (North-South Faces)

Description

Data Worksheet


Bridge No: 910126

Drawn By: VWW

Date: 08/17/2009

File Name: S0010000384

Bridge Inspection Field Sketch



VERIFIED BY: S. GURME 8/10/2021

Title
Crutch Bent Sketch (West - East Faces)

Description
Data Worksheet

Bridge No: 910126

Drawn By: VWW

Date: 08/17/2009

File Name: S0010000295