
									NOTES	AS-BUILT REPAIR QUANTITY TABLE					
									SHOTCRETE REPAIR	REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE	DECK UNDERSIDE REPAIR - SPAN C				
BEAM REPAIR QUANTITY TABLE										BASED ON THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE		ESTI	ESTIMATE		ÇTUAL
STEEL	STEEL PLATES		STIFFENER			STEEL DIAPHRAGM			ERI - EPOXY RESIN INJECTION REPLACE NUT	N DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ENTER THE ACTUAL QUANTITIES INTO THE AS-BUILT REPAIR QUANTITY TABLE.	SHOTCRETE REPAIR	AREA SQ. FT.	VOLUME CU. FT.	AREA SQ. FT.	VOLUME CU. FT.
	LBS.		LBS.			LBS.		(RN)			UNDERSIDE OF DECK	0.0	0.0		<u> </u>
											UNDERSIDE OF OVERHANG	1.8	0.9		ļ]
ESTIMATE	ACTUAL	ESTIN	ИАТЕ	ACTUAL	ESTIMATE	ACTU	JAL	(RW)	REPLACE WASHER	FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.	DIAPHRAGM	0.0	0.0		<b></b>
0.0		15	.3		0.0					TOR SHOTERETE REFAILS, SEE STEERET ROVISIONS.					<u> </u>
								(S)	STIFFENER REPAIR	SHOTCRETE REPAIRS MAY BE REPLACED WITH CONCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.	OTHER REPAIRS	EST	IMATE	AC	CTUAL
								$\bigcirc$		CONTRACTOR SHALL SAWCUT TO A NOMINAL DEPTH OF 1/2"					
										BUT REINFORCING STEEL SHALL NOT BE DAMAGED.	VALUES IN CHART REPRESENT ESTI	MATED REPAI	R TOTALS AFT	ER REMOVAL	OF
										CONTRACTOR SHALL REMOVE SURFACE CONCRETE TO VERIFY THAT SAWCUT DEPTH WILL NOT DAMAGE EXISTING REINFORCING STEEL.	UNSOUND CONCRETE, MINIMUM OI TO SAWCUT. SEE "OVERHANG, DIA	<sup>-</sup> 1" BEHIND F	REBAR AND MI	NIMUM 2" CL	EARANCE
	Α	NTICIP	ATED E	BEAM REP	AIR LOCA	TIONS									
		1	1							FOR UNDERSIDE OF DECK AND OVERHANG REPAIRS, SEE "OVERHANG, DIAPHRAGM AND BRIDGE RAIL REPAIR					
SPAN BEAM	LOCATION	REPAIR TYPE	DIM "A"	DIM "B"	DIM "C"	DIM "D"	DIM "E"	DIM "F"		DETAILS'' SHEET.					
C 1	BENT 2	S	9"	4 <sup>3</sup> ⁄ <sub>4</sub> "						FOR EPOXY RESIN INJECTION, SEE SPECIAL PROVISIONS.					
										PRIOR TO CLEANING AND PAINTING, REPLACE AND/OR					
										TIGHTEN MISSING NUTS AND WASHERS. PAYMENT FOR THE WASHERS AND NUTS SHALL BE CONSIDERED INCIDENTAL TO VARIOUS PAY ITEMS.					
										FOR STIFFENER REPAIR, SEE "BEAM PLATING REPAIR DETAILS" SHEET.					

											NOTES	AS-BUILT R	EPAIR QUANTITY	TABLE	
										SHOTCRETE REPAIR	REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE BASED ON THE BEST INFORMATION AVAILABLE. IF	DECK UNDERSIDE REPAIR - SPAN C			
BEAM REPAIR QUANTITY TABLE						ABLE				ERI - EPOXY RESIN INJECTION	ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE N DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ENTER		ESTIMATE	ACTUAL	
STEEL PLATES		STIFFENER		STEEL DIAPHRAGM				SHOTCRETE REPAIR	AREA VOLUME SQ. FT. CU. FT.			AREA VOLUME SQ. FT. CU. FT.			
LBS.			LBS.			LBS.		RN)	REPLACE NUT	THE ACTUAL QUANTITIES INTO THE AS-BUILT REPAIR QUANTITY TABLE.	UNDERSIDE OF DECK UNDERSIDE OF OVERHANG	<u>0.0</u> 0.0 1.8 0.9			
ESTIM	ATE	ACTUAL	ESTIM	IATE	ACTUAL	ESTIMATE	ACTUA	(RV	(W)	REPLACE WASHER	FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.	DIAPHRAGM	0.0 0.0		
0.0	)		15	.3		0.0		S	s	STIFFENER REPAIR	SHOTCRETE REPAIRS MAY BE REPLACED WITH CONCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.	OTHER REPAIRS	ESTIMATE	ACTUAL	
											CONTRACTOR SHALL SAWCUT TO A NOMINAL DEPTH OF 1/2" BUT REINFORCING STEEL SHALL NOT BE DAMAGED.	VALUES IN CHART REPRESENT ES	TIMATED REPAIR TOTALS AFTE	R REMOVAL OF	
											CONTRACTOR SHALL REMOVE SURFACE CONCRETE TO VERIFY THAT SAWCUT DEPTH WILL NOT DAMAGE EXISTING REINFORCING STEEL.	UNSOUND CONCRETE, MINIMUM TO SAWCUT. SEE "OVERHANG, DI	OF 1" BEHIND REBAR AND MIN	IIMUM 2" CLEARANCE	
		Α	NTICIP	ATED B	EAM REP	AIR LOCA	TIONS				FOR UNDERSIDE OF DECK AND OVERHANG REPAIRS, SEE				
SPAN	BEAM	LOCATION	REPAIR TYPE	DIM "A"	DIM "B"	DIM "C"	DIM "D"	DIM "E" DIM "F"			"OVERHANG, DIAPHRAGM AND BRIDGE RAIL REPAIR DETAILS'' SHEET.				
С	1	BENT 2	S	9"	4 <sup>3</sup> ⁄ <sub>4</sub> "						FOR EPOXY RESIN INJECTION, SEE SPECIAL PROVISIONS.				
											PRIOR TO CLEANING AND PAINTING, REPLACE AND/OR TIGHTEN MISSING NUTS AND WASHERS. PAYMENT FOR THE WASHERS AND NUTS SHALL BE CONSIDERED INCIDENTAL TO VARIOUS PAY ITEMS.				
											FOR STIFFENER REPAIR, SEE "BEAM PLATING REPAIR				

FOR BEAM REPAIR - PLATING, SEE SPECIAL PROVISIONS.



DRAWN BY :	A. SORSENGINH	DATE :	6/2022
CHECKED BY :	S.AGUILAR HERNANDEZ	DATE :	6/2022

+

+

	PROJEC C BRIDGE SHEET 3 OF	HERO	KEE	BPR.6 CO 0009	5 <b>1</b> UNTY
12/12/2022 WINN CAROL ACTESSION SEAL 031583 PRASAU			RALEIGH	NSPORTA	
EA6F794150BF4B7		REVIS	TONS		SHEET NO.
DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED	№. вт: 1 2	DATE: I	чо. ву: З 4	DATE:	SILET NO. S1-12 TOTAL SHEETS 25