

R:\15BPR61\Structures\FinalPlans\401_037_15BPR61_SMU_B2C_S19_190009.dgn ksedai

+

+

| AS-BUILT REPAIR QUANTITY TABLE | | | | | | | | |
|---|------------|--------------|------------|--------------|--|--|--|--|
| BENT 2 SPAN C FACE | QUANTITIES | | | | | | | |
| | ESTIMATE | | ACTUAL | | | | | |
| SHOTCRETE REPAIRS | AREA SF | VOLUME CF | AREA SF | VOLUME CF | | | | |
| CAP | 37.0 | 18.5 | | | | | | |
| COLUMN | 51.3 | 25.7 | | | | | | |
| EPOXY RESIN INJECTION | | LIN. FT. | | LIN. FT. | | | | |
| САР | | 0.0 | | | | | | |
| COLUMN | | 0.0 | | | | | | |
| VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL | | | | | | | | |

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MINIMUM OF 1" BEHIND REBAR AND MINIMUM OF 2" CLEARANCE TO SAWCUT. FOR REPAIR DETAILS, SEE ``TYPICAL CAP AND COLUMN REPAIR DETAILS'' SHEET.


NOTES:

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE BASED ON THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ENTER THE ACTUAL QUANTITIES INTO THE AS-BUILT REPAIR QUANTITY TABLE.

FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR EPOXY RESIN INJECTION, SEE SPECIAL PROVISIONS.

FOR CAP AND COLUMN REPAIR DETAILS, SEE " TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.



SHOTCRETE REPAIR AREA

EPOXY RESIN INJECTION (ERI)

| | | CHERO | 10 | | UNTY | | |
|--|--|-------|---------|-------|--------------------------|--|--|
| 12/12/2022 MARTH CAROLINA OFESSION SEAL O31583 Doctomer District Krishna P. Sedai EA6F794150BF4B7 | STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH | | | | | | |
| | REVISIONS SHEET NO. | | | | | | |
| OCUMENT NOT CONSIDERED FINAL UNLESS ALL | NO. ВҮ: 1 | DATE: | NO. BY: | DATE: | S1-19 TOTAL SHEETS | | |
| SIGNATURES COMPLETED | 2 | | 4 4 | | 25 | | |