

AS-BUILT REPAIR QUANTITY TABLE							
SPANS A, B AND C							
TOP OF DECK REPAIRS							
		ESTIM	ESTIMATE		ACTUAL		
SCARIFYING BRIDGE DECK		829.	829.3 SY				
HYDRO-DEMOLITION OF BRIDGE DECK		829.	3 SY				
CLASS II SURFACE PREPARATION			8 SY				
LATEX MODIFIED CONCRETE OVERLAY- VERY EARLY STRENGTH			40.5 CY				
PLACING & FINISHING LMC-VES OVERLAY			3 SY				
BRIDGE JOINT DEMOLITION		80.	6 SF				
GROOVING BRIDGE FLOORS		6830	O SF				
UNDERSIDE OF DECK REPAIRS							
	QUANTITIES						
SHOTCRETE REPAIRS	ESTI	ESTIMATE		ACTUAL			
	AREA SF	VOLUME CF	ARE SF		VOLUME CF		
UNDERSIDE OF DECK	0.0	0.0					
OVERHANG DIAPHRAGMS	0.0	0.0					
UNDERSIDE OF OVERHANG	0.0	0.0					
INTERIOR DIAPHRAGMS	0.0	0.0					
	ESTIMATE		ACTUAL				
UNDERSIDE EPOXY RESIN INJECTION	0.0 LF						

VALUES IN CHART REPRESENT ESTIMATED UNDERSIDE OF DECK REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2" CLEAR TO SAW CUT. SEE REPAIR DETAILS.

RAWN BY :	B.E.LANNING	DATE: 10/2022
	B.E. ATKINSON	DATE: 10/2022
SIGN ENGI	NEER OF RECORD : B.E. ATKINSON	DATE : 10/2022

+

1/12/2023 9:19:21 AM


PLAN OF SPANS



BRIDGE JOINT DEMOLITION

CLASS II SURFACE PREPARATION DECK SCARIFICATION, HYDRO-DEMOLITION AND LATEX MODIFIED CONCRETE OVERLAY-VES





NOTES:

TEST LOCATION	*CONC COV
	(IN
#1	13⁄
#2	2 ³ /
#3	2 ¹ /
#4	21/
#5	21/
#6	2 ³ /

EVALUATION DATED 08/30/22.

