BEAM REPAIR QUANTITY TABLE									
STEEL PLATES		STIFFENER		STEEL BEARING KEEPER ANGLE ASSEMBLY					
LBS.		LBS.		EA.					
ESTIMATE	ACTUAL	ESTIMATE	ACTUAL	ESTIMATE	ACTUAL				
0.0		25.0		1					

ANTICIPATED BEAM REPAIR LOCATIONS

DIM ``B"

4½"

RN	

SHOTCRETE REPAIR

ERI - EPOXY RESIN INJECTION DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER



S

DIM ``F"




REPLACE NUT

REPLACE WASHER

STEEL BEARING KEEPER

STIFFENER REPAIR

ANGLE ASSEMBLY



CONTRACTOR SHALL SAWCUT TO A NOMINAL DEPTH OF 1/2" BUT REINFORCING STEEL SHALL NOT BE DAMAGED.

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE

ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE

LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ENTER

BASED ON THE BEST INFORMATION AVAILABLE. IF

WILL NOTE ON THE DRAWINGS THE APPROXIMATE

THE ACTUAL QUANTITIES INTO THE AS-BUILT REPAIR

FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

CONTRACTOR SHALL REMOVE SURFACE CONCRETE TO VERIFY THAT SAWCUT DEPTH WILL NOT DAMAGE EXISTING REINFORCING STEEL.

FOR UNDERSIDE OF DECK AND OVERHANG REPAIRS, SEE "OVERHANG, DIAPHRAGM AND BRIDGE RAIL REPAIR DETAILS" SHEET.

FOR EPOXY RESIN INJECTION, SEE SPECIAL PROVISIONS.

PRIOR TO CLEANING AND PAINTING, REPLACE AND/OR TIGHTEN MISSING NUTS AND WASHERS. PAYMENT FOR THE WASHERS AND NUTS SHALL BE CONSIDERED INCIDENTAL TO VARIOUS PAY ITEMS.

FOR STIFFENER REPAIR, SEE "BEAM PLATING REPAIR DETAILS" SHEET.

FOR BEAM REPAIR - PLATING, SEE SPECIAL PROVISIONS.

FOR STEEL BEARING KEEPER ANGLE ASSEMBLY, SEE SPECIAL PROVISIONS.

FOR STEEL BEARING KEEPER ANGLE ASSEMBLY DETAILS.

NOTES

QUANTITY TABLE.

SEE "STEEL BEARING KEEPER ANGLE ASEMBLY DETAILS" SHEET. JOINT ☐ JOINT____ @ BENT 3 @ BENT 4 (G1) (s)-BRIDGE (G3)(G4)

DIM ``E"

AS-BUILT REPAIR QUANTITY TABLE								
DECK UNDERSIDE REPAIR - SPAN D								
	ESTIMATE		ACTUAL					
SHOTCRETE REPAIR	AREA SQ. FT.	VOLUME CU. FT.	AREA SQ. FT.	VOLUME CU. FT.				
UNDERSIDE OF DECK	0.0	0.0						
UNDERSIDE OF OVERHANG	0.0	0.0						
DIAPHRAGM	0.0	0.0						
OTHER REPAIRS	ESTIMATE		ACTUAL					
	I							

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MINIMUM OF 1" BEHIND REBAR AND MINIMUM 2" CLEARANCE TO SAWCUT. SEE "OVERHANG, DIAPHRAGM AND BRIDGE RAIL REPAIR DETAILS" SHEET

> PROJECT NO. 15BPR.125.3 CHEROKEE COUNTY

190009 BRIDGE NO. ____

SHEET 4 OF 5

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION

DECK UNDERSIDE REPAIR SPAN D

REVISIONS DATE: DOCUMENT NOT CONSIDERED
FINAL UNLESS ALL
SIGNATURES COMPLETED TOTAL SHEETS

A. SORSENGINH DRAWN BY S. AGUILA HERNANDEZ

SPAN | BEAM |

D

LOCATION

BENT 3

TYPE

S