


	BEAM	REPAIR	QU	ANTITIY	TAB	LE	
OITED STEEL	DI ATEC	CTEEL DI ATE	2	CTEEL DIAD		DEAM DEDAID	

BOLTED STEEL PLATES | STEEL PLATES STEEL DIAPHRAGM I BEAM REPAIR CUI-OU LBS. ACTUAL ESTIMATE ACTUAL ESTIMATE ACTUAL ESTIMATE ACTUAL **ESTIMATE** 0.0 87.0 0.0 0.0

ANTICIPATED STEEL REPAIR LOCATIONS										
REPAIR TYPE	BEAM	LOCATION	DIM. "A"	DIM. "B''	DIM. "C''	DIM. "D''				
W	4	BENT 4	15"	15"						

(SEE SHEETS S2-26, S2-27 AND S2-28 FOR BEAM REPAIR DETAILS AND DIMENSIONS.)

S. T. SANDOR _ DATE : <u>2/1/23</u> DRAWN BY : DATE : 5/31/23 W. C. SMITH CHECKED BY :



LIMITS OF ZONE PAINTING

1.0 0.3 CONCRETE DIAPHRAGM 16.2 13.4 17.5 5.8 VOLUME AREA AREA VOLUME CONCRETE REPAIRS UNDERSIDE OF DECK CONCRETE DIAPHRAGM LINEAR LINEAR **EPOXY RESIN INJECTION** 3.0 CONCRETE DIAPHRAGM **CONCRETE OVERHANG** AREA AREA ZONE PAINTING 225.4 VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1" BEHIND REBAR AND MIN. 2" CLEAR TO SAWCUT. SEE REPAIR DETAILS.

SHOTCRETE REPAIR AREA

QUANTITIES

ACTUAL

VOLUME


CF

AREA

ESTIMATE

AREA

VOLUME




CONCRETE REPAIR AREA



ZONE PAINTING



EPOXY RESIN INJECTION



BEAM NUMBER

WEB PLATING REPAIR

BOTTOM FLANGE PLATING REPAIR

BOLTED WEB PLATE REPAIR BOLTED FLANGE PLATE REPAIR

BEAM REPAIR CUT-OUT

B-5981

PROJECT NO.____

DUPLIN COUNTY

BRIDGE NO. 300017

SHEET 5 OF 5

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION

DECK UNDERSIDE REPAIR SPAN E

William C. Smith

SEAL 054816

SHEET NO **REVISIONS** 10/24/2023 S2-14 DATE: DATE: BY: DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

10/17/2023 R:\Structures\Plans\300017\402_027_B5981_SMU_ DUR_E_S2-14_300017.dgn