

DECK UNDERSIDE REPAIR QUANTITY TABLE DECK UNDERSIDE REPAIRS SPAN A QUANTITIES **ESTIMATE** ACTUAL AREA VOLUME AREA VOLUME SHOTCRETE REPAIRS SF UNDERSIDE OF DECK 2.0 0.7 CONCRETE DIAPHRAGM 0.7 0.2 OVERHANG 0 VOLUME VOLUME CONCRETE REPAIRS CF UNDERSIDE OF DECK 0 0 CONCRETE DIAPHRAGM **OVERHANG**

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1" BEHIND REBAR AND MIN. 1" CLEAR TO SAWCUT. SEE REPAIR DETAILS.

NOTES

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN BASED ON THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ENTER THE ACTUAL QUANTITIES INTO THE REPAIR QUANTITY TABLE.

CONCRETE REPAIRS MAYBE SUBSTITUTED IN LIEU OF SHOTCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR DECK REPAIR DETAILS, SEE SHEET S2-9.

FOR OVERHANG & DIAPHRAGM REPAIR DETAILS, SEE S2-10.

SEAL ** 030024

PROJECT NO. HI-0015 **COLUMBUS** COUNTY

230086

BRIDGE NO. ___

SHEET 1 OF 3

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION

DECK UNDERSIDE REPAIR SPAN A

SHEET NO REVISIONS S2**-**6 DATE: DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

REPAIR KEY

SHOTCRETE REPAIR AREA

CONCRETE REPAIR AREA



EPOXY RESIN INJECTION



GIRDER NUMBER

S. T. SANDOR DRAWN BY : _ DATE : 10/23 G. AYES CHECKED BY : __ DESIGN ENGINEER OF RECORD:

11/21/2023 S:\DPG1\Division6\HI-0015\230086\PLANS\402_011_HI0015_SMU_DUR_A_S2-6_230086.dgn aabraha