

REPAIR KEY


SECTION A-A

SHOTCRETE REPAIR AREA


CAP REPAIR


CONCRETE REPAIR AREA (FORM AND POUR)

PLAN OF COLUMN



| SPLICE | LENGTH TABLE | | | | | |
|---------------|----------------------------------|--|--|--|--|--|
| BAR SIZE | MIN. SPLICE LENGTH | | | | | |
| #4 | 2'-5" 3'-0" 3'-7" 4'-2" | | | | | |
| #5 | | | | | | |
| #6 | | | | | | |
| #7 | | | | | | |
| #8 | 4'-9" | | | | | |
| #9 | 5'-4" | | | | | |
| #10 | 6′-0″ | | | | | |
| #11 | 6′-8″ | | | | | |





ELEVATION

PEDESTAL WALL REPAIR



NOTES

TYPICAL BENT CAP REPAIRS ARE SHOWN. REPAIR DETAILS SIMILAR FOR END BENT CAPS AND STRUTS.

THE METHOD USED TO DELINEATE THE AREAS OF UNSOUND CONCRETE TO BE REPAIRED SHALL NOT PERMANENTLY MARK THE CONCRETE, LEAVE ANY RESIDUE AFTER REMOVAL OR REQUIRE HARSH CHEMICALS TO REMOVE.

THE CONTRACTOR SHALL REMOVE THE DETERIORATED CONCRETE IN ACCORDANCE WITH THE GUIDELINES SET IN THESE NOTES, IN THE SPECIAL PROVISIONS AND THE STANDARD SPECIFICATIONS.

REMOVE UNSOUND CONCRETE TO THE EXTENT NECESSARY, MINIMUM OF 1"BEHIND REBAR AND MINIMUM OF 2" CLEARANCE TO SAWCUT.

NO MORE THAN ONE-THIRD OF THE CAP OR COLUMN CIRCUMFERENCE SHALL BE REMOVED AT ONE TIME. SHOULD IT BECOME NECESSARY TO REMOVE MORE THAN 30% OF A CAP OR COLUMN CROSS SECTIONAL AREA, NOTIFY THE ENGINEER PRIOR TO PROCEEDING.

SIMULTANEOUS REMOVAL OF UNSOUND CONCRETE MAY BE PERMITTED ON MORE THAN ONE FACE OF A CAP AND/OR COLUMN, BUT NO MORE THAN 3 OF THE CIRCUMFERENCE SHALL BE REMOVED AT ONE TIME. IF REMOVAL EXTENDS MORE THAN $1\frac{1}{2}$ BEHIND THE MAIN REINFORCING BARS. NOTIFY THE ENGINEER PRIOR TO PROCEEDING. ON COLUMNS AND PILES, NO MORE THAN 10 VERTICAL FEET MAY BE EXPOSED AT ONE TIME BEFORE PLACEMENT OF REPAIR CONCRETE.

REINFORCING STEEL WHICH IS DETERMINED BY THE ENGINEER TO BE REPLACED, SHALL BE REMOVED TO A POINT WHERE IT IS SOUND. THE PATCH SHALL EXTEND A SUFFICIENT DISTANCE BEYOND THIS POINT TO DEVELOP A SPLICE LENGTH SPECIFIED IN THE TABLE ON THIS SHEET.

THE #4 "U" DOWELS ARE REQUIRED ONLY AROUND THE ANCHOR BOLTS. THE EXISTING REINFORCING STEEL IN THE PEDESTAL WALL SHALL BE CLEANED, STRAIGHTENED AND REMAIN IN PLACE.

FOR ADHESIVELY ANCHORED ANCHOR BOLTS OR DOWELS, SEE STANDARD SPECIFICATIONS.


COAT ALL REPAIR SURFACE AREAS ON THE TOP OF CAPS, INCLUDING CHAMFERS, WITH EPOXY PROTECTIVE COATING, OVERLAPPING THE REPAIR AREA BY A MINIMUM OF 3"ON ALL POSSIBLE SIDES.

FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR CONCRETE REPAIRS, SEE SPECIAL PROVISIONS.

CLEAN ALL EXPOSED REINFORCING BARS AND PRESTRESSED STRANDS IN ACCORDANCE WITH APPROPRIATE SPECIAL PROVISIONS. FOR BARS WITH MORE THAN 10% SECTION LOSS, SPLICE AND SECURELY TIE SUPPLEMENTAL REINFORCING BARS AS NEEDED. NOTE AND PROVIDE DETAILED DOCUMENTATION, INCLUDING LOCATION AND SEVERITY, OF ALL DAMAGE TO PRESTRESSED STRANDS THAT EXCEEDS 10% SECTION LOSS. IF FIVE OR MORE STRANDS ARE DAMAGED, NOTIFY THE ENGINEER PRIOR TO PLACEMENT OF REPAIR MATERIAL.

> PROJECT NO. HI-0015 COLUMBUS COUNTY 230086 BRIDGE NO.



STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH STANDARD TYPICAL CAP AND COLUMN REPAIR DETAILS

| | 11, 11, 1013 | | | | | | | |
|--|-------------------------|-----|-----------|-------|-----|-----|-------|-----------------|
| | | | REVISIONS | | | | | |
| | DOCUMENT NOT CONSIDERED | NO. | BY: | DATE: | NO. | BY: | DATE: | S2-18 |
| | FINAL UNLESS ALL | 1 | | | 3 | | | TOTAL SHEETS |
| | SIGNATURES COMPLETED | 2 | | | 4 | | |] 18 |

ELEVATION OF COLUMN

COLUMN REPAIR

ASSEMBLED BY : S. T. SANDOR DATE : 10/2023 CHECKED BY : G. AYES DATE : 10/2023 DRAWN BY : NAP 8/18

CHECKED BY :

S:\DPG1\Division6\HI-0015\230086\PLANS\402_035_HI0015_SMU_SBR_S2-18_230086.dgn