

AS-BUILT REPAIR QUANTITY TABLE					
BENT 1 SPAN B FACE	QUANTITIES				
	ESTIMATE		ACTUAL		
SHOTCRETE REPAIRS	AREA SF	VOLUME CF	AREA SF	VOLUME CF	
САР	86.0	21.5			
COLUMN	1.5	0.4			
CONCRETE REPAIRS	AREA SF	VOLUME CF	AREA SF	VOLUME CF	
САР	0.0	0.0			
EPOXY RESIN INJECTION		LN.FT.		LN.FT.	
CAP		25.5			
COLUMN		0.0			

NOTES:

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE BASED ON THE BEST INFORMATION AVAILABLE.IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ENTER THE ACTUAL QUANTITIES INTO THE AS-BUILT REPAIR QUANTITY TABLE.

CLEAN AND REMOVE DEBRIS FROM THE TOP OF THE CAP AND APPLY EPOXY PROTECTIVE COATING. EPOXY COATING SHALL BE APPLIED TO THE TOP SURFACE OF THE CAP. THE CONTRACTOR SHALL NOT COAT THE AREA OF THE CAP BENEATH THE MASONARY PLATES.FOR EPOXY COATING, SEE SPECIAL PROVISIONS.

SHOTCRETE REPAIRS MAY BE REPLACED WITH CONCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

FOR CAP AND COLUMN REPAIRS, SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS", SHEET.

FOR SHOTCRETE REPAIR, SEE SPECIAL PROVISIONS.

FOR CONCRETE REPAIR, SEE SPECIAL PROVISIONS.

FOR EPOXY RESIN INJECTION, SEE SPECIAL PROVISIONS.

SHOTCRETE REPAIR (SCR)



CONCRETE REPAIR (CR)

 \sim

EPOXY RESIN INJECTION (ERI)

	PROJECT NO. I-5941				
	DURHAM COUNTY				
BRIDGE NO. 310108					
SHEET 3 OF 4					
DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED Docusigned by: Havain AseAning 19141A6AF2EAN TH CAROL SEAL 20103 MGNEER	STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH SUBSTRUCTURE REPAIR BENT 1 SPAN B FACE				
11/13/2023	REVISIONS SHEET NO.				
E.L. ROBINSON E N G I N E E R I N G LE N G I N E E R I N G LE N G I N E E R I N G LI Status S	NO. BY: DATE: NO. BY: DATE: S1-10 1 3				