

AS-BUILT REPAIR QUANTITY TABLE							
	QUANTITIES						
BENT 2 SPAN B FACE	ESTIMATE		ACTUAL				
SHOTCRETE REPAIRS	AREA SF	VOLUME CF	AREA SF	VOLUME CF			
САР	4.0	1.0					
COLUMN	19.0	5.0					
CONCRETE REPAIRS	AREA SF	VOLUME CF	AREA SF	VOLUME CF			
САР	0.0	0.0					
EPOXY RESIN INJECTION		LN.FT.		LN.FT.			
САР		3.0					
COLUMN		0.0					
EPOXY COATING		SQ.FT.		LN.FT.			
САР		252.0					

NOTES:

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE BASED ON THE BEST INFORMATION AVAILABLE.IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ENTER THE ACTUAL QUANTITIES INTO THE AS-BUILT REPAIR QUANTITY TABLE.

CLEAN AND REMOVE DEBRIS FROM THE TOP OF THE CAP AND APPLY EPOXY PROTECTIVE COATING. EPOXY COATING SHALL BE APPLIED TO THE TOP SURFACE OF THE CAP. THE CONTRACTOR SHALL NOT COAT THE AREA OF THE CAP BENEATH THE MASONARY PLATES.FOR EPOXY COATING, SEE SPECIAL PROVISIONS.

SHOTCRETE REPAIRS MAY BE REPLACED WITH CONCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

FOR CAP AND COLUMN REPAIRS, SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS", SHEET.

FOR SHOTCRETE REPAIR, SEE SPECIAL PROVISIONS.

FOR CONCRETE REPAIR, SEE SPECIAL PROVISIONS.

FOR EPOXY RESIN INJECTION, SEE SPECIAL PROVISIONS.

SHOTCRETE REPAIR (SCR)



CONCRETE REPAIR (CR)

EPOXY RESIN INJECTION (ERI)

	PROJECT N DUF	O. I RHAM	<u>-594:</u> co	UNTY			
BRIDGE NO. 310135							
SHEET 4 OF 8							
DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED	STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH						
HRVgin Asertine 19141A6AF2E3ND2 TH CAROL	SUBSTRUCTURE REPAIR SEAL 20103 BENT 2 SPAN B FACE						
SEAL 20103							
11/13/2023	REVISIONS SHEET NO.						
3362 Six Forks Rd.	NO. BY: DATE:		DATE:	S3-14			
E.L. ROBINSON E N G I N E E R I N G LING I N E E R I N G LING I N E E R I N G License: C-22 9	1 2	3 4		total sheets 18			