

SECTION THRU CAP (EXAMPLE ONLY. ACTUAL REBAR SIZES & LOCATIONS MAY VARY)

CAP REPAIR

NOTE

CONTRACTOR SHALL SAW CUT TO A NOMINAL DEPTH OF $^{\prime}\!\!/_2$ " BUT REINFORCING STEEL SHALL NOT BE DAMAGED.

CONTRACTOR SHALL REMOVE SURFACE CONCRETE TO VERIFY THAT SAWCUT DEPTH WILL NOT DAMAGE EXISTING REINFORCING

CONTRACTOR SHALL SAW CUT THE REPAIR AREAS SO THAT THE CORNERS ARE SQUARE AS INDICATED ON THE DETAILS.

CONCRETE REPAIRS MAY BE SUBSTITUTED IN LIEU OF SHOTCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR EPOXY RESIN INJECTION, SEE SPECIAL PROVISIONS.

* IF CONFINEMENT STEEL IS NOT PRESENT, THEN REPAIR LENGTH SHALL NOT EXCEED 10 FEET.

ELEVATION OF CAP

-★ EXPOSED REBAR TO BE BLAST


CZ″ MIN. (TYP.)

CLEANED (TYP.)

REMOVE 1" (MIN.) BEHIND —

ANY EXPOSED REBAR

1/2" DEEP SAW-CUT (TYP.)



PLAN OF COLUMN

COLUMN REPAIR

PROJECT NO. I-5941 DURHAM COUNTY BRIDGE NO. 108, 112, 135,

DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED Karzin Asefa

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION

SUBSTRUCTURE

TYPICAL CAP AND COLUMN REPAIR DETAILS

11/13/2023 REVISIONS SHEET NO. S-74 NO. BY: DATE: BY: DATE: E.L. ROBINSON 3362 Six Forks Rd. Raleigh, N.C. 27609 Tel: 984.960.2810 TOTAL SHEETS

SHEET 2 OF 2

DATE : 3/2023 M. HOGAN DRAWN BY : DATE : 7/2023 JIA XU CHECKED BY : _____ DESIGN ENGINEER OF RECORD: F.ASEFNIA DATE: 11/2023