



PROJECT NO. 8.2353001		ID. B-3450		COUNTY Durham		GEOLOGIST D. Goodnight							
SITE DESCRIPTION Bridge No. 122 Over Sandy Creek on SR 1116 (Garrett Road)						GROUND WATER (ft)							
BORING NO. D-EB2		BORING LOCATION 4+16		OFFSET CL		ALIGNMENT -DET2-							
COLLAR ELEV. 249.9 ft		NORTHING 803280.55		EASTING 2007648.54		0 HR. 4.6							
TOTAL DEPTH 34.1 ft		DRILL MACHINE Mobile B-57		DRILL METHOD 3-7/8" Tricone Wash Rotary		HAMMER TYPE 140 lb. Manual							
DATE STARTED 10/14/02		COMPLETED 10/14/02		SURFACE WATER DEPTH NA									
ELEV. (ft)	DEPTH (ft)	BLOW COUNT			BLOWS PER FOOT					SAMP. NO.	LOG MOI	SOIL AND ROCK DESCRIPTION	
		0.5ft	0.5ft	0.5ft	0	20	40	60	80				100
249.9													249.9 0.00
248.9	1.0	2	2	2							SS-21	23.8%	248.9 3.0
246.4	3.5	3	2	1									246.9 3.0
243.9	6.0	2	1	2									241.9 8.0
241.4	8.5	2	5	9							SS-22	20.0%	237.9 12.0
236.4	13.5	2	2	3									237.9 12.0
231.4	18.5	2	3	3									226.4 23.5
226.4	23.5	25	75/0.2										226.4 23.5
221.4	28.5	60/0.1											222.9 27.0
216.4	33.5												218.9 31.0
													215.8 34.1

PROJECT: 8.2353001 ID: B-3450 COUNTY: Durham
DESCRIPTION(1): Bridge No. 122 over Sandy Creek on SR 1116 (Garrett Road)

INFORMATION ON EXISTING BRIDGES Information obtained from: field inspection
 microfilm(Reel: ___ Pos: ___)
 other Bridge Survey and Hydraulic Design Report dated 5/10/02
COUNTY BRIDGE NO. 122' BRIDGE LENGTH 75' NO. BENTS IN: CHANNEL 1 FLOOD PLAIN 1

FOUNDATION TYPE: Steel H-Piles and timber abutments, interior bent-2 H-piles have concrete bases

EVIDENCE OF SCOUR(2):
ABUTMENTS OR END BENT SLOPES: Deep ravines and drainages intersect main channel on downstream side. Wing walls and abutments appear to be rotting in places.

INTERIOR BENTS: Not evident

CHANNEL BED: Large scour depression directly under the existing bridge
Undercutting of banks directly under existing bridge; trees falling into the channel
CHANNEL BANKS: away from existing bridge.

EXISTING SCOUR PROTECTION:
TYPE(3): Boulders/rip rap under existing bridge; timber wing/retaining walls
EXTENT(4): Boulders and rip rap are only in the channel underneath the existing bridge
EFFECTIVENESS(5): minimal; large scour depression is evident underneath the existing bridge

OBSTRUCTIONS(6) (DAMS,DEBRIS,ETC.): Fallen trees are across channel at various points upstream and downstream of existing bridge; old timber piles from previous bridge under existing bridge; tires, mattress, and other debris under existing bridge and in channel.

DESIGN INFORMATION
CHANNEL BED MATERIAL(7) (SAMPLE RESULTS ATTACHED): Fine to coarse SAND (A-3 and A-1-b)
CHANNEL BANK MATERIAL(8) (SAMPLE RESULTS ATTACHED): Variably clayey and variably silty fine to coarse SAND (A-1-b and A-2-4), very clayey fine to coarse very sandy SILT (A-4), and silty coarse to fine very sandy CLAY (A-6) weathered rock and non-crystalline rock (triassic mudstone and sandstone)
FOUNDATION BEARING MATERIAL(9): sandstone
CHANNEL BANK COVER(10): hardwood trees, grass, brush, wood debris
FLOOD PLAIN WIDTH(11): Approximately 500 feet
FLOOD PLAIN COVER(12): hardwood trees, grass, brush, wood debris