


NOTE:

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

FOR STRUCTURE REPAIRS, SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET S-72.

EPOXY COATING SHALL BE APPLIED TO THE TOP FACE OF THE BENT CAP.




TOP OF CAP

CONCRETE REPAIR


SHOTCRETE REPAIR

ERI - EPOXY RESIN INJECTION



COL 1


END VIEW
WEST FACE



COL 1


COL 2

ELEVATION
SOUTH FACE



COL 2


END VIEW
EAST FACE



COL 2

COL 1

ELEVATION
NORTH FACE




BOTTOM OF CAP

REPAIR QUANTITY TABLE				
REPAIRS BENT 2	QUANTITIES			
	ESTIMATE		ACTUAL	
SHOTCRETE REPAIRS	AREA SF.	VOLUME CF.	AREA SF.	VOLUME CF.
CAP (VERTICAL FACE)				
CAP (HORIZONTAL FACE)	1.8	0.5		
COLUMN (VERTICAL FACE)	0.7	0.2		
CONCRETE REPAIRS				
EPOXY RESIN INJECTION		LN. FT.		LN. FT.
CAP		12.2		
COLUMN		3.5		
EPOXY COATING		SQ. FT.		SQ. FT.
TOP OF CAP		80.2		

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1" BEHIND REBAR AND MIN. 1" CL TO SAWCUT. SEE REPAIR DETAILS.

PROJECT NO. I-5788
HARNETT COUNTY
BRIDGE NO.: 73

SHEET 3 OF 4



DocuSigned by:
Jing H. Fang
E7208440977435...

1/28/2016

STATE OF NORTH CAROLINA
DEPARTMENT OF TRANSPORTATION
RALEIGH
SUBSTRUCTURE REPAIR
BENT 2
NBL

REVISIONS						SHEET NO. S-60 TOTAL SHEETS 72
NO.	BY:	DATE:	NO.	BY:	DATE:	
1			3			
2			4			

DRAWN BY : A. SORSENGINH DATE : 10/30/15
CHECKED BY : S. B. WILLIAMS DATE : 11/4/15