




PLAN - TOP OF CAP



SPAN C VIEW - ELEVATION



PLAN - BOTTOM OF CAP



SPAN D VIEW - ELEVATION

AS-BUILT REPAIR QUANTITY TABLE QUANTITIES REPAIRS BENT 3 ESTIMATE ACTUAL AREA SF VOLUME CF SHOTCRETE REPAIRS 0.0 0.0 0.0 COLUMN 0.0 AREA SF VOLUME CF VOLUME CF CONCRETE REPAIRS 9.5 6.0 ***** COLUMN 1.0 1.5 * LN. FT LN. FT EPOXY RESIN INJECTION CAP 5.0 COLUMN 0.0 SQ. FT SQ. FT EPOXY COATING TOP OF BENT CAP 125

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MINIMUM OF 1" BEHIND REBAR AND MINIMUM 2" CLEAR TO SAWCUT. SEE REPAIR DETAILS.

NOTES:

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE.

CLEAN AND REMOVE DEBRIS FROM TOP OF CAP AND APPLY EPOXY PROTECTIVE COATING.EPOXY COATING SHALL BE APPLIED TO THE TOP FACE OF THE CAP. THE CONTRACTOR SHALL NOT COAT THE AREA OF THE CAP BENEATH THE MASONRY PLATES. FOR EPOXY COATING, SEE SPECIAL PROVISIONS.

* QUANTITY HAS BEEN INCREASED DUE TO THE POTENTIAL FOR FURTHER DETERIORATION SINCE THE FIELD INSPECTION BY STRUCTURES MANAGEMENT UNIT.

FOR REPAIR DETAILS. SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.

FOR BRIDGE JACKING DETAILS, SEE "JACKING DETAILS" SHEET.

John

9/27/2016

SEAL

32492



DAMAGED AREA

EPOXY RESIN INJECTION

PROJECT NO. I-5809

McDOWELL COUNTY

BRIDGE NO. 151

SHEET 3 OF 3

STATE OF NORTH CAROLINA

DEPARTMENT OF TRANSPORTATION
RALEIGH

BENT 3

REVISIONS SHEET NO DOCUMENT NOT CONSIDERED 1 STATE: NO. BY: DATE: S-47

FINAL UNLESS ALL SIGNATURES COMPLETED 2 4 6 68

 DRAWN BY :
 J.P. ADAMS
 DATE : 5/2016

 CHECKED BY :
 T.L. AVERETTE
 DATE : 5/2016