REPAIR QUANTITY TABLE NOTES: REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE INSPECTOR OR ENGINEER THE CONTRACTOR SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR QUANTITY TABLE. REPAIRS BENT 11-S ESTIMATE SHOTCRETE REPAIRS CAP (VERTICAL FACE) 15.7 CAP (HORIZONTAL, CORNER) 0.0 FOR CAP REPAIR DETAILS, SEE "TYPICAL CAP REPAIR DETAILS" SHEET. 0.0 PILE COLLAR (VERT FACE) FOR "SHOTCRETE REPAIRS", SEE SPECIAL PROVISIONS. 0.0 PILE COLLAR (HORIZ FACE) FOR "EPOXY RESIN INJECTION", SEE SPECIAL PROVISIONS. EPOXY RESIN INJECTION VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS. 2.5 SF ¬ 0.5 SF --0.4 SF 1.0 ERI 2.0 ERI -- 5.5 SF (ALL AROUND) NORTH FACE WEST FACE SOUTH FACE EAST FACE PROJECT NO. - SHOTCRETE REPAIR TYRRELL ERI - EPOXY RESIN INJECTION BRIDGE NO. STATE OF NORTH CAROLINA
DEPARTMENT OF TRANSPORTATION PLAN BOTTOM OF CAP DocuSigned by: Paul Bryant 3653D2AF1B77448.. 8/11/2016 DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED P. D. BRYANT

QUANTITIES

VOLUME CF

6.5

0.0

0.0

0.0

LN.FT.

3.0

ACTUAL

B-5936

DATE:

S-326

7

BENT 11-S

COUNTY

VOLUME CF

LN.FT.

DATE : 4-2016

DATE: 4-2016

DRAWN BY : _

CHECKED BY :

W. M. CLARKE