

+

+

AS-BUILT REPAIR QUANTITY TABLE								
TOP OF DECK REPAIRS								
		ESTIMATE		ACTUAL				
SCARIFYING BRIDGE DECK		164 SY						
HYDRO-DEMOLITION OF BRIDGE DECK		164 SY						
CLASS II SURFACE PREPARATION		16.0 SY *						
CLASS III SURFACE PREPARATION		0.5 SY *						
BRIDGE JOINT DEMOLITION		0.0 SF						
EPOXY RESIN INJECTION		0.0 LF						
CONCRETE FOR DECK REPAIR	3.0 CF *							
UNDERSIDE OF DECK REPAIRS								
SHOTCRETE REPAIRS	EST	IMATE	ACTUAL					
	AREA SF	VOLUME CF	AREA SF	VOLUME CF				
UNDERSIDE OF DECK	0.0	0.0						
OVERHANG DIAPHRAGMS	0.0	0.0						
UNDERSIDE OF OVERHANG	0.0	0.0						
INTERIOR DIAPHRAGMS	0.0	0.0						
	ESTIMATE		ACTUAL					
UNDERSIDE EPOXY RESIN INJECTION	4.0 LF							
VALUES IN CHARTS REPRESENT ESTIMATED UNDERSIDE OF DECK								

MEDIES IN CHARTS REFRESENT ESTIMATED UNDERSIDE OF DEC REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MINIMUM OF 1" BEHIND REBAR AND MINIMUM 2" CLEARANCE TO SAWCUT.SEE REPAIR DETAILS.

	APPROX.CLASS II AREA
	APPROX.CLASS III AREA
	UNDERSIDE REPAIR
	DIAPHRAGM REPAIR
	CURB AND RAIL REPAIR
•¹ €	TEST LOCATION
ERI	EPOXY RESIN INJECTION

PROJECT NO. <u>I-5892</u> <u>BUNCOMBE</u> COUNTY BRIDGE NO. <u>415</u>							
John Andrean naccon 7BC3008EE09770-14	L DEPA	RTMENT PLAN	RALEIGH	SPAN	TION		
	REVISIONS SHEET NO.						
DOCUMENT NOT CONSIDERED	NO. BY:		NO. BY:	DATE:	S-13		
FINAL UNLESS ALL	1		3		TOTAL SHEETS		
SIGNATURES COMPLETED	2		4		68		