## NOTES: REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE AS-BUILT REPAIR QUANTITY TABLE. FOR CAP REPAIRS, SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET. SHOTCRETE REPAIRS MAY BE REPLACED WITH CONCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER. FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS. FOR EPOXY RESIN INJECTION, SEE SPECIAL PROVISIONS. \* QUANTITY HAS BEEN INCREASED DUE TO THE POTENTIAL FOR FURTHER DETERIORATION SINCE THE FIELD INSPECTION BY STRUCTURES MANAGEMENT UNIT. 1.0 LF EPOXY RESIN-INJECTION PLAN 1.0 LF EPOXY RESIN-INJECTION 2.0 LF -EPOXY RESIN INJECTION 1.0 LF -EPOXY RESIN 6.7 SF CONCRETE -REPAIR INJECTION 1.0 SF SHOTCRETE -REPAIR 1.0 LF -EPOXY RESIN INJECTION 2.0 LF EPOXY RESIN— INJECTION 1.5 LF -EPOXY RESIN INJECTION 1.0 LF EPOXY RESIN-1.5 LF EPOXY RESIN-INJECTION 2.0 LF EPOXY RESIN-INJECTION 3.0 SF SHOTCRETE REPAIR 2.0 LF -EPOXY RESIN INJECTION INJECTION ELEVATION AS-BUILT REPAIR QUANTITY TABLE DAMAGED AREA REPAIRS END BENT 2 QUANTITIES ESTIMATE ACTUAL I-5892 PROJECT NO.\_ EPOXY RESIN INJECTION AREA SF AREA SF VOLUME CF VOLUME CF SHOTCRETE REPAIRS BUNCOMBE COUNTY CAP 4.0 3.0 \* 429 BRIDGE NO. AREA SF VOLUME CF -DocuSigned by: CONCRETE REPAIRS John Manual DEPARTMENT OF TRANSPORTATION 7BC SEAL 32492 FND BENT 2 CAP 6.7 5.0 \* LN. FT LN. FT **EPOXY RESIN INJECTION** END BENT 2 · NOINEER 13.5 YANNA VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MINIMUM OF 1" BEHIND REBAR AND MINIMUM 1" CLEARANCE TO SAWCUT. SEE REPAIR DETAILS. 1/21/2017 REVISIONS SHEET NO S-47 DATE: DRAWN BY : R.L.PUTEK DOCUMENT NOT CONSIDERE FINAL UNLESS ALL SIGNATURES COMPLETED \_ DATE : \_\_06/16\_ CHECKED BY : S. WANCE DATE: 10/16