

AS-BUILT REPAIR QUANTITY TABLE REPAIRS QUANTITIES BENT 4 (LEFT) ESTIMATE ACTUAL AREA SF AREA VOLUME VOLUME SHOTCRETE REPAIRS CF 36.6 15.3 * COLUMNS & STRUTS 20.1 8.4 * VOLUME AREA VOLUME CONCRETE REPAIRS SF CF CF CAP 2.8 ***** 6.6 COLUMNS & STRUTS 10.5 4.4 * LN. FT EPOXY RESIN INJECTION 0.0 COLUMNS & STRUTS 0.0 SQ. FT. SQ. FT. EPOXY COATING TOP OF BENT CAP 109

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1" BEHIND REBAR AND 2" MIN. CLEAR TO SAWCUT. SEE REPAIR DETAILS.

NOTES

REPAIR LOCATIONS AND ESTIMATED QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE REPAIR SUMMARY OF QUANTITIES TABLE.

SHOTCRETE REPAIRS MAY BE SUBSTITUTED IN LIEU OF CONCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

FOR REPAIR DETAILS, SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.

EPOXY COATING SHALL BE APPLIED TO THE TOP FACE OF THE CAP. THE CONTRACTOR SHALL NOT COAT THE AREA OF THE CAP BENEATH THE MASONRY PLATES. FOR EPOXY COATING, SEE SPECIAL PROVISIONS.

* QUANTITY HAS BEEN INCREASED DUE TO THE POTENTIAL FOR FURTHER DETERIORATION SINCE THE FIELD INSPECTION BY STRUCTURES MANAGEMENT UNIT.

CONCRETE REPAIRS TO THE BENT CAP MAY REQUIRE BRIDGE JACKING. FOR BRIDGE JACKING, SEE "JACKING DETAILS" SHEET.

DAMAGED AREA

EPOXY RESIN INJECTION

PROJECT NO. I-5000 GASTON _ COUNTY 120

SHEET 1 OF 6

BRIDGE NO._

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION

> BENT 4 SPAN D FACE (LEFT SECTION)

> > SHEET NO S-16

REVISIONS DATE:

DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED