

This electronic collection of documents is provided for the convenience of the user and is Not a Certified Document -

The documents contained herein were originally issued and sealed by the individuals whose names and license numbers appear on each page, on the dates appearing with their signature on that page. This file or an individual page shall not be considered a certified document.




PROJECT LENGTH BRUNSWICK COUNTY	2018 STANDARD SPECIFICATIONS	
#71 = 0.34 MILE	<i>LETTING DATE :</i> JUNE 19, 2018	KISINGER CAM & ASSOCIATI
		5.

state N.C.		project reference no. 5BPR.16	SHEET NO.	total sheets 73
STAT	e proj. No.	F. A. PROJ. NO.	DESCRIPT	10N
15	BPR.16	_	P.E.	
15	BPR.16	_	CONS	T.



OJECT: I5BPR.16	IND	EX OF SHEETS - STRUC
Ha	1	TITLE SHEET
37	1A	INDEX OF SHEETS
H	S-1	SUMMARY OF QUANTITIES - STRUCTURES
12	S-2A	GENERAL NOTES
	S-2B	GENERAL NOTES
	S-3	GENERAL DRAWING
	S-4	PLAN OF SPANS APPROACH SLABS 1 & 2
	S-5	PLAN OF SPAN 1
H	S-6	PLAN OF SPAN 2
	S-7	PLAN OF SPAN 3
O	S-8	PLAN OF SPAN 4
	S-9	PLAN OF SPAN 5
PR	S-10	PLAN OF SPAN 6
	S-11	PLAN OF SPAN 7
	S-12	PLAN OF SPAN 8
	S-13	PLAN OF SPAN 9
	S-14	PLAN OF SPAN 10
	S-15	PLAN OF SPAN 11
	S-16	PLAN OF SPAN 12
	S-17	PLAN OF SPAN 13
	S-18	PLAN OF SPAN 14
	S-19	PLAN OF SPAN 15
	S-20	PLAN OF SPAN 16
	S-21	PLAN OF SPAN 17
	S-22	PLAN OF SPAN 18
	S-23	PLAN OF SPAN 19
	S-24	PLAN OF SPAN 20
	S-25	PLAN OF SPAN 22
	S-26 S-27	PLAN OF SPAN 22 PLAN OF SPAN 23
	S-27 S-28	TYPICAL SECTIONS - PPC OVERLAY
	S-28	JOINT DETAILS - APPR SLAB & PPC GDR SPANS
	S-29 S-30	JOINT DETAILS - AFFR SLAD & FFC ODR SFANS
0	S-30 S-31	APPROACH MILLING & TYPICAL ROADWAY SECTIONS
0	S-32	CONCRETE RESTORATION DETAILS - SUPERSTRUCTURE
Ž	S-33	CONCRETE RESTORATION DETAILS - SUPERSTRUCTURE
4	S-34	CONCRETE RESTORATION DETAILS - SUBSTRUCTURE
C204200	S-35	SUBSTRUCTURE CONCRETE REPAIRS - END BENTS 1 & 2



• •

C

CONTRA



4800 SIX FORKS ROAD SUITE 120 RALEIGH, NC 27609 (919) 882-7839

CTURES

S-36	SUBSTRUCTURE CONCRETE REPAIRS - BENT 1
S-37	SUBSTRUCTURE CONCRETE REPAIRS - BENT 2
S-38	SUBSTRUCTURE CONCRETE REPAIRS - BENT 3
S-39	SUBSTRUCTURE CONCRETE REPAIRS - BENT 4
S-40	SUBSTRUCTURE CONCRETE REPAIRS - BENT 5
S-41	SUBSTRUCTURE CONCRETE REPAIRS - BENT 6
S-42	SUBSTRUCTURE CONCRETE REPAIRS - BENT 7
S-43	SUBSTRUCTURE CONCRETE REPAIRS - BENT 8
S-44	SUBSTRUCTURE CONCRETE REPAIRS - BENT 9
S-45	SUBSTRUCTURE CONCRETE REPAIRS - BENT 10
S-46	SUBSTRUCTURE CONCRETE REPAIRS - BENT 11
S-47	SUBSTRUCTURE CONCRETE REPAIRS - BENT 12
S-48	SUBSTRUCTURE CONCRETE REPAIRS - BENT 13
S-49	SUBSTRUCTURE CONCRETE REPAIRS - BENT 14
S-50	SUBSTRUCTURE CONCRETE REPAIRS - BENT 15
S-51	SUBSTRUCTURE CONCRETE REPAIRS - BENT 16
S-52	SUBSTRUCTURE CONCRETE REPAIRS - BENT 17
S-53	SUBSTRUCTURE CONCRETE REPAIRS - BENT 18
S-54	SUBSTRUCTURE CONCRETE REPAIRS - BENT 19
S-55	SUBSTRUCTURE CONCRETE REPAIRS - BENT 20
S-56	SUBSTRUCTURE CONCRETE REPAIRS - BENT 21
S-57	SUBSTRUCTURE CONCRETE REPAIRS - BENT 22
S-58	CHANNEL BENT FOOTING ZINC METALIZING DETAILS - BENTS 10, 13
S-59	CHANNEL BENT FOOTING BULK ANODE DETAILS - BENTS 11, 12
S-60	SUPERSTRUCTURE DEFICIENCIES
S-61	SUPERSTRUCTURE DEFICIENCIES
S-62	SUPERSTRUCTURE DEFICIENCIES
S-63	SUPERSTRUCTURE DEFICIENCIES
S-64	ELECTRICAL REPAIRS TO NAV. LIGHTING SYSTEM
S-65	JACKING DETAILS
S-66	BEARING REPLACEMENT DETAILS
S-67	FENDER SYSTEM - EXISTING AND PROPOSED LAYOUT
S-68	FENDER SYSTEM - PROPOSED LAYOUT AND ELEVATION
S-69	FENDER SYSTEM - TYPICAL SECTIONS & DETAILS
S-70	FENDER SYSTEM - TYPICAL SECTIONS & DETAILS
S-71	FENDER SYSTEM - TYPICAL SECTIONS & DETAILS
S-72	FENDER SYSTEM - TYPICAL SECTIONS & DETAILS
S-73	STANDARD NOTES




state N.C.	STATE]	sheet NO. 1A	TOTAL SHEETS 73		
STAT	e proj. No.	F. A. PROJ. NO.	DESCRIPT	TION	
15	BPR.16	_	P.E.		
15	BPR.16	_	CONS	ST.	

16 ISBPR •• **PROJEC**

SUMMARY OF QUANTITIES


	GROOVING BRIDGE FLOORS	POLLUTION CONTROL	CLASS II, SURFACE PREPARATION	ELASTOMERIC BEARINGS	REPAIRS TO PRESTRESSED CONCRETE GIRDERS	CONCRETE REPAIRS	SHOTCRETE REPAIRS	EPOXY RESIN INJECTION	REMOVAL OF EXISTING FENDER SYSTEM	COMPOSITE FENDER SYSTEM	BRIDGE JOINT REMOVAL	SILICONE JOINT SEALANT	PPC MATERIALS	CP SYSTEM ZINC ALUMINUM SPRAY	
	SQ.FT.	LUMP SUM	SQ. YDS.	LUMP SUM	CU.FT.	CU.FT.	CU.FT.	LIN.FT.	LUMP SUM	LUMP SUM	LIN.FT.	LIN.FT.	CU.YDS.	SQ.FT.	
SUPERSTRUCTURE	53721		6		210	46		534			132	788	192		
SUBSTRUCTURE						145	1031	606						975	
TOTAL	53721	LUMP SUM	6	LUMP SUM	210	191	1031	1140	LUMP SUM	LUMP SUM	132	788	192	975	
_				TOTAL	BILL	OF MA	TERIA	L - S7	FRUCTL	IRES C	ONT. —				
	EPOXY PROTECTIVE COATING	SCARIFYING BRIDGE DECK	SHOTBLASTING BRIDGE DECK	PLACING AND FINISHING PPC OVERLAY	CONCRETE DECK REPAIR FOR PPC OVERLAY	SINGLE PILE JACKET	THREE PILE JACKET	SEVEN PILE JACKET	CP SYSTEM (ZINC BULK ANODES)	BRIDGE JACKING (TYPE I)					
	SQ.FT.	SQ.YDS.	SQ.YDS.	SQ.YDS.	SQ. YDS.	EA.	EA.	EA.	EA.	EA.					
SUPERSTRUCTURE		6674	6674	6674	6										
SUBSTRUCTURE	3527					16	68	4	22						
TOTAL	3527	6674	6674	6674	6	16	68	4	22	3					

C204200 **•** • C CONTRA





4800 SIX FORKS ROAD SUITE 120 RALEIGH, NC 27609 (919) 882-7839



STATE	STAT	E PROJECT REFERENCE NO.	SHEET NO.	TOTAL SHEETS
N.C.	1	5BPR.16	S=1	73
STAT	e proj. No.	F. A. PROJ. NO.	DESCRIPT	ION
15	BPR.16	_	P.E.	
15	BPR.16	_	CONS	T.

DRAWINGS AND DIMENSIONS:

- DO NOT SCALE DRAWINGS FOR DIMENSIONS NOT GIVEN.
- VERIFY ALL EXISTING FIELD CONDITIONS AND DIMENSIONS (INCLUDING MINIMUM VERTICAL CLEARANCE) PRIOR TO COMMENCING REPAIRS OR ORDERING ANY MATERIAL. NOTIFY ENGINEER OF ANY DISCREPANCIES FOUND. 3. ALL DIMENSIONS ARE IN FEET AND INCHES.

DESIGN SPECIFICATIONS:

LRFD BRIDGE DESIGN SPECIFICATIONS (8TH EDITION, 2017) 2018 NCDOT STANDARD SPECIFICATIONS AND PROJECT SPECIAL PROVISIONS.

PROJECT SCOPE:

- POLYESTER POLYMER CONCRETE (PPC) OVERLAY
- SUPERSTRUCTURE CONCRETE REPAIRS SUBSTRUCTURE CONCRETE REPAIRS
- EXPANSION JOINT REPLACEMENT/INSTALLATION
- BEARING REPLACEMENT
- GALVANIC CATHODIC PROTECTION METALIZING GALVANIC CATHODIC PROTECTION - BULK ANODE
- FENDER SYSTEM REHABILIATION 8.
- APPROACH ROADWAY MILLING AND RESURFACING

GENERAL NOTES:

- IT IS THE CONTRACTOR'S RESPONSIBILITY TO FOLLOW ALL STATE AND FEDERAL REQUIREMENTS.
- 2. FOR SUBMITTAL OF FALSEWORK AND FORMWORK. SEE SPECIAL PROVISIONS.
- 3. FOR SUBMITTAL OF WORKING DRAWINGS, SEE SPECIAL PROVISIONS.
- 4. FOR CONTROL OF TRAFFIC AND LIMITS ON PHASING CONSTRUCTION, SEE TRANSPORTATION MANAGEMENT PLAN.
- 5. FOR SURFACE PREPARATION FOR PPC OVERLAY, SEE SPECIAL PROVISIONS. FOR POLYESTER POLYMER CONCRETE (PPC), SEE SPECIAL PROVISIONS.
- 7. FOR SILICONE JOINT SEALANT, SEE SPECIAL PROVISIONS.
- FOR EPOXY RESIN INJECTION, SEE SPECIAL PROVISIONS. 8.
- 9. FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.
- 10. FOR CONCRETE REPAIRS. SEE PLAN DETAILS AND SPECIAL PROVISIONS.
- 11. FOR CONCRETE DECK REPAIR FOR PPC OVERLAY, SEE SPECIAL PROVISIONS.
- 12. FOR ADHESIVELY ANCHORED RODS AND DOWELS, SEE ARTICLE 420-13 OF THE STANDARD SPECIFICATIONS. 13. ALL PROPOSED EXPANSION JOINT DIMENSIONS, OPENINGS AND BLOCKOUTS ARE SHOWN AT 60°F, CONTRACTOR SHALL FOLLOW MANUFACTURER'S INSTALLATION GUIDELINES AND MAKE ANY NECESSARY ADJUSTMENTS.
- 14. WORK ON BRIDGE SHALL BE PERFORMED SO AS NOT TO ALLOW DEBRIS TO FALL INTO THE WATER. THE CONTRACTOR SHALL SUBMIT PLANS FOR CONSTRUCTION IN ACCORDANCE WITH ARTICLE 402-2 OF THE STANDARD SPECIFICATIONS.
- 15. PRIOR TO BEGINNING WORK, THE CONTRACTOR SHALL SUBMIT FOR REVIEW AND APPROVAL, A COMPLETE SEQUENCE OF TASKS FOR EACH OPERATION AFFECTING THE BRIDGE SURFACE AND/OR VEHICLE/MARINE TRAFFIC.
- 16. ANY DAMAGE TO EXISTING REINFORCING STEEL, DURING CONTRACTOR'S OPERATIONS, SHALL BE REPAIRED AS DIRECTED BY THE ENGINEER AND PERFORMED AT NO ADDITIONAL COST.
- 17. FOR CRANE SAFETY, SEE SPECIAL PROVISIONS.
- 18. FOR MAINTENANCE OF WATER TRAFFIC. SEE SPECIAL PROVISIONS.
- 19. FOR WORK IN, OVER OR ADJANCE TO NAVIGABLE WATERS, SEE SPECIAL PROVISIONS.

PROJECT COORDINATES:

NC 130/HOLDEN BEACH ROAD IS AN EAST/WEST ROUTE AND THE BRIDGE BEGINS ON THE MAINLAND SIDE AND ENDS ON THE BEACH SIDE. ALTHOUGH THE BRIDGE IS ORIENTED IN THE NORTH/SOUTH CARDINAL DIRECTION, REFERENCE IN THESE PLANS, BRIDGE INSPECTION REPORTS, AND OTHER DATA IS BASED ON END BENT 1 BEING LOCATED AT THE MAINLAND SIDE AND END BENT 2 BEING LOCATED AT THE BEACH SIDE. IN AN ATTEMPT TO BE CONSISTENT WITH THE CURRENT BRIDGE INSPECTION REPORT, END BENT 1 WILL BE LABELED THE "WEST"END OF THE BRIDGE AND END BENT 2 WILL BE LABELED THE "EAST"END.

DATUM:

ALL ELEVATIONS REFER TO NGVD '29 UNLESS NOTED OTHERWISE.

ENVIRONMENT:

SUPERSTRUCTURE: EXTREMELY AGGRESSIVE - COASTAL SUBSTRUCTURE: EXTREMELY AGGRESSIVE - COASTAL

SITE CONDITIONS:

HABITAT BEYOND THE LIMITS OF CONSTRUCTION SHALL NOT BE DISTURBED.

CONCRETE CLASS:

SEE PROJECT SPECIAL PROVISIONS FOR CONCRETE REPAIR MATERIALS.

CONCRETE COVER:

- CONCRETE COVER SHOWN IN THE PLANS DOES NOT INCLUDE PLACEMENT OR FABRICATION TOLERANCES UNLESS SHOWN AS "MINIMUM COVER." SEE NCDOT SPECIFICATIONS FOR ALLOWABLE REINFORCEMENT PLACEMENT TOLERANCES.
- CONSTRUCTION JOINTS ARE PERMITTED ONLY AT LOCATIONS SPECIFIED IN THE PLANS. ADDITIONAL CONSTRUCTION JOINTS OR ALTERATIONS TO THOSE SHOWN REQUIRE THE ENGINEER'S APPROVAL.

CONCRETE FINISHES:

FINISH IN ACCORDANCE WITH THE LATEST NCDOT SPECIFICATIONS. MATCH EXISTING FINISH ON ALL EXPOSED EDGES UNLESS OTHERWISE NOTED. A CLASS 5 FINISH COATING SHALL BE APPLIED TO THE BEAM ENDS WHERE CONCRETE REPAIRS HAVE BEEN PERFORMED.MATCHING THE COLOR OF SURROUNDING CONCRETE.

REINFORCING STEEL:

CHECKED BY : _____

ALL REINFORCING STEEL SHALL BE ASTM A615-96, GRADE 60.

DIEGO A. AGUIRRE DATE : 03-2018

ALL DIMENSIONS PERTAINING TO LOCATION OF REINFORCEMENT ARE TO CENTERLINE OF BARS EXCEPT WHERE THE CLEAR DIMENSION IS SHOWN TO FACE OF CONCRETE. REINFORCEMENT DETAIL DIMENSIONS ARE OUT-TO-OUT OF BARS.

KISINGER CAMPO	4800 SIX FORKS ROA RALEIGH, NC 27609 (919) 882-7839	D SUITE 120
DRAWN BY :	JACOB H. DUKE	_ DATE : _03-2018

DESIGN ENGINEER OF RECORD : <u>SAMUEL L.CULLUM</u> DATE	: _03-2018_
G:\4	0/2018 1201720.03-Brunswick-71\Structures\401_025_15BPR.16_SMU_GN01_S-2A_090071.dgn r:jduke

—

ADJACENT EDGE CONCRETE REPAIRS:

WHEN PROPOSED CONCRETE REPAIRS (OR DETERMINED LOCATIONS) ARE ADJACENT TO A CORNER, REPAIR ON THE ADJACENT EDGE SHOULD BE ANTICIPATED IN ADDITION TO THE AREA SHOWN ON SUBSTRUCTURE CONCRETE REPAIR SHEETS. CONTRACTOR IS RESPONSIBLE FOR THIS REPAIR AT ALL LOCATIONS REGARDLESS OF CALL-OUT ON RESPECTIVE SHEET(S).

LIMIT OF REPAIRS:

- EXTENT OF THE REPAIRS IS EXPECTED TO VARY DURING CONSTRUCTION. SIGNIFICANT CHANGES.

FORMS CONSTRUCTION:

FORMS MUST BE SUPPORTED BY THE EXISTING STRUCTURE. FULL DEPTH COFFERDAMS WILL NOT BE ACCEPTED. THE CONTRACTOR SHALL SUBMIT DETAILED PLANS FOR FORMS AND FALSEWORK TO BE USED FOR CONSTRUCTION OF THE PIER AND CONCRETE REPAIR. CONSTRUCTION SURVEYING:

ALL SURVEYING AND STAKING NECESSARY TO COMPLETE THE PROPOSED WORK IS INCIDENTAL TO ALL OTHER PAY ITEMS FOR THIS PROJECT. ENVIRONMENTAL NOTES:

STANDARD CONSTRUCTION CONDITIONS SHALL BE IMPLEMENTED FOR THE FOLLOWING PROTECTED/ENDANGERED SPECIES AS APPLICABLE AND INCLUDED IN CONTRACT DOCUMENTS.

- A. WEST INDIAN MANATEE
- B. VARIOUS SEA TURTLE SPECIES
- C. ATLANTIC STURGEON

POLLUTION CONTROL:


- PRIOR TO COMMENCING ANY CONSTRUCTION ACTIVITIES.
- 2. THE CONTRACTOR SHALL NOT ALLOW, AT ANY TIME, ANY DISCHARGE OR MATERIALS TO FALL INTO THE WATERWAY.
- AND BEST MANAGEMENT PRACTICES.
- 4. NO OFFSITE IMPACTS SHALL BE PERMITTED.
- 5. A CONTAINMENT PLAN IS REQUIRED FOR FENDER PILE CLEANING AND COATING. AS WELL AS. CONCRETE REPAIR.

MISCELLANEOUS NOTES:

- 1. THE CONTRACTOR IS RESPONSIBLE TO SUBMIT A JACKING PLAN FOR EACH OPERATION TO THE ENGINEER FOR APPROVAL PRIOR TO BRIDGE JACKING.
- 2. THE CONTRACTOR WILL BE RESPONSIBLE FOR SECURING PLANS FOR POLYMERIC FENDER REPLACEMENT, SEE PLANS AND SPECIFICATIONS FOR FURTHER DETAILS.
- 3. PAYMENT FOR INCIDENTAL ITEMS NOT SPECIFICALLY COVERED IN THE INDIVIDUAL BID ITEMS SHALL BE INCLUDED IN THE CONTRACT UNIT PRICE FOR THE BID ITEMS CONTAINED IN THE CONTRACT.
- 4. FOR ICT. SEE CONTRACT DOCUMENTS AND TRANSPORTATION MANAGEMENT PLANS.

DOWEL DETAIL:

r				ı
(U)	1.			
DOWEL SIZE	HOLE DIAMETER	EMBEDMENT LENGTH	MIN LAP LENGTH	2
4	⁵ ⁄8″	8″	1'-9"	2.
5	³ /4″	9″	2'-2"	
6	7⁄8″	11″	2'-7"	3.
8	1 ¹ /8″	1'-4"	4'-6"	



LIMITS OF REPAIRS PROVIDED IN THESE PLANS ARE BASED ON PREVIOUS NBIS ELEMENT INSPECTIONS AND LIMITED FIELD WORK. THE 2. DUE TO TIME SINCE INSPECTION. DEFICIENCIES MAY HAVE DETERIORATED OR INCREASED IN NUMBER. NOTIFY THE ENGINEER OF

1. THE CONTRACTOR SHALL SUBMIT A POLLUTION CONTROL PLAN TO THE ENGINEER IN ACCORDANCE THE NCDOT STANDARD SPECIFICATIONS. 3. THE CONTRACTORS SHALL SUBMIT TO THE ENGINEER AN EROSION CONTROL PLAN AS REQUIRED BY THE NCDOT STANDARD SPECIFICATIONS

ANY REQUIRED DOWEL HOLES SHALL BE

ACCORDING TO THE DETAIL AND NCDOT

DRILLED INTO EXISTING CONCRETE

SPECIFICATIONS. NOTIFY THE ENGINEER OF ANY BR BARS OR BARS WHICH ARE DETERM TO HAVE A SECTION LOSS OF 25% GREATER.	OKEN INED				
INSTALL DOWELS IN ACCORDANCE	WITH				
NCDOT SPECIFICATIONS.	PROJEC	T NO.	15	BPR.1	6
		RUNS			
			VICN	CO	UNTY
	BRIDGE	NO		71	
	SHEET 1 OF	2			
ABOVE)	DEPA	state RTMENT	OF NORTH CAR OF TRAN RALEIGH	NSPORTA	TION
DocuSigned by: Sanuel Cullun 19C97095C75A467 5/10/2018 12:43:55 PM PSF L CULLUT		GENEF	RAL N	NOTES	
· · · · · · · · · · · · · · · · · · ·					
		REVIS			SHEET NO.
DOCUMENT NOT CONSIDERED FINAL UNLESS ALL	NO. ВҮ: 1	DATE:	NO. BY:	DATE:	S-2A TOTAL SHEETS
SIGNATURES COMPLETED	2		4		73

CONSTRUCTION OPERATIONS:

- 1. FOR WORK ADJACENT TO THE PUBLIC, THE CONTRACTOR IS RESPONSIBLE TO ADEQUATELY PROTECT THE TRAVELING PUBLIC. THIS INCLUDES, BUT IS NOT LIMITED TO FENCING OFF OPERATIONS, SIDEWALK CLOSURES, LANE CLOSURES, DEBRIS SHIELDS, ETC.
- 2. COORDINATE ANY FACILITY CLOSURES IN ACCORDANCE WITH THE TRAFFIC MANAGEMENT PLANS AND THE SPECIAL PROVISIONS.

WORK ON THE WATER:

- 1. CONTACT THE US COAST GUARD 30 DAYS PRIOR TO IN-WATER CONSTRUCTION ACTIVITIES. THE NAVIGABLE CHANNEL SHALL NOT BE BLOCKED DURING CONSTRUCTION. FOR U.S. COAST GUARD CONTACT INFORMATION. SEE SPECIAL PROVISION FOR "COORDINATION WITH THE U.S. COAST GUARD".
- 2. THE CONTRACTOR SHALL LIMIT SUBSTRUCTURE REPAIRS AND CONTAINMENT, TO HALF OF THE CHANNEL SPAN AT A TIME IN ORDER TO REDUCE THE IMPACTS TO BOATERS.
- 3. THE CONTRACTOR SHALL MONITOR VHF RADIO AND COMMUNICATE WITH MARINE TRAFFIC AS NECESSARY.CONTRACTOR SHALL MONITOR CHANNEL 16.
- 4. THE CONTRACTOR SHALL NOTIFY AND/OR COORDINATE WITH THE COAST GUARD WHENEVER THE CONTRACTOR PLANS TO BE IN THE WATER FOR ANY PERIOD OF TIME.
- 5. THE CONTRACTOR SHALL BE RESPONSIBLE FOR MAINTAINING AND ADJUSTING ALL NAVIGATIONAL LIGHTS AS NECESSARY THROUGHOUT THE LIFE OF THE PROJECT.

MARINE TRAFFIC:

+

+


MARINE TRAFFIC CONSTRUCTION SIGNS SHALL BE PLACED ON BOTH FACES OF EACH BRIDGE AT THE LOCATIONS WHERE WORK IS BEING PERFORMED. PLACEMENT OF THE SIGNS SHALL BE SUCH THAT THEY ARE CLEARLY VISIBLE TO THE APPROACHING MARINE TRAFFIC. BARGES LEFT IN WATER IN LOW-LIGHT CONDITIONS SHALL BE ILLUMINATED SO AS TO BE VISIBLE TO MARINE TRAFFIC.

LOCAL TRAFFIC AND PUBLIC USAGE:

- 1. FOR LANE CLOSURE TIMES AND RESTRICTIONS, SEE TRANSPORTATION MANAGEMENT PLAN.
- 2. ONLY CLOSE OR NARROW LANES UNDER THE BRIDGE AT AREAS WHERE WORK IS BEING PERFORMED. DO NOT CLOSE OR NARROW LANES IN AREAS UNDER THE BRIDGE IF NO WORK IS BEING PERFORMED.
- 3. ACCESS TO ALL PUBLIC FACILITIES SHALL REMAIN OPEN THROUGHOUT THE LIFE OF THE PROJECT. SUCH FACILITIES ARE INCLUDED BUT ARE NOT LIMITED TO: BOAT RAMPS, GAZEBOS, PARKING AREAS, RESTROOMS, ETC.


FINAL PAVEMENT MARKINGS AND MARKERS


- 1. FOR FINAL PAVEMENT MARKING PLANS, SEE TRANSPORTATION MANAGEMENT PLANS.
- 2. FOR FINAL PAVEMENT MARKINGS AND MARKERS, SEE STANDARD SPECIFICATIONS.
- 3. PLACE (PERMANENT) (4") THERMOPLASTIC MARKINGS ON FINAL ASPHALT SURFACES.
- 4. PLACE (PERMANENT) (4") COLD APPLIED PLASTIC MARKINGS ON FINAL CONCRETE SURFACES.
- 5. ANY UNANTICIPATED REMOVAL OF PAVEMENT MARKINGS AND MARKERS SHALL BE REPLACED IN KIND.



	CONSTRUCTION SEQUENCE									
	1		ELECTRICAL REPAIRS TO NAVIGATION	AL LIGHT SYSTEM						
ASE	2		DECK CONCRETE REPAIRS							
Н	3		BEARING REPLACEMENT							
PRESERVATION PHASE	4	PPC OVERLAY	SUPERSTRUCTURE CONCRETE REPAIRS	SUBSTRUCTURE CONCRETE REPAIRS	FENDER RETROFIT					
	5	ASPHALT R	OADWAY MILLING AND RESURFACING							
BRIDGE	6	EXPANSION	I JOINT REPLACEMENT/INSTALLATION	GALVANIC CATHODIC PROTECTION						

SIGN N		нвс	(атү 2	SIGN NO.	STAT	ION(S)				
PAN	NEL.	E	BORE	DER							
WIDTH	5′-0	" WIC)ТН	1″							
HEIGHT	3'-0	" RAD	II	2″							
LEGEND	Blac	k col	OR	Black							
COLOR	Yello	W									
SYMBC	L(S)	ANGL	-	Х	Y	WID	ΗT				
SIGN NO.	NO.OF POSTS	EDGE LAN CLEAR	IE I	COLL	JMN SIZE		ERAGE ENGTH				
I		ICLAN							F	BORDE	- F
											-'
									F	R=2″ H=1″	
									F	R=2″ H=1″	
								NO. OF	F	R=2″ H=1″	
COPY			0					NO. OF	F	R=2″ H=1″	
COPY		2	0	 V 4.6	E 4.1	R 4.4	H 4.7		F T LIGHT	R=2" H=1"	
		.2 4			_		_	E	F 1 LIGHT	R=2" H=1" fixtuf D	
SPACE	-		1.3	4.6	4.1	4.4	4.7	E 3.6	F 1 LIGHT	R=2" H=1" FIXTUF D 3.4	
SPACE Copy	-		1. 3 В	4.6 R	4.1 I	4.4 D	4.7 G	E 3.6 E	F T LIGHT A 4.7	<pre>2" H=1" FIXTUF D 3.4 L</pre>	
SPACE COPY SPACE	18.	.5 4	1.3 B 1.4	4.6 R 4.4	4.1 I 2.2	4.4 D 4.4	4.7 G 4.6	E 3.6 E 3.1	F 1 4.7 18.5	R=2" H=1" FIXTUF D 3.4 L 23	
SPACE COPY SPACE COPY	18.	.5 4	1.3 В 1.4 С	4.6 R 4.4 0	4.1 I 2.2 N	4.4 D 4.4 S	4.7 C 4.6 T	E 3.6 E 3.1 R	F T 4.7 18.5 U	R=2" H=1" FIXTUF D 3.4 L 23 C	
SPACE COPY SPACE COPY SPACE	18. 5.8	.5 4	1.3 В 1.4 С	4.6 R 4.4 0	4.1 I 2.2 N	4.4 D 4.4 S	4.7 C 4.6 T	E 3.6 E 3.1 R	F T 4.7 18.5 U	R=2" H=1" FIXTUF D 3.4 L 23 C	
SPACE COPY SPACE COPY SPACE	18. 5.8	.5 4	1.3 В 1.4 С	4.6 R 4.4 0	4.1 I 2.2 N	4.4 D 4.4 S	4.7 C 4.6 T	E 3.6 E 3.1 R	F T 4.7 18.5 U	R=2" H=1" FIXTUF D 3.4 L 23 C	
SPACE COPY SPACE COPY SPACE SPACE	18, 5.{	.5 4	1.3 В 1.4 С	4.6 R 4.4 0	4.1 I 2.2 N	4.4 D 4.4 S	4.7 C 4.6 T	E 3.6 E 3.1 R	F T 4.7 18.5 U	R=2" H=1" FIXTUF D 3.4 L 23 C	
SPACE COPY SPACE COPY SPACE COPY	18, 5.{	.5 4	1.3 В 1.4 С	4.6 R 4.4 0	4.1 I 2.2 N	4.4 D 4.4 S	4.7 C 4.6 T	E 3.6 E 3.1 R	F T 4.7 18.5 U	R=2" H=1" FIXTUF D 3.4 L 23 C	





5/10/2018 G:\4201720.03-Brunswick-71\Structures\401_030_15BPR.16_SMU_GD1_S-3_090071.dgn

+


+

User:jduke

STATION	BENT #	STATION	BENT #	STATION	BENT #	STATION
13+78.04	BENT 10	17+82.00	BENT 15	22+52.00	BENT 20	26+13.50
14+53.55	BENT 11	18+82.58	BENT 16	23+35.00	BENT 21	26+99.50
15+36.88	BENT 12	19+99.83	BENT 17	24+15.50	BENT 22	27+49.52
16+20.22	BENT 13	20+86.00	BENT 18	25+01.50	END BENT 2	28+00.00
17+01.11	BENT 14	21+69.00	BENT 19	25+57 . 50		

	HYDRAULI DESIGN HIGH (MEAN HIGH TI FREQUENCY OF (HURRICANE BA FLOOD ELEVAT	WATER ELEN IDE) FLOOD: ACKWATER)		INITI 2.4 F 100 14.8	YR.	SIGN:
- 4.46 44.3″RT. , 945′ FT/FT	NOTES: CURVE DATA B STATIONING, S SET AND CURR	PAN AND B	ENT NUMBI	ERS BASEI	D ON PLAI	 N
- END BRIDGE						
1 PF 2 SU 3 SU 4 E2 5 BF 6 G/ 7 G/ 8 FF 9 AF	PE LEGEND: PC OVERLAY (TY JPERSTRUCTURE JBSTRUCTURE CO KPANSION JOIN EARING REPLACE ALVANIC CATHON ALVANIC CATHON ENDER SYSTEM IN PPROACH ROADW REPAIRS TYPIC	(P) CONCRETE RE ONCRETE RE T REPLACEN EMENT DIC PROTEC DIC PROTEC REHABILITA AY MILLIN	EPAIRS (TY MENT/INST CTION - M CTION - B ATION G AND RES	YP) ALLATION ETALIZIN ULK ANOD SURFACING	NG PE	
		PROJEC BF BRIDGE	RUNSW	/ICK		6 DUNTY
DocuSigned by: Samel Cullen 19C97095C75A467	NOP TH CARO/ NOP ESS/ON SEAL 043571 NG INE ^E UCL L CULIN		state RTMENT	RALEIGH	NSPORTA	
FINAL L	OT CONSIDERED INLESS ALL S COMPLETED	NO. ВҮ: 1 2		IONS NO. вү: З Д	DATE:	SHEET NO. S-3 TOTAL SHEETS 73

+



	RALEIGH, NC 27609 (919) 882-7839			
DRAWN BY :	DIEGO A. AGUIRRE	DATE	:	03-2018
CHECKED BY :	JACOB H. DUKE	DATE	:	03-2018
DESIGN ENGINEER (OF RECORD : SAMUEL L.CULLUM	DATE	:	03-2018

AS-BUILT REPAIR QUA	ANTITY	TABLE
TOP OF DECK REF	PAIRS	
WEST APPROACH	SLAB	
	ESTIMATE	ACTUAL
SCARIFYING BRIDGE DECK	29 SY	
CLASS II SURFACE PREPARATION	0.2 SY *	
CONCRETE DECK REPAIR FOR PPC OVERLAY	0.2 SY *	
PPC MATERIALS	1.1 CY	
PLACING & FINISHING PPC OVERLAY	29 SY	
GROOVING BRIDGE FLOORS	222 SF	
EAST APPROACH	SLAB	
	ESTIMATE	ACTUAL
SCARIFYING BRIDGE DECK	29 SY	
CLASS II SURFACE PREPARATION	0.2 SY *	
CONCRETE DECK REPAIR FOR PPC OVERLAY	0.2 SY *	
PPC MATERIALS	1.1 CY	
PLACING & FINISHING PPC OVERLAY	29 SY	
GROOVING BRIDGE FLOORS	222 SF	

NOTES:

Samuel L C

5/9/2018 2:14

- 19C97095C75A467

SEAL

043571

REPAIR LOCATIONS AND ESTIMATED QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE AS-BUILT REPAIR QUANTITY TABLE.

CONCRETE COVER FOR TOP BARS IN THE DECK SLAB IS $2\frac{1}{2}$ " PER THE EXISTING BRIDGE PLANS. ACTUAL CONCRETE COVER SHALL BE DETERMINED BY THE CONTRACTOR AND PRESENTED TO THE ENGINEER PRIOR TO BEGINNING SCARIFICATION.

CURRENT AVERAGE COVER IS EXPECTED TO BE FROM $1\frac{1}{2}$ TO $2\frac{1}{2}$ BASED ON VISUAL INSPECTION.

* MINOR QUANTITIES OF CLASS II AREAS ARE ANTICIPATED, PARTICULARLY NEAR JOINTS. HOWEVER, DUE TO THEIR SMALL SIZE, THE CLASS II LOCATIONS HAVE NOT BEEN DELINEATED ON THESE PLANS. THE CLASS II QUANTITIES INDICATED ARE ANTICIPATED TO BE SUFFICIENT FOR THE ACTUAL QUANTITIES ENCOUNTERED.

GROOVING BRIDGE FLOORS QUANITITY BASED ON WIDTHS OF TRAVEL LANES PLUS 6" ON EACH SIDE.

COORDINATE THIS SHEET WITH S-28 FOR THE PPC OVERLAY.

FOR SECTIONS A-A, B-B, AND C-C SEE SHEET S-29.


FOR SECTION D-D AND DETAILS OF JOINT AT BARRIER SEE SHEET S-30.


PROJECT NO	15BPR.16
BRUNSW	ICK COUNTY

71 BRIDGE NO.____

PLAN OF S	SPANS
-----------	-------

		REVISIONS				SHEET NO.	
DOCUMENT NOT CONSIDERED	N0.	BY:	DATE:	NO.	BY:	DATE:	S-4
FINAL UNLESS ALL	1			3			TOTAL SHEETS
SIGNATURES COMPLETED	2			4			73





DESIGN ENGINEER OF RECORD : SAMUEL L.CULLUM DATE : 03-2018

PLAN

AS-BUILT REPAIR QUA	ANTITY	TABLE			
TOP OF DECK REPAIRS					
SPAN 1					
	ESTIMATE	ACTUAL			
SCARIFYING BRIDGE DECK	254 SY				
CLASS II SURFACE PREPARATION	0.2 SY *				
CONCRETE DECK REPAIR FOR PPC OVERLAY	0.2 SY *				
SHOTBLASTING BRIDGE DECK	254 SY				
PPC MATERIALS	7.3 CY				
PLACING & FINISHING PPC OVERLAY	254 SY				
GROOVING BRIDGE FLOORS	2043 SF				

NOTES:

Samuel L Co

5/9/2018 2:14

- 19C97095C75A467

SEAL

043571

REPAIR LOCATIONS AND ESTIMATED QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE AS-BUILT REPAIR QUANTITY TABLE.

CONCRETE COVER FOR TOP BARS IN THE DECK SLAB IS 21/2" PER THE EXISTING BRIDGE PLANS. ACTUAL CONCRETE COVER SHALL BE DETERMINED BY THE CONTRACTOR AND PRESENTED TO THE ENGINEER PRIOR TO BEGINNING SCARIFICATION.

CURRENT AVERAGE COVER IS EXPECTED TO BE FROM $1\frac{1}{2}$ " TO $2\frac{1}{2}$ " BASED ON VISUAL INSPECTION.

* MINOR QUANTITIES OF CLASS II AREAS ARE ANTICIPATED, PARTICULARLY NEAR JOINTS. HOWEVER, DUE TO THEIR SMALL SIZE, THE CLASS II LOCATIONS HAVE NOT BEEN DELINEATED ON THESE PLANS. THE CLASS II QUANTITIES INDICATED ARE ANTICIPATED TO BE SUFFICIENT FOR THE ACTUAL QUANTITIES ENCOUNTERED.

GROOVING BRIDGE FLOORS QUANITITY BASED ON WIDTHS OF TRAVEL LANES PLUS 6"ON EACH SIDE.

COORDINATE THIS SHEET WITH S-28 FOR THE PPC OVERLAY.

FOR SECTIONS A-A, B-B, AND C-C SEE SHEET S-29.

FOR SECTION D-D AND DETAILS OF JOINT AT BARRIER SEE SHEET S-30.


PROJECT NO.	15BPR.16
BRUNSW	ICK COUNTY


BRIDGE NO.

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH

PL	AN	OF	SPAN
	SF	PAN	1

			REV	ISION	S		SHEET NO.
DOCUMENT NOT CONSIDERED	N0.	BY:	DATE:	NO.	BY:	DATE:	S-5
FINAL UNLESS ALL	1			3			TOTAL SHEETS
SIGNATURES COMPLETED	2			4			73





DESIGN ENGINEER OF RECORD : SAMUEL L.CULLUM DATE : 03-2018

PLAN

AS-BUILT REPAIR QUANTITY TABLE TOP OF DECK REPAIRS SPAN 2 ESTIMATE ACTUAL 252 SY SCARIFYING BRIDGE DECK CLASS II SURFACE PREPARATION 0.2 SY * CONCRETE DECK REPAIR FOR PPC OVERLAY 0.2 SY * SHOTBLASTING BRIDGE DECK 252 SY PPC MATERIALS 7.2 CY PLACING & FINISHING PPC OVERLAY 252 SY 2030 SF GROOVING BRIDGE FLOORS

NOTES:

Samuel L. C.

5/9/2018 2:14

- 19C97095C75A467

SEAL

043571

REPAIR LOCATIONS AND ESTIMATED QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE AS-BUILT REPAIR QUANTITY TABLE.

CONCRETE COVER FOR TOP BARS IN THE DECK SLAB IS 21/2" PER THE EXISTING BRIDGE PLANS. ACTUAL CONCRETE COVER SHALL BE DETERMINED BY THE CONTRACTOR AND PRESENTED TO THE ENGINEER PRIOR TO BEGINNING SCARIFICATION.

CURRENT AVERAGE COVER IS EXPECTED TO BE FROM $1\frac{1}{2}$ "TO $2\frac{1}{2}$ "BASED ON VISUAL INSPECTION.

* MINOR QUANTITIES OF CLASS II AREAS ARE ANTICIPATED, PARTICULARLY NEAR JOINTS. HOWEVER, DUE TO THEIR SMALL SIZE, THE CLASS II LOCATIONS HAVE NOT BEEN DELINEATED ON THESE PLANS. THE CLASS II QUANTITIES INDICATED ARE ANTICIPATED TO BE SUFFICIENT FOR THE ACTUAL QUANTITIES ENCOUNTERED.

GROOVING BRIDGE FLOORS QUANITITY BASED ON WIDTHS OF TRAVEL LANES PLUS 6"ON EACH SIDE.

COORDINATE THIS SHEET WITH S-28 FOR THE PPC OVERLAY.

FOR SECTIONS A-A, B-B, AND C-C SEE SHEET S-29.

FOR SECTION D-D AND DETAILS OF JOINT AT BARRIER SEE SHEET S-30.


PROJECT NO	15BPR.16
BRUNSW	ICK COUNTY


BRIDGE NO.

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH

PL	AN	OF	SPAN
	SF	PAN	2

		REVISIONS					SHEET NO.
DOCUMENT NOT CONSIDERED	NO.	BY:	DATE:	NO.	BY:	DATE:	S-6
FINAL UNLESS ALL	1			3			TOTAL SHEETS
SIGNATURES COMPLETED	2			4			73





DESIGN ENGINEER OF RECORD : SAMUEL L.CULLUM DATE : 03-2018 5/9/2018 G:\4201720.03-Brunswick-71\Structures\401_050_15BPR.16_SMU_DSR3_S-7_090071.dgn User:jduke

PLAN

AS-BUILT REPAIR QUANTITY TABLE

TOP OF DECK REPAIRS

SPAN 3

JI AN J		
	ESTIMATE	ACTUAL
SCARIFYING BRIDGE DECK	252 SY	
CLASS II SURFACE PREPARATION	0.2 SY *	
CONCRETE DECK REPAIR FOR PPC OVERLAY	0.2 SY *	
SHOTBLASTING BRIDGE DECK	252 SY	
PPC MATERIALS	7.2 CY	
PLACING & FINISHING PPC OVERLAY	252 SY	
GROOVING BRIDGE FLOORS	2030 SF	

NOTES:

Samuel L. C.

5/9/2018 2:14

- 19C97095C75A467

SEAL

043571

REPAIR LOCATIONS AND ESTIMATED QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE AS-BUILT REPAIR QUANTITY TABLE.

CONCRETE COVER FOR TOP BARS IN THE DECK SLAB IS $2\frac{1}{2}$ " PER THE EXISTING BRIDGE PLANS. ACTUAL CONCRETE COVER SHALL BE DETERMINED BY THE CONTRACTOR AND PRESENTED TO THE ENGINEER PRIOR TO BEGINNING SCARIFICATION.

CURRENT AVERAGE COVER IS EXPECTED TO BE FROM $1\frac{1}{2}$ " TO $2\frac{1}{2}$ " BASED ON VISUAL INSPECTION.

* MINOR QUANTITIES OF CLASS II AREAS ARE ANTICIPATED, PARTICULARLY NEAR JOINTS. HOWEVER, DUE TO THEIR SMALL SIZE, THE CLASS II LOCATIONS HAVE NOT BEEN DELINEATED ON THESE PLANS. THE CLASS II QUANTITIES INDICATED ARE ANTICIPATED TO BE SUFFICIENT FOR THE ACTUAL QUANTITIES ENCOUNTERED.

GROOVING BRIDGE FLOORS QUANITITY BASED ON WIDTHS OF TRAVEL LANES PLUS 6" ON EACH SIDE.

COORDINATE THIS SHEET WITH S-28 FOR THE PPC OVERLAY.

FOR SECTIONS A-A, B-B, AND C-C SEE SHEET S-29.

FOR SECTION D-D AND DETAILS OF JOINT AT BARRIER SEE SHEET S-30.


PROJECT NO	15BPR.16
BRUNSW	ICK COUNTY


BRIDGE NO._

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH

PL	AN	OF	SPAN
	SF	PAN	3

			REVI	ISION	IS		SHEET NO.
DOCUMENT NOT CONSIDERED	N0.	BY:	DATE:	NO.	BY:	DATE:	S-7
FINAL UNLESS ALL	1			3			TOTAL SHEETS
SIGNATURES COMPLETED	2			4			73





DESIGN ENGINEER OF RECORD : SAMUEL L.CULLUM DATE : 03-2018

+

PLAN

AS-BUILT REPAIR QUANTITY TABLE

TOP OF DECK REPAIRS

SPAN 4

JI AN H		
	ESTIMATE	ACTUAL
SCARIFYING BRIDGE DECK	252 SY	
CLASS II SURFACE PREPARATION	0.2 SY *	
CONCRETE DECK REPAIR FOR PPC OVERLAY	0.2 SY *	
SHOTBLASTING BRIDGE DECK	252 SY	
PPC MATERIALS	7.2 CY	
PLACING & FINISHING PPC OVERLAY	252 SY	
GROOVING BRIDGE FLOORS	2030 SF	

NOTES:

Samuel L. Co

- 19C97095C75A467

5/9/2018 2:14

SEAL

043571

REPAIR LOCATIONS AND ESTIMATED QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE AS-BUILT REPAIR QUANTITY TABLE.

CONCRETE COVER FOR TOP BARS IN THE DECK SLAB IS $2\frac{1}{2}$ " PER THE EXISTING BRIDGE PLANS. ACTUAL CONCRETE COVER SHALL BE DETERMINED BY THE CONTRACTOR AND PRESENTED TO THE ENGINEER PRIOR TO BEGINNING SCARIFICATION.

CURRENT AVERAGE COVER IS EXPECTED TO BE FROM $1\frac{1}{2}$ " TO $2\frac{1}{2}$ " BASED ON VISUAL INSPECTION.

* MINOR QUANTITIES OF CLASS II AREAS ARE ANTICIPATED, PARTICULARLY NEAR JOINTS. HOWEVER, DUE TO THEIR SMALL SIZE, THE CLASS II LOCATIONS HAVE NOT BEEN DELINEATED ON THESE PLANS. THE CLASS II QUANTITIES INDICATED ARE ANTICIPATED TO BE SUFFICIENT FOR THE ACTUAL QUANTITIES ENCOUNTERED.

GROOVING BRIDGE FLOORS QUANITITY BASED ON WIDTHS OF TRAVEL LANES PLUS 6" ON EACH SIDE.

COORDINATE THIS SHEET WITH S-28 FOR THE PPC OVERLAY.

FOR SECTIONS A-A, B-B, AND C-C SEE SHEET S-29.

FOR SECTION D-D AND DETAILS OF JOINT AT BARRIER SEE SHEET S-30.

PROJECT	NO	<u>15BPR.16</u>
BRU	NSW	ICK COUNTY


BRIDGE NO.____


STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH

71

PLAN OF SPAN SPAN 4

			REVI	SION	IS		SHEET NO.
DOCUMENT NOT CONSIDERED	NO.	BY:	DATE:	NO.	BY:	DATE:	S-8
FINAL UNLESS ALL	1			3			TOTAL SHEETS
SIGNATURES COMPLETED	2			4			73





DESIGN ENGINEER OF RECORD : <u>SAMUEL L.CULLUM</u> DATE : <u>03-2018</u> 5/9/2018 G:\4201720.03-Brunswick-71\Structures\401_060_15BPR.16_SMU_DSR5_S-9_090071.dgn User:jduke PLAN

AS-BUILT REPAIR QUANTITY TABLE

TOP OF DECK REPAIRS

SPAN 5

JI AN J		
	ESTIMATE	ACTUAL
SCARIFYING BRIDGE DECK	252 SY	
CLASS II SURFACE PREPARATION	0.2 SY *	
CONCRETE DECK REPAIR FOR PPC OVERLAY	0.2 SY *	
SHOTBLASTING BRIDGE DECK	252 SY	
PPC MATERIALS	7.2 CY	
PLACING & FINISHING PPC OVERLAY	252 SY	
GROOVING BRIDGE FLOORS	2030 SF	

NOTES:

Samuel L. Co

5/9/2018 2:14

- 19C97095C75A467

SEAL

043571

REPAIR LOCATIONS AND ESTIMATED QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE AS-BUILT REPAIR QUANTITY TABLE.

CONCRETE COVER FOR TOP BARS IN THE DECK SLAB IS 21/2" PER THE EXISTING BRIDGE PLANS. ACTUAL CONCRETE COVER SHALL BE DETERMINED BY THE CONTRACTOR AND PRESENTED TO THE ENGINEER PRIOR TO BEGINNING SCARIFICATION.

CURRENT AVERAGE COVER IS EXPECTED TO BE FROM $1\frac{1}{2}$ "TO $2\frac{1}{2}$ "BASED ON VISUAL INSPECTION.

* MINOR QUANTITIES OF CLASS II AREAS ARE ANTICIPATED, PARTICULARLY NEAR JOINTS. HOWEVER, DUE TO THEIR SMALL SIZE, THE CLASS II LOCATIONS HAVE NOT BEEN DELINEATED ON THESE PLANS. THE CLASS II QUANTITIES INDICATED ARE ANTICIPATED TO BE SUFFICIENT FOR THE ACTUAL QUANTITIES ENCOUNTERED.

GROOVING BRIDGE FLOORS QUANITITY BASED ON WIDTHS OF TRAVEL LANES PLUS 6"ON EACH SIDE.

COORDINATE THIS SHEET WITH S-28 FOR THE PPC OVERLAY.

FOR SECTIONS A-A, B-B, AND C-C SEE SHEET S-29.

FOR SECTION D-D AND DETAILS OF JOINT AT BARRIER SEE SHEET S-30.


PROJECT NO	15BPR.16
BRUNSWI	

BRIDGE NO.

STATE OF NORTH CAROLINA
DEPARTMENT OF TRANSPORTATION
RALEIGH

ΡL	AN	OF	SPAN
	SF	PAN	5

			REV	ISION	S		SHEET NO.
DOCUMENT NOT CONSIDERED	N0.	BY:	DATE:	NO.	BY:	DATE:	S-9
FINAL UNLESS ALL	1			3			TOTAL SHEETS
SIGNATURES COMPLETED	2			4			73





CHECKED BY : _____ JACOB H. DUKE ___ DATE : _____03-2018___ DESIGN ENGINEER OF RECORD : SAMUEL L.CULLUM DATE : 03-2018

5/9/2018 G:\4201720.03-Brunswick-71\Structures\401_065_15BPR.16_SMU_DSR6_S-10_090071.dgn User:jduke

PLAN

AS-BUILT REPAIR QUANTITY TABLE

TOP OF DECK REPAIRS

SPAN 6

JI AN O		
	ESTIMATE	ACTUAL
SCARIFYING BRIDGE DECK	252 SY	
CLASS II SURFACE PREPARATION	0.2 SY *	
CONCRETE DECK REPAIR FOR PPC OVERLAY	0.2 SY *	
SHOTBLASTING BRIDGE DECK	252 SY	
PPC MATERIALS	7.2 CY	
PLACING & FINISHING PPC OVERLAY	252 SY	
GROOVING BRIDGE FLOORS	2030 SF	

NOTES:

Samuel L. C.

5/9/2018 2:14

- 19C97095C75A467

SEAL

043571

REPAIR LOCATIONS AND ESTIMATED QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE AS-BUILT REPAIR QUANTITY TABLE.

CONCRETE COVER FOR TOP BARS IN THE DECK SLAB IS $2\frac{1}{2}$ " PER THE EXISTING BRIDGE PLANS. ACTUAL CONCRETE COVER SHALL BE DETERMINED BY THE CONTRACTOR AND PRESENTED TO THE ENGINEER PRIOR TO BEGINNING SCARIFICATION.

CURRENT AVERAGE COVER IS EXPECTED TO BE FROM $1\frac{1}{2}$ " TO $2\frac{1}{2}$ " BASED ON VISUAL INSPECTION.

* MINOR QUANTITIES OF CLASS II AREAS ARE ANTICIPATED, PARTICULARLY NEAR JOINTS. HOWEVER, DUE TO THEIR SMALL SIZE, THE CLASS II LOCATIONS HAVE NOT BEEN DELINEATED ON THESE PLANS. THE CLASS II QUANTITIES INDICATED ARE ANTICIPATED TO BE SUFFICIENT FOR THE ACTUAL QUANTITIES ENCOUNTERED.

GROOVING BRIDGE FLOORS QUANITITY BASED ON WIDTHS OF TRAVEL LANES PLUS 6" ON EACH SIDE.

COORDINATE THIS SHEET WITH S-28 FOR THE PPC OVERLAY.

FOR SECTIONS A-A, B-B, AND C-C SEE SHEET S-29.

FOR SECTION D-D AND DETAILS OF JOINT AT BARRIER SEE SHEET S-30.


PROJECT NO	15BPR.16
BRUNSW	


BRIDGE NO.___

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH

PL	AN	OF	SPAN
	SF	PAN	6

		REVI	SIO	۱S		SHEET NO.
NO.	BY:	DATE:	NO.	BY:	DATE:	S-10
1			3			TOTAL SHEETS
2			4			73
	1	1	NO. BY: DATE:	NO. BY: DATE: NO.	1 3	NO. BY: DATE: NO. BY: DATE: 1 3





DESIGN ENGINEER OF RECORD : <u>SAMUEL L.CULLUM</u> DATE : <u>03-2018</u> 5/9/2018 G:\4201720.03-Brunswick-71\Structures\401_070_15BPR.16_SMU_DSR7_S-11_090071.dgn User:jduke PLAN

AS-BUILT REPAIR QUANTITY TABLE

TOP OF DECK REPAIRS

SPAN 7

JI AN I		
	ESTIMATE	ACTUAL
SCARIFYING BRIDGE DECK	278 SY	
CLASS II SURFACE PREPARATION	0.2 SY *	
CONCRETE DECK REPAIR FOR PPC OVERLAY	0.2 SY *	
SHOTBLASTING BRIDGE DECK	278 SY	
PPC MATERIALS	8.0 CY	
PLACING & FINISHING PPC OVERLAY	278 SY	
GROOVING BRIDGE FLOORS	2241 SF	

NOTES:

Samuel L. C.

5/9/2018 2:14

- 19C97095C75A467

SEAL

043571

REPAIR LOCATIONS AND ESTIMATED QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE AS-BUILT REPAIR QUANTITY TABLE.

CONCRETE COVER FOR TOP BARS IN THE DECK SLAB IS 21/2" PER THE EXISTING BRIDGE PLANS. ACTUAL CONCRETE COVER SHALL BE DETERMINED BY THE CONTRACTOR AND PRESENTED TO THE ENGINEER PRIOR TO BEGINNING SCARIFICATION.

CURRENT AVERAGE COVER IS EXPECTED TO BE FROM $1\frac{1}{2}$ "TO $2\frac{1}{2}$ "BASED ON VISUAL INSPECTION.

* MINOR QUANTITIES OF CLASS II AREAS ARE ANTICIPATED, PARTICULARLY NEAR JOINTS. HOWEVER, DUE TO THEIR SMALL SIZE, THE CLASS II LOCATIONS HAVE NOT BEEN DELINEATED ON THESE PLANS. THE CLASS II QUANTITIES INDICATED ARE ANTICIPATED TO BE SUFFICIENT FOR THE ACTUAL QUANTITIES ENCOUNTERED.

GROOVING BRIDGE FLOORS QUANITITY BASED ON WIDTHS OF TRAVEL LANES PLUS 6"ON EACH SIDE.

COORDINATE THIS SHEET WITH S-28 FOR THE PPC OVERLAY.

FOR SECTIONS A-A, B-B, AND C-C SEE SHEET S-29.

FOR SECTION D-D AND DETAILS OF JOINT AT BARRIER SEE SHEET S-30.


PROJECT NO	15BPR.16
BRUNSWI	


BRIDGE NO.____

STATE OF NORTH CAROLINA
DEPARTMENT OF TRANSPORTATION
RALEIGH

PL	AN	OF	SPAN
	SF	PAN	7

			REV	ISION	S		SHEET NO.
DOCUMENT NOT CONSIDERED	NO.	BY:	DATE:	NO.	BY:	DATE:	S-11
FINAL UNLESS ALL	1			3			TOTAL SHEETS
SIGNATURES COMPLETED	2			4			73





DESIGN ENGINEER OF RECORD : SAMUEL L.CULLUM DATE : 03-2018

5/9/2018 G:\4201720.03-Brunswick-71\Structures\401_075_15BPR.16_SMU_DSR8_S-12_090071.dgn User:jduke PLAN

AS-BUILT REPAIR QUANTITY TABLE

TOP OF DECK REPAIRS

SPAN 8

JI AN O		
	ESTIMATE	ACTUAL
SCARIFYING BRIDGE DECK	278 SY	
CLASS II SURFACE PREPARATION	0.2 SY *	
CONCRETE DECK REPAIR FOR PPC OVERLAY	0.2 SY *	
SHOTBLASTING BRIDGE DECK	278 SY	
PPC MATERIALS	8.0 CY	
PLACING & FINISHING PPC OVERLAY	278 SY	
GROOVING BRIDGE FLOORS	2241 SF	

NOTES:

Samuel L. C.

5/9/2018 2:14

- 19C97095C75A467

SEAL

043571

REPAIR LOCATIONS AND ESTIMATED QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE AS-BUILT REPAIR QUANTITY TABLE.

CONCRETE COVER FOR TOP BARS IN THE DECK SLAB IS 21/2" PER THE EXISTING BRIDGE PLANS. ACTUAL CONCRETE COVER SHALL BE DETERMINED BY THE CONTRACTOR AND PRESENTED TO THE ENGINEER PRIOR TO BEGINNING SCARIFICATION.

CURRENT AVERAGE COVER IS EXPECTED TO BE FROM $1\frac{1}{2}$ "TO $2\frac{1}{2}$ "BASED ON VISUAL INSPECTION.

* MINOR QUANTITIES OF CLASS II AREAS ARE ANTICIPATED, PARTICULARLY NEAR JOINTS. HOWEVER, DUE TO THEIR SMALL SIZE, THE CLASS II LOCATIONS HAVE NOT BEEN DELINEATED ON THESE PLANS. THE CLASS II QUANTITIES INDICATED ARE ANTICIPATED TO BE SUFFICIENT FOR THE ACTUAL QUANTITIES ENCOUNTERED.

GROOVING BRIDGE FLOORS QUANITITY BASED ON WIDTHS OF TRAVEL LANES PLUS 6"ON EACH SIDE.

COORDINATE THIS SHEET WITH S-28 FOR THE PPC OVERLAY.

FOR SECTIONS A-A, B-B, AND C-C SEE SHEET S-29.

FOR SECTION D-D AND DETAILS OF JOINT AT BARRIER SEE SHEET S-30.


PROJECT NO	15BPR.16
BRUNSWI	


BRIDGE NO.

STATE OF NORTH CAROLINA
DEPARTMENT OF TRANSPORTATION
RALEIGH

PL	AN	OF	SPAN
	SF	PAN	8

			REV	ISION	S		SHEET NO.
DOCUMENT NOT CONSIDERED	NO.	BY:	DATE:	NO.	BY:	DATE:	S-12
FINAL UNLESS ALL	1			3			TOTAL SHEETS
SIGNATURES COMPLETED	2			4			73





DESIGN ENGINEER OF RECORD : SAMUEL L.CULLUM DATE : 03-2018 5/9/2018 G:\4201720.03-Brunswick-71\Structures\401_080_15BPR.16_SMU_DSR9_S-13_090071.dgn User:jduke



PLAN

|--|

TOP OF DECK REPAIRS

SPAN 9

	ESTIMATE	ACTUAL
SCARIFYING BRIDGE DECK	270 SY	
CLASS II SURFACE PREPARATION	0.2 SY *	
CONCRETE DECK REPAIR FOR PPC OVERLAY	0.2 SY *	
SHOTBLASTING BRIDGE DECK	270 SY	
PPC MATERIALS	7.7 CY	
PLACING & FINISHING PPC OVERLAY	270 SY	
GROOVING BRIDGE FLOORS	2173 SF	

NOTES:

Samuel L. Co

5/9/2018 2:14

- 19C97095C75A467

SEAL

043571

REPAIR LOCATIONS AND ESTIMATED QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE AS-BUILT REPAIR QUANTITY TABLE.

CONCRETE COVER FOR TOP BARS IN THE DECK SLAB IS $2^{1}/_{2}$ " PER THE EXISTING BRIDGE PLANS. ACTUAL CONCRETE COVER SHALL BE DETERMINED BY THE CONTRACTOR AND PRESENTED TO THE ENGINEER PRIOR TO BEGINNING SCARIFICATION.

CURRENT AVERAGE COVER IS EXPECTED TO BE FROM $1\frac{1}{2}$ " TO $2\frac{1}{2}$ " BASED ON VISUAL INSPECTION.

* MINOR QUANTITIES OF CLASS II AREAS ARE ANTICIPATED, PARTICULARLY NEAR JOINTS. HOWEVER, DUE TO THEIR SMALL SIZE, THE CLASS II LOCATIONS HAVE NOT BEEN DELINEATED ON THESE PLANS. THE CLASS II QUANTITIES INDICATED ARE ANTICIPATED TO BE SUFFICIENT FOR THE ACTUAL QUANTITIES ENCOUNTERED.

GROOVING BRIDGE FLOORS QUANITITY BASED ON WIDTHS OF TRAVEL LANES PLUS 6" ON EACH SIDE.

COORDINATE THIS SHEET WITH S-28 FOR THE PPC OVERLAY.

FOR SECTIONS A-A, B-B, AND C-C SEE SHEET S-29.

FOR SECTION D-D AND DETAILS OF JOINT AT BARRIER SEE SHEET S-30.


PROJECT	NO	<u>15BPF</u>	<u>R.16</u>
BRUI	NSWI	СК	COUNTY


BRIDGE NO.____

71

PL	AN	OF	SPAN
	SF	PAN	9

			REV	[SION	S		SHEET NO.
DOCUMENT NOT CONSIDERED	N0.	BY:	DATE:	N0.	BY:	DATE:	S-13
FINAL UNLESS ALL	1			3			TOTAL SHEETS
SIGNATURES COMPLETED	2			4			73





DESIGN ENGINEER OF RECORD : SAMUEL L.CULLUM DATE : 03-2018 5/9/2018 G:\4201720.03-Brunswick-71\Structures\401_085_15BPR.16_SMU_DSR10_S-14_090071.dgn User:jduke

PLAN

AS-BUILT REPAIR QUANTITY TABLE

TOP OF DECK REPAIRS

SPAN 10

JI AN IO		
	ESTIMATE	ACTUAL
SCARIFYING BRIDGE DECK	270 SY	
CLASS II SURFACE PREPARATION	0.2 SY *	
CONCRETE DECK REPAIR FOR PPC OVERLAY	0.2 SY *	
SHOTBLASTING BRIDGE DECK	270 SY	
PPC MATERIALS	7.7 CY	
PLACING & FINISHING PPC OVERLAY	270 SY	
GROOVING BRIDGE FLOORS	2175 SF	

NOTES:

Samuel L. Cu

5/9/2018 2:14

- 19C97095C75A467

SEAL

043571

REPAIR LOCATIONS AND ESTIMATED QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE AS-BUILT REPAIR QUANTITY TABLE.

CONCRETE COVER FOR TOP BARS IN THE DECK SLAB IS $2\frac{1}{2}$ " PER THE EXISTING BRIDGE PLANS. ACTUAL CONCRETE COVER SHALL BE DETERMINED BY THE CONTRACTOR AND PRESENTED TO THE ENGINEER PRIOR TO BEGINNING SCARIFICATION.

CURRENT AVERAGE COVER IS EXPECTED TO BE FROM $1\frac{1}{2}$ " TO $2\frac{1}{2}$ " BASED ON VISUAL INSPECTION.

* MINOR QUANTITIES OF CLASS II AREAS ARE ANTICIPATED, PARTICULARLY NEAR JOINTS. HOWEVER, DUE TO THEIR SMALL SIZE, THE CLASS II LOCATIONS HAVE NOT BEEN DELINEATED ON THESE PLANS. THE CLASS II QUANTITIES INDICATED ARE ANTICIPATED TO BE SUFFICIENT FOR THE ACTUAL QUANTITIES ENCOUNTERED.

GROOVING BRIDGE FLOORS QUANITITY BASED ON WIDTHS OF TRAVEL LANES PLUS 6" ON EACH SIDE.

COORDINATE THIS SHEET WITH S-28 FOR THE PPC OVERLAY.

FOR SECTIONS A-A, B-B, AND C-C SEE SHEET S-29.

FOR SECTION D-D AND DETAILS OF JOINT AT BARRIER SEE SHEET S-30.


PROJECT NO	15BPR.16
BRUNSW	


BRIDGE NO.____

71

PLAN	ÛF	25	AN
SP	AN	10	

			REVI	SION	IS		SHEET NO.
DOCUMENT NOT CONSIDERED	N0.	BY:	DATE:	NO.	BY:	DATE:	S-14
FINAL UNLESS ALL	1			3			TOTAL SHEETS
SIGNATURES COMPLETED	2			4			73





DESIGN ENGINEER OF RECORD : SAMUEL L.CULLUM DATE : 03-2018 5/9/2018 G:\4201720.03-Brunswick-71\Structures\401_090_15BPR.16_SMU_DSR11_S-15_090071.dgn User:jduke

PLAN

AS-BUILT REPAIR QUANTITY TABLE

TOP OF DECK REPAIRS

SPAN 11

	ESTIMATE	ACTUAL
SCARIFYING BRIDGE DECK	336 SY	
CLASS II SURFACE PREPARATION	0.2 SY *	
CONCRETE DECK REPAIR FOR PPC OVERLAY	0.2 SY *	
SHOTBLASTING BRIDGE DECK	336 SY	
PPC MATERIALS	9.6 CY	
PLACING & FINISHING PPC OVERLAY	336 SY	
GROOVING BRIDGE FLOORS	2707 SF	

NOTES:

Samuel L. Co

- 19C97095C75A467

5/9/2018 2:14

SEAL

043571

REPAIR LOCATIONS AND ESTIMATED QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE AS-BUILT REPAIR QUANTITY TABLE.

CONCRETE COVER FOR TOP BARS IN THE DECK SLAB IS $2\frac{1}{2}$ " PER THE EXISTING BRIDGE PLANS. ACTUAL CONCRETE COVER SHALL BE DETERMINED BY THE CONTRACTOR AND PRESENTED TO THE ENGINEER PRIOR TO BEGINNING SCARIFICATION.

CURRENT AVERAGE COVER IS EXPECTED TO BE FROM $1\frac{1}{2}$ " TO $2\frac{1}{2}$ " BASED ON VISUAL INSPECTION.

* MINOR QUANTITIES OF CLASS II AREAS ARE ANTICIPATED, PARTICULARLY NEAR JOINTS. HOWEVER, DUE TO THEIR SMALL SIZE, THE CLASS II LOCATIONS HAVE NOT BEEN DELINEATED ON THESE PLANS. THE CLASS II QUANTITIES INDICATED ARE ANTICIPATED TO BE SUFFICIENT FOR THE ACTUAL QUANTITIES ENCOUNTERED.

GROOVING BRIDGE FLOORS QUANITITY BASED ON WIDTHS OF TRAVEL LANES PLUS 6" ON EACH SIDE.

COORDINATE THIS SHEET WITH S-28 FOR THE PPC OVERLAY.

FOR SECTIONS A-A, B-B, AND C-C SEE SHEET S-29.

FOR SECTION D-D AND DETAILS OF JOINT AT BARRIER SEE SHEET S-30.

PROJECT NO	15BPR.16
BRUNSWI	CK COUNTY


BRIDGE NO.____


STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH

71

PLAN OF SPAN SPAN 11

			REV	ISION	S		SHEET NO.
DOCUMENT NOT CONSIDERED	N0.	BY:	DATE:	NO.	BY:	DATE:	S-15
FINAL UNLESS ALL	1			3			TOTAL SHEETS
SIGNATURES COMPLETED	2			4			73





DESIGN ENGINEER OF RECORD : SAMUEL L.CULLUM DATE : 03-2018 5/9/2018 G:\4201720.03-Brunswick-71\Structures\401_095_15BPR.16_SMU_DSR12_S-16_090071.dgn User:jduke

PLAN

AS-BUILT REPAIR QUANTITY TABLE

TOP OF DECK REPAIRS

SPAN 12

	ESTIMATE	ACTUAL
SCARIFYING BRIDGE DECK	391 SY	
CLASS II SURFACE PREPARATION	0.2 SY *	
CONCRETE DECK REPAIR FOR PPC OVERLAY	0.2 SY *	
SHOTBLASTING BRIDGE DECK	391 SY	
PPC MATERIALS	11.1 CY	
PLACING & FINISHING PPC OVERLAY	391 SY	
GROOVING BRIDGE FLOORS	3157 SF	

NOTES:

Samuel L. Co

5/9/2018 2:14

- 19C97095C75A467

SEAL

043571

REPAIR LOCATIONS AND ESTIMATED QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE AS-BUILT REPAIR QUANTITY TABLE.

CONCRETE COVER FOR TOP BARS IN THE DECK SLAB IS $2\frac{1}{2}$ " PER THE EXISTING BRIDGE PLANS. ACTUAL CONCRETE COVER SHALL BE DETERMINED BY THE CONTRACTOR AND PRESENTED TO THE ENGINEER PRIOR TO BEGINNING SCARIFICATION.

CURRENT AVERAGE COVER IS EXPECTED TO BE FROM $1\frac{1}{2}$ " TO $2\frac{1}{2}$ " BASED ON VISUAL INSPECTION.

* MINOR QUANTITIES OF CLASS II AREAS ARE ANTICIPATED, PARTICULARLY NEAR JOINTS. HOWEVER, DUE TO THEIR SMALL SIZE, THE CLASS II LOCATIONS HAVE NOT BEEN DELINEATED ON THESE PLANS. THE CLASS II QUANTITIES INDICATED ARE ANTICIPATED TO BE SUFFICIENT FOR THE ACTUAL QUANTITIES ENCOUNTERED.

GROOVING BRIDGE FLOORS QUANITITY BASED ON WIDTHS OF TRAVEL LANES PLUS 6" ON EACH SIDE.

COORDINATE THIS SHEET WITH S-28 FOR THE PPC OVERLAY.

FOR SECTIONS A-A, B-B, AND C-C SEE SHEET S-29.

FOR SECTION D-D AND DETAILS OF JOINT AT BARRIER SEE SHEET S-30.

PROJECT N	o. 15BF	PR.16
BRUNS	SWICK	_ COUNTY


BRIDGE NO.____

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH

ΡL	AN	OF	SPAN
	SP	AN	12

	REVISIONS				SHEET NO.		
DOCUMENT NOT CONSIDERED	N0.	BY:	DATE:	NO.	BY:	DATE:	S-16
FINAL UNLESS ALL	1			3			TOTAL SHEETS
SIGNATURES COMPLETED	2			4			73

+



DRAWN BY :	DIEGO A. AGUIRRE	
CHECKED BY :	JACOB H. DUKE	DATE : <u>03-2018</u>
DESIGN ENGINEER	OF RECORD : SAMUEL L.CULLUN	<u>DATE : 03-2018</u>

AS-BUILT REPAIR QUANTITY TABLE

TOP OF DECK REPAIRS

SPAN 13

	ESTIMATE	ACTUAL
SCARIFYING BRIDGE DECK	287 SY	
CLASS II SURFACE PREPARATION	0.2 SY *	
CONCRETE DECK REPAIR FOR PPC OVERLAY	0.2 SY *	
SHOTBLASTING BRIDGE DECK	287 SY	
PPC MATERIALS	8.2 CY	
PLACING & FINISHING PPC OVERLAY	287 SY	
GROOVING BRIDGE FLOORS	2318 SF	

NOTES:

Samuel L. C.

5/9/2018 2:14

- 19C97095C75A467

SEAL

043571

REPAIR LOCATIONS AND ESTIMATED QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE AS-BUILT REPAIR QUANTITY TABLE.

CONCRETE COVER FOR TOP BARS IN THE DECK SLAB IS $2^{1}/_{2}$ " PER THE EXISTING BRIDGE PLANS. ACTUAL CONCRETE COVER SHALL BE DETERMINED BY THE CONTRACTOR AND PRESENTED TO THE ENGINEER PRIOR TO BEGINNING SCARIFICATION.

CURRENT AVERAGE COVER IS EXPECTED TO BE FROM $1\frac{1}{2}$ " TO $2\frac{1}{2}$ " BASED ON VISUAL INSPECTION.

* MINOR QUANTITIES OF CLASS II AREAS ARE ANTICIPATED, PARTICULARLY NEAR JOINTS. HOWEVER, DUE TO THEIR SMALL SIZE, THE CLASS II LOCATIONS HAVE NOT BEEN DELINEATED ON THESE PLANS. THE CLASS II QUANTITIES INDICATED ARE ANTICIPATED TO BE SUFFICIENT FOR THE ACTUAL QUANTITIES ENCOUNTERED.

GROOVING BRIDGE FLOORS QUANITITY BASED ON WIDTHS OF TRAVEL LANES PLUS 6" ON EACH SIDE.

COORDINATE THIS SHEET WITH S-28 FOR THE PPC OVERLAY.

FOR SECTIONS A-A, B-B, AND C-C SEE SHEET S-29.

FOR SECTION D-D AND DETAILS OF JOINT AT BARRIER SEE SHEET S-30.


PROJECT NO	15BPR.16
BRUNSW	


71

BRIDGE NO.____

ΡL	AN	OF	SPAN
	SP	AN	13

			REV]	ISION	IS		SHEET NO.
DOCUMENT NOT CONSIDERED	NO.	BY:	DATE:	NO.	BY:	DATE:	S-17
FINAL UNLESS ALL	1			3			TOTAL SHEETS
SIGNATURES COMPLETED	2			4			73





DESIGN ENGINEER OF RECORD : SAMUEL L.CULLUM DATE : 03-2018 5/9/2018 G:\4201720.03-Brunswick-71\Structures\401_105_15BPR.16_SMU_DSR14_S-18_090071.dgn

User:jduke

PLAN

AS-BUILT REPAIR QUANTITY TABLE

TOP OF DECK REPAIRS

SPAN 14

	т	K I	т.
JO		Ν	

	SPAN 14		
-		ESTIMATE	ACTUAL
	SCARIFYING BRIDGE DECK	277 SY	
	CLASS II SURFACE PREPARATION	0.2 SY *	
	CONCRETE DECK REPAIR FOR PPC OVERLAY	0.2 SY *	
	SHOTBLASTING BRIDGE DECK	277 SY	
	PPC MATERIALS	7.9 CY	
	PLACING & FINISHING PPC OVERLAY	277 SY	
	GROOVING BRIDGE FLOORS	2232 SF	

NOTES:

Samuel L. Co

5/9/2018 2:14

- 19C97095C75A467

SEAL

043571

REPAIR LOCATIONS AND ESTIMATED QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE AS-BUILT REPAIR QUANTITY TABLE.

CONCRETE COVER FOR TOP BARS IN THE DECK SLAB IS $2^{1}/_{2}$ " PER THE EXISTING BRIDGE PLANS. ACTUAL CONCRETE COVER SHALL BE DETERMINED BY THE CONTRACTOR AND PRESENTED TO THE ENGINEER PRIOR TO BEGINNING SCARIFICATION.

CURRENT AVERAGE COVER IS EXPECTED TO BE FROM $1\frac{1}{2}$ " TO $2\frac{1}{2}$ " BASED ON VISUAL INSPECTION.

* MINOR QUANTITIES OF CLASS II AREAS ARE ANTICIPATED, PARTICULARLY NEAR JOINTS. HOWEVER, DUE TO THEIR SMALL SIZE, THE CLASS II LOCATIONS HAVE NOT BEEN DELINEATED ON THESE PLANS. THE CLASS II QUANTITIES INDICATED ARE ANTICIPATED TO BE SUFFICIENT FOR THE ACTUAL QUANTITIES ENCOUNTERED.

GROOVING BRIDGE FLOORS QUANITITY BASED ON WIDTHS OF TRAVEL LANES PLUS 6" ON EACH SIDE.

COORDINATE THIS SHEET WITH S-28 FOR THE PPC OVERLAY.

FOR SECTIONS A-A, B-B, AND C-C SEE SHEET S-29.

FOR SECTION D-D AND DETAILS OF JOINT AT BARRIER SEE SHEET S-30.


PROJECT NO	15BPR.16
BRUNSW	ICK COUNTY


BRIDGE NO.____

71

PL	AN	OF	SPAN
	SP	AN	14

			REV	ISION	S		SHEET NO.
DOCUMENT NOT CONSIDERED	N0.	BY:	DATE:	NO.	BY:	DATE:	S-18
FINAL UNLESS ALL	1			3			TOTAL SHEETS
SIGNATURES COMPLETED	2			4			73





DESIGN ENGINEER OF RECORD : SAMUEL L.CULLUM DATE : 03-2018 5/9/2018 G:\4201720.03-Brunswick-71\Structures\401_110_15BPR.16_SMU_DSR15_S-19_090071.dgn

User:jduke

AS-BUILT REPAIR QUANTITY TABLE

TOP OF DECK REPAIRS

SPAN 15

	ESTIMATE	ACTUAL
SCARIFYING BRIDGE DECK	277 SY	
CLASS II SURFACE PREPARATION	0.2 SY *	
CONCRETE DECK REPAIR FOR PPC OVERLAY	0.2 SY *	
SHOTBLASTING BRIDGE DECK	277 SY	
PPC MATERIALS	7.9 CY	
PLACING & FINISHING PPC OVERLAY	277 SY	
GROOVING BRIDGE FLOORS	2232 SF	

NOTES:

Samuel L Co

5/9/2018 2:14

- 19C97095C75A467

SEAL

043571

REPAIR LOCATIONS AND ESTIMATED QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE AS-BUILT REPAIR QUANTITY TABLE.

CONCRETE COVER FOR TOP BARS IN THE DECK SLAB IS $2\frac{1}{2}$ " PER THE EXISTING BRIDGE PLANS. ACTUAL CONCRETE COVER SHALL BE DETERMINED BY THE CONTRACTOR AND PRESENTED TO THE ENGINEER PRIOR TO BEGINNING SCARIFICATION.

CURRENT AVERAGE COVER IS EXPECTED TO BE FROM $1\frac{1}{2}$ " TO $2\frac{1}{2}$ " BASED ON VISUAL INSPECTION.

* MINOR QUANTITIES OF CLASS II AREAS ARE ANTICIPATED, PARTICULARLY NEAR JOINTS. HOWEVER, DUE TO THEIR SMALL SIZE, THE CLASS II LOCATIONS HAVE NOT BEEN DELINEATED ON THESE PLANS. THE CLASS II QUANTITIES INDICATED ARE ANTICIPATED TO BE SUFFICIENT FOR THE ACTUAL QUANTITIES ENCOUNTERED.

GROOVING BRIDGE FLOORS QUANITITY BASED ON WIDTHS OF TRAVEL LANES PLUS 6" ON EACH SIDE.

COORDINATE THIS SHEET WITH S-28 FOR THE PPC OVERLAY.

FOR SECTIONS A-A, B-B, AND C-C SEE SHEET S-29.

FOR SECTION D-D AND DETAILS OF JOINT AT BARRIER SEE SHEET S-30.

PROJECT NO	15BPR.16
BRUNSW	ICK COUNTY


BRIDGE NO.____


STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION

PARIMENI	UF	IRANSPURIATION
	RAI	LEIGH

ΡL	AN	OF	SPAN
	SP	AN	15

			REV	ISION	S		SHEET NO.
DOCUMENT NOT CONSIDERED	NO.	BY:	DATE:	NO.	BY:	DATE:	S-19
FINAL UNLESS ALL	1			3			TOTAL SHEETS
SIGNATURES COMPLETED	2			4			73





DESIGN ENGINEER OF RECORD : SAMUEL L.CULLUM DATE : 03-2018 5/9/2018 G:\4201720.03-Brunswick-71\Structures\401_115_15BPR.16_SMU_DSR16_S-20_090071.dgn User:jduke

AS-BUILT REPAIR QUANTITY TABLE

TOP OF DECK REPAIRS

SPAN 16

	ESTIMATE	ACTUAL
SCARIFYING BRIDGE DECK	277 SY	
CLASS II SURFACE PREPARATION	0.2 SY *	
CONCRETE DECK REPAIR FOR PPC OVERLAY	0.2 SY *	
SHOTBLASTING BRIDGE DECK	277 SY	
PPC MATERIALS	7.9 CY	
PLACING & FINISHING PPC OVERLAY	277 SY	
GROOVING BRIDGE FLOORS	2232 SF	

NOTES:

Samuel L. Co

- 19C97095C75A467

5/9/2018 2:14

SEAL

043571

REPAIR LOCATIONS AND ESTIMATED QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE AS-BUILT REPAIR QUANTITY TABLE.

CONCRETE COVER FOR TOP BARS IN THE DECK SLAB IS $2\frac{1}{2}$ " PER THE EXISTING BRIDGE PLANS. ACTUAL CONCRETE COVER SHALL BE DETERMINED BY THE CONTRACTOR AND PRESENTED TO THE ENGINEER PRIOR TO BEGINNING SCARIFICATION.

CURRENT AVERAGE COVER IS EXPECTED TO BE FROM $1\frac{1}{2}$ " TO $2\frac{1}{2}$ " BASED ON VISUAL INSPECTION.

* MINOR QUANTITIES OF CLASS II AREAS ARE ANTICIPATED, PARTICULARLY NEAR JOINTS. HOWEVER, DUE TO THEIR SMALL SIZE, THE CLASS II LOCATIONS HAVE NOT BEEN DELINEATED ON THESE PLANS. THE CLASS II QUANTITIES INDICATED ARE ANTICIPATED TO BE SUFFICIENT FOR THE ACTUAL QUANTITIES ENCOUNTERED.

GROOVING BRIDGE FLOORS QUANITITY BASED ON WIDTHS OF TRAVEL LANES PLUS 6" ON EACH SIDE.

COORDINATE THIS SHEET WITH S-28 FOR THE PPC OVERLAY.

FOR SECTIONS A-A, B-B, AND C-C SEE SHEET S-29.

FOR SECTION D-D AND DETAILS OF JOINT AT BARRIER SEE SHEET S-30.


PROJECT NO.	15BPR.16
BRUNSW	


BRIDGE NO.____

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH

ΡL	AN	OF	SPAN
	SP	AN	16

			REVI	SION	IS		SHEET NO.
DOCUMENT NOT CONSIDERED	N0.	BY:	DATE:	NO.	BY:	DATE:	S-20
FINAL UNLESS ALL	1			3			TOTAL SHEETS
SIGNATURES COMPLETED	2			4			73





___ DATE : _____03-2018___ DESIGN ENGINEER OF RECORD : SAMUEL L.CULLUM DATE : 03-2018 5/9/2018 G:\4201720.03-Brunswick-71\Structures\401_120_15BPR.16_SMU_DSR17_S-21_090071.dgn

User:jduke

PLAN

AS-BUILT REPAIR QUANTITY TABLE

TOP OF DECK REPAIRS

SPAN 17

	ESTIMATE	ACTUAL
SCARIFYING BRIDGE DECK	269 SY	
CLASS II SURFACE PREPARATION	0.2 SY *	
CONCRETE DECK REPAIR FOR PPC OVERLAY	0.2 SY *	
SHOTBLASTING BRIDGE DECK	269 SY	
PPC MATERIALS	7.9 CY	
PLACING & FINISHING PPC OVERLAY	269 SY	
GROOVING BRIDGE FLOORS	2165 SF	

NOTES:

Samuel L. Co

- 19C97095C75A467

5/9/2018 2:14

SEAL

043571

REPAIR LOCATIONS AND ESTIMATED QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE AS-BUILT REPAIR QUANTITY TABLE.

CONCRETE COVER FOR TOP BARS IN THE DECK SLAB IS $2\frac{1}{2}$ " PER THE EXISTING BRIDGE PLANS. ACTUAL CONCRETE COVER SHALL BE DETERMINED BY THE CONTRACTOR AND PRESENTED TO THE ENGINEER PRIOR TO BEGINNING SCARIFICATION.

CURRENT AVERAGE COVER IS EXPECTED TO BE FROM $1\frac{1}{2}$ " TO $2\frac{1}{2}$ " BASED ON VISUAL INSPECTION.

* MINOR QUANTITIES OF CLASS II AREAS ARE ANTICIPATED, PARTICULARLY NEAR JOINTS. HOWEVER, DUE TO THEIR SMALL SIZE, THE CLASS II LOCATIONS HAVE NOT BEEN DELINEATED ON THESE PLANS. THE CLASS II QUANTITIES INDICATED ARE ANTICIPATED TO BE SUFFICIENT FOR THE ACTUAL QUANTITIES ENCOUNTERED.

GROOVING BRIDGE FLOORS QUANITITY BASED ON WIDTHS OF TRAVEL LANES PLUS 6" ON EACH SIDE.

COORDINATE THIS SHEET WITH S-28 FOR THE PPC OVERLAY.

FOR SECTIONS A-A, B-B, AND C-C SEE SHEET S-29.

FOR SECTION D-D AND DETAILS OF JOINT AT BARRIER SEE SHEET S-30.

PROJECT NO	15BPR.16
BRUNSW	ICK COUNTY


BRIDGE NO.____

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH

PL	AN	OF	SPAN
	SP	AN	17

			REVI	SION	IS		SHEET NO.
DOCUMENT NOT CONSIDERED	NO.	BY:	DATE:	NO.	BY:	DATE:	S-21
FINAL UNLESS ALL	1			3			TOTAL SHEETS
SIGNATURES COMPLETED	2			4			73

+



AS-BUILT REPAIR QUANTITY TABLE

TOP OF DECK REPAIRS

SPAN 18

51711110		
	ESTIMATE	ACTUAL
SCARIFYING BRIDGE DECK	287 SY	
CLASS II SURFACE PREPARATION	0.2 SY *	
CONCRETE DECK REPAIR FOR PPC OVERLAY	0.2 SY *	
SHOTBLASTING BRIDGE DECK	287 SY	
PPC MATERIALS	8.2 CY	
PLACING & FINISHING PPC OVERLAY	287 SY	
GROOVING BRIDGE FLOORS	2313 SF	

NOTES:

Samuel L. Co

- 19C97095C75A467

5/9/2018 2:14

SEAL

043571

REPAIR LOCATIONS AND ESTIMATED QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE AS-BUILT REPAIR QUANTITY TABLE.

CONCRETE COVER FOR TOP BARS IN THE DECK SLAB IS $2\frac{1}{2}$ " PER THE EXISTING BRIDGE PLANS. ACTUAL CONCRETE COVER SHALL BE DETERMINED BY THE CONTRACTOR AND PRESENTED TO THE ENGINEER PRIOR TO BEGINNING SCARIFICATION.

CURRENT AVERAGE COVER IS EXPECTED TO BE FROM $1\frac{1}{2}$ " TO $2\frac{1}{2}$ " BASED ON VISUAL INSPECTION.

* MINOR QUANTITIES OF CLASS II AREAS ARE ANTICIPATED, PARTICULARLY NEAR JOINTS. HOWEVER, DUE TO THEIR SMALL SIZE, THE CLASS II LOCATIONS HAVE NOT BEEN DELINEATED ON THESE PLANS. THE CLASS II QUANTITIES INDICATED ARE ANTICIPATED TO BE SUFFICIENT FOR THE ACTUAL QUANTITIES ENCOUNTERED.

GROOVING BRIDGE FLOORS QUANITITY BASED ON WIDTHS OF TRAVEL LANES PLUS 6" ON EACH SIDE.

COORDINATE THIS SHEET WITH S-28 FOR THE PPC OVERLAY.

FOR SECTIONS A-A, B-B, AND C-C SEE SHEET S-29.

FOR SECTION D-D AND DETAILS OF JOINT AT BARRIER SEE SHEET S-30.

PROJECT NO	15BPR.16
BRUNSW	ICK COUNTY

BRIDGE NO.____


STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION


71

PLAN	OF	SPAN
SP	AN	18

RALEIGH

			REVI	SION	S		SHEET NO.
DOCUMENT NOT CONSIDERED	N0.	BY:	DATE:	NO.	BY:	DATE:	S-22
FINAL UNLESS ALL	1			3			TOTAL SHEETS
SIGNATURES COMPLETED	2			4			73





___ DATE : _____03-2018___ DESIGN ENGINEER OF RECORD : SAMUEL L.CULLUM DATE : 03-2018

5/9/2018 G:\4201720.03-Brunswick-71\Structures\401_130_15BPR.16_SMU_DSR19_S-23_090071.dgn User:jduke

PLAN

AS-BUILT REPAIR QUANTITY TABLE

TOP OF DECK REPAIRS

SPAN 19

	ESTIMATE	ACTUAL
SCARIFYING BRIDGE DECK	187 SY	
CLASS II SURFACE PREPARATION	0.2 SY *	
CONCRETE DECK REPAIR FOR PPC OVERLAY	0.2 SY *	
SHOTBLASTING BRIDGE DECK	187 SY	
PPC MATERIALS	5.4 CY	
PLACING & FINISHING PPC OVERLAY	187 SY	
GROOVING BRIDGE FLOORS	1503 SF	

NOTES:

Samuel L. Co

5/9/2018 2:14

- 19C97095C75A467

SEAL

043571

REPAIR LOCATIONS AND ESTIMATED QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE AS-BUILT REPAIR QUANTITY TABLE.

CONCRETE COVER FOR TOP BARS IN THE DECK SLAB IS $2\frac{1}{2}$ " PER THE EXISTING BRIDGE PLANS. ACTUAL CONCRETE COVER SHALL BE DETERMINED BY THE CONTRACTOR AND PRESENTED TO THE ENGINEER PRIOR TO BEGINNING SCARIFICATION.

CURRENT AVERAGE COVER IS EXPECTED TO BE FROM $1\frac{1}{2}$ " TO $2\frac{1}{2}$ " BASED ON VISUAL INSPECTION.

* MINOR QUANTITIES OF CLASS II AREAS ARE ANTICIPATED, PARTICULARLY NEAR JOINTS. HOWEVER, DUE TO THEIR SMALL SIZE, THE CLASS II LOCATIONS HAVE NOT BEEN DELINEATED ON THESE PLANS. THE CLASS II QUANTITIES INDICATED ARE ANTICIPATED TO BE SUFFICIENT FOR THE ACTUAL QUANTITIES ENCOUNTERED.

GROOVING BRIDGE FLOORS QUANITITY BASED ON WIDTHS OF TRAVEL LANES PLUS 6" ON EACH SIDE.

COORDINATE THIS SHEET WITH S-28 FOR THE PPC OVERLAY.

FOR SECTIONS A-A, B-B, AND C-C SEE SHEET S-29.

FOR SECTION D-D AND DETAILS OF JOINT AT BARRIER SEE SHEET S-30.


PROJECT NO	15BPR.16
BRUNSW	ICK COUNTY


BRIDGE NO.____

71

PL	AN	OF	SPAN
	SP	AN	19

			REVI	SION	IS		SHEET NO.
DOCUMENT NOT CONSIDERED	N0.	BY:	DATE:	NO.	BY:	DATE:	S-23
FINAL UNLESS ALL	1			3			TOTAL SHEETS
SIGNATURES COMPLETED	2			4			73





DESIGN ENGINEER OF RECORD : SAMUEL L.CULLUM DATE : 03-2018

PLAN

AS-BUILT REPAIR QUANTITY TABLE

TOP OF DECK REPAIRS

SPAN 20

	ESTIMATE	ACTUAL
SCARIFYING BRIDGE DECK	187 SY	
CLASS II SURFACE PREPARATION	0.2 SY *	
CONCRETE DECK REPAIR FOR PPC OVERLAY	0.2 SY *	
SHOTBLASTING BRIDGE DECK	187 SY	
PPC MATERIALS	5.4 CY	
PLACING & FINISHING PPC OVERLAY	187 SY	
GROOVING BRIDGE FLOORS	1503 SF	

NOTES:

Samuel L. Co

- 19C97095C75A467

5/9/2018 2:14

SEAL

043571

REPAIR LOCATIONS AND ESTIMATED QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE AS-BUILT REPAIR QUANTITY TABLE.

CONCRETE COVER FOR TOP BARS IN THE DECK SLAB IS $2\frac{1}{2}$ " PER THE EXISTING BRIDGE PLANS. ACTUAL CONCRETE COVER SHALL BE DETERMINED BY THE CONTRACTOR AND PRESENTED TO THE ENGINEER PRIOR TO BEGINNING SCARIFICATION.

CURRENT AVERAGE COVER IS EXPECTED TO BE FROM $1\frac{1}{2}$ " TO $2\frac{1}{2}$ " BASED ON VISUAL INSPECTION.

* MINOR QUANTITIES OF CLASS II AREAS ARE ANTICIPATED, PARTICULARLY NEAR JOINTS. HOWEVER, DUE TO THEIR SMALL SIZE, THE CLASS II LOCATIONS HAVE NOT BEEN DELINEATED ON THESE PLANS. THE CLASS II QUANTITIES INDICATED ARE ANTICIPATED TO BE SUFFICIENT FOR THE ACTUAL QUANTITIES ENCOUNTERED.

GROOVING BRIDGE FLOORS QUANITITY BASED ON WIDTHS OF TRAVEL LANES PLUS 6" ON EACH SIDE.

COORDINATE THIS SHEET WITH S-28 FOR THE PPC OVERLAY.

FOR SECTIONS A-A, B-B, AND C-C SEE SHEET S-29.

FOR SECTION D-D AND DETAILS OF JOINT AT BARRIER SEE SHEET S-30.


PROJECT NO.	15BPR.16
BRUNS	NICK COUNTY


BRIDGE NO.____

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH

PL	AN	OF	SPAN
	SP	AN	20

			REVI	ISION	S		SHEET NO.
DOCUMENT NOT CONSIDERED	NO.	BY:	DATE:	NO.	BY:	DATE:	S-24
FINAL UNLESS ALL	1			3			TOTAL SHEETS
SIGNATURES COMPLETED	2			4			73





AS-BUILT REPAIR QUANTITY TABLE

TOP OF DECK REPAIRS

SPAN 21

	ESTIMATE	ACTUAL
SCARIFYING BRIDGE DECK	287 SY	
CLASS II SURFACE PREPARATION	0.2 SY *	
CONCRETE DECK REPAIR FOR PPC OVERLAY	0.2 SY *	
SHOTBLASTING BRIDGE DECK	287 SY	
PPC MATERIALS	8.2 CY	
PLACING & FINISHING PPC OVERLAY	287 SY	
GROOVING BRIDGE FLOORS	2313 SF	

NOTES:

Samuel L. Co

5/9/2018 2:14

- 19C97095C75A467

SEAL

043571

REPAIR LOCATIONS AND ESTIMATED QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE AS-BUILT REPAIR QUANTITY TABLE.

CONCRETE COVER FOR TOP BARS IN THE DECK SLAB IS $2\frac{1}{2}$ " PER THE EXISTING BRIDGE PLANS. ACTUAL CONCRETE COVER SHALL BE DETERMINED BY THE CONTRACTOR AND PRESENTED TO THE ENGINEER PRIOR TO BEGINNING SCARIFICATION.

CURRENT AVERAGE COVER IS EXPECTED TO BE FROM $1\frac{1}{2}$ " TO $2\frac{1}{2}$ " BASED ON VISUAL INSPECTION.

* MINOR QUANTITIES OF CLASS II AREAS ARE ANTICIPATED, PARTICULARLY NEAR JOINTS. HOWEVER, DUE TO THEIR SMALL SIZE, THE CLASS II LOCATIONS HAVE NOT BEEN DELINEATED ON THESE PLANS. THE CLASS II QUANTITIES INDICATED ARE ANTICIPATED TO BE SUFFICIENT FOR THE ACTUAL QUANTITIES ENCOUNTERED.

GROOVING BRIDGE FLOORS QUANITITY BASED ON WIDTHS OF TRAVEL LANES PLUS 6" ON EACH SIDE.

COORDINATE THIS SHEET WITH S-28 FOR THE PPC OVERLAY.

FOR SECTIONS A-A, B-B, AND C-C SEE SHEET S-29.

FOR SECTION D-D AND DETAILS OF JOINT AT BARRIER SEE SHEET S-30.

PROJECT NO	15BPR.16
BRUNSW	ICK COUNTY

BRIDGE NO.____


71


ΡL	AN	OF	SPAN
	SP	AN	21

			REVI	ISION	IS		SHEET NO.
DOCUMENT NOT CONSIDERED	NO.	BY:	DATE:	NO.	BY:	DATE:	S-25
FINAL UNLESS ALL	1			3			TOTAL SHEETS
SIGNATURES COMPLETED	2			4			73

-

+





5/9/2018

DESIGN ENGINEER OF RECORD : SAMUEL L.CULLUM DATE : 03-2018 G:\4201720.03-Brunswick-71\Structures\401_145_15BPR.16_SMU_DSR22_S-26_090071.dgn User:jduke

AS-BUILT REPAIR QUANTITY TABLE TOP OF DECK REPAIRS SPAN 22 ESTIMATE ACTUAL 167 SY SCARIFYING BRIDGE DECK CLASS II SURFACE PREPARATION 0.2 SY * 0.2 SY * CONCRETE DECK REPAIR FOR PPC OVERLAY 167 SY SHOTBLASTING BRIDGE DECK PPC MATERIALS 4.9 CY 167 SY PLACING & FINISHING PPC OVERLAY 1342 SF GROOVING BRIDGE FLOORS

NOTES:

Samuel L. Co

5/9/2018 2:14

- 19C97095C75A467

SEAL

043571

REPAIR LOCATIONS AND ESTIMATED QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE AS-BUILT REPAIR QUANTITY TABLE.

CONCRETE COVER FOR TOP BARS IN THE DECK SLAB IS $2\frac{1}{2}$ " PER THE EXISTING BRIDGE PLANS. ACTUAL CONCRETE COVER SHALL BE DETERMINED BY THE CONTRACTOR AND PRESENTED TO THE ENGINEER PRIOR TO BEGINNING SCARIFICATION.

CURRENT AVERAGE COVER IS EXPECTED TO BE FROM $1\frac{1}{2}$ " TO $2\frac{1}{2}$ " BASED ON VISUAL INSPECTION.

* MINOR QUANTITIES OF CLASS II AREAS ARE ANTICIPATED, PARTICULARLY NEAR JOINTS. HOWEVER, DUE TO THEIR SMALL SIZE, THE CLASS II LOCATIONS HAVE NOT BEEN DELINEATED ON THESE PLANS. THE CLASS II QUANTITIES INDICATED ARE ANTICIPATED TO BE SUFFICIENT FOR THE ACTUAL QUANTITIES ENCOUNTERED.

GROOVING BRIDGE FLOORS QUANITITY BASED ON WIDTHS OF TRAVEL LANES PLUS 6" ON EACH SIDE.

COORDINATE THIS SHEET WITH S-28 FOR THE PPC OVERLAY.

FOR SECTIONS A-A, B-B, AND C-C SEE SHEET S-29.

FOR SECTION D-D AND DETAILS OF JOINT AT BARRIER SEE SHEET S-30.

PROJECT NO	15BPR.16
BRUNSW	ICK COUNTY

BRIDGE NO.____


STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH


PL	AN	OF	SPAN
	SP	AN	22

			SHEET NO.				
DOCUMENT NOT CONSIDERED	N0.	BY:	DATE:	N0.	BY:	DATE:	S-26
FINAL UNLESS ALL	1			3			TOTAL SHEETS
SIGNATURES COMPLETED	2			4			73

-

+





DESIGN ENGINEER OF RECORD : SAMUEL L.CULLUM DATE : 03-2018

AS-BUILT REPAIR QUANTITY TABLE TOP OF DECK REPAIRS SPAN 23 ESTIMATE ACTUAL 169 SY SCARIFYING BRIDGE DECK 0.2 SY * CLASS II SURFACE PREPARATION 0.2 SY * CONCRETE DECK REPAIR FOR PPC OVERLAY 169 SY SHOTBLASTING BRIDGE DECK PPC MATERIALS 4.9 CY PLACING & FINISHING PPC OVERLAY 169 SY 1354 SF GROOVING BRIDGE FLOORS

NOTES:

Samuel L

- 19C97095C75A467

5/9/2018 2:14

SEAL

043571

REPAIR LOCATIONS AND ESTIMATED QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE AS-BUILT REPAIR QUANTITY TABLE.

CONCRETE COVER FOR TOP BARS IN THE DECK SLAB IS $2\frac{1}{2}$ " PER THE EXISTING BRIDGE PLANS. ACTUAL CONCRETE COVER SHALL BE DETERMINED BY THE CONTRACTOR AND PRESENTED TO THE ENGINEER PRIOR TO BEGINNING SCARIFICATION.

CURRENT AVERAGE COVER IS EXPECTED TO BE FROM $1\frac{1}{2}$ " TO $2\frac{1}{2}$ " BASED ON VISUAL INSPECTION.

* MINOR QUANTITIES OF CLASS II AREAS ARE ANTICIPATED, PARTICULARLY NEAR JOINTS. HOWEVER, DUE TO THEIR SMALL SIZE, THE CLASS II LOCATIONS HAVE NOT BEEN DELINEATED ON THESE PLANS. THE CLASS II QUANTITIES INDICATED ARE ANTICIPATED TO BE SUFFICIENT FOR THE ACTUAL QUANTITIES ENCOUNTERED.

GROOVING BRIDGE FLOORS QUANITITY BASED ON WIDTHS OF TRAVEL LANES PLUS 6" ON EACH SIDE.

COORDINATE THIS SHEET WITH S-28 FOR THE PPC OVERLAY.

FOR SECTIONS A-A, B-B, AND C-C SEE SHEET S-29.

FOR SECTION D-D AND DETAILS OF JOINT AT BARRIER SEE SHEET S-30.

PROJECT NO	0. <u>15BPR.16</u>	
BRUNS	<u>SWICK</u> cou	NTY

71


BRIDGE NO.____

STATE OF NORTH CAROLINA							
DEPARTMENT	OF	TRANSPORTATION					
RALEIGH							


PL	AN	OF	SPAN
	SP	AN	23

			REV	ISION	S		SHEET NO.
DOCUMENT NOT CONSIDERED	NO.	BY:	DATE:	NO.	BY:	DATE:	S-27
FINAL UNLESS ALL	1			3			TOTAL SHEETS
SIGNATURES COMPLETED	2			4			73

+



+




NOTES:

FOR SILICONE JOINT SEALANT, SEE SPECIAL PROVISIONS.

SILICONE JOINT SEALANT AND BACKER ROD SHAL BE INSTALLED AS PER MANUFACTURER'S RECOMMENDATIONS.

FOR DIM "A", SEE TABLE 1 ON SHEET S-30.

	PROJEC	CT NO.	15	BPR.1	6				
	BF	BRUNSWICK COUNTY							
	BRIDG	E NO		71					
	SHEET 1 O	- 2							
DocuSigned by:	DEPA		E OF NORTH CAR OF TRAN RALEIGH	OLINA NSPORTA	TION				
Samuel L Culture SEAL 19C97095C75A467 043571		JOIN	T DE	TAILS					
5/9/2018 2:14 SUPPORT OF SUPPORT	S	APPRO PANS 1	DACH S -10 AN	ND 14-2	3				
		REVIS	IONS		SHEET NO.				
DOCUMENT NOT CONSIDERED	NO. BY:	DATE:	NO. BY:	DATE:	S-29				
FINAL UNLESS ALL SIGNATURES COMPLETED	1 2		<u> ৩</u> ব্রু		TOTAL SHEETS 73				



NOTES:

FOR SILICONE JOINT SEALANT, SEE SPECIAL PROVISIONS.

SILICONE JOINT SEALANT AND BACKER ROD SHALL BE INSTALLED AS PER MANUFACTURER'S RECOMMENDATIONS.

FOR DIM "A", SEE TABLE 1.


WORK THIS SHEET WITH SHEET S-29.

* NON-SAG SILICONE JOINT SEALANT TO BE PLACED AND ALLOWED TO SET, PRIOR TO PLACEMENT OF SELF-LEVELING SILICONE JOINT SEALANT.

	TABLE 1	Table Date 3-2018
DIM "A" @ 65°F	BENT/JOINTS	(MEASUREMENTS FROM FIELD VISIT)
1"	BENTS: 22	
1 ¹ /4″	BENTS: 7, 17, 18, 20, 21	
1 ³ ⁄8″	BENTS: 1, 16	
11/2″	BENTS: 4, 5, 6, 8, 9, 14, 15, 19	
15⁄8″	BENTS: 2, 3	
1¾″	BENTS: END BENT#1	
2"	BENTS: END BENT#2	
21/2″	BENTS: 10, 12, 13	
25⁄8"	BENTS: 11	

	PROJEC BF BRIDGE	RUNSV	VICK		6 OUNTY	
	SHEET 2 C)F 2				
DocuSigned by:	STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH					
Samuel L Culture 19C97095C75A467 043571 5/9/2018 2:14 5/9/2018 2:14	TAILS					
		AND	JOINT	AND 13 TABLE	,	
		REVIS	SIONS		SHEET NO.	
DOCUMENT NOT CONSIDERED	NO. BY:	DATE:	NO. BY:	DATE:	S-30	
FINAL UNLESS ALL	1		3		TOTAL SHEETS	
SIGNATURES COMPLETED	2		4		73	






+

TYPICAL ROADWAY SECTION

KISINGER CAMPO & ASSOCIATES	4800 SIX FORKS ROA RALEIGH, NC 27609 (919) 882-7839	AD SUITE 120
DRAWN BY :	DIEGO A. AGUIRRE	DATE :
CHECKED BY :	JACOB H. DUKE	DATE :03-2018
DESIGN ENGINEER C	OF RECORD : <u>SAMUEL L.CULLUN</u>	DATE : <u>03-2018</u>
		5/9/2018

5/9/2018 G:\4201720.03-Brunswick-71\Structures\401_170_15BPR.16_SMU_APP01_S-31_090071.dgn User:jduke


TO HOLDEN BEACH




AS-BUILT QUANTITY TABLE				
	ESTIMATE	ACTUAL		
NCIDENTAL MILLING	145 SY			
SPHALT CONCRETE SURFACE COURSE, TYPE S9.5C	12.0 TONS			

NOTES:

INCIDENTAL MILLING - EXISTING APPROACH ASPHALT PAVEMENT TO BE MILLED AS NECESSARY TO ATTAIN MINIMUM 1"DEPTH OF NEW ASPHALT PAVEMENT.NEW ASPHALT PAVEMENT SHALL BE OF THICKNESS NECESSARY TO PROVIDE A SMOOTH TRANSITION BETWEEN THE ROADWAY AND THE BRIDGE DECK. THE NEW ASPHALT PAVEMENT THICKNESS MAY EXCEED 1"DUE TO SETTLEMENT OF THE EXISTING APPROACH.



INCIDENTAL MILLING



Samuel L

- 19C97095C75A4

5/9/2018 2:14

SEAL

04357

ASPHALT CONCRETE SURFACE COURSE, TYPE S9.5C

PROJECT NO. 15BPR.16

BRUNSWICK COUNTY

BRIDGE NO.____


71

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH


APPROACH

MILLING AND TYPICAL ROADWAY SECTIONS

		REVISIONS					
DOCUMENT NOT CONSIDERED	NO. BY:	DATE:	NO. BY:	DATE:	S-31		
FINAL UNLESS ALL	1		3		TOTAL SHEETS		
SIGNATURES COMPLETED	2		4		73		



CHECKED BY :	DIEGO A.AGUIRRE	_ DATE : <u>03-2018</u>
DESIGN ENGINEER	OF RECORD : SAMUEL L. CULLUM	DATE : 03-2018
		5/9/2018 G:\4201720.03-Brupswick-71\Structu



REQUIRED

SIMPLE PATCH CONFIGURATION

AT CORNER LOCATIONS PROVIDE RIGHT ANGLE CUTS. PATCH CONFIGURATION SHALL BE KEPT AS SIMPLE AS POSSIBLE.INDIVIDUAL REPAIR AREAS WITHIN 2 FEET SHALL BE JOINED AT THE DIRECTION OF THE ENGINEER.

TYPICAL CRACK REPAIR METHOD


- 1. OBTAIN ENGINEER'S APPROVAL TO CARRY OUT CRACK REPAIR (IN LIEU OF SPALL REPAIR)FOR CASES WHERE ADJACENT CONCRETE IS OTHERWISE SOUND AND CRACKING IS NOT A RESULT OF CORRODING REINFORCEMENT.
- 2. ADDRESS CRACKS IN NEW CONSTRUCTION IN ACCORDANCE WITH PROJECT SPECIAL PROVISIONS. ADDRESS EXISTING CRACKS IN ACCORDANCE WITH THIS SHEET AND PROJECT SPECIAL PROVISIONS.
- 3. REMOVE UNSOUND CONCRETE FROM CRACK AREA.
- 4. THE CONTRACTOR SHALL SUBMIT A PLAN FOR CONTROL AND DISPOSAL OF DEBRIS TO THE ENGINEER FOR APPROVAL.
- 5. FOR CRACKS UP TO 1/8" USE AN EPOXY RESIN WITH MINIMUMS OF VISCOSITY OF 325 CPS,28 DAY COMPRESSIVE STRENGTH OF 13000 PSI. FOR CRACKS 1/8" TO 1/4", USE AN INJECTION GEL OR EQUAL NON-SAG PASTE WITH 28 DAY COMPRESSIVE STRENGTH OF 10000 PSI.
- 6. TO SEAL CRACK SURFACES PRIOR TO CRACK INJECTION, USE INJECTION GEL WITH MINIMUM 28 DAY COMPRESSIVE STRENGTH OF 12000 PSI.
- 7. ENGINEER TO APPROVE CRACK AND CAP SEAL MATERIAL PRIOR TO BEGINNING OF CONSTRUCTION.
- 8. APPLY CLASS II FINISH AT COMPLETION OF CRACK REPAIR TO REMOVE FINS OR KNOBS.

CONCRETE	REPAIR SCHEDULE					
REPAIR AREA	APPROVED MATERIAL					
BEAMS	CONCRETE REPAIRS (PPC GIRDERS)					
PIER FOOTINGS	<pre>``FORM AND POUR" CONCRETE REPAIR</pre>					
OTHER SUBSTRUCTURE	SHOTCRETE, OR CONTRACTOR OPTION					


SEE PPC PLANS AND PSP FOR TOP OF DECK CONCRETE REPAIRS.

PRESTRESSED GIRDER REPAIR NOTES

IF AFTER UNSOUND CONCRETE REMOVAL ON GIRDERS, MORE THAN 50% SECTION LOSS IS NOTED ON THE PRESTRESSING STRANDS, OR A SEVERED PRESTRESSING STRAND IS ENCOUNTERED, NOTIFY THE ENGINEER PRIOR TO PROCEEDING WITH CONCRETE REPAIR.



TYPICAL DELAMINATIONS AND SPALLS



EXISTING SECTION —

4.

TYPICAL SPALL WITH EXPOSED REBAR

CONCRETE REPAIR NOTES


PERFORM A SOUNDING SURVEY IN THE PRESENCE OF THE ENGINEER TO IDENTIFY ALL LOCATIONS IN NEED OF CONCRETE REPAIR.

2. GAIN CONCURRENCE ON ALL REPAIR AREAS AT EACH LOCATION PRIOR TO COMMENCING WORK AT THE BENT.


3. THE DETERIORATED AREAS SHOWN ON OTHER PAGES ARE BASED ON INFRARED SURVEYS, BRIDGE INSPECTION REPORT, AND PARTIAL FIELD REVIEWS OF THE STRUCTURE. AS SUCH, THEY ARE FOR INFORMATIONAL PURPOSES AND SUBJECT TO CHANGE BASED ON CONTINUED DETERIORATION.

GENERALLY EXTEND REPAIR AREAS 2"-3" INTO SOUND CONCRETE BEYOND EDGE OF SPALLS AND SQUARE OFF AREAS IN ACCORDANCE WITH DETAILS ON THIS SHEET.


	PROJECT NO. <u>15BPR.16</u> <u>BRUNSWICK</u> COUNTY BRIDGE NO. <u>71</u>					
DocuSigned by: Samuel L Collem 19C97095C75A467. 5/9/2018 2:14:59200 FDHNEF.	SHEET 1 OF 2 STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH CONCRETE RESTORATION DETAILS					
TAMUEL L CULTUR	SUPERSTRUCTURE					
		SHEET NO.				
DOCUMENT NOT CONSIDERED	NO. BY:	DATE: NO.	BY:	DATE:		
FINAL UNLESS ALL SIGNATURES COMPLETED	1	③ 4			total sheets 73	



GIRDER WEB REPAIR




GIRDER FLANGE REPAIR



5/9/2018 G:\4201720.03-Brunswick-71\Structures\401_180_15BPR.16_SMU_CR02_S-33_090071.dgn User:jduke







PRESTRESSED GIRDER REPAIR SEQUENCE:

- SOUND CONCRETE TO DETERMINE EXTENTS OF REPAIR LOCATION (PHOTO REQUIRED).
- REMOVE SURFACE CONCRETE TO VERIFY THAT SAW CUT DEPTH WILL NOT DAMAGE 2. EXISTING REINFORCING STEEL. SAW CUT AROUND REPAIR AREA TO A NOMINAL DEPTH OF $\frac{1}{2}$ ".
- 3. REMOVE CONCRETE WITHIN SAW CUT AREA TO MINIMUM DEPTH 1/2" DEPTH. IF CONCRETE IS DAMAGED BEYOND THE ORIGINAL SAW CUT, A NEW SAW CUT IS REQUIRED.
- 4. ▲ IF MORE THAN HALF THE CIRCUMFERENCE OF A REINFORCING BAR IS EXPOSED DURING THIS PROCESS, REMOVE ADDITIONAL CONCRETE TO 1"BEHIND THE BAR. THIS DOES NOT APPLY TO PRESTRESS STRANDS.
- 5. ALL UNSOUND CONCRETE MUST BE REMOVED. HOWEVER, PRESTRESSED STRAND SHOULD NOT BE DISTURBED UNLESS ABSOLUTELY NECESSARY. USE EXTREME CARE TO NOT DAMAGE STRANDS.
- CLEAN ALL EXPOSED REINFORCING BARS AND PRESTRESSED 6. STRANDS.FOR BAR WITH MORE THAN 10% SECTION LOSS, SPLICE AND SECURELY TIE SUPPLEMENTAL REINFORCING BARS AS NEEDED. NOTE AND PROVIDE DETAILED DOCUMENTATION, INCLUDING LOCATION AND SEVERITY OF ALL DAMAGE TO PRESTRESSED STRANDS THAT EXCEEDS 10% SECTION LOSS. IF FIVE OR MORE STRANDS ARE DAMAGED, NOTIFY THE ENGINEER PRIOR TO PLACEMENT OF REPAIR MATERIAL.
- REMOVE ALL LOOSE OR WEAKENED MATERIAL THEN CLEAN THE REPAIR AREA OF DIRT, 7. GREASE, OIL, AND FOREIGN MATTER.
- PREPARE SURFACE AND PLACE APPROVED MATERIAL ACCORDING TO MANUFACTURER'S 8. RECOMMENDATIONS. MAXIMUM AGGREGATE SIZE FOR REPAIR MATERIAL SHALL NOT EXCEED ⅔ THE MINIMUM REPAIR DEPTH.
- FOR GIRDER REPAIRS, SEE PROJECT SPECIAL PROVISION FOR REPAIRS TO PRESTRESSED 9. CONCRETE GIRDERS AND SEE SHEETS S-60 THRU S-63 FOR DEFICIENCIES.

NOTES:

PREPACKAGED MATERIAL IS REQUIRED.


FOR REPAIRS OVER TRAFFIC AND SHALLOW REPAIRS THAT DO NOT ENGAGE REINFORCEMENT, ANCHOR PATCH MATERIAL USING 1/4" GALVANIZED BOLTS, EPOXY ANCHORED WITH 2"EMBEDMENT.PLACE BOLTS IN A 6"GRID.USE A LATEX OR EPOXY PATH MATERIAL FOR IMPROVED BOND.USE EXTREME CARE TO NOT DAMAGE STRANDS.

PROJECT NO. 158PR.16 BRUNSWICK _ COUNTY 71 BRIDGE NO.____ SHEET 2 OF 2 STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH CONCRETE RESTORATION Samuel L. Cu SEAL - 19C97095C75A467 DETAILS 043571 5/9/2018 2:14 SUPERSTRUCTURE SHEET NO. REVISIONS S-33 NO. DATE: DATE: BY: BY: DOCUMENT NOT CONSIDERED TOTAL SHEETS FINAL UNLESS ALL


73

SIGNATURES COMPLETED

+



ED, DELAMINATED O	R CRACKED
RETE (REMOVE UNTIL	_ SOUND CONCRETE
DUND AND 1"MIN.BE	HIND ANY
SED REBAR (TYP.)	




CONCRETE REPAIR AREA (FORM AND POUR)

SHOTCRETE REPAIR AREA

EPOXY RESIN INJECTION (ERI)

10 VERTICAL FEET AT ONCE OR $\frac{1}{2}$ COLUMN


		RUNSV	VICK	5 <u>BPR.1</u> cc 71	6 OUNTY
DocuSigned by: Samuel L Culturn 19C97095C75A467. 5/9/2018 2:14:597097.501NE EP. L CULTURN	STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH CONCRETE RESTORATION DETAILS SUBSTRUCTURE				
	REVISIONS SHEET NO.				
DOCUMENT NOT CONSIDERED	NO. BY:	DATE:	NO. BY:	DATE:	S-34
FINAL UNLESS ALL SIGNATURES COMPLETED	1 2		3 4		TOTAL SHEETS 73



—

CHECKED BY : ______JACOB H. DUKE

DESIGN ENGINEER OF RECORD : SAMUEL L.CULLUM DATE : 03-2018



_ DATE : <u>03-2018</u>

AS-BUILT REPAIR QUANTITY TABLE					
END BENT 1 & 2		QUANT	ITIES		
END DENTIAZ	ESTI	ΜΑΤΕ	ACT	UAL	
SHOTCRETE REPAIRS	AREA SQ.FT.	VOLUME CU.FT.	AREA SQ.FT.	VOLUME CU.FT.	
САР	1.9	1.0			
COLUMN/PILE	N/A	N/A			
CONCRETE REPAIRS	AREA SQ.FT.	VOLUME CU.FT.	AREA SQ.FT.	VOLUME CU.FT.	
САР	-	-			
EPOXY RESIN INJECTION		LIN.FT.		LIN.FT.	
САР		-			
COLUMN/PILE		N/A			

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE. MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2"CLEARANCE TO SAWCUT.FOR REPAIR DETAILS, SEE "CONCRETE RESTORATION DETAILS - SUBSTRUCTURE" SHEET.

NOTES:

REPAIR LOCATIONS AND ESTIMATED QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE AS-BUILT REPAIR QUANTITY TABLE.

CONCRETE COVER FOR EXTERIOR BARS IN THE CAP IS 3" ON THE BOTTOM FACE, 2"ELSEWHERE, AND 3" ON THE COLUMNS PER EXISTING BRIDGE PLANS. ACTUAL CONCRETE COVER SHALL BE DETERMINED BY THE CONTRACTOR AND PRESENTED TO THE ENGINEER PRIOR TO BEGINNING SCARIFICATION.

CURRENT AVERAGE COVER IS EXPECTED TO BE FROM 2" TO 3" ON THE CAP AND FROM $2^{1}/_{2}$ " TO 3" ON THE COLUMNS BASED ON VISUAL INSPECTION.

SEE TITLE SHEET FOR PROJECT CARDINAL DIRECTION DESIGNATION.

FOR CONCRETE AND SHOTCRETE REPAIRS, SEE CONCRETE RESTORATION DETAILS - SUBSTRUCTURE SHEET AND SPECIAL PROVISIONS.

***** QUANTITIES OF CONCRETE REPAIR AREAS ARE ANTICIPATED UNDER BEARING AREAS. DUE TO LACK OF INFORMATION, ALL AREAS ARE NOT KNOWN. QUANTITY INCLUDES CONTINGENCIES AND ARE ANTICIPATED TO BE SUFFICIENT FOR ACTUAL QUANTITIES ENCOUNTERED. FOR CONCRETE REPAIRS SEE CONCRETE RESTORATION DETAILS.


ALL DEFECT QUANTITIES ON STRUTS AND COLUMN FOOTINGS ARE LISTED WITH THE QUANTITIES FOR THE CAP.

SHOTCRETE REPAIRS MAY BE REPLACED WITH CONCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

COAT ALL SURFACE AREAS OF THE TOP OF THE CAP INCLUDING CHAMFERS, WITH EPOXY PROTECTIVE COATING. DO NOT COAT THE AREA UNDER THE ELASTOMERIC BEARINGS.

	PROJEC BF BRIDGE	RUNSV		<u>BPR.1</u> C0 71	6 UNTY
DocuSigned by: Samuel L Calling 19C97095C75A467. 5/9/2018 2:14:59CPT SphNEFR.	СС	RTMENT SUBS NCRE	RALEIGH	NSPORTA	RS
		REVIS	IONS		SHEET NO.
DOCUMENT NOT CONSIDERED	NO. BY:	DATE:	NO. BY:	DATE:	S-35
FINAL UNLESS ALL SIGNATURES COMPLETED	1		গ ধ		total sheets 73

-



G:\4201720.03-Brunswick-71\Structures\401_195_15BPR.16_SMU_B01_S-36_090071.dgn User:jduke

AS-BUILT REPAIR QUANTITY TABLE						
		QUANT	ITIES			
BENT 1	ESTI	ΜΑΤΕ	ACT	UAL		
SHOTCRETE REPAIRS	AREA SQ.FT.	VOLUME CU.FT.	AREA SQ.FT.	VOLUME CU.FT.		
САР	35.3	17.7				
COLUMN/PILE	-	-				
CONCRETE REPAIRS	AREA SQ.FT.	VOLUME CU.FT.	AREA SQ.FT.	VOLUME CU.FT.		
САР	5.3	2.6				
EPOXY RESIN INJECTION		LIN.FT.		LIN.FT.		
САР		7 . 5				
COLUMN/PILE		-				
VALUES IN CUART DEPRESENT ES						

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE.MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2"CLEARANCE TO SAWCUT.FOR REPAIR DETAILS, SEE "CONCRETE RESTORATION DETAILS - SUBSTRUCTURE" SHEET.

NOTES:

REPAIR LOCATIONS AND ESTIMATED QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE AS-BUILT REPAIR QUANTITY TABLE.

CONCRETE COVER FOR EXTERIOR BARS IN THE CAP IS 3" ON THE BOTTOM FACE, 2"ELSEWHERE, AND 3" ON THE COLUMNS PER EXISTING BRIDGE PLANS. ACTUAL CONCRETE COVER SHALL BE DETERMINED BY THE CONTRACTOR AND PRESENTED TO THE ENGINEER PRIOR TO BEGINNING SCARIFICATION.

CURRENT AVERAGE COVER IS EXPECTED TO BE FROM 2"TO 3" ON THE CAP AND FROM $2^{1}/_{2}$ "TO 3" ON THE COLUMNS BASED ON VISUAL INSPECTION.

SEE TITLE SHEET FOR PROJECT CARDINAL DIRECTION DESIGNATION.

FOR CONCRETE AND SHOTCRETE REPAIRS, SEE CONCRETE RESTORATION DETAILS - SUBSTRUCTURE SHEET AND SPECIAL PROVISIONS.


* OUANTITIES OF CONCRETE REPAIR AREAS ARE ANTICIPATED UNDER BEARING AREAS.DUE TO LACK OF INFORMATION, ALL AREAS ARE NOT KNOWN. QUANTITY INCLUDES CONTINGENCIES AND ARE ANTICIPATED TO BE SUFFICIENT FOR ACTUAL QUANTITIES ENCOUNTERED.FOR CONCRETE REPAIRS SEE CONCRETE RESTORATION DETAILS.

ALL DEFECT QUANTITIES ON STRUTS AND COLUMN FOOTINGS ARE LISTED WITH THE QUANTITIES FOR THE CAP.


SHOTCRETE REPAIRS MAY BE REPLACED WITH CONCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

COAT ALL SURFACE AREAS OF THE TOP OF THE CAP INCLUDING CHAMFERS, WITH EPOXY PROTECTIVE COATING. DO NOT COAT THE AREA UNDER THE ELASTOMERIC BEARINGS.

	PROJEC BF BRIDGE	RUNSV		5BPR.1 cc 	6 DUNTY
DocuSigned by: Samuel L Column 19C97095C75A467 5/9/2018 2:14: SEAL 043571 5/9/2018 2:14: SEAL 043571		tion RS			
		REVIS	SIONS		SHEET NO.
DOCUMENT NOT CONSIDERED	NO. BY:	DATE:	NO. BY:	DATE:	S-36
FINAL UNLESS ALL	1		3		TOTAL SHEETS
SIGNATURES COMPLETED	2		4		73



—



G:\4201720.03-Brunswick-71\Structures\401_200_15BPR.16_SMU_B02_S-37_090071.dgn User:jduke

AS-BUILT REPAIR QUANTITY TABLE						
BENT 2		QUANT	ITIES			
	ESTI	ΜΑΤΕ	ACT	UAL		
SHOTCRETE REPAIRS	AREA SQ.FT.	AREA VOLUME SQ.FT. CU.FT.		VOLUME CU.FT.		
САР	99.4	49.7				
COLUMN/PILE	-	-				
CONCRETE REPAIRS	AREA SQ.FT.	VOLUME CU.FT.	AREA SQ.FT.	VOLUME CU.FT.		
САР	14.9	7.5				
EPOXY RESIN INJECTION		LIN.FT.		LIN.FT.		
САР		5.0				
COLUMN/PILE		-				
VALUES TN CHART REPRESENT ES						

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE.MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2"CLEARANCE TO SAWCUT.FOR REPAIR DETAILS, SEE "CONCRETE RESTORATION DETAILS - SUBSTRUCTURE" SHEET.

NOTES:

REPAIR LOCATIONS AND ESTIMATED QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE AS-BUILT REPAIR QUANTITY TABLE.

CONCRETE COVER FOR EXTERIOR BARS IN THE CAP IS 3" ON THE BOTTOM FACE, 2"ELSEWHERE, AND 3" ON THE COLUMNS PER EXISTING BRIDGE PLANS. ACTUAL CONCRETE COVER SHALL BE DETERMINED BY THE CONTRACTOR AND PRESENTED TO THE ENGINEER PRIOR TO BEGINNING SCARIFICATION.

CURRENT AVERAGE COVER IS EXPECTED TO BE FROM 2"TO 3" ON THE CAP AND FROM $2^{1}/_{2}$ "TO 3" ON THE COLUMNS BASED ON VISUAL INSPECTION.

SEE TITLE SHEET FOR PROJECT CARDINAL DIRECTION DESIGNATION.

FOR CONCRETE AND SHOTCRETE REPAIRS, SEE CONCRETE RESTORATION DETAILS - SUBSTRUCTURE SHEET AND SPECIAL PROVISIONS.


* OUANTITIES OF CONCRETE REPAIR AREAS ARE ANTICIPATED UNDER BEARING AREAS.DUE TO LACK OF INFORMATION, ALL AREAS ARE NOT KNOWN. QUANTITY INCLUDES CONTINGENCIES AND ARE ANTICIPATED TO BE SUFFICIENT FOR ACTUAL QUANTITIES ENCOUNTERED.FOR CONCRETE REPAIRS SEE CONCRETE RESTORATION DETAILS.

ALL DEFECT QUANTITIES ON STRUTS AND COLUMN FOOTINGS ARE LISTED WITH THE QUANTITIES FOR THE CAP.

SHOTCRETE REPAIRS MAY BE REPLACED WITH CONCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

COAT ALL SURFACE AREAS OF THE TOP OF THE CAP INCLUDING CHAMFERS, WITH EPOXY PROTECTIVE COATING. DO NOT COAT THE AREA UNDER THE ELASTOMERIC BEARINGS.

BF	RUNSI			6 UNTY
STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH SUBSTRUCTURE CONCRETE REPAIRS BENT 2				
REVISIONS SHEET NO.				
NO. BY:	DATE:	NO. BY:	DATE:	S-37
1				TOTAL SHEETS 73
	BRIDGE DEPA CC	BRUNSA BRIDGE NO DEPARTMENT SUBS CONCRE E NO. BY: DATE: 1	BRUNSWICK BRIDGE NO DEPARTMENT OF TRA RALEIGH SUBSTRUC CONCRETE F BENT NO. BY: DATE: NO. BY: 1	BRUNSWICK BRIDGE NO. 71 STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTA RALEIGH SUBSTRUCTURE CONCRETE REPAI BENT 2 REVISIONS NO. BY: DATE: NO. BY: DATE: 1 3



G:\4201720.03-Brunswick-71\Structures\401_205_15BPR.16_SMU_B03_S-38_090071.dgn User:jduke

AS-BUILT REPAIR QUANTITY TABLE						
BENT 3		QUANT	ITIES			
DEINIJ	ESTI	ΜΑΤΕ	ACT	UAL		
SHOTCRETE REPAIRS	AREA SQ.FT.	VOLUME CU.FT.	AREA SQ.FT.	VOLUME CU.FT.		
САР	111.8	55.9				
COLUMN/PILE	21.8	10.9				
CONCRETE REPAIRS	AREA SQ.FT.	VOLUME CU.FT.	AREA SQ.FT.	VOLUME CU.FT.		
САР	16.8	8.4				
EPOXY RESIN INJECTION		LIN.FT.		LIN.FT.		
САР		5.3				
COLUMN/PILE		3.3				

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE. MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2"CLEARANCE TO SAWCUT.FOR REPAIR DETAILS, SEE "CONCRETE RESTORATION DETAILS - SUBSTRUCTURE" SHEET.

NOTES:

REPAIR LOCATIONS AND ESTIMATED QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE AS-BUILT REPAIR QUANTITY TABLE.

CONCRETE COVER FOR EXTERIOR BARS IN THE CAP IS 3" ON THE BOTTOM FACE, 2"ELSEWHERE, AND 3" ON THE COLUMNS PER EXISTING BRIDGE PLANS. ACTUAL CONCRETE COVER SHALL BE DETERMINED BY THE CONTRACTOR AND PRESENTED TO THE ENGINEER PRIOR TO BEGINNING SCARIFICATION.

CURRENT AVERAGE COVER IS EXPECTED TO BE FROM 2" TO 3" ON THE CAP AND FROM $2^{1}/_{2}$ " TO 3" ON THE COLUMNS BASED ON VISUAL INSPECTION.

SEE TITLE SHEET FOR PROJECT CARDINAL DIRECTION DESIGNATION.

FOR CONCRETE AND SHOTCRETE REPAIRS, SEE CONCRETE RESTORATION DETAILS - SUBSTRUCTURE SHEET AND SPECIAL PROVISIONS.


***** QUANTITIES OF CONCRETE REPAIR AREAS ARE ANTICIPATED UNDER BEARING AREAS. DUE TO LACK OF INFORMATION. ALL AREAS ARE NOT KNOWN. QUANTITY INCLUDES CONTINGENCIES AND ARE ANTICIPATED TO BE SUFFICIENT FOR ACTUAL QUANTITIES ENCOUNTERED. FOR CONCRETE REPAIRS SEE CONCRETE RESTORATION DETAILS.

ALL DEFECT QUANTITIES ON STRUTS AND COLUMN FOOTINGS ARE LISTED WITH THE QUANTITIES FOR THE CAP.

SHOTCRETE REPAIRS MAY BE REPLACED WITH CONCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

COAT ALL SURFACE AREAS OF THE TOP OF THE CAP INCLUDING CHAMFERS, WITH EPOXY PROTECTIVE COATING. DO NOT COAT THE AREA UNDER THE ELASTOMERIC BEARINGS.

	PROJEC BF BRIDGE	RUNSI			<u>BPR.1</u> CO	6 UNTY
DocuSigned by: Samad L Column 19C97095C75A467 5/9/2018 2:14: SEAL 043571 5/9/2018 2:14: SEAL 043571	STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH SUBSTRUCTURE CONCRETE REPAIRS BENT 3					
	REVISIONS SHEET NO.					
DOCUMENT NOT CONSIDERED	NO. BY:	DATE:		BY:	DATE:	S-38
FINAL UNLESS ALL SIGNATURES COMPLETED	1		3 4			TOTAL SHEETS 73



User:jduke

AS-BUILT REPAIR QUANTITY TABLE						
BENT 4		QUANT	ITIES			
DEINI 4	ESTI	ΜΑΤΕ	ACT	UAL		
SHOTCRETE REPAIRS	AREA SQ.FT.	VOLUME CU.FT.	AREA SQ.FT.	VOLUME CU.FT.		
САР	39.1	19.6				
COLUMN/PILE	5.6	2.8				
CONCRETE REPAIRS	AREA SQ.FT.	VOLUME CU.FT.	AREA SQ.FT.	VOLUME CU.FT.		
САР	5.9	2.9				
EPOXY RESIN INJECTION		LIN.FT.		LIN.FT.		
САР		3.8				
COLUMN/PILE		9.3				
VALUES IN CUART DEPRESENT ES						

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE. MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2"CLEARANCE TO SAWCUT.FOR REPAIR DETAILS, SEE "CONCRETE RESTORATION DETAILS - SUBSTRUCTURE" SHEET.

NOTES:

REPAIR LOCATIONS AND ESTIMATED QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE AS-BUILT REPAIR QUANTITY TABLE.

CONCRETE COVER FOR EXTERIOR BARS IN THE CAP IS 3" ON THE BOTTOM FACE, 2"ELSEWHERE, AND 3" ON THE COLUMNS PER EXISTING BRIDGE PLANS. ACTUAL CONCRETE COVER SHALL BE DETERMINED BY THE CONTRACTOR AND PRESENTED TO THE ENGINEER PRIOR TO BEGINNING SCARIFICATION.

CURRENT AVERAGE COVER IS EXPECTED TO BE FROM 2" TO 3" ON THE CAP AND FROM $2^{1}/_{2}$ " TO 3" ON THE COLUMNS BASED ON VISUAL INSPECTION.

SEE TITLE SHEET FOR PROJECT CARDINAL DIRECTION DESIGNATION.

FOR CONCRETE AND SHOTCRETE REPAIRS, SEE CONCRETE RESTORATION DETAILS - SUBSTRUCTURE SHEET AND SPECIAL PROVISIONS.

***** QUANTITIES OF CONCRETE REPAIR AREAS ARE ANTICIPATED UNDER BEARING AREAS. DUE TO LACK OF INFORMATION, ALL AREAS ARE NOT KNOWN. QUANTITY INCLUDES CONTINGENCIES AND ARE ANTICIPATED TO BE SUFFICIENT FOR ACTUAL QUANTITIES ENCOUNTERED. FOR CONCRETE REPAIRS SEE CONCRETE RESTORATION DETAILS.

ALL DEFECT QUANTITIES ON STRUTS AND COLUMN FOOTINGS ARE LISTED WITH THE QUANTITIES FOR THE CAP.


SHOTCRETE REPAIRS MAY BE REPLACED WITH CONCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

COAT ALL SURFACE AREAS OF THE TOP OF THE CAP INCLUDING CHAMFERS, WITH EPOXY PROTECTIVE COATING. DO NOT COAT THE AREA UNDER THE ELASTOMERIC BEARINGS.

	PROJEC BF BRIDGE	RUNSI		СК	<u>BPR.1</u> CO 71	6 UNTY
DocuSigned by: Samuel L Culturn 19C97095C75A467 5/9/2018 2:14 SEAL 043571 5/9/2018 2:14	STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH SUBSTRUCTURE CONCRETE REPAIRS BENT 4					
	REVISIONS SHEET NO.					
DOCUMENT NOT CONSIDERED	NO. BY:	DATE:	NO.	BY:	DATE:	S-39
FINAL UNLESS ALL SIGNATURES COMPLETED	1 2		3 4			TOTAL SHEETS 73

+

_



G:\4201720.03-Brunswick-71\Structures\401_215_15BPR.16_SMU_B05_S-40_090071.dgn User:jduke

AS-BUILT REPAIR QUANTITY TABLE							
BENT 5		QUANT	ITIES				
DENIJ	ESTI	ΜΑΤΕ	ACT	UAL			
SHOTCRETE REPAIRS	AREA SQ.FT.	VOLUME CU.FT.	AREA SQ.FT.	VOLUME CU.FT.			
САР	75.0	37.5					
COLUMN/PILE	16.0	8.0					
CONCRETE REPAIRS	AREA SQ.FT.	VOLUME CU.FT.	AREA SQ.FT.	VOLUME CU.FT.			
САР	11.3	5.6					
EPOXY RESIN INJECTION		LIN.FT.		LIN.FT.			
САР		16.5					
COLUMN/PILE		-					
VALUES IN CUART DEPRESENT ES							

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE. MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2"CLEARANCE TO SAWCUT.FOR REPAIR DETAILS, SEE "CONCRETE RESTORATION DETAILS - SUBSTRUCTURE" SHEET.

NOTES:

REPAIR LOCATIONS AND ESTIMATED QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE AS-BUILT REPAIR QUANTITY TABLE.

CONCRETE COVER FOR EXTERIOR BARS IN THE CAP IS 3" ON THE BOTTOM FACE, 2"ELSEWHERE, AND 3" ON THE COLUMNS PER EXISTING BRIDGE PLANS. ACTUAL CONCRETE COVER SHALL BE DETERMINED BY THE CONTRACTOR AND PRESENTED TO THE ENGINEER PRIOR TO BEGINNING SCARIFICATION.

CURRENT AVERAGE COVER IS EXPECTED TO BE FROM 2" TO 3" ON THE CAP AND FROM $2^{1}/_{2}$ " TO 3" ON THE COLUMNS BASED ON VISUAL INSPECTION.

SEE TITLE SHEET FOR PROJECT CARDINAL DIRECTION DESIGNATION.

FOR CONCRETE AND SHOTCRETE REPAIRS, SEE CONCRETE RESTORATION DETAILS - SUBSTRUCTURE SHEET AND SPECIAL PROVISIONS.


***** OUANTITIES OF CONCRETE REPAIR AREAS ARE ANTICIPATED UNDER BEARING AREAS. DUE TO LACK OF INFORMATION, ALL AREAS ARE NOT KNOWN. QUANTITY INCLUDES CONTINGENCIES AND ARE ANTICIPATED TO BE SUFFICIENT FOR ACTUAL QUANTITIES ENCOUNTERED. FOR CONCRETE REPAIRS SEE CONCRETE RESTORATION DETAILS.

ALL DEFECT QUANTITIES ON STRUTS AND COLUMN FOOTINGS ARE LISTED WITH THE QUANTITIES FOR THE CAP.

SHOTCRETE REPAIRS MAY BE REPLACED WITH CONCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

COAT ALL SURFACE AREAS OF THE TOP OF THE CAP INCLUDING CHAMFERS, WITH EPOXY PROTECTIVE COATING. DO NOT COAT THE AREA UNDER THE ELASTOMERIC BEARINGS.

	PROJEC BF BRIDGE	RUNSI			CO	6 UNTY
DocuSigned by: Samuel L Culturn 19C97095C75A467 5/9/2018 2:14:57000 5/9/2018 2:14:570000 5/9/2018 2:14:570000 5/9/2018 2:14:570000 5/9/2018 2:14:570000 5/9/2018 2:14:5700000 5/9/2018 2:14:57000000000000000000000000000000000000	STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH SUBSTRUCTURE CONCRETE REPAIRS BENT 5					
		REVI	SIONS			SHEET NO.
DOCUMENT NOT CONSIDERED	NO. BY:	DATE:		3Y:	DATE:	S-40
FINAL UNLESS ALL SIGNATURES COMPLETED	1 2		3 4			total Sheets 73



G:\4201720.03-Brunswick-71\Structures\401_220_15BPR.16_SMU_B06_S-41_090071.dgn User:jduke

AS-BUILT REPAIR QUANTITY TABLE								
		QUANT	ITIES					
BENT 6	ESTI	ΜΑΤΕ	ACT	UAL				
SHOTCRETE REPAIRS	AREA SQ.FT.	VOLUME CU.FT.	AREA SQ.FT.	VOLUME CU.FT.				
САР	108.5	54.3						
COLUMN/PILE	-	-						
CONCRETE REPAIRS	AREA SQ.FT.	VOLUME CU.FT.	AREA SQ.FT.	VOLUME CU.FT.				
САР	16.3	8.1						
EPOXY RESIN INJECTION		LIN.FT.		LIN.FT.				
САР		1.8						
COLUMN/PILE		_						
		VALUES IN CUART REPRESENT ESTIMATED REPAIR TOTALS AFTER						

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE. MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2"CLEARANCE TO SAWCUT.FOR REPAIR DETAILS. SEE "CONCRETE RESTORATION DETAILS - SUBSTRUCTURE" SHEET.

NOTES:

REPAIR LOCATIONS AND ESTIMATED QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER. THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE AS-BUILT REPAIR QUANTITY TABLE.

CONCRETE COVER FOR EXTERIOR BARS IN THE CAP IS 3" ON THE BOTTOM FACE, 2"ELSEWHERE, AND 3" ON THE COLUMNS PER EXISTING BRIDGE PLANS. ACTUAL CONCRETE COVER SHALL BE DETERMINED BY THE CONTRACTOR AND PRESENTED TO THE ENGINEER PRIOR TO BEGINNING SCARIFICATION.

CURRENT AVERAGE COVER IS EXPECTED TO BE FROM 2" TO 3" ON THE CAP AND FROM $2^{1}/_{2}$ " TO 3" ON THE COLUMNS BASED ON VISUAL INSPECTION.

SEE TITLE SHEET FOR PROJECT CARDINAL DIRECTION DESIGNATION.

FOR CONCRETE AND SHOTCRETE REPAIRS, SEE CONCRETE RESTORATION DETAILS - SUBSTRUCTURE SHEET AND SPECIAL PROVISIONS.


***** OUANTITIES OF CONCRETE REPAIR AREAS ARE ANTICIPATED UNDER BEARING AREAS. DUE TO LACK OF INFORMATION. ALL AREAS ARE NOT KNOWN. QUANTITY INCLUDES CONTINGENCIES AND ARE ANTICIPATED TO BE SUFFICIENT FOR ACTUAL QUANTITIES ENCOUNTERED. FOR CONCRETE REPAIRS SEE CONCRETE RESTORATION DETAILS.

ALL DEFECT QUANTITIES ON STRUTS AND COLUMN FOOTINGS ARE LISTED WITH THE QUANTITIES FOR THE CAP.

SHOTCRETE REPAIRS MAY BE REPLACED WITH CONCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

COAT ALL SURFACE AREAS OF THE TOP OF THE CAP INCLUDING CHAMFERS, WITH EPOXY PROTECTIVE COATING. DO NOT COAT THE AREA UNDER THE ELASTOMERIC BEARINGS.

	PROJEC BF BRIDGE	RUNSI		5BPR.1 cc 71	6 DUNTY
DocuSigned by: Samad L Column 19C97095C75A467 5/9/2018 2:14:50000 5/9/2018 2:14:50000 5/9/2018 2:14:500000 5/9/2018 2:14:500000000000000000000000000000000000		SUBS		ANSPORTA CTURE REPAI	
		REVIS	SIONS		SHEET NO.
DOCUMENT NOT CONSIDERED	NO. BY:	DATE:	NO. BY:	DATE:	S-41
FINAL UNLESS ALL SIGNATURES COMPLETED	1 2		3 4		total sheets 73



G:\4201720.03-Brunswick-71\Structures\401_225_15BPR.16_SMU_B07_S-42_090071.dgn User:jduke

AS-BUILT REPAIR QUANTITY TABLE							
BENT 7		QUANT	ITIES				
DEINI	ESTI	ΜΑΤΕ	ACT	UAL			
SHOTCRETE REPAIRS	AREA SQ.FT.	VOLUME CU.FT.	AREA SQ.FT.	VOLUME CU.FT.			
САР	45.9	23.0					
COLUMN/PILE	12.3	6.1					
CONCRETE REPAIRS	AREA SQ.FT.	VOLUME CU.FT.	AREA SQ.FT.	VOLUME CU.FT.			
САР	6.9	3.4					
EPOXY RESIN INJECTION		LIN.FT.		LIN.FT.			
САР		2.5					
COLUMN/PILE		42.0					
VALUES TN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER							

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE.MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2"CLEARANCE TO SAWCUT.FOR REPAIR DETAILS, SEE "CONCRETE RESTORATION DETAILS - SUBSTRUCTURE" SHEET.

NOTES:

REPAIR LOCATIONS AND ESTIMATED QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE AS-BUILT REPAIR QUANTITY TABLE.

CONCRETE COVER FOR EXTERIOR BARS IN THE CAP IS 3" ON THE BOTTOM FACE, 2"ELSEWHERE, AND 3" ON THE COLUMNS PER EXISTING BRIDGE PLANS. ACTUAL CONCRETE COVER SHALL BE DETERMINED BY THE CONTRACTOR AND PRESENTED TO THE ENGINEER PRIOR TO BEGINNING SCARIFICATION.

CURRENT AVERAGE COVER IS EXPECTED TO BE FROM 2" TO 3" ON THE CAP AND FROM $2^{1}/_{2}$ " TO 3" ON THE COLUMNS BASED ON VISUAL INSPECTION.

SEE TITLE SHEET FOR PROJECT CARDINAL DIRECTION DESIGNATION.

FOR CONCRETE AND SHOTCRETE REPAIRS, SEE CONCRETE RESTORATION DETAILS - SUBSTRUCTURE SHEET AND SPECIAL PROVISIONS.


* QUANTITIES OF CONCRETE REPAIR AREAS ARE ANTICIPATED UNDER BEARING AREAS.DUE TO LACK OF INFORMATION, ALL AREAS ARE NOT KNOWN.QUANTITY INCLUDES CONTINGENCIES AND ARE ANTICIPATED TO BE SUFFICIENT FOR ACTUAL QUANTITIES ENCOUNTERED.FOR CONCRETE REPAIRS SEE CONCRETE RESTORATION DETAILS.

ALL DEFECT QUANTITIES ON STRUTS AND COLUMN FOOTINGS ARE LISTED WITH THE QUANTITIES FOR THE CAP.

SHOTCRETE REPAIRS MAY BE REPLACED WITH CONCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

COAT ALL SURFACE AREAS OF THE TOP OF THE CAP INCLUDING CHAMFERS, WITH EPOXY PROTECTIVE COATING. DO NOT COAT THE AREA UNDER THE ELASTOMERIC BEARINGS.

	PROJEC BF BRIDGE	RUNSI	NIC	15BPR.1 K co 71	. <u>6</u> DUNTY
DocuSigned by: Samad L Column 19C97095C75A467 5/9/2018 2:14:50 Point SEAL 043571 5/9/2018 2:14:50 Point Schult EL L Column		SUBS	OF T RALEI	JCTURE REPAI	
		REVI	SIONS		SHEET NO.
DOCUMENT NOT CONSIDERED	NO. BY:	DATE:	NO. BY	DATE:	S-42
FINAL UNLESS ALL SIGNATURES COMPLETED	1		3 4		TOTAL SHEETS 73



AS-BUILT REPAIR QUANTITY TABLE							
BENT 8		QUANT	ITIES				
DEINIO	ESTI	ΜΑΤΕ	ACT	UAL			
SHOTCRETE REPAIRS	AREA SQ.FT.	VOLUME CU.FT.	AREA SQ.FT.	VOLUME CU.FT.			
САР	22.6	11.3					
COLUMN/PILE	169.0	84.5					
CONCRETE REPAIRS	AREA SQ.FT.	VOLUME CU.FT.	AREA SQ.FT.	VOLUME CU.FT.			
САР	3.4	1.7					
EPOXY RESIN INJECTION		LIN.FT.		LIN.FT.			
САР		-					
COLUMN/PILE		37 . 5					
VALUES TN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER							

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE.MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2"CLEARANCE TO SAWCUT.FOR REPAIR DETAILS, SEE "CONCRETE RESTORATION DETAILS - SUBSTRUCTURE" SHEET.

NOTES:

REPAIR LOCATIONS AND ESTIMATED QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE AS-BUILT REPAIR QUANTITY TABLE.

CONCRETE COVER FOR EXTERIOR BARS IN THE CAP IS 3" ON THE BOTTOM FACE, 2"ELSEWHERE, AND 3" ON THE COLUMNS PER EXISTING BRIDGE PLANS. ACTUAL CONCRETE COVER SHALL BE DETERMINED BY THE CONTRACTOR AND PRESENTED TO THE ENGINEER PRIOR TO BEGINNING SCARIFICATION.

CURRENT AVERAGE COVER IS EXPECTED TO BE FROM 2" TO 3" ON THE CAP AND FROM $2^{1}/_{2}$ " TO 3" ON THE COLUMNS BASED ON VISUAL INSPECTION.

SEE TITLE SHEET FOR PROJECT CARDINAL DIRECTION DESIGNATION.

FOR CONCRETE AND SHOTCRETE REPAIRS, SEE CONCRETE RESTORATION DETAILS - SUBSTRUCTURE SHEET AND SPECIAL PROVISIONS.


* QUANTITIES OF CONCRETE REPAIR AREAS ARE ANTICIPATED UNDER BEARING AREAS.DUE TO LACK OF INFORMATION, ALL AREAS ARE NOT KNOWN.QUANTITY INCLUDES CONTINGENCIES AND ARE ANTICIPATED TO BE SUFFICIENT FOR ACTUAL QUANTITIES ENCOUNTERED.FOR CONCRETE REPAIRS SEE CONCRETE RESTORATION DETAILS.

ALL DEFECT QUANTITIES ON STRUTS AND COLUMN FOOTINGS ARE LISTED WITH THE QUANTITIES FOR THE CAP.

SHOTCRETE REPAIRS MAY BE REPLACED WITH CONCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

COAT ALL SURFACE AREAS OF THE TOP OF THE CAP INCLUDING CHAMFERS, WITH EPOXY PROTECTIVE COATING. DO NOT COAT THE AREA UNDER THE ELASTOMERIC BEARINGS.

BI	RUNSI	NICK		6 DUNTY
	SUBS NCRE	OF TR RALEIGH	ANSPORTA CTURE REPAI	
	REVI	SIONS		SHEET NO.
NO. BY:	DATE:	NO. BY:	DATE:	S-43
1		3 4		TOTAL SHEETS 73
		BRUNS BRIDGE NO DEPARTMENT SUBS CONCRE E NO. BY: DATE: 1	BRIDGE NO. BRIDGE NO. DEPARTMENT OF TR RALEIGH SUBSTRU CONCRETE BENT REVISIONS NO. BY: DATE: NO. BY: 1	BRUNSWICK BRIDGE NO. 71 DEPARTMENT OF TRANSPORTA RALEIGH SUBSTRUCTURE CONCRETE REPAI BENT 8 REVISIONS



G:\4201720.03-Brunswick-71\Structures\401_235_15BPR.16_SMU_B09_S-44_090071.dgn User:jduke

AS-BUILT REPAIR QUANTITY TABLE						
BENT 9		QUANT	ITIES			
DEINI 9	ESTI	ΜΑΤΕ	ACT	UAL		
SHOTCRETE REPAIRS	AREA SQ.FT.	VOLUME CU.FT.	AREA SQ.FT.	VOLUME CU.FT.		
САР	132.9	66.5				
COLUMN/PILE	123.7	61.8				
CONCRETE REPAIRS	AREA SQ.FT.	VOLUME CU.FT.	AREA SQ.FT.	VOLUME CU.FT.		
САР	19.9	10.0				
EPOXY RESIN INJECTION		LIN.FT.		LIN.FT.		
САР		_				
COLUMN/PILE		-				
VALUES TN CHART REPRESENT ESTTMATED REPATR TOTALS AFTER						

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE. MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2"CLEARANCE TO SAWCUT.FOR REPAIR DETAILS, SEE "CONCRETE RESTORATION DETAILS - SUBSTRUCTURE" SHEET.

NOTES:

REPAIR LOCATIONS AND ESTIMATED QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE AS-BUILT REPAIR QUANTITY TABLE.

CONCRETE COVER FOR EXTERIOR BARS IN THE CAP IS 3" ON THE BOTTOM FACE, 2"ELSEWHERE, AND 3" ON THE COLUMNS PER EXISTING BRIDGE PLANS. ACTUAL CONCRETE COVER SHALL BE DETERMINED BY THE CONTRACTOR AND PRESENTED TO THE ENGINEER PRIOR TO BEGINNING SCARIFICATION.

CURRENT AVERAGE COVER IS EXPECTED TO BE FROM 2" TO 3" ON THE CAP AND FROM $2^{1}/_{2}$ " TO 3" ON THE COLUMNS BASED ON VISUAL INSPECTION.

SEE TITLE SHEET FOR PROJECT CARDINAL DIRECTION DESIGNATION.

FOR CONCRETE AND SHOTCRETE REPAIRS, SEE CONCRETE RESTORATION DETAILS - SUBSTRUCTURE SHEET AND SPECIAL PROVISIONS.


* QUANTITIES OF CONCRETE REPAIR AREAS ARE ANTICIPATED UNDER BEARING AREAS.DUE TO LACK OF INFORMATION, ALL AREAS ARE NOT KNOWN.QUANTITY INCLUDES CONTINGENCIES AND ARE ANTICIPATED TO BE SUFFICIENT FOR ACTUAL QUANTITIES ENCOUNTERED.FOR CONCRETE REPAIRS SEE CONCRETE RESTORATION DETAILS.

ALL DEFECT QUANTITIES ON STRUTS AND COLUMN FOOTINGS ARE LISTED WITH THE QUANTITIES FOR THE CAP.

SHOTCRETE REPAIRS MAY BE REPLACED WITH CONCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

COAT ALL SURFACE AREAS OF THE TOP OF THE CAP INCLUDING CHAMFERS, WITH EPOXY PROTECTIVE COATING. DO NOT COAT THE AREA UNDER THE ELASTOMERIC BEARINGS.

	PROJEC BF BRIDGE	RUNSI		5 <u>BPR.1</u> co 71	6 UNTY
DocuSigned by: Samad L Column 19C97095C75A467 5/9/2018 2:14: SEAL 043571 5/9/2018 2:14: SEAL 043571		SUBS		ANSPORTA CTURE REPAI	
		REVIS	SIONS		SHEET NO.
DOCUMENT NOT CONSIDERED	NO. BY:	DATE:	NO. BY:	DATE:	S-44
FINAL UNLESS ALL SIGNATURES COMPLETED	1 2		3 4		total sheets 73



G:\4201720.03-Brunswick-71\Structures\401_240_15BPR.16_SMU_B10_S-45_090071.dgn User:jduke

AS-BUILT REPAIR QUANTITY TABLE								
BENT 10		QUANT	ITIES					
DENT IU	ESTI	ΜΑΤΕ	ACT	UAL				
SHOTCRETE REPAIRS	AREA SQ.FT.	VOLUME CU.FT.	AREA SQ.FT.	VOLUME CU.FT.				
САР	21.6	10.8						
COLUMN/PILE	6.0	3.0						
CONCRETE REPAIRS	AREA SQ.FT.	VOLUME CU.FT.	AREA SQ.FT.	VOLUME CU.FT.				
САР	13.5	6.8						
EPOXY RESIN INJECTION		LIN.FT.		LIN.FT.				
САР		-						
COLUMN/PILE		-						

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE.MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2"CLEARANCE TO SAWCUT.FOR REPAIR DETAILS, SEE "CONCRETE RESTORATION DETAILS - SUBSTRUCTURE" SHEET.

NOTES:

REPAIR LOCATIONS AND ESTIMATED QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE AS-BUILT REPAIR QUANTITY TABLE.

CONCRETE COVER FOR EXTERIOR BARS IN THE CAP IS 3" ON THE BOTTOM FACE, 2"ELSEWHERE, AND 3" ON THE COLUMNS PER EXISTING BRIDGE PLANS. ACTUAL CONCRETE COVER SHALL BE DETERMINED BY THE CONTRACTOR AND PRESENTED TO THE ENGINEER PRIOR TO BEGINNING SCARIFICATION.

CURRENT AVERAGE COVER IS EXPECTED TO BE FROM 2" TO 3" ON THE CAP AND FROM $2^{1}/_{2}$ " TO 3" ON THE COLUMNS BASED ON VISUAL INSPECTION.

SEE TITLE SHEET FOR PROJECT CARDINAL DIRECTION DESIGNATION.

FOR CONCRETE AND SHOTCRETE REPAIRS, SEE CONCRETE RESTORATION DETAILS - SUBSTRUCTURE SHEET AND SPECIAL PROVISIONS.

* OUANTITIES OF CONCRETE REPAIR AREAS ARE ANTICIPATED UNDER BEARING AREAS.DUE TO LACK OF INFORMATION, ALL AREAS ARE NOT KNOWN. QUANTITY INCLUDES CONTINGENCIES AND ARE ANTICIPATED TO BE SUFFICIENT FOR ACTUAL QUANTITIES ENCOUNTERED.FOR CONCRETE REPAIRS SEE CONCRETE RESTORATION DETAILS.

ALL DEFECT QUANTITIES ON STRUTS AND COLUMN FOOTINGS ARE LISTED WITH THE QUANTITIES FOR THE CAP.


SHOTCRETE REPAIRS MAY BE REPLACED WITH CONCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

COAT ALL SURFACE AREAS OF THE TOP OF THE CAP INCLUDING CHAMFERS, WITH EPOXY PROTECTIVE COATING. DO NOT COAT THE AREA UNDER THE ELASTOMERIC BEARINGS.

	PROJEC BF BRIDGE	RUNSV		<u>.5BPR.1</u> <cc 71</cc 	<u>6</u> DUNTY
DocuSigned by: Samuel L Column 19C97095C75A467 5/9/2018 2:14:57000 5/9/2018 2:14:57000 5/9/2018 2:14:570000 5/9/2018 2:14:570000 5/9/2018 2:14:57000000000000000000000000000000000000		rtment SUBS NCRE	RALEIG	RANSPORTA UCTURE REPAI	
		REVIS	SIONS		SHEET NO.
DOCUMENT NOT CONSIDERED	NO. BY:	DATE:	NO. BY:	DATE:	S-45
FINAL UNLESS ALL SIGNATURES COMPLETED	1		3		TOTAL SHEETS
SIGNATURES COMPLETED	2		4		73

-

User:jduke



AS-BUILT REPAIR QUANTITY TABLE							
BENT 11		QUANT	ITIES				
DENTI	ESTI	ΜΑΤΕ	ACT	UAL			
SHOTCRETE REPAIRS	AREA SQ.FT.	VOLUME CU.FT.	AREA SQ.FT.	VOLUME CU.FT.			
САР	-	-					
COLUMN/PILE	4.2	2.1					
CONCRETE REPAIRS	AREA SQ.FT.	VOLUME CU.FT.	AREA SQ.FT.	VOLUME CU.FT.			
САР	-	-					
EPOXY RESIN INJECTION		LIN.FT.		LIN.FT.			
САР		49.5					
COLUMN/PILE		-					

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE.MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2"CLEARANCE TO SAWCUT.FOR REPAIR DETAILS, SEE "CONCRETE RESTORATION DETAILS - SUBSTRUCTURE" SHEET.

NOTES:

REPAIR LOCATIONS AND ESTIMATED QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE AS-BUILT REPAIR QUANTITY TABLE.

CONCRETE COVER FOR EXTERIOR BARS IN THE CAP IS 3" ON THE BOTTOM FACE, 2"ELSEWHERE, AND 3" ON THE COLUMNS PER EXISTING BRIDGE PLANS. ACTUAL CONCRETE COVER SHALL BE DETERMINED BY THE CONTRACTOR AND PRESENTED TO THE ENGINEER PRIOR TO BEGINNING SCARIFICATION.

CURRENT AVERAGE COVER IS EXPECTED TO BE FROM 2" TO 3" ON THE CAP AND FROM $2^{1}/_{2}$ " TO 3" ON THE COLUMNS BASED ON VISUAL INSPECTION.

SEE TITLE SHEET FOR PROJECT CARDINAL DIRECTION DESIGNATION.

FOR CONCRETE AND SHOTCRETE REPAIRS, SEE CONCRETE RESTORATION DETAILS - SUBSTRUCTURE SHEET AND SPECIAL PROVISIONS.

***** QUANTITIES OF CONCRETE REPAIR AREAS ARE ANTICIPATED UNDER BEARING AREAS. DUE TO LACK OF INFORMATION, ALL AREAS ARE NOT KNOWN. QUANTITY INCLUDES CONTINGENCIES AND ARE ANTICIPATED TO BE SUFFICIENT FOR ACTUAL QUANTITIES ENCOUNTERED. FOR CONCRETE REPAIRS SEE CONCRETE RESTORATION DETAILS.

ALL DEFECT QUANTITIES ON STRUTS AND COLUMN FOOTINGS ARE LISTED WITH THE QUANTITIES FOR THE CAP.

SHOTCRETE REPAIRS MAY BE REPLACED WITH CONCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.


COAT ALL SURFACE AREAS OF THE TOP OF THE CAP INCLUDING CHAMFERS, WITH EPOXY PROTECTIVE COATING. DO NOT COAT THE AREA UNDER THE ELASTOMERIC BEARINGS.

	PROJEC BF BRIDGE	RUNSI		5 <u>BPR.1</u> CO 71	6 UNTY
DocuSigned by: Samuel L Column 19C97095C75A467 5/9/2018 2:14: SEAL 043571 5/9/2018 2:14: SEAL 043571		tion RS			
		REVIS	SIONS		SHEET NO.
DOCUMENT NOT CONSIDERED	NO. BY:	DATE:	NO. BY:	DATE:	S-46
FINAL UNLESS ALL SIGNATURES COMPLETED	1 2		3 4		TOTAL SHEETS 73
STONATONES COMPLETED	ß		(4)		73

+

-

User:jduke



AS-BUILT REPA	IR QL	JANTI	TY TA	ABLE
BENT 12		QUANT	ITIES	
DEINI IZ	ESTI	ΜΑΤΕ	ACT	UAL
SHOTCRETE REPAIRS	AREA SQ.FT.	VOLUME CU.FT.	AREA SQ.FT.	VOLUME CU.FT.
САР	-	-		
COLUMN/PILE	12.0	6.0		
CONCRETE REPAIRS	AREA SQ.FT.	VOLUME CU.FT.	AREA SQ.FT.	VOLUME CU.FT.
САР	1.5	0.8		
EPOXY RESIN INJECTION		LIN.FT.		LIN.FT.
САР		-		
COLUMN/PILE		-		
VALUES TH CUART DEPRESENT FO				

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE.MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2"CLEARANCE TO SAWCUT.FOR REPAIR DETAILS, SEE "CONCRETE RESTORATION DETAILS - SUBSTRUCTURE" SHEET.

NOTES:

REPAIR LOCATIONS AND ESTIMATED QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE AS-BUILT REPAIR QUANTITY TABLE.

CONCRETE COVER FOR EXTERIOR BARS IN THE CAP IS 3" ON THE BOTTOM FACE, 2"ELSEWHERE, AND 3" ON THE COLUMNS PER EXISTING BRIDGE PLANS. ACTUAL CONCRETE COVER SHALL BE DETERMINED BY THE CONTRACTOR AND PRESENTED TO THE ENGINEER PRIOR TO BEGINNING SCARIFICATION.

CURRENT AVERAGE COVER IS EXPECTED TO BE FROM 2" TO 3" ON THE CAP AND FROM $2^{1}/_{2}$ " TO 3" ON THE COLUMNS BASED ON VISUAL INSPECTION.

SEE TITLE SHEET FOR PROJECT CARDINAL DIRECTION DESIGNATION.

FOR CONCRETE AND SHOTCRETE REPAIRS, SEE CONCRETE RESTORATION DETAILS - SUBSTRUCTURE SHEET AND SPECIAL PROVISIONS.

***** QUANTITIES OF CONCRETE REPAIR AREAS ARE ANTICIPATED UNDER BEARING AREAS. DUE TO LACK OF INFORMATION, ALL AREAS ARE NOT KNOWN. QUANTITY INCLUDES CONTINGENCIES AND ARE ANTICIPATED TO BE SUFFICIENT FOR ACTUAL QUANTITIES ENCOUNTERED. FOR CONCRETE REPAIRS SEE CONCRETE RESTORATION DETAILS.


ALL DEFECT QUANTITIES ON STRUTS AND COLUMN FOOTINGS ARE LISTED WITH THE QUANTITIES FOR THE CAP.

SHOTCRETE REPAIRS MAY BE REPLACED WITH CONCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

COAT ALL SURFACE AREAS OF THE TOP OF THE CAP INCLUDING CHAMFERS, WITH EPOXY PROTECTIVE COATING. DO NOT COAT THE AREA UNDER THE ELASTOMERIC BEARINGS.

	PROJEC BF BRIDGE	RUNSV		5 <u>BPR.1</u> C0 71	6 UNTY	
DocuSigned by: Samuel L Culture 19C97095C75A467. 5/9/2018 2:14:59CP/FELLCULTURE	STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH SUBSTRUCTURE CONCRETE REPAIRS BENT 12					
		REVIS			SHEET NO.	
DOCUMENT NOT CONSIDERED	NO. BY:	DATE:	NO. BY:	DATE:	S-47 TOTAL SHEETS	
FINAL UNLESS ALL SIGNATURES COMPLETED	2		<u>।</u> 4		SHEETS 73	

—



G:\4201720.03-Brunswick-71\Structures\401_255_15BPR.16_SMU_B13_S-48_090071.dgn User:jduke

AS-BUILT REPA	IR QL	JANTI	TY TA	ABLE				
BENT 13		QUANT	ITIES					
DENTIJ	ESTI	ΜΑΤΕ	ACT	UAL				
SHOTCRETE REPAIRS	AREA SQ.FT.	VOLUME CU.FT.	AREA SQ.FT.	VOLUME CU.FT.				
САР	1.6	0.8						
COLUMN/PILE	82.0	41.0						
CONCRETE REPAIRS	AREA SQ.FT.	VOLUME CU.FT.	AREA SQ.FT.	VOLUME CU.FT.				
САР	0.2	0.1						
EPOXY RESIN INJECTION		LIN.FT.		LIN.FT.				
САР		-						
COLUMN/PILE		-						

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE. MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2"CLEARANCE TO SAWCUT.FOR REPAIR DETAILS, SEE "CONCRETE RESTORATION DETAILS - SUBSTRUCTURE" SHEET.

NOTES:

REPAIR LOCATIONS AND ESTIMATED QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE AS-BUILT REPAIR QUANTITY TABLE.

CONCRETE COVER FOR EXTERIOR BARS IN THE CAP IS 3" ON THE BOTTOM FACE, 2"ELSEWHERE, AND 3" ON THE COLUMNS PER EXISTING BRIDGE PLANS. ACTUAL CONCRETE COVER SHALL BE DETERMINED BY THE CONTRACTOR AND PRESENTED TO THE ENGINEER PRIOR TO BEGINNING SCARIFICATION.

CURRENT AVERAGE COVER IS EXPECTED TO BE FROM 2" TO 3" ON THE CAP AND FROM $2^{1}/_{2}$ " TO 3" ON THE COLUMNS BASED ON VISUAL INSPECTION.

SEE TITLE SHEET FOR PROJECT CARDINAL DIRECTION DESIGNATION.

FOR CONCRETE AND SHOTCRETE REPAIRS, SEE CONCRETE RESTORATION DETAILS - SUBSTRUCTURE SHEET AND SPECIAL PROVISIONS.


***** QUANTITIES OF CONCRETE REPAIR AREAS ARE ANTICIPATED UNDER BEARING AREAS. DUE TO LACK OF INFORMATION. ALL AREAS ARE NOT KNOWN. QUANTITY INCLUDES CONTINGENCIES AND ARE ANTICIPATED TO BE SUFFICIENT FOR ACTUAL QUANTITIES ENCOUNTERED. FOR CONCRETE REPAIRS SEE CONCRETE RESTORATION DETAILS.

ALL DEFECT QUANTITIES ON STRUTS AND COLUMN FOOTINGS ARE LISTED WITH THE QUANTITIES FOR THE CAP.

SHOTCRETE REPAIRS MAY BE REPLACED WITH CONCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

COAT ALL SURFACE AREAS OF THE TOP OF THE CAP INCLUDING CHAMFERS, WITH EPOXY PROTECTIVE COATING. DO NOT COAT THE AREA UNDER THE ELASTOMERIC BEARINGS.

	PROJEC BF BRIDGE	RUNSI	VIC	<u>15BPR.1</u> Kcc 71	. <u>6</u> DUNTY	
DocuSigned by: Samad L Calenn 19C97095C75A467 5/9/2018 2:14:597097095C75A467	STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH SUBSTRUCTURE CONCRETE REPAIRS BENT 13					
		REVI	SIONS		SHEET NO.	
DOCUMENT NOT CONSIDERED	NO. BY:	DATE:	NO. BY	: DATE:	S-48	
FINAL UNLESS ALL SIGNATURES COMPLETED	1		3 4		TOTAL SHEETS 73	



G:\4201720.03-Brunswick-71\Structures\401_260_15BPR.16_SMU_B14_S-49_090071.dgn User:jduke

AS-BUILT REPAIR QUANTITY TABLE							
BENT 14		QUANT	ITIES				
DENI 14	ESTI	ΜΑΤΕ	ACT	UAL			
SHOTCRETE REPAIRS	AREA SQ.FT.	VOLUME CU.FT.	AREA SQ.FT.	VOLUME CU.FT.			
САР	16.4	8.2					
COLUMN/PILE	16.7	8.3					
CONCRETE REPAIRS	AREA SQ.FT.	VOLUME CU.FT.	AREA SQ.FT.	VOLUME CU.FT.			
САР	2.5	1.2					
EPOXY RESIN INJECTION		LIN.FT.		LIN.FT.			
САР		1.5					
COLUMN/PILE		5.5					

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE.MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2"CLEARANCE TO SAWCUT.FOR REPAIR DETAILS, SEE "CONCRETE RESTORATION DETAILS - SUBSTRUCTURE" SHEET.

NOTES:

REPAIR LOCATIONS AND ESTIMATED QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE AS-BUILT REPAIR QUANTITY TABLE.

CONCRETE COVER FOR EXTERIOR BARS IN THE CAP IS 3" ON THE BOTTOM FACE, 2"ELSEWHERE, AND 3" ON THE COLUMNS PER EXISTING BRIDGE PLANS. ACTUAL CONCRETE COVER SHALL BE DETERMINED BY THE CONTRACTOR AND PRESENTED TO THE ENGINEER PRIOR TO BEGINNING SCARIFICATION.

CURRENT AVERAGE COVER IS EXPECTED TO BE FROM 2" TO 3" ON THE CAP AND FROM $2^{1}/_{2}$ " TO 3" ON THE COLUMNS BASED ON VISUAL INSPECTION.

SEE TITLE SHEET FOR PROJECT CARDINAL DIRECTION DESIGNATION.

FOR CONCRETE AND SHOTCRETE REPAIRS, SEE CONCRETE RESTORATION DETAILS - SUBSTRUCTURE SHEET AND SPECIAL PROVISIONS.

* QUANTITIES OF CONCRETE REPAIR AREAS ARE ANTICIPATED UNDER BEARING AREAS.DUE TO LACK OF INFORMATION, ALL AREAS ARE NOT KNOWN.QUANTITY INCLUDES CONTINGENCIES AND ARE ANTICIPATED TO BE SUFFICIENT FOR ACTUAL QUANTITIES ENCOUNTERED.FOR CONCRETE REPAIRS SEE CONCRETE RESTORATION DETAILS.

ALL DEFECT QUANTITIES ON STRUTS AND COLUMN FOOTINGS ARE LISTED WITH THE QUANTITIES FOR THE CAP.


SHOTCRETE REPAIRS MAY BE REPLACED WITH CONCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

COAT ALL SURFACE AREAS OF THE TOP OF THE CAP INCLUDING CHAMFERS, WITH EPOXY PROTECTIVE COATING. DO NOT COAT THE AREA UNDER THE ELASTOMERIC BEARINGS.

	PROJEC BF BRIDGE	RUNSI				6 UNTY
DocuSigned by: Samuel L Column 19C97095C75A467 5/9/2018 2:14: SEAL 043571 5/9/2018 2:14: SEAL 043571	STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH SUBSTRUCTURE CONCRETE REPAIRS BENT 14					
		REVI	SIONS			SHEET NO.
DOCUMENT NOT CONSIDERED	NO. BY:	DATE:		Y:	DATE:	S-49
FINAL UNLESS ALL	1		3			TOTAL SHEETS
SIGNATURES COMPLETED	2		4			73

+

—



G:\4201720.03-Brunswick-71\Structures\401_265_15BPR.16_SMU_B15_S-50_090071.dgn User:jduke

AS-BUILT REPAIR QUANTITY TABLE							
	QUANT	ITIES					
ESTI	ΜΑΤΕ	ACT	UAL				
AREA SQ.FT.	VOLUME CU.FT.	AREA SQ.FT.	VOLUME CU.FT.				
116.0	58.0						
-	-						
AREA SQ.FT.	VOLUME CU.FT.	AREA SQ.FT.	VOLUME CU.FT.				
17.4	8.7						
EPOXY RESIN INJECTION			LIN.FT.				
САР							
	5.5						
	ESTI AREA SQ.FT. 116.0 - AREA SQ.FT. 17.4	QUANT ESTIMATE AREA SQ.FT. VOLUME CU.FT. 116.0 58.0 AREA SQ.FT. VOLUME CU.FT. 17.4 8.7 ION LIN.FT. 16.8	QUANTITIESESTIMATEACTAREA SO.FT.VOLUME CU.FT.AREA SO.FT.116.058.0AREA SO.FT.VOLUME CU.FT.AREA SO.FT.17.48.7-IONLIN.FT16.8				

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE.MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2"CLEARANCE TO SAWCUT.FOR REPAIR DETAILS, SEE "CONCRETE RESTORATION DETAILS - SUBSTRUCTURE" SHEET.

NOTES:

REPAIR LOCATIONS AND ESTIMATED QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE AS-BUILT REPAIR QUANTITY TABLE.

CONCRETE COVER FOR EXTERIOR BARS IN THE CAP IS 3" ON THE BOTTOM FACE, 2"ELSEWHERE, AND 3" ON THE COLUMNS PER EXISTING BRIDGE PLANS. ACTUAL CONCRETE COVER SHALL BE DETERMINED BY THE CONTRACTOR AND PRESENTED TO THE ENGINEER PRIOR TO BEGINNING SCARIFICATION.

CURRENT AVERAGE COVER IS EXPECTED TO BE FROM 2" TO 3" ON THE CAP AND FROM $2^{1}/_{2}$ " TO 3" ON THE COLUMNS BASED ON VISUAL INSPECTION.

SEE TITLE SHEET FOR PROJECT CARDINAL DIRECTION DESIGNATION.

FOR CONCRETE AND SHOTCRETE REPAIRS, SEE CONCRETE RESTORATION DETAILS - SUBSTRUCTURE SHEET AND SPECIAL PROVISIONS.

* OUANTITIES OF CONCRETE REPAIR AREAS ARE ANTICIPATED UNDER BEARING AREAS.DUE TO LACK OF INFORMATION, ALL AREAS ARE NOT KNOWN. QUANTITY INCLUDES CONTINGENCIES AND ARE ANTICIPATED TO BE SUFFICIENT FOR ACTUAL QUANTITIES ENCOUNTERED.FOR CONCRETE REPAIRS SEE CONCRETE RESTORATION DETAILS.

ALL DEFECT QUANTITIES ON STRUTS AND COLUMN FOOTINGS ARE LISTED WITH THE QUANTITIES FOR THE CAP.


SHOTCRETE REPAIRS MAY BE REPLACED WITH CONCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

COAT ALL SURFACE AREAS OF THE TOP OF THE CAP INCLUDING CHAMFERS, WITH EPOXY PROTECTIVE COATING. DO NOT COAT THE AREA UNDER THE ELASTOMERIC BEARINGS.

	PROJEC BF BRIDGE	RUNSV		5 <u>BPR.1</u> cc 71	6 OUNTY
DocuSigned by: Samuel L Column 19C97095C75A467 5/9/2018 2:14: SEAL 043571 5/9/2018 2:14: SEAL 043571		tion RS			
		REVIS	SIONS		SHEET NO.
DOCUMENT NOT CONSIDERED	NO. BY:	DATE:	NO. BY:	DATE:	S-50
FINAL UNLESS ALL SIGNATURES COMPLETED	1 2		3 4		TOTAL SHEETS 73

+

_



G:\4201720.03-Brunswick-71\Structures\401_270_15BPR.16_SMU_B16_S-51_090071.dgn User:jduke

AS-BUILT REPAIR QUANTITY TABLE							
	QUANT	ITIES					
ESTI	ΜΑΤΕ	ACT	UAL				
AREA SQ.FT.	VOLUME CU.FT.	AREA SQ.FT.	VOLUME CU.FT.				
21.0	10.5						
25 . 5	12.8						
AREA SQ.FT.	VOLUME CU.FT.	AREA SQ.FT.	VOLUME CU.FT.				
3.2	1.6						
EPOXY RESIN INJECTION			LIN.FT.				
САР							
	18.0						
	ESTI AREA SQ.FT. 21.0 25.5 AREA SQ.FT. 3.2	QUANT ESTIMATE AREA SQ.FT. VOLUME CU.FT. 21.0 10.5 25.5 12.8 AREA SQ.FT. VOLUME CU.FT. 3.2 1.6 ION LIN.FT. 12.0	QUANTITIESESTIMATEACTAREA SO.FT.VOLUME CU.FT.AREA SO.FT.21.010.5				

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE. MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2"CLEARANCE TO SAWCUT.FOR REPAIR DETAILS. SEE "CONCRETE RESTORATION DETAILS - SUBSTRUCTURE" SHEET.

NOTES:

REPAIR LOCATIONS AND ESTIMATED QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER. THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE AS-BUILT REPAIR QUANTITY TABLE.

CONCRETE COVER FOR EXTERIOR BARS IN THE CAP IS 3" ON THE BOTTOM FACE, 2"ELSEWHERE, AND 3" ON THE COLUMNS PER EXISTING BRIDGE PLANS. ACTUAL CONCRETE COVER SHALL BE DETERMINED BY THE CONTRACTOR AND PRESENTED TO THE ENGINEER PRIOR TO BEGINNING SCARIFICATION.

CURRENT AVERAGE COVER IS EXPECTED TO BE FROM 2" TO 3" ON THE CAP AND FROM $2^{1}/_{2}$ " TO 3" ON THE COLUMNS BASED ON VISUAL INSPECTION.

SEE TITLE SHEET FOR PROJECT CARDINAL DIRECTION DESIGNATION.

FOR CONCRETE AND SHOTCRETE REPAIRS, SEE CONCRETE RESTORATION DETAILS - SUBSTRUCTURE SHEET AND SPECIAL PROVISIONS.

***** OUANTITIES OF CONCRETE REPAIR AREAS ARE ANTICIPATED UNDER BEARING AREAS. DUE TO LACK OF INFORMATION. ALL AREAS ARE NOT KNOWN. QUANTITY INCLUDES CONTINGENCIES AND ARE ANTICIPATED TO BE SUFFICIENT FOR ACTUAL QUANTITIES ENCOUNTERED. FOR CONCRETE REPAIRS SEE CONCRETE RESTORATION DETAILS.


ALL DEFECT QUANTITIES ON STRUTS AND COLUMN FOOTINGS ARE LISTED WITH THE QUANTITIES FOR THE CAP.

SHOTCRETE REPAIRS MAY BE REPLACED WITH CONCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

COAT ALL SURFACE AREAS OF THE TOP OF THE CAP INCLUDING CHAMFERS, WITH EPOXY PROTECTIVE COATING. DO NOT COAT THE AREA UNDER THE ELASTOMERIC BEARINGS.

	PROJEC BF BRIDGE	RUNSV	VIC	CK		6 UNTY
DocuSigned by: Samuel L Column 19C97095C75A467 5/9/2018 2:14:50000 5/9/2018 2:14:50000 5/9/2018 2:14:500000 5/9/2018 2:14:500000000000000000000000000000000000	STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATIO RALEIGH SUBSTRUCTURE CONCRETE REPAIRS BENT 16					
		REVIS	SIONS			SHEET NO.
DOCUMENT NOT CONSIDERED	NO. BY:	DATE:		BY:	DATE:	S-51
FINAL UNLESS ALL SIGNATURES COMPLETED	1 2		3 4			total Sheets 73

_



G:\4201720.03-Brunswick-71\Structures\401_275_15BPR.16_SMU_B17_S-52_090071.dgn User:jduke

AS-BUILT REPAIR QUANTITY TABLE							
BENT 17		QUANT	ITIES				
DENT IT ESTIN		ΜΑΤΕ	ACTUAL				
SHOTCRETE REPAIRS	AREA SQ.FT.	VOLUME CU.FT.	AREA SQ.FT.	VOLUME CU.FT.			
САР	27.7	13.9					
COLUMN/PILE	11.3	5.7					
CONCRETE REPAIRS	AREA SQ.FT.	VOLUME CU.FT.	AREA SQ.FT.	VOLUME CU.FT.			
CAP 4.2		2.1					
EPOXY RESIN INJECT	LIN.FT.		LIN.FT.				
САР		8.0					
COLUMN/PILE		38.0					
			-	-			

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE. MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2"CLEARANCE TO SAWCUT.FOR REPAIR DETAILS. SEE "CONCRETE RESTORATION DETAILS - SUBSTRUCTURE" SHEET.

NOTES:

REPAIR LOCATIONS AND ESTIMATED QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER. THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE AS-BUILT REPAIR QUANTITY TABLE.

CONCRETE COVER FOR EXTERIOR BARS IN THE CAP IS 3" ON THE BOTTOM FACE, 2"ELSEWHERE, AND 3" ON THE COLUMNS PER EXISTING BRIDGE PLANS. ACTUAL CONCRETE COVER SHALL BE DETERMINED BY THE CONTRACTOR AND PRESENTED TO THE ENGINEER PRIOR TO BEGINNING SCARIFICATION.

CURRENT AVERAGE COVER IS EXPECTED TO BE FROM 2" TO 3" ON THE CAP AND FROM $2^{1}/_{2}$ " TO 3" ON THE COLUMNS BASED ON VISUAL INSPECTION.

SEE TITLE SHEET FOR PROJECT CARDINAL DIRECTION DESIGNATION.

FOR CONCRETE AND SHOTCRETE REPAIRS, SEE CONCRETE RESTORATION DETAILS - SUBSTRUCTURE SHEET AND SPECIAL PROVISIONS.

***** QUANTITIES OF CONCRETE REPAIR AREAS ARE ANTICIPATED UNDER BEARING AREAS. DUE TO LACK OF INFORMATION. ALL AREAS ARE NOT KNOWN. QUANTITY INCLUDES CONTINGENCIES AND ARE ANTICIPATED TO BE SUFFICIENT FOR ACTUAL QUANTITIES ENCOUNTERED. FOR CONCRETE REPAIRS SEE CONCRETE RESTORATION DETAILS.

ALL DEFECT QUANTITIES ON STRUTS AND COLUMN FOOTINGS ARE LISTED WITH THE QUANTITIES FOR THE CAP.


SHOTCRETE REPAIRS MAY BE REPLACED WITH CONCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

COAT ALL SURFACE AREAS OF THE TOP OF THE CAP INCLUDING CHAMFERS, WITH EPOXY PROTECTIVE COATING. DO NOT COAT THE AREA UNDER THE ELASTOMERIC BEARINGS.

	PROJEC BF BRIDGE	RUNSI		CK	<u>3PR.1</u> CO 7 <u>1</u>	6 UNTY
DocuSigned by: Samad L Column 19C97095C75A467 5/9/2018 2:14: SEAL 043571 5/9/2018 2:14: SEAL 043571	STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH SUBSTRUCTURE CONCRETE REPAIRS BENT 17					
		REVI	SIONS			SHEET NO.
DOCUMENT NOT CONSIDERED	NO. BY:	DATE:		BY:	DATE:	S-52
FINAL UNLESS ALL SIGNATURES COMPLETED	1		3 4			total sheets 73

+

_



G:\4201720.03-Brunswick-71\Structures\401_280_15BPR.16_SMU_B18_S-53_090071.dgn User:jduke

AS-BUILT REPAIR QUANTITY TABLE							
BENT 18		QUANT	ITIES				
DENT TO ESTIN		ΜΑΤΕ	ACTUAL				
SHOTCRETE REPAIRS	AREA SQ.FT.	VOLUME CU.FT.	AREA SQ.FT.	VOLUME CU.FT.			
САР	93.7	46.9					
COLUMN/PILE	-	-					
CONCRETE REPAIRS	PAIRS AREA SQ.FT.		AREA SQ.FT.	VOLUME CU.FT.			
CAP 14.1		7.0					
EPOXY RESIN INJECTION		LIN.FT.		LIN.FT.			
САР		8.5					
COLUMN/PILE		4.5					

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE. MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2"CLEARANCE TO SAWCUT.FOR REPAIR DETAILS, SEE "CONCRETE RESTORATION DETAILS - SUBSTRUCTURE" SHEET.

NOTES:

REPAIR LOCATIONS AND ESTIMATED QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER. THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE AS-BUILT REPAIR QUANTITY TABLE.

CONCRETE COVER FOR EXTERIOR BARS IN THE CAP IS 3" ON THE BOTTOM FACE, 2"ELSEWHERE, AND 3" ON THE COLUMNS PER EXISTING BRIDGE PLANS. ACTUAL CONCRETE COVER SHALL BE DETERMINED BY THE CONTRACTOR AND PRESENTED TO THE ENGINEER PRIOR TO BEGINNING SCARIFICATION.

CURRENT AVERAGE COVER IS EXPECTED TO BE FROM 2" TO 3" ON THE CAP AND FROM $2^{1}/_{2}$ " TO 3" ON THE COLUMNS BASED ON VISUAL INSPECTION.

SEE TITLE SHEET FOR PROJECT CARDINAL DIRECTION DESIGNATION.

FOR CONCRETE AND SHOTCRETE REPAIRS, SEE CONCRETE RESTORATION DETAILS - SUBSTRUCTURE SHEET AND SPECIAL PROVISIONS.

***** QUANTITIES OF CONCRETE REPAIR AREAS ARE ANTICIPATED UNDER BEARING AREAS. DUE TO LACK OF INFORMATION, ALL AREAS ARE NOT KNOWN. QUANTITY INCLUDES CONTINGENCIES AND ARE ANTICIPATED TO BE SUFFICIENT FOR ACTUAL QUANTITIES ENCOUNTERED. FOR CONCRETE REPAIRS SEE CONCRETE RESTORATION DETAILS.

ALL DEFECT QUANTITIES ON STRUTS AND COLUMN FOOTINGS ARE LISTED WITH THE QUANTITIES FOR THE CAP.


SHOTCRETE REPAIRS MAY BE REPLACED WITH CONCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

COAT ALL SURFACE AREAS OF THE TOP OF THE CAP INCLUDING CHAMFERS, WITH EPOXY PROTECTIVE COATING. DO NOT COAT THE AREA UNDER THE ELASTOMERIC BEARINGS.

	PROJEC BF BRIDGE	RUNSI		<u>15BPR.1</u> Kcc 71	<u>6</u> DUNTY	
DocuSigned by: Samuel L Column 19C97095C75A467 5/9/2018 2:14: SEAL 043571 5/9/2018 2:14: SEAL 043571	STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH SUBSTRUCTURE CONCRETE REPAIRS BENT 18					
		REVIS	SIONS		SHEET NO.	
DOCUMENT NOT CONSIDERED	NO. BY:	DATE:	NO. BY	DATE:	S-53	
FINAL UNLESS ALL SIGNATURES COMPLETED	1		3 4		TOTAL SHEETS 73	

_

—



G:\4201720.03-Brunswick-71\Structures\401_285_15BPR.16_SMU_B19_S-54_090071.dgn User:jduke

AS-BUILT REPAIR QUANTITY TABLE							
BENT 19		QUANT	ITIES				
DEINI 19 ESTI		ΜΑΤΕ	ACTUAL				
SHOTCRETE REPAIRS	AREA SQ.FT.	VOLUME CU.FT.	AREA SQ.FT.	VOLUME CU.FT.			
САР	26.4	13.2					
COLUMN/PILE	33.0	16.5					
CONCRETE REPAIRS	AIRS AREA SQ.FT.		AREA SQ.FT.	VOLUME CU.FT.			
CAP 4.0		2.0					
EPOXY RESIN INJECTION		LIN.FT.		LIN.FT.			
САР		29.3					
COLUMN/PILE		24.0					

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE.MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2"CLEARANCE TO SAWCUT.FOR REPAIR DETAILS, SEE "CONCRETE RESTORATION DETAILS - SUBSTRUCTURE" SHEET.

NOTES:

REPAIR LOCATIONS AND ESTIMATED QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE AS-BUILT REPAIR QUANTITY TABLE.

CONCRETE COVER FOR EXTERIOR BARS IN THE CAP IS 3" ON THE BOTTOM FACE, 2"ELSEWHERE, AND 3" ON THE COLUMNS PER EXISTING BRIDGE PLANS. ACTUAL CONCRETE COVER SHALL BE DETERMINED BY THE CONTRACTOR AND PRESENTED TO THE ENGINEER PRIOR TO BEGINNING SCARIFICATION.

CURRENT AVERAGE COVER IS EXPECTED TO BE FROM 2" TO 3" ON THE CAP AND FROM $2^{1}/_{2}$ " TO 3" ON THE COLUMNS BASED ON VISUAL INSPECTION.

SEE TITLE SHEET FOR PROJECT CARDINAL DIRECTION DESIGNATION.

FOR CONCRETE AND SHOTCRETE REPAIRS, SEE CONCRETE RESTORATION DETAILS - SUBSTRUCTURE SHEET AND SPECIAL PROVISIONS.

* QUANTITIES OF CONCRETE REPAIR AREAS ARE ANTICIPATED UNDER BEARING AREAS.DUE TO LACK OF INFORMATION, ALL AREAS ARE NOT KNOWN.QUANTITY INCLUDES CONTINGENCIES AND ARE ANTICIPATED TO BE SUFFICIENT FOR ACTUAL QUANTITIES ENCOUNTERED.FOR CONCRETE REPAIRS SEE CONCRETE RESTORATION DETAILS.


ALL DEFECT QUANTITIES ON STRUTS AND COLUMN FOOTINGS ARE LISTED WITH THE QUANTITIES FOR THE CAP.

SHOTCRETE REPAIRS MAY BE REPLACED WITH CONCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

COAT ALL SURFACE AREAS OF THE TOP OF THE CAP INCLUDING CHAMFERS, WITH EPOXY PROTECTIVE COATING. DO NOT COAT THE AREA UNDER THE ELASTOMERIC BEARINGS.

	PROJEC BF BRIDGE	RUNSI		CK	<u>3PR.1</u> CO 71	6 UNTY
DocuSigned by: Samuel L Column 19C97095C75A467 5/9/2018 2:14: SEAL 043571 5/9/2018 2:14: SEAL 043571	STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH SUBSTRUCTURE CONCRETE REPAIRS BENT 19					
		REVIS	SIONS			SHEET NO.
DOCUMENT NOT CONSIDERED	NO. BY:	DATE:		BY:	DATE:	S-54
FINAL UNLESS ALL SIGNATURES COMPLETED	1		3 4			TOTAL SHEETS 73

-



AS-BUILT REPAIR QUANTITY TABLE							
	QUANT	ITIES					
BENT 20 ESTIN		ACTUAL					
AREA SQ.FT.	VOLUME CU.FT.	AREA SQ.FT.	VOLUME CU.FT.				
54.9	27.4						
23.6							
AREA SQ.FT.	VOLUME CU.FT.	AREA SQ.FT.	VOLUME CU.FT.				
CAP 8.2							
EPOXY RESIN INJECTION			LIN.FT.				
САР							
	94.0						
	ESTI AREA SQ.FT. 54.9 23.6 AREA SQ.FT. 8.2	QUANT ESTIMATE AREA SQ.FT. VOLUME CU.FT. 54.9 27.4 23.6 11.8 23.6 11.8 AREA SQ.FT. VOLUME CU.FT. 8.2 4.1 ION LIN.FT. 16.0	QUANTITIESESTIMATEACTAREA SQ.FT.VOLUME CU.FT.AREA SQ.FT.54.927.4				

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE.MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2"CLEARANCE TO SAWCUT.FOR REPAIR DETAILS, SEE "CONCRETE RESTORATION DETAILS - SUBSTRUCTURE" SHEET.

NOTES:

REPAIR LOCATIONS AND ESTIMATED QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE AS-BUILT REPAIR QUANTITY TABLE.

CONCRETE COVER FOR EXTERIOR BARS IN THE CAP IS 3" ON THE BOTTOM FACE, 2"ELSEWHERE, AND 3" ON THE COLUMNS PER EXISTING BRIDGE PLANS. ACTUAL CONCRETE COVER SHALL BE DETERMINED BY THE CONTRACTOR AND PRESENTED TO THE ENGINEER PRIOR TO BEGINNING SCARIFICATION.

CURRENT AVERAGE COVER IS EXPECTED TO BE FROM 2"TO 3" ON THE CAP AND FROM $2^{1}/_{2}$ " TO 3" ON THE COLUMNS BASED ON VISUAL INSPECTION.

SEE TITLE SHEET FOR PROJECT CARDINAL DIRECTION DESIGNATION.

FOR CONCRETE AND SHOTCRETE REPAIRS, SEE CONCRETE RESTORATION DETAILS - SUBSTRUCTURE SHEET AND SPECIAL PROVISIONS.


* OUANTITIES OF CONCRETE REPAIR AREAS ARE ANTICIPATED UNDER BEARING AREAS.DUE TO LACK OF INFORMATION, ALL AREAS ARE NOT KNOWN.OUANTITY INCLUDES CONTINGENCIES AND ARE ANTICIPATED TO BE SUFFICIENT FOR ACTUAL OUANTITIES ENCOUNTERED.FOR CONCRETE REPAIRS SEE CONCRETE RESTORATION DETAILS.

ALL DEFECT QUANTITIES ON STRUTS AND COLUMN FOOTINGS ARE LISTED WITH THE QUANTITIES FOR THE CAP.


SHOTCRETE REPAIRS MAY BE REPLACED WITH CONCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

COAT ALL SURFACE AREAS OF THE TOP OF THE CAP INCLUDING CHAMFERS, WITH EPOXY PROTECTIVE COATING. DO NOT COAT THE AREA UNDER THE ELASTOMERIC BEARINGS.

	PROJEC BF BRIDGE	RUNSI		K	<u>3PR.1</u> CO 71	6 UNTY
DocuSigned by: Samuel L Culturn 19C97095C75A467 5/9/2018 2:14:57000 5/9/2018 2:14:570000 5/9/2018 2:14:570000 5/9/2018 2:14:570000 5/9/2018 2:14:570000 5/9/2018 2:14:5700000 5/9/2018 2:14:57000000000000000000000000000000000000	STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH SUBSTRUCTURE CONCRETE REPAIRS BENT 20					
		REVIS	SIONS			SHEET NO.
DOCUMENT NOT CONSIDERED	NO. BY:	DATE:	NO. B1	r:	DATE:	S-55
FINAL UNLESS ALL SIGNATURES COMPLETED	1		3 4			TOTAL SHEETS 73



—



G:\4201720.03-Brunswick-71\Structures\401_295_15BPR.16_SMU_B21_S-56_090071.dgn

User:jduke

CAP 18.3 9.2 COLUMN/PILE 24.8 12.4	AS-BUILT REPAIR QUANTITY TABLE							
ESTIMATEACTUALSHOTCRETE REPAIRSAREA SQ.FT.VOLUME CU.FT.AREA SQ.FT.VOLU CU.FT.CAP18.39.2	QUANTITIES							
CAP 18.3 9.2 COLUMN/PILE 24.8 12.4	1ATE ACTUAL							
COLUMN/PILE 24.8 12.4	VOLUME AREA VOLUME CU.FT. SQ.FT. CU.FT.							
	9.2							
	12.4							
CONCRETE REPAIRS AREA VOLUME AREA VOLU SQ.FT. CU.FT. SQ.FT. CU.F	VOLUME AREA VOLUME CU.FT. SQ.FT. CU.FT.							
CAP 33.4 16.7	16.7							
EPOXY RESIN INJECTION LIN.FT. LIN.	LIN.FT. LIN.FT.							
CAP 16.0	16.0							
COLUMN/PILE 9.5	9.5							

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE. MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2"CLEARANCE TO SAWCUT.FOR REPAIR DETAILS, SEE "CONCRETE RESTORATION DETAILS - SUBSTRUCTURE" SHEET.

NOTES:

REPAIR LOCATIONS AND ESTIMATED QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE AS-BUILT REPAIR QUANTITY TABLE.

CONCRETE COVER FOR EXTERIOR BARS IN THE CAP IS 3" ON THE BOTTOM FACE, 2"ELSEWHERE, AND 3" ON THE COLUMNS PER EXISTING BRIDGE PLANS. ACTUAL CONCRETE COVER SHALL BE DETERMINED BY THE CONTRACTOR AND PRESENTED TO THE ENGINEER PRIOR TO BEGINNING SCARIFICATION.

CURRENT AVERAGE COVER IS EXPECTED TO BE FROM 2"TO 3" ON THE CAP AND FROM $2^{1}/_{2}$ " TO 3" ON THE COLUMNS BASED ON VISUAL INSPECTION.

SEE TITLE SHEET FOR PROJECT CARDINAL DIRECTION DESIGNATION.

FOR CONCRETE AND SHOTCRETE REPAIRS, SEE CONCRETE RESTORATION DETAILS - SUBSTRUCTURE SHEET AND SPECIAL PROVISIONS.

***** QUANTITIES OF CONCRETE REPAIR AREAS ARE ANTICIPATED UNDER BEARING AREAS. DUE TO LACK OF INFORMATION, ALL AREAS ARE NOT KNOWN. QUANTITY INCLUDES CONTINGENCIES AND ARE ANTICIPATED TO BE SUFFICIENT FOR ACTUAL QUANTITIES ENCOUNTERED.FOR CONCRETE REPAIRS SEE CONCRETE RESTORATION DETAILS.


ALL DEFECT QUANTITIES ON STRUTS AND COLUMN FOOTINGS ARE LISTED WITH THE QUANTITIES FOR THE CAP.

SHOTCRETE REPAIRS MAY BE REPLACED WITH CONCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

COAT ALL SURFACE AREAS OF THE TOP OF THE CAP INCLUDING CHAMFERS, WITH EPOXY PROTECTIVE COATING. DO NOT COAT THE AREA UNDER THE ELASTOMERIC BEARINGS.

	PROJEC BF BRIDGE	RUNSI		<u>15BPR.1</u> KC 71	L <u>6</u> DUNTY	
DocuSigned by: Samad L Column 19C97095C75A467 5/9/2018 2:14: SEAL 043571 5/9/2018 2:14: SEAL 043571	STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH SUBSTRUCTURE CONCRETE REPAIRS BENT 21					
		REVIS	SIONS		SHEET NO.	
DOCUMENT NOT CONSIDERED	NO. BY:	DATE:	NO. BY	DATE:	S-56	
FINAL UNLESS ALL SIGNATURES COMPLETED	1		3 4		TOTAL SHEETS 73	

-



G:\4201720.03-Brunswick-71\Structures\401_300_15BPR.16_SMU_B22_S-57_090071.dgn User:jduke

AS-BUILT REPAIR QUANTITY TABLE							
	QUANT	ITIES					
BENT 22 esti			ACTUAL				
AREA SQ.FT.	VOLUME CU.FT.	AREA SQ.FT.	VOLUME CU.FT.				
25.4	12.7						
22.6	11.3						
AREA SQ.FT.	VOLUME CU.FT.	AREA SQ.FT.	VOLUME CU.FT.				
CAP 34.2							
EPOXY RESIN INJECTION			LIN.FT.				
САР							
	1.0						
	ESTI AREA SQ.FT. 25.4 22.6 AREA SQ.FT. 34.2	QUANT ESTIMATE AREA SQ.FT. VOLUME CU.FT. 25.4 12.7 22.6 11.3 AREA SQ.FT. VOLUME CU.FT. 34.2 17.1 ION LIN.FT. 9.0	QUANTITIESESTIMATEACTAREA SQ.FT.VOLUME CU.FT.AREA SQ.FT.25.412.722.611.3AREA SQ.FT.VOLUME CU.FT.AREA SQ.FT.34.217.1IONLIN.FT.9.09.0				

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE.MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2"CLEARANCE TO SAWCUT.FOR REPAIR DETAILS. SEE "CONCRETE RESTORATION DETAILS - SUBSTRUCTURE" SHEET.

NOTES:

REPAIR LOCATIONS AND ESTIMATED QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE AS-BUILT REPAIR QUANTITY TABLE.

CONCRETE COVER FOR EXTERIOR BARS IN THE CAP IS 3" ON THE BOTTOM FACE, 2"ELSEWHERE, AND 3" ON THE COLUMNS PER EXISTING BRIDGE PLANS. ACTUAL CONCRETE COVER SHALL BE DETERMINED BY THE CONTRACTOR AND PRESENTED TO THE ENGINEER PRIOR TO BEGINNING SCARIFICATION.

CURRENT AVERAGE COVER IS EXPECTED TO BE FROM 2"TO 3" ON THE CAP AND FROM $2^{1}/_{2}$ " TO 3" ON THE COLUMNS BASED ON VISUAL INSPECTION.

SEE TITLE SHEET FOR PROJECT CARDINAL DIRECTION DESIGNATION.

FOR CONCRETE AND SHOTCRETE REPAIRS, SEE CONCRETE RESTORATION DETAILS - SUBSTRUCTURE SHEET AND SPECIAL PROVISIONS.


***** QUANTITIES OF CONCRETE REPAIR AREAS ARE ANTICIPATED UNDER BEARING AREAS. DUE TO LACK OF INFORMATION, ALL AREAS ARE NOT KNOWN. QUANTITY INCLUDES CONTINGENCIES AND ARE ANTICIPATED TO BE SUFFICIENT FOR ACTUAL QUANTITIES ENCOUNTERED.FOR CONCRETE REPAIRS SEE CONCRETE RESTORATION DETAILS.

ALL DEFECT QUANTITIES ON STRUTS AND COLUMN FOOTINGS ARE LISTED WITH THE QUANTITIES FOR THE CAP.

SHOTCRETE REPAIRS MAY BE REPLACED WITH CONCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

COAT ALL SURFACE AREAS OF THE TOP OF THE CAP INCLUDING CHAMFERS, WITH EPOXY PROTECTIVE COATING. DO NOT COAT THE AREA UNDER THE ELASTOMERIC BEARINGS.

	PROJEC BF BRIDGE	RUNSI	NIC	<u>15BPR.1</u> Kcc 71	6)UNTY		
DocuSigned by: Samuel L Culturn 19C97095C75A467 5/9/2018 2:14 SEAL 043571 5/9/2018 2:14	STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH SUBSTRUCTURE CONCRETE REPAIRS BENT 22						
	REVISIONS SHEET NO.						
DOCUMENT NOT CONSIDERED	NO. BY:	DATE:	NO. BY:	DATE:	S-57		
FINAL UNLESS ALL SIGNATURES COMPLETED	1		3 4		TOTAL SHEETS 73		



NO METALIZING SHALL BE PERFORMED UNTIL THE CONCRETE RESTORATION HAS BEEN APPROVED BY THE ENGINEER. METALIZE AT NO LESS THAN 10 (TEN) DAYS AFTER PLACING CONCRETE. BUT NO MORE THAN 90 (NINETY) DAYS. CONNECT METALIZING CONNECTION PLATE IMMEDIATELY AFTER COMPLETING METALIZING. APPLY A ZINC SILICATE OVERCOAT AT NO MORE THAN 72 HOURS COAT CONNECTION PLATE WITH EPOXY AT NO MORE THAN 96

REMOVE ALL UNSOUND CONCRETE FROM THE BENT FOOTINGS IN ACCORDANCE WITH CONCRETE RESTORATION DETAILS AND PROJECT SPECIAL PROVISIONS FOR CONCRETE

THE CONTRACTOR SHALL SUBMIT A PLAN FOR CONTROL AND DISPOSAL OF DEBRIS TO THE ENGINEER FOR APPROVAL.

3. FOR SPALLS OR DELAMINATIONS ON THE FOOTINGS GREATER THAN 2'-O"WIDE OR LONG AND GREATER THAN 1"DEEP, RESTORE CONCRETE TO ORIGINAL PROFILE IN ACCORDANCE WITH CONCRETE RESTORATION DETAILS SHEET AND PROJECT SPECIAL PROVISIONS FOR CONCRETE REPAIR.

FOR ANY CONCRETE AREAS THAT WOULD BE ISOLATED FROM PROPOSED CONTINUITY BY EXISTING SUPERFICIAL CRACKING, FILL CRACKS WITH EPOXY PRIOR TO METALIZING PER PROJECT SPECIAL PROVISIONS FOR EPOXY INJECTION OF CRACKS.

ALL VERTICAL FACES OF THE FOOTING SHALL BE METALIZED. CONNECTION BETWEEN PLATE AND REINFORCING STEEL SHALL BE PROVIDED VIA A $\frac{5}{16}$ DIAMETER STAINLESS STEEL ALL THREADED ROD AS DESCRIBED IN THE CONNECTION PLATE DETAIL. THE CONNECTION PLATES SHALL BE LOCATED IN AREAS OF SOUND CONCRETE AS DETAILED IN THE PROJECT SPECIAL PROVISIONS FOR CATHODIC PROTECTION AND SHALL BE INSTALLED ON DIFFERENT BARS.

CHECK INTERBAR CONTINUITY. REINFORCING BARS REQUIRING CONTINUITY CORRECTION SHALL BE MADE CONTINUOUS USING STEEL WIRE RESISTANCE WELDED OR BRAZED TO EVERY REBAR. ALL EXPOSED BARS SHALL BE MADE CONTINUOUS. COAT ALL CONTINUITY CORRECTION WELDS WITH NON-CONDUCTIVE EPOXY.

7. CHECK ELECTRICAL CONTINUITY BETWEEN ALL PLATES IN ACCORDANCE WITH THE PROJECT SPECIAL PROVISIONS FOR CATHODIC PROTECTION.

METALIZE AND PLACE CONNECTION PLATES IN ACCORDANCE WITH PROJECT SPECIAL PROVISIONS FOR CATHODIC PROTECTION.

APPLY A ZINC SILICATE OVERCOAT TO THE METALIZED AREAS AS DESCRIBED IN THE PROJECT SPECIAL PROVISIONS FOR CATHODIC PROTECTION-INTERMEDIATE BENT METALIZING. THE ENGINEER MUST APPROVE THE METALIZING PRIOR TO THE OVERCOAT

10. SEE PROJECT SPECIAL PROVISIONS FOR ADDITIONAL METALIZING REQUIREMENTS AND ACCEPTANCE CRITERIA. (PSP: CATHODIC PROTECTION-INTERMEDIATE BENT METALIZING)

11. SEQUENCE CLEANING AND COATING IN ORDER TO AVOID DELETERIOUS SUBSTANCES INHIBITING PROPOSED COATINGS.


12. ALL HARDWARE AND MATERIAL ITEMS ON THIS SHEET ARE INCIDENTAL TO PAY ITEM FOR ZINC ALUMINUM SPRAY.

13. THOROUGHLY CLEAR THE ALL VERTICAL FACES OF THE FOOTINGS OF ANY MARINE GROWTH AND DEBRIS BEFORE ALL PERFOMING ANY OF THE ASSOCIATED WORK FOR FOOTING METALIZATION.


PROJECT NO	15BPR.16
BRUNSWI	CK COUNTY
BRIDGE NO	71

TH CARO	DEPA		E OF NORTH CAR OF TRAI RALEIGH	OLINA NSPORTA	TION
DocuSigned by: Samuel L Culture 19C97095C75A467. 5/9/2018 2:14:597 PM FOTNEF!		TING C META		G DETA	
		REVIS	SIONS		SHEET NO.
DOCUMENT NOT CONSIDERED	NO. BY:	DATE:	NO. BY:	DATE:	S-58
FINAL UNLESS ALL	1		3		TOTAL SHEETS
SIGNATURES COMPLETED	2		4		73

+



(ft. from nearest bent, etc)Bent #lane, at EB 1EB 1oughoutoughoutoughoutoughoutoughout1oughout1am, 1' from Bent1from Bent2Bent2Bent1am, 1' from Bent1am, 1' from Bent1am, 1' from Bent1am, 1' from Bent1am, 1' from Bent2and faces, at Bent2and faces, at Bent2	Delam(x10) Cracking (RC and Other)Delam(x13) Cracking (RC and Other)(x3) SpallsSpallUnsound Patched AreaDelamSpall(x2) SpallsSpallSpallSpall	Length(ft.) Width(ft.) Assumed Depth (ft.) 2.5 1.5	Actual (C.F.) ISpa	An #Component4Girder 44Girder 54Girder 54Lt. Bridge Rail4Rt. Bridge Rail5Girder 15Girder 25Girder 3	Location (ft. from nearest bent, etc)Bottom face, 1' from BentBottom of beam, starts 30' from BentSouth face, 1' from Bentat random throughoutat random throughoutBottom of beam, at mid spanFact and earner, at Part	Bent # 3 3 3 3	Defect Description Delam Unsound Patched Area Spall	Length(ft.) Width(ft.) Depth(ft.) 0.75 0.75 5.5 1.5	Actual (C.F.) Actual Depth (ft
oughoutoughoutoughoutoughoutoughoutoughout1am, 1' from Bent1from Bent2Bent1am, 1' from Bent1am, 1' from Bent1am, 1' from Bent1am, 1' from Bent1am, 1' from Bent11am, 1' from Bent11<	(x10) Cracking (RC and Other)Delam(x13) Cracking (RC and Other)(x3) SpallsSpallUnsound Patched AreaDelamSpall(x2) SpallsSpallSpallSpall	2.5 1.5 10 1.5 2.5 1.5 13 1.5 3.5 1.5 1.5 1.75 0.75 0.75 0.75 0.75 2.5 1.5	Deptin (nt.)	4Girder 54Girder 54Lt. Bridge Rail4Rt. Bridge Rail5Girder 15Girder 2	Bottom of beam, starts 30' from BentSouth face, 1' from Bentat random throughoutat random throughoutBottom of beam, at mid span	3 3 3	Unsound Patched Area		
oughoutoughoutoughoutoughoutoughoutoughout1am, 1' from Bent1from Bent2Bent1am, 1' from Bent1am, 1' from Bent1am, 1' from Bent1am, 1' from Bent1am, 1' from Bent11am, 1' from Bent11<	(x10) Cracking (RC and Other)Delam(x13) Cracking (RC and Other)(x3) SpallsSpallUnsound Patched AreaDelamSpall(x2) SpallsSpallSpallSpall	10 1.5 2.5 1.5 13 1.5 3.5 1.5 1.5 1.75 0.75 0.75 0.75 0.75 0.75 0.75 1.5 1.5		4Girder 54Girder 54Lt. Bridge Rail4Rt. Bridge Rail5Girder 15Girder 2	Bottom of beam, starts 30' from BentSouth face, 1' from Bentat random throughoutat random throughoutBottom of beam, at mid span	3 3	Unsound Patched Area		
oughoutoughoutoughoutoughoutoughout1am, 1' from Bent1from Bent2Bent2Bent1am, 1' from Bent1am, 1' from Bent1am, 1' from Bent1bent2and a Bent11 <tr< td=""><td>Delam(x13) Cracking (RC and Other)(x3) SpallsSpallUnsound Patched AreaDelamSpall(x2) SpallsSpallSpallSpall</td><td>2.5 1.5 13 1.5 3.5 1.5 1.5 1.75 0.75 0.75 0.75 0.75 0.75 0.75 2.5 1.5</td><td></td><td>4Girder 54Lt. Bridge Rail4Rt. Bridge Rail5Girder 15Girder 2</td><td>South face, 1' from Bent at random throughout at random throughout Bottom of beam, at mid span</td><td>3</td><td></td><td></td><td></td></tr<>	Delam(x13) Cracking (RC and Other)(x3) SpallsSpallUnsound Patched AreaDelamSpall(x2) SpallsSpallSpallSpall	2.5 1.5 13 1.5 3.5 1.5 1.5 1.75 0.75 0.75 0.75 0.75 0.75 0.75 2.5 1.5		4Girder 54Lt. Bridge Rail4Rt. Bridge Rail5Girder 15Girder 2	South face, 1' from Bent at random throughout at random throughout Bottom of beam, at mid span	3			
oughout1am, 1' from Bent1from Bent2Bent2Bent1am, 1' from Bent1Bent2am, 1' from Bent1bent2and faces, at Bent1	(x3) Spalls Spall Unsound Patched Area Delam Spall (x2) Spalls Spall Spall Spall	3.5 1.5 1.5 1.75 0.75 2.5 1.5 0.75 0.75 0.75 0.75 0.75 0.75 0.75 2.5 1.5 0.75		4 Rt. Bridge Rail 5 Girder 1 5 Girder 2	at random throughout Bottom of beam, at mid span			0.75 0.75	
1am, 1' from Bentfrom Bent2Bent2Bent1am, 1' from Bent1Bent2afaces, at Bent1	Spall Unsound Patched Area Delam Spall (x2) Spalls Spall Spall Spall	1.5 1.75 0.75 2.5 1.5		5 Girder 1 5 Girder 2	Bottom of beam, at mid span		(x15) Cracking (RC and Other)	15.5 1.5	
from Bent2Bent2Bent1Im, 1' from Bent1Bent2faces, at Bent1	Unsound Patched Area Delam Spall (x2) Spalls Spall Spall Spall	2.5 1.5 0.75 0.75 0.75 0.75 2.5 1.5		5 Girder 2	, <u> </u>		(x5) Cracking (RC and Other)	5.5 1.5	
from Bent2Bent2Bent1Im, 1' from Bent1Bent2faces, at Bent1	Delam Spall (x2) Spalls Spall Spall	0.75 0.75 0.75 0.75 2.5 1.5				-	Unsound Patched Area	22.5 2.5	
Bent2Bent1am, 1' from Bent1Bent2faces, at Bent1	Spall (x2) Spalls Spall Spall	0.75 0.75 2.5 1.5			East end corner, at Bent Bottom face, 31' from Bent	5	Delam Spall	0.75 2 0.75 1.25 1 1	
Bent1am, 1' from Bent1Bent2a faces, at Bent1	(x2) Spalls Spall Spall	2.5 1.5		5 Girder 3	Bottom face, 2' from Bent	5	Delam	2.25 1.5	
Bent2faces, at Bent1	Spall	0.75 0.75		5 Girder 5	Bottom face, 31' from Bent	5	Spall	1 1	
faces, at Bent 1				5 Lt. Bridge Rail	South face, 18" from Bent	5	Spall	0.75 1.5	
,		1.75 2		5 Lt. Bridge Rail	at random throughout		(x7) Cracking (RC and Other)	7.5	
m 1' from Bont 2	(x2) Delam	2 3		5 Lt. Bridge Rail	at random throughout		(x2) Spalls	0.75 0.75	
,	Spall Spall			5 Lt. Bridge Rail	at random throughout		(x3) Spalls	0.75 1	
Bent1Im, 1' from Bent2	Spall Delam	1 1.25 1.25 0.75		5 Rt. Bridge Rail 5 Rt. Bridge Rail	at random throughout at random throughout		(x7) Cracking (RC and Other) (x2) Spalls	4.5 1.5 1.5 0.75	
Bent 1						5		5.5 3	
oughout	(x8) Cracking (RC and Other)	8.5 1.5			North face, at mid span	-	Spall	1.5 1.5 0.75	
from Bent 1	Exposed Rebar	1.5 1.5		6 Girder 1	South face, 1' from West end		Spall	2 2.25	
oughout	(x5) Cracking (RC and Other)	5.5 1.5		6 Girder 1	Bottom of beam, 1' from Bent	5	Unsound Patched Area	1.25 2.5	
2	Spall	1.5 1		6 Girder 1	North face, 3" from West end	_	Cracking (PSC)	2 1.5	
,					South face, at Bent	6			
,					,	5			
am, starts 30' from Bent 3					,	6			
am, starts 30' from Bent 2	Unsound Patched Area	5.25 1.75		6 Girder 3	Bottom face, 31' from Bent	6	Spall	0.75 0.75	
am, starts 2' from Bent 3	Delam	2.75 1.75		6 Girder 4	Bottom face, 31' from Bent	6	Spall	1 0.75	
from Bent 2	Delam	1 1		6 Girder 5	Bottom face, 1' from Bent	5	Unsound Patched Area	1.25 2.25	
from Bent 2	(x2) Delam	2.5 2		6 Lt. Bridge Rail	at random throughout		(x8) Cracking (RC and Other)	8.5 1.5	
Bent 3	- P				,	5			
,					,	6			
from Bent 2					-			1 1	
am, 30' from Bent 3	Delam				North face, at Bent	6		2 1	
Bent 2	Delam	1.25 1.5		7 Girder 1	Bottom face, 31' from Bent	6	Spall	0.75 1	
am, 1' from Bent 2	Unsound Patched Area	1.25 2.25		7 Girder 2	Bottom face, 31' from Bent	6	Spall	0.75 0.75	
Bent 3	Delam	1 1.25		7 Girder 2	North face, at Bent	7	Spall	0.75 1	
am, 30' from Bent 2				7 Girder 2	North face, at Bent	6	Spall		
Bent 2					,	6	•		
oughout					,	6			
oughout				7 Girder 4	South face, at Bent	7		2.5 1	
Bent 4	Spall	0.75 2 0.75		7 Girder 4	Bottom face, 2' from Bent	7	Delam	2 1.25	
from Bent 4	Spall	1 1.25		7 Girder 4	Bottom face, 1' from Bent	7	Spall	0.75 1	
at Bent 3	Unsound Patched Area	1.5 2.25		7 Girder 5	Bottom face, 1' from Bent	6	Spall	0.75 1.75	
at Bent 4	Unsound Patched Area	6 2.5		7 Girder 5	North face, at Bent	6	Spall		
at Bent 3		1 1				6		3.3 1.3 1 1	
	Delam					8	Spall	1 1.5	
B ou from a man a man a from a man a man a from a man a ma a man a man	ent1ighout1om Bent1ighout2, starts 25' from Bent3, 1' from Bent2, starts 33' from Bent3, starts 30' from Bent3, starts 30' from Bent2, starts 2' from Bent3, starts 2' from Bent2, starts 2' from Bent3om Bent2om Bent2om Bent2arts at Bent3om Bent2, 30' from Bent3ent2, 1' from Bent2ent3, 30' from Bent2ent2, 1' from Bent2ent3, 30' from Bent4ent4om Bent3ent4om Bent4om Bent4om Bent3, 1' from Bent2ent3, 30' from Bent4ent4om Bent4om Bent4om Bent4om Bent4om Bent4om Bent4om Bent4om Bent4om Bent4om Bent3and4om Bent4om Bent3and4and4and4and4and4and4and<	ent1Cracking (PSC)ighout(x8) Cracking (RC and Other)om Bent1Exposed Rebarighout(x5) Cracking (RC and Other)2Spall, starts 25' from Bent3Unsound Patched Area, 1' from Bent2Unsound Patched Area, starts 30' from Bent3Unsound Patched Area, starts 30' from Bent2Unsound Patched Area, starts 30' from Bent2Unsound Patched Area, starts 30' from Bent2Unsound Patched Area, starts 30' from Bent2Delamom Bent2Delamom Bent2Delamom Bent2Insound Patched Area, starts 30' from Bent3Delamom Bent2(x2) Delamom Bent2Unsound Patched Area, starts 30' from Bent2Unsound Patched Area, at Bent2Unsound Patched Areaom Bent2Delam, 1' from Bent2Delam, 3' from Bent2Delam, 3' from Bent2Spallent2Spallghout(x4) Cracking (RC and Other)ment4Spallom Bent3Unsound Patched Areaent3Unsound Patched Area<	ent 1 Cracking (PSC) 3.5 2.5 ghout (x8) Cracking (R C and Other) 8.5 1.5 om Bent 1 Exposed Rehar 1.5 1.5 ighout (x5) Cracking (R C and Other) 5.5 1.5 ighout (x5) Cracking (R C and Other) 5.5 1.5 ighout (x5) Cracking (R C and Other) 5.5 1.5 istres 35' from Bent 3 Unsound Patched Area 2.5 1.75 istarts 30' from Bent 3 Unsound Patched Area 4.5 1.5 istarts 30' from Bent 2 Unsound Patched Area 5.25 1.75 istarts 30' from Bent 2 Unsound Patched Area 5.25 1.75 istarts 30' from Bent 2 Unsound Patched Area 5.25 1.75 om Bent 2 Usound Patched Area 2.5 2 nt 3 Spail 0.75 0.75 2 nts at Bent 2 Unsound Patched Area 3.5 1.5 1.5 <	ent1Cracking (PSC)3,52,51111ghout(K8) Cracking (RC and Other)8,51,51.51111ghout1Exposed Penbar1,51,51.511 </th <th>ent1Cracking (PSC)3.52.55Rt.Bridge Rallghout(x3) (racking (RC and Other)8.51.56Girder 1ghout(x5) Cracking (RC and Other)5.51.56Girder 1ghout(x5) Cracking (RC and Other)5.51.56Girder 1ghout(x5) Cracking (RC and Other)5.51.56Girder 1ghout2Spall1.51.766Girder 111.51.7566Girder 2starts 25 from Bent2Unsound Patched Area2.51.7566Girder 2starts 30 from Bent3Unsound Patched Area5.251.7566Girder 3starts 30 from Bent3Delam2.751.7566Girder 3starts 30 from Bent2Unsound Patched Area5.251.7566Girder 3starts 20 from Bent2Unsound Patched Area2.51.7566Lt. Bridge Rallstarts 20 from Bent2Unsound Patched Area2.51.566Girder 3starts 20 from Bent2Unsound Patched Area3.51.566Girder 3starts 20 from Bent2Unsound Patched Area3.51.566Girder 1starts 20 from Bent3Bolam0.750.75767Girder 1<</th> <th>endOncolong (PSO)3.52.5VVSR. Brigge PailNorth Securit from BertghoutISignedin (RG and Other)8.51.5II8.6Giffer ISorth fac. 1' from North Securit from Securi</th> <th>end1.00x-lang/PSD3.53.50.00.06.58.7R.1 megradNot hour, then, 3.1 megrad5.7gmb110x-lang/PSD1.51.51.51.600.0<</th> <th>endi</th> <th>end1.00.400 (arbig) (mode)3.63.7<</th>	ent1Cracking (PSC)3.52.55Rt.Bridge Rallghout(x3) (racking (RC and Other)8.51.56Girder 1ghout(x5) Cracking (RC and Other)5.51.56Girder 1ghout(x5) Cracking (RC and Other)5.51.56Girder 1ghout(x5) Cracking (RC and Other)5.51.56Girder 1ghout2Spall1.51.766Girder 111.51.7566Girder 2starts 25 from Bent2Unsound Patched Area2.51.7566Girder 2starts 30 from Bent3Unsound Patched Area5.251.7566Girder 3starts 30 from Bent3Delam2.751.7566Girder 3starts 30 from Bent2Unsound Patched Area5.251.7566Girder 3starts 20 from Bent2Unsound Patched Area2.51.7566Lt. Bridge Rallstarts 20 from Bent2Unsound Patched Area2.51.566Girder 3starts 20 from Bent2Unsound Patched Area3.51.566Girder 3starts 20 from Bent2Unsound Patched Area3.51.566Girder 1starts 20 from Bent3Bolam0.750.75767Girder 1<	endOncolong (PSO)3.52.5VVSR. Brigge PailNorth Securit from BertghoutISignedin (RG and Other)8.51.5II8.6Giffer ISorth fac. 1' from North Securit from Securi	end1.00x-lang/PSD3.53.50.00.06.58.7R.1 megradNot hour, then, 3.1 megrad5.7gmb110x-lang/PSD1.51.51.51.600.0<	endi	end1.00.400 (arbig) (mode)3.63.7<



5/9/2018 G:\4201720.03-Brunswick-71\Structures\401_315_15BPR.16_SMU_DEF01_S-60_090071.dgn User:jduke

DOCUMENT NOT CONSIDERED	NO.	BY:	DATE:	NO.	BY:	DATE:	S-60
FINAL UNLESS ALL	ใ			3			TOTAL SHEETS
SIGNATURES COMPLETED	2			4			73

		E	Brunswick	x #71		As-Built (Quantities			E	Brunswick	#71			As-Built C	Quantities
Span #	Component	Location (ft. from nearest bent, etc)	Bent #	Defect Description	Length(ft.)	Width(ft.) Depth(ft.) Actual (C.F.)	Actual Depth (ft.)	Span #	Component	Location (ft. from nearest bent, etc)	Bent #	Defect Description	Length(ft.)	Width(ft.) De	epth(ft.) Actual (C.F.)	Actual Depth (ft.)
8	Girder 1	South face, at Bent	7	Delam	1.5	1.5		10	Girder 2	North face, 3' from Bent	10	Spall	0.75	0.75		
8	Girder 1	Bottom face, 31' from Bent	7	Spall	0.75	0.75		10	Girder 3	Bottom face, at strand hold down locations		(x2) Spalls	2	1		
8	Girder 1	Bottom face, 31' from Bent	8	Spall	0.75	0.75		10	Girder 3	Bottom face, 1' from Bent	10	Spall	1	1		+
8	Girder 1 Girder 2	North face, 3' from Bent North & South faces, at Bent	8	Exposed Rebar (x2) Spalls	1.5	1.5 1.25		10 10	Girder 4 Girder 4	Bottom face, at strand hold down locations North face, at Bent	10	(x2) Spalls Spall	0.75	1 0.75		+
8	Girder 2	Bottom face, 1' from Bent	8	Spall	1	1.25		10	Girder 4	South face, at Bent	10	Delam	1	1.25		+
8	Girder 2	Bottom face, 1' from Bent	7	Spall	1	1.25		10	Girder 5	North face, at Bent	10	Delam	1.5	1.5		
8	Girder 2	South face, at Bent	8	(x2) Spalls	1.5	1		10	Girder 5	Bottom face, 1' from Bent	10	Delam	1.25	1.5		
8	Girder 2	North & South faces, at Bent	7	(x3) Spalls	3	1		10	Lt. Bridge Rail	at random throughout		(x11) Cracking (RC and Other)	11.5	1.5		
8	Girder 2	Bottom face, 31' from Bent	7	Spall ())	0.75	0.75		10	Rt. Bridge Rail	at random throughout		(x13) Cracking (RC and Other)	13.5	1.5		
8	Girder 3 Girder 3	Bottom face, 1' from Bent North face, at Bent	8	(x2) Spalls Spall	3	1.75		10	0	North face, 3' from Bent Eastbound lane, 7' from Bent	10 10	Spall Spall	0.75 1.25	0.75 1.5		
8	Girder 3	South face, at Bent	8	Spall	1.25	1.5		11		at random throughout		(x23) Cracking (RC and Other)	23.5	1.5		
8	Girder 3	Bottom face, 31' from Bent	8	Spall	1.25	1		11	Rt. Bridge Rail	at random throughout		(x5) Cracking (RC and Other)	5.5	1.5		
8	Girder 3	South face, at Bent	8	Spall	0.75	0.75		11	Girder 1	North face, at diaphragm locations		(x2) Unsound Patched Area	2	1		1
8	Girder 3	South face, at Bent	7	Delam	2	2		11	Girder 2	North face, at East end		Unsound Patched Area	0.75	1		
8	Girder 3	Bottom face, 31' from Bent	7	Spall	0.75	0.75		11	Girder 2	North face, starts 6" from East end.		Cracking (PSC)	1.75	1.5		
8	Girder 4	North face, at Bent	8	(x2) Spalls	2	1.25		11	Girder 2	South face, at Bent	10	Spall	0.75	0.75		
8	Girder 4 Girder 5	North face, at Bent South face, at East end	7	(x2) Spalls Cracking (PSC)	2 1.5	1.25 1.5		11 11	Girder 3 Girder 3	East face West face		Spall (x5) Spalls	1.25 3.75	1.25 0.75	1	+
8	Girder 5	South face, at Bent	8	Cracking (PSC)	2.25	1.5		11	Girder 3	North face, at Bent	11	Spall	0.75	1		
8	Girder 5	North & South faces, 1' from Bent	8	(x4) Spalls	5	1.75		11	Girder 4	North face, 1' from Bent	11	Spall	1	1.5		
8	Girder 5	at mid span		Spall	1.5	1.5		11	Girder 4	South face, at West end		Spall	1	2.75		
8	Girder 5	North face, 1' from Bent	7	Cracking (PSC)	1.5	1.5		11	Girder 4	South face, 1' from Bent	11	Cracking (PSC)	2	1.5		
8	Girder 5	South face, at Bent	7	Spall	1	1		12	Curved Concrete Deck	Eastbound lane, 3' from Bent	11	Unsound Patched Area	3.5	3.5		
8	Girder 5	Bottom face, starts 2' from Bent	8	Delam	5.5	1.5		12	Girder 1	South face, at Bent	12	Unsound Patched Area	2	1.5		
8	Girder 5	Bottom face, 30' from Bent	8	Delam	9.5	1.5		12	Girder 2	North face, at Bent	12	Spall	1		1	
8	Girder 5 Lt. Bridge Rail	North face, at Bent at random throughout	1	Exposed Rebar (x9) Cracking (RC and Other)	1 .5 9.5	1.5 1.5		12 12	Girder 2 Girder 3	North face, at Bent South face, at Bent	11	Spall Unsound Patched Area	1.25 1.5	0.75 1.75	0.75	+
8	Rt. Bridge Rail	at random throughout		(x6) Cracking (RC and Other)	6.5	1.5		12	Girder 3	North face, at Bent	12	Unsound Patched Area	2.5	2.25		
9	Girder 1	North face, at mid span		Unsound Patched Area	1.5	1.5		12	Girder 3	North face, at Bent	12	Unsound Patched Area	3.25	1		
9	Girder 1	Bottom face, 31' from Bent	8	Spall	0.75	0.75		12	Girder 3	South face, 1' from Bent	11	Spall	1	1		
9	Girder 1	Bottom face, 31' from Bent	9	Spall	0.75	0.75		12	Girder 4	South face, starts at Bent	12	Cracking (PSC)	18.5	2.5		
9	Girder 2	Bottom face, 1' from Bent	9	Spall	1.5	1		12	Girder 4	South face, at Bent	12	Spall	1.25		0.75	
9	Girder 2	South face, at Bent	9	Delam	1.5	2.25		12	Girder 4	North face, 3' from Bent	11	Unsound Patched Area	2.5	1.25		<u> </u>
9	Girder 2	North face, at Bent	9	Spall	0.75			12	Girder 4	South face, at Bent	11	(x2) Cracking (PSC)	<u> </u>	4.5		+
9	Girder 3 Girder 3	South face, at Bent South face, starts 1' from Bent	9	Spall Delam	0.75	0.75		12 12	Lt. Bridge Rail Lt. Bridge Rail	at random throughout North & South faces, 29' from Bent	12	(x19) Cracking (RC and Other) Cracking (RC and Other)	19.5	1.5 1.5		
9	Girder 3	Bottom face, 31' from Bent	8	Spall	1	1		12	Rt. Bridge Rail	North face, at random throughout		(x2) Spalls	1.5	0.75		+
9	Girder 4	Bottom face, 1' from Bent	9	Spall	0.75	1		12	Rt. Bridge Rail	at random throughout		Delam	24.5	1.5		
9	Girder 4	South face, 1' from Bent	9	Spall	0.75	1		13	Girder 2	North face, at Bent	12	(x4) Cracking (PSC)	10	1.5		
9	Girder 5	Bottom face 1' from Bent	9	Spall	1	1		13	Girder 2	North face, at Bent	13	(x2) Spalls	1.5	0.75		
9	Lt. Bridge Rail	at random throughout		(x8) Cracking (RC and Other)	8.5	1.5		13	Girder 3	South face, 1' from Bent	13	Spall	1	1.5		<u> </u>
9	Rt. Bridge Rail	at random throughout ck Eastbound lane, at Bent Joint	10	(x7) Cracking (RC and Other) Spall	7.5	1.5		13 13	Girder 3	North face, at Bent	12 13	Spall Spall	0.75	0.75 1		
10	Girder 1	Bottom face, 31' from from Bent	10 10	Spall	3.5 1			13 13	Girder 3 Girder 4	North face, at Bent South face, at Bent	13	Spall	0.75		0.75	+
10	Girder 1	Bottom face, 31' from Bent	9	Spall		1		13	Girder 4	South face, 1' from Bent	13	Cracking (PSC)	2.5	2.5		+
10	Girder 2	North face, at Bent	10	Spall	0.75	1.25		13	Girder 4	South face, at Bent	13	Cracking (PSC)	4.5	4.5		1
10	Girder 2	Bottom face, at strand hold down locations		(x2) Spalls	2	1		13	Girder 4	North face, at Bent	12	Spall	0.75	1		
10	Girder 2	North face, at Bent	10	Delam	1.5	2		13	Girder 4	North face, at Bent	12	Spall	1	1		
					NOTES:										. <u>15BPR</u> WICK (
															71	
						FECTS WERE TAKEN FROM THE							BRI	DGE NO.	71	
						LOCATIONS AND ESTIMATED	QUANTITIE	IS ARE	GIVEN WITH THE				SHEET	2 OF 4		




DRAWN BY : AARON J.MCMILLA	AN DATE :	_	03-2018
CHECKED BY : DIEGO A.AGUIR	RE DATE :	_	03-2018
DESIGN ENGINEER OF RECORD : SAMUEL	L.CULLUM DATE :	_	03-2018

5/9/2018 G:\4201720.03-Brunswick-71\Structures\401_320_15BPR.16_SMU_DEF02_S-61_090071.dgn User:jduke

3. THE ENGINEER SHALL FILL OUT THE AS-BUILT REPAIR QUANTITY FOR EACH LISTED DEFICIENCY. 4. COORDINATE THIS SHEET WITH SHEETS S-32 THRU S-57. 5. IF ADDITIONAL REPAIRS, NOT SHOWN ON SHEETS S-35 THRU S-57, ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE CORRESPONDING SHEET THE APPROXIMATE LOCATIONS AND THE DESCRIPTION OF THE REPAIRS, AND WILL ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE AS-BUILT REPAIR QUANTITIES TABLE.

STAT	E OF NO	ORTH CAROLINA
DEPARTMENT	OF	TRANSPORTATION
	RA	LEIGH





			REVI	SION	١S		SHEET NO.
DOCUMENT NOT CONSIDERED	NO.	BY:	DATE:	NO.	BY:	DATE:	S-61
FINAL UNLESS ALL	1			3			TOTAL SHEETS
SIGNATURES COMPLETED	2			4			73

| Location (ft. from nearest bent, etc)Iat random throughoutINorth face, at random throughout | Brunswick
 | . 471

 |
 |
 | | | | | | | | | |
 | | | |

--
--

--
--|---|--|---|---
---|---|---|--|---|---
---|--|---|---|
| I at random throughout |
 | 、 <i>带(</i> 上

 |
 | Ι
 | I | As-Built C | Quantities | | | B | runswick | #71 | |
 | | As-Built C | Quantities |
| | Bent #
 | Defect Description

 | Length(ft.)
 | Width(ft.)
 | Depth(ft.) | Actual (C.F.) | Actual
Depth (ft.) | Span # | Component | Location (ft. from nearest bent, etc) | Bent # | Defect Description | Length(ft.) | Width(ft.)
 | Depth(ft.) | Actual (C.F.) | Actual
Depth (ft |
| North face, at random throughout |
 | (x11) Cracking (PSC)

 | 11.5
 | 1.5
 | | | | 16 | Girder 3 | North face, at Bent | 16 | Delam | 3 | 1.5
 | | | |
| il at random throughout |
 | (x2) Spalls
(x9) Cracking (PSC)

 | 1.5
9.5
 | 0.75
1.5
 | | | | 16
16 | Girder 3
Girder 4 | South face, 6" from end of beam, at Bent
South face, at Bent | 16 | Spall
Spall | 1.25
0.75 | 0.75
 | | | |
| North face, at random throughout |
 | (x2) Spalls

 | <u> </u>
 | 0.75
 | | | | 16 | Girder 5 | Bottom & South faces, 3' from Bent | 15 | (x2) Unsound Patched Area | 13 | 2
 | | | |
| Deck Eastboound lane, at Bent | 13
 | Delam

 | 2.5
 | 1.25
 | | | | 16 | Girder 5 | South face, 3" from end of beam, at Bent | 16 | Spall | 1 | 1
 | | | |
| North face, at mid span |
 | Unsound Patched Area

 | 1
 | 1
 | | | | 16 | Lt. Bridge Rail | Top of North face, starts 12' from Bent | 16 | (x7) Spalls | 10.5 | 1
 | | | |
| South face, 1" from end of beam, at Bent | 14
 | Cracking (PSC)

 | 1.5
1.5
 | 1.5
0.75
 | 0.75 | | | 16
17 | Lt. Bridge Rail | at random throughout | 17 | (x13) Cracking (RC and Other) | 13.5 | 1.5
1.5
 | | | |
| Bottom face, at Bent
West face | 13
 | Spall (x2) Spalls

 | 1.5
 |
 | 0.75 | | | | Girder 1
Girder 1 | South face, at Bent
3" from beam end. South face, at Bent | 17 | Cracking (PSC)
Spall | 0.75 |
 | | | |
| at end of beam, at Bent | 14
 | Delam

 | 1.5
 | 1.5
 | | | | 17 | Girder 1 | Northeast corner, at Bent | 17 | Delam | 1 | 3
 | 0.75 | | |
| 31' from Bent | 14
 | Spall

 | 1
 | 1
 | | | | 17 | Girder 2 | South face, at beam end, at Bent | 17 | Cracking (PSC) | 1.5 | 2
 | | | |
| South face, at Bent | 14
 | Delam

 | 1.25
 | 2.25
 | | | | 17 | Girder 2 | Bottom of beam, at Bent | 16 | Spall | 1.25 |
 | | | |
| | 14
 | •

 |
 |
 | | | | _ | | , | 17 | | |
 | | | |
| North face, at Bent | 13
 | Spall

 | 0.75
 | 0.75
 | | | | 17 | Girder 3 | Bottom of beam, at Bent | 16 | Spall | 1.25 | 1
 | | | |
| West face |
 | Spall

 | 1.5
 | 2
 | 1 | | | 17 | Girder 4 | North face, at Bent | 17 | Delam | 4.5 | 2.5
 | | | |
| South face, at mid span |
 | Unsound Patched Area

 | 1
 | 1
 | | | | 17 | Girder 4 | 2" from beam end, South face, at Bent | 17 | Spall | 0.75 | 1.25
 | | | |
| near end of beam, at Bent | 14
 | Delam

 | 1.75
 | 1.5
 | | | | 17 | Girder 4 | North face, at Bent
Bottom of beam, at Bent | 16 | Spall
Spall | 0.75 |
 | 0.75 | | |
| I at random throughout
I South face, 6' from Bent | 14
 |

 | 8.5
1.5
 | 1.5
1
 | | | | 17 | Girder 4
Girder 5 | at mid span, South face | 1 | Spall | 1.5 | 1.25
 | | | |
| il at random throughout |
 | (x8) Cracking (RC and Other)

 | 8.5
 | 1.5
 | | | | 17 | Girder 5 | North face, at Bent | 17 | Spall | 1.5 | 3.5
 | 0.75 | | |
| North face, at random throughout |
 | (x2) Spalls

 | 1.5
 | 0.75
 | | | | 17 | Girder 5 | North face, at Bent | 16 | Spall | 3.5 | 2
 | | | |
| Bottom face, 23' from Bent | 14
 | Unsound Patched Area

 | 4.5
 | 1.25
 | | | | 17 | Girder 5 | Bottom of beam, 31' from Bent | 16 | Spall | 1.5 | 1.25
 | | | |
| , |
 |

 |
 | 2
 | | | | | | , | | | |
 | 1 | | |
| Bottom face, 8' from Bent | 14
 | Delam

 | 2
 | 1.25
 | | | | 17 | Girder 5 | North face, at Bent | 16 | Cracking (PSC) | 1 | 2
 | - | | |
| Bottom face, 20' from Bent | 14
 | Delam

 | 2.5
 | 1.25
 | | | | 17 | Girder 5 | Bottom face, 14' from Bent | 17 | Delam | 3.5 | 2
 | | | |
| Bottom face, at strand hold down locations |
 | Spall

 | 1
 | 0.75
 | | | | 17 | Lt. Bridge Rail | at random throughout | | (x16) Cracking (RC and Other) | 16.5 | 1.5
 | | | |
| Southeast corner, at Bent |
 | •

 |
 | 2
 | 0.75 | | | 17 | - | at random throughout | 47 | (x15) Cracking (RC and Other) | | 1.5
 | | | |
| , |
 |

 | 1.75
 | 2
1.5
 | 0.75 | | | 17 | - | | 17 | • | | 1
 | | | |
| South face, at Bent | 15
 | Spall

 | 1.25
 | 1.75
 | | | | 18 | Girder 2 | Bottom flange, North face, 4' from Bent | 17 | Spall | 1.75 | 0.75
 | 0.75 | | |
| North face, at end of beam, at Bent | 15
 | Spall

 | 1.25
 | 2
 | | | | 18 | Girder 2 | 4" from beam end, North face, at Bent | 17 | Spall | 0.75 | 0.75
 | | | |
| Bottom face, at Bent | 14
 | Cracking (PSC)

 | 3.5
 | 1.5
 | | | | 18 | Girder 3 | North face, 1.5" from beam end, at Bent | 17 | Cracking (PSC) | 1.75 | 1.5
 | | | |
| |
 |

 |
 | 1.5
 | | | | | | , | 18 | | |
 | | | |
| 4" from beam end, at Bent |
 |

 |
 | 1.5
 | | | | | | Bottom face, at Bent | 17 | | 3.5 | 1.5
 | | | |
| North face, at end of beam, at Bent | 14
 | Spall

 | 1
 | 1
 | 2.5 | | | 18 | Girder 3 | South face, at Bent | 17 | Delam | 1.5 | 1.25
 | | | |
| South & Bottom faces, near mid-span |
 | Unsound Patched Area

 | 6.5
 | 1.5
 | 0.75 | | | 18 | Girder 3 | Bottom face, 12' from Bent | 17 | Delam | 5.5 | 0.75
 | 1.5 | | |
| South face, 3" from end of beam, at Bent |
 |

 |
 |
 | | | | | Girder 4 | South face, 5" from end of beam, at Bent | 18 | | 2.25 |
 | | | |
| , , , |
 |

 | 0.75
 |
 | 0.75 | | | _ | | , | | | |
 | | | |
| North face, 10" from end of beam, at Bent | 14
 | Spall

 | 1
 | 0.75
 | | | | 18 | Girder 4 | North face, at Bent | 17 | Delam | 1.75 | 1.75
 | | | |
| I at random throughout |
 | (x9) Cracking (RC and Other)

 | 9.5
 | 1.5
 | | | | 18 | Girder 4 | North face, 4" from end of beam, at Bent | 18 | Spall | 1 | 1
 | | | |
| I South face, 35' from Bent | 15
 | Spall

 | 0.75
 | 0.75
 | | | | 18 | Girder 5 | South face, 3" from end of beam, at Bent | 18 | Cracking (PSC) | 2.75 | 1.5
 | | | |
| |
 |

 |
 |
 | | | | _ | U | | | | |
 | | | |
| Deck Underside, at Beam 5, at Bent | 16
 | Spall

 | 4.5
 | 1
 | 1 | | | 18 | Rt. Bridge Rail | | 18 | Spall | 0.75 | 0.75
 | | | |
| South face, at Bent | 16
 | Spall

 | 1.25
 | 2.75
 | | | | 19 0 | | Deck underside, above Beam 1, at Bent | 18 | Spall | 1 | 1
 | 0.75 | | |
| South face, 3" from end of beam, at Bent | 16
 | Spall

 | 1.25
 | 1
 | | | | 19 | Girder 1 | South face, 5" from beam end, at Bent | 18 | Delam | 1.25 | 1.25
 | | | |
| | West faceat end of beam, at Bent31' from BentSouth face, at BentWest faceBottom face, 1' from BentNorth face, at BentWest faceSouth face, at mid spannear end of beam, at Bentat random throughoutSouth face, 6' from Bentat random throughoutNorth face, at random throughoutBottom face, 23' from BentBottom face, 23' from BentBottom face, at Bentnear end of beam, at BentBottom face, 8' from BentBottom face, 8' from BentBottom face, 20' from BentBottom face, at strand hold down locationsSoutheast corner, at BentNortheast corner, at BentSouth face, at end of beam, at BentSouth face, at BentNortheast corner, at BentSouth face, at end of beam, at BentSouth face, at BentNorth face, at BentNorth face, at BentSouth face of web, 8'' from end, at Bent4'' from beam end, at BentSouth face, at end of beam, at BentSouth face, 3'' from end of beam, at BentSouth face, 3''' from end of beam, at BentSouth face, 4''' from end of beam, at BentNorth face, at BentNorth face, at BentNorth face, at Co''' from end of beam, at BentSouth face, 3''' from end of beam, at BentAuth face, 10''' from end of beam, at BentNorth face, at Bent </td <td>West face14at end of beam, at Bent1431' from Bent14South face, at Bent14West face14Bottom face, 1' from Bent14North face, at Bent13West face13South face, at mid span14at random throughout14at random throughout14at random throughout14Bottom face, 6' from Bent14at random throughout14Bottom face, 23' from Bent14Bottom face, at Pent14Bottom face, at Sent14Bottom face, at Strand hold down locations15South face, at Bent15South face, at Bent15North face, at Bent15North face, at Bent14South face, at Bent14South face, at Bent14South face, at Bent15North face, at Bent15North face, at Bent15North face, at Bent14South face, at Bent14South face, at Bent15North face, at Bent15North face, at Bent15<td>West face(x2) Spallsat end of beam, at Bent14Delam31' from Bent14DelamSouth face, at Bent14SpallBottom face, 1' from Bent14SpallNorth face, at Bent13SpallWest faceSpallSouth face, at Bent13SpallWest faceSpallSouth face, at mid spanUnsound Patched Areanear end of beam, at Bent14Delamat random throughout(x8) Cracking (RC and Other)South face, at mid span(x8) Cracking (RC and Other)North face, at random throughout(x8) Cracking (RC and Other)North face, at random throughout(x2) SpallsBottom face, 23' from Bent14Unsound Patched AreaBottom face, 23' from Bent14Unsound Patched AreaBottom face, at Bent13SpallBottom face, at Bent14DelamBottom face, at Strand hold down locationsSoutheast corner, at Bent15SpallNorth face, at Bent15Southeast corner, at Bent15SpallNorth face, at Bent15SpallNorth face, at Bent14DelamSoutheast corner, at Bent15SpallNorth face, at Bent15SpallNorth face, at Bent15SpallNorth face, at Bent14DelamSoutheast corner, at Bent15<td< td=""><td>West face(x2) Spalls1at end of beam, at Bent14Delam1.532. from Bent14Spall1South face, at Bent14Delam1.25West faceSpall0.75Bottom face, at Irom Bent14Spall1.25North face, at Bent13Spall0.75South face, at mid spanUnsound Patched Area1near end of beam, at Bent14Delam1.75at random throughout(x8) Cracking (RC and Other)8.5South face, at random throughout(x8) Cracking (RC and Other)8.5North face, at random throughout(x9) Spalls1.5Bottom face, 37 from Bent14Unsound Patched Area4.5Bottom face, 37 from Bent14Unsound Patched Area4.5Bottom face, 37 from Bent14Delam1.75Bottom face, 38 from Bent14Delam2.5Bottom face, 37 from Bent14Delam2.5Bottom face, 38 from Bent14Delam2.5Bottom face, 38 from Bent15Spall1Southeast corner, at Bent15Spall1Southeast corner, at Bent15Spall1Southeast corner, at Bent15Spall1Southeast corner, at Bent15Spall1.25North face, at end hold down locationsSpall1Southeast corner, at Bent15Spall1.25North face, at end hold down locationsSpa</td><td>West face (x2) Spalls 1 0.75 at end of beam, at Bent 14 Delam 1.5 1.5 31 from Bent 14 Spall 1 1 South face, at Bent 14 Spall 1.25 2.25 West face Spall 0.75 1.75 1.75 Bottom face, 1'rom Bent 14 Spall 0.75 0.75 North face, at Bent 13 Spall 0.75 0.75 South face, at Indiagan Unsound Patched Area 1 1 near end of beam, at Bent 14 Delam 1.75 1.5 South face, efform Bent 14 Delam 1.75 1.5 at random throughout (x8) Gracking (R C and Other) 8.5 1.5 South face, at Bent 13 Spall 1.5 1 at aradom throughout (x9) Spalls 1.5 1 1.5 South face, at Bent 13 Spall 1.5 1.2 Bottom face, 37 form Bent 1.4 <</td><td>West face (x2) Spalls 1 0.75 at end of beam, at Bent 144 Delam 1.5 1.5 Suff fore Bent 144 Spall 1.5 1.5 West face Spall 0.75 1.75 West face Spall 0.75 1.75 West face Spall 0.75 0.75 West face Spall 0.75 0.75 West face Spall 0.75 0.75 West face Spall 0.75 1.5 South face, at mid span 14 Delam 1.5 1 Rer end of beam, at Bent 144 Delam 1.5 1 At random throughout (x3) Cracking (RC and Other) 8.5 1.5 South face, 6' from Bent 144 Unsound Patched Area 4.5 1.25 Bottom face, 23' from Bent 144 Unsound Patched Area 4.5 1.25 Bottom face, 3' from Bent 144 Delam 1.5 2 Bottom face, 3' strand hold dwn location</td><td>West face10.7510.75at end of learn, at Bent14Delarn1.51.5South face, at Eent14Spail1.51.5Wost face, at Eent14Spail0.751.76West face13Spail0.751.761.6North face, at Bent13Spail0.750.761.6North face, at Bent13Spail1.521South face, at mid spain14Delarn1.751.51.5North face, at mid spain14Delarn1.751.51.5South face, for moment14Delarn1.751.51.5South face, for moment14Delarn1.751.51.5South face, for moment14Delarn1.51.51.5South face, for moment14Delarn1.51.51.5North face, at random throughout128O.753.51.51.5Bottom face, 20 from Bent1.4Delarn1.51.51.5Bottom face, 20 from Bent1.4Delarn2.51.251.5Bottom face, 20 from Bent1.4Delarn2.51.251.5Bottom face, 20 from Bent1.4Delarn2.51.251.5Bottom face, 20 from Bent1.5Spail1.40.751.761.5Bottom face, 20 from Bent1.5Spail1.51.51.51.51.5Bo</td><td>West face (x2) Spuils 1 0.75 () () at rand or beam, at Bent 1.4 Delam 1.5 1.5 () () Surf trans, at Bent 1.4 Delam 1.25 2.25 () () South face, at Bent 1.4 Delam 1.26 2.75 () () Bottom face, at Bent 1.4 Spail 0.75 1.75 () () West face Spail 0.75 1.5 () () () West face, at time span Unsound Patched Ares 1 1 () () South face, at time span Unsound Patched Ares 1.5 1.5 () () At random throughout (AS) Gracking (RG and Other) 8.55 1.5 () () South face, at time span 1.4 Unsound Patched Area 1.5 1.5 () () South face, at time throughout (AS) Gracking (RG and Other) 8.5 1.5 () () South face, at</td><td>Vest Isce(-2) Spalls10.75//////17at end of beam, at Bent1.40.98m1.51.51.51.717South face, at Bent1.40.98m0.751.751.751.751.751.75Bottom face, 3t Fom Bent1.4Spall0.750.751.751.751.751.77Bottom face, 3t Fom Bent1.4Spall0.750.750.751.771.771.77Noth face, at Bent1.3Spall0.750.750.751.77</td><td>West free 1 0.75 0 17 0 inder 1 ist ord of Dama at Bast 14 5pail 1.5 1.5 1.7 0 inder 1 Sk from Bert 1.4 5pail 1.15 2.8 1.7 0 inder 2 South face, at Bart 1.24 6pail 0.75 1.75 1.7 0 inder 2 Bottom face, 1f from Bert 1.3 5pail 0.75 0.75 1.7 0 inder 2 Bottom face, 1f from Bert 1.4 5pail 1.5 1.7 0 inder 3 South face, at Bert 1.3 5pail 1.5 1.7 0 inder 4 South face, at Bent 1.4 1 1.7 0 inder 4 South face, At Bent 1.4 1.5 1.5 1.7 0 inder 4 South face, At Bent 1.4 0 inder 4 1.7 0 inder 4 South face, At Bent 1.4 0 inder 4 1.5 1.5 1.7 0 inder 5 South face, At Bent 1.4 0 inder 5 1.5</td><td>Wate of each of the set of t</td><td>Vertices
and end scaleDisplayDisplayIDD<</td><td>MemiM</td><td>Network Nome A No No No No <t< td=""><td>PictorPict</td><td>Network Network <</td><td>Index Image Image <</td></t<></td></td<></td></td> | West face14at end of beam, at Bent1431' from Bent14South face, at Bent14West face14Bottom face, 1' from Bent14North face, at Bent13West face13South face, at mid span14at random throughout14at random throughout14at random throughout14Bottom face, 6' from Bent14at random throughout14Bottom face, 23' from Bent14Bottom face, at Pent14Bottom face, at Sent14Bottom face, at Strand hold down locations15South face, at Bent15South face, at Bent15North face, at Bent15North face, at Bent14South face, at Bent14South face, at Bent14South face, at Bent15North face, at Bent15North face, at Bent15North face, at Bent14South face, at Bent14South face, at Bent15North face, at Bent15North face, at Bent15 <td>West face(x2) Spallsat end of beam, at Bent14Delam31' from Bent14DelamSouth face, at Bent14SpallBottom face, 1' from Bent14SpallNorth face, at Bent13SpallWest faceSpallSouth face, at Bent13SpallWest faceSpallSouth face, at mid spanUnsound Patched Areanear end of beam, at Bent14Delamat random throughout(x8) Cracking (RC and Other)South face, at mid span(x8) Cracking (RC and Other)North face, at random throughout(x8) Cracking (RC and Other)North face, at random throughout(x2) SpallsBottom face, 23' from Bent14Unsound Patched AreaBottom face, 23' from Bent14Unsound Patched AreaBottom face, at Bent13SpallBottom face, at Bent14DelamBottom face, at Strand hold down locationsSoutheast corner, at Bent15SpallNorth face, at Bent15Southeast corner, at Bent15SpallNorth face, at Bent15SpallNorth face, at Bent14DelamSoutheast corner, at Bent15SpallNorth face, at Bent15SpallNorth face, at Bent15SpallNorth face, at Bent14DelamSoutheast corner, at Bent15<td< td=""><td>West face(x2) Spalls1at end of beam, at Bent14Delam1.532. from Bent14Spall1South face, at Bent14Delam1.25West faceSpall0.75Bottom face, at Irom Bent14Spall1.25North face, at Bent13Spall0.75South face, at mid spanUnsound Patched Area1near end of beam, at Bent14Delam1.75at random throughout(x8) Cracking (RC and Other)8.5South face, at random throughout(x8) Cracking (RC and Other)8.5North face, at random throughout(x9) Spalls1.5Bottom face, 37 from Bent14Unsound Patched Area4.5Bottom face, 37 from Bent14Unsound Patched Area4.5Bottom face, 37 from Bent14Delam1.75Bottom face, 38 from Bent14Delam2.5Bottom face, 37 from Bent14Delam2.5Bottom face, 38 from Bent14Delam2.5Bottom face, 38 from Bent15Spall1Southeast corner, at Bent15Spall1Southeast corner, at Bent15Spall1Southeast corner, at Bent15Spall1Southeast corner, at Bent15Spall1.25North face, at end hold down locationsSpall1Southeast corner, at Bent15Spall1.25North face, at end hold down locationsSpa</td><td>West face (x2) Spalls 1 0.75 at end of beam, at Bent 14 Delam 1.5 1.5 31 from Bent 14 Spall 1 1 South face, at Bent 14 Spall 1.25 2.25 West face Spall 0.75 1.75 1.75 Bottom face, 1'rom Bent 14 Spall 0.75 0.75 North face, at Bent 13 Spall 0.75 0.75 South face, at Indiagan Unsound Patched Area 1 1 near end of beam, at Bent 14 Delam 1.75 1.5 South face, efform Bent 14 Delam 1.75 1.5 at random throughout (x8) Gracking (R C and Other) 8.5 1.5 South face, at Bent 13 Spall 1.5 1 at aradom throughout (x9) Spalls 1.5 1 1.5 South face, at Bent 13 Spall 1.5 1.2 Bottom face, 37 form Bent 1.4 <</td><td>West face (x2) Spalls 1 0.75 at end of beam, at Bent 144 Delam 1.5 1.5 Suff fore Bent 144 Spall 1.5 1.5 West face Spall 0.75 1.75 West face Spall 0.75 1.75 West face Spall 0.75 0.75 West face Spall 0.75 0.75 West face Spall 0.75 0.75 West face Spall 0.75 1.5 South face, at mid span 14 Delam 1.5 1 Rer end of beam, at Bent 144 Delam 1.5 1 At random throughout (x3) Cracking (RC and Other) 8.5 1.5 South face, 6' from Bent 144 Unsound Patched Area 4.5 1.25 Bottom face, 23' from Bent 144 Unsound Patched Area 4.5 1.25 Bottom face, 3' from Bent 144 Delam 1.5 2 Bottom face, 3' strand hold dwn location</td><td>West face10.7510.75at end of learn, at Bent14Delarn1.51.5South face, at Eent14Spail1.51.5Wost face, at Eent14Spail0.751.76West face13Spail0.751.761.6North face, at Bent13Spail0.750.761.6North face, at Bent13Spail1.521South face, at mid spain14Delarn1.751.51.5North face, at mid spain14Delarn1.751.51.5South face, for moment14Delarn1.751.51.5South face, for moment14Delarn1.751.51.5South face, for moment14Delarn1.51.51.5South face, for moment14Delarn1.51.51.5North face, at random throughout128O.753.51.51.5Bottom face, 20 from Bent1.4Delarn1.51.51.5Bottom face, 20 from Bent1.4Delarn2.51.251.5Bottom face, 20 from Bent1.4Delarn2.51.251.5Bottom face, 20 from Bent1.4Delarn2.51.251.5Bottom face, 20 from Bent1.5Spail1.40.751.761.5Bottom face, 20 from Bent1.5Spail1.51.51.51.51.5Bo</td><td>West face (x2) Spuils 1 0.75 () () at rand or beam, at Bent 1.4 Delam 1.5 1.5 () () Surf trans, at Bent 1.4 Delam 1.25 2.25 () () South face, at Bent 1.4 Delam 1.26 2.75 () () Bottom face, at Bent 1.4 Spail 0.75 1.75 () () West face Spail 0.75 1.5 () () () West face, at time span Unsound Patched Ares 1 1 () () South face, at time span Unsound Patched Ares 1.5 1.5 () () At random throughout (AS) Gracking (RG and Other) 8.55 1.5 () () South face, at time span 1.4 Unsound Patched Area 1.5 1.5 () () South face, at time throughout (AS) Gracking (RG and Other) 8.5 1.5 () () South face, at</td><td>Vest Isce(-2) Spalls10.75//////17at end of beam, at Bent1.40.98m1.51.51.51.717South face, at Bent1.40.98m0.751.751.751.751.751.75Bottom face, 3t Fom Bent1.4Spall0.750.751.751.751.751.77Bottom face, 3t Fom Bent1.4Spall0.750.750.751.771.771.77Noth face, at Bent1.3Spall0.750.750.751.77</td><td>West free 1 0.75 0 17 0 inder 1 ist ord of Dama at Bast 14 5pail 1.5 1.5 1.7 0 inder 1 Sk from Bert 1.4 5pail 1.15 2.8 1.7 0 inder 2 South face, at Bart 1.24 6pail 0.75 1.75 1.7 0 inder 2 Bottom face, 1f from Bert 1.3 5pail 0.75 0.75 1.7 0 inder 2 Bottom face, 1f from Bert 1.4 5pail 1.5 1.7 0 inder 3 South face, at Bert 1.3 5pail 1.5 1.7 0 inder 4 South face, at Bent 1.4 1 1.7 0 inder 4 South face, At Bent 1.4 1.5 1.5 1.7 0 inder 4 South face, At Bent 1.4 0 inder 4 1.7 0 inder 4 South face, At Bent 1.4 0 inder 4 1.5 1.5 1.7 0 inder 5 South face, At Bent 1.4 0 inder 5 1.5</td><td>Wate of each of the set of t</td><td>Vertices
and end scaleDisplayDisplayIDD<</td><td>MemiM</td><td>Network Nome A No No No No <t< td=""><td>PictorPict</td><td>Network Network <</td><td>Index Image Image <</td></t<></td></td<></td> | West face(x2) Spallsat end of beam, at Bent14Delam31' from Bent14DelamSouth face, at Bent14SpallBottom face, 1' from Bent14SpallNorth face, at Bent13SpallWest faceSpallSouth face, at Bent13SpallWest faceSpallSouth face, at mid spanUnsound Patched Areanear end of beam, at Bent14Delamat random throughout(x8) Cracking (RC and Other)South face, at mid span(x8) Cracking (RC and Other)North face, at random throughout(x8) Cracking (RC and Other)North face, at random throughout(x2) SpallsBottom face, 23' from Bent14Unsound Patched AreaBottom face, 23' from Bent14Unsound Patched AreaBottom face, at Bent13SpallBottom face, at Bent14DelamBottom face, at Strand hold down locationsSoutheast corner, at Bent15SpallNorth face, at Bent15Southeast corner, at Bent15SpallNorth face, at Bent15SpallNorth face, at Bent14DelamSoutheast corner, at Bent15SpallNorth face, at Bent15SpallNorth face, at Bent15SpallNorth face, at Bent14DelamSoutheast corner, at Bent15 <td< td=""><td>West face(x2) Spalls1at end of beam, at Bent14Delam1.532. from Bent14Spall1South face, at Bent14Delam1.25West faceSpall0.75Bottom face, at Irom Bent14Spall1.25North face, at Bent13Spall0.75South face, at mid spanUnsound Patched Area1near end of beam, at Bent14Delam1.75at random throughout(x8) Cracking (RC and Other)8.5South face, at random throughout(x8) Cracking (RC and Other)8.5North face, at random throughout(x9) Spalls1.5Bottom face, 37 from Bent14Unsound Patched Area4.5Bottom face, 37 from Bent14Unsound Patched Area4.5Bottom face, 37 from Bent14Delam1.75Bottom face, 38 from Bent14Delam2.5Bottom face, 37 from Bent14Delam2.5Bottom face, 38 from Bent14Delam2.5Bottom face, 38 from Bent15Spall1Southeast corner, at Bent15Spall1Southeast corner, at Bent15Spall1Southeast corner, at Bent15Spall1Southeast corner, at Bent15Spall1.25North face, at end hold down locationsSpall1Southeast corner, at Bent15Spall1.25North face, at end hold down locationsSpa</td><td>West face (x2) Spalls 1 0.75 at end of beam, at Bent 14 Delam 1.5 1.5 31 from Bent 14 Spall 1 1 South face, at Bent 14 Spall 1.25 2.25 West face Spall 0.75 1.75 1.75 Bottom face, 1'rom Bent 14 Spall 0.75 0.75 North face, at Bent 13 Spall 0.75 0.75 South face, at Indiagan Unsound Patched Area 1 1 near end of beam, at Bent 14 Delam 1.75 1.5 South face, efform Bent 14 Delam 1.75 1.5 at random throughout (x8) Gracking (R C and Other) 8.5 1.5 South face, at Bent 13 Spall 1.5 1 at aradom throughout (x9) Spalls 1.5 1 1.5 South face, at Bent 13 Spall 1.5 1.2 Bottom face, 37 form Bent 1.4 <</td><td>West face (x2) Spalls 1 0.75 at end of beam, at Bent 144 Delam 1.5 1.5 Suff fore Bent 144 Spall 1.5 1.5 West face Spall 0.75 1.75 West face Spall 0.75 1.75 West face Spall 0.75 0.75 West face Spall 0.75 0.75 West face Spall 0.75 0.75 West face Spall 0.75 1.5 South face, at mid span 14 Delam 1.5 1 Rer end of beam, at Bent 144 Delam 1.5 1 At random throughout (x3) Cracking (RC and Other) 8.5 1.5 South face, 6' from Bent 144 Unsound Patched Area 4.5 1.25 Bottom face, 23' from Bent 144 Unsound Patched Area 4.5 1.25 Bottom face, 3' from Bent 144 Delam 1.5 2 Bottom face, 3' strand hold dwn location</td><td>West face10.7510.75at end of learn, at Bent14Delarn1.51.5South face, at Eent14Spail1.51.5Wost face, at Eent14Spail0.751.76West face13Spail0.751.761.6North face, at Bent13Spail0.750.761.6North face, at Bent13Spail1.521South face, at mid spain14Delarn1.751.51.5North face, at mid spain14Delarn1.751.51.5South face, for moment14Delarn1.751.51.5South face, for moment14Delarn1.751.51.5South face, for moment14Delarn1.51.51.5South face, for moment14Delarn1.51.51.5North face, at random throughout128O.753.51.51.5Bottom face, 20 from Bent1.4Delarn1.51.51.5Bottom face, 20 from Bent1.4Delarn2.51.251.5Bottom face, 20 from Bent1.4Delarn2.51.251.5Bottom face, 20 from Bent1.4Delarn2.51.251.5Bottom face, 20 from Bent1.5Spail1.40.751.761.5Bottom face, 20 from Bent1.5Spail1.51.51.51.51.5Bo</td><td>West face (x2) Spuils 1 0.75 () () at rand or beam, at Bent 1.4 Delam 1.5 1.5 () () Surf trans, at Bent 1.4 Delam 1.25 2.25 () () South face, at Bent 1.4 Delam 1.26 2.75 () () Bottom face, at Bent 1.4 Spail 0.75 1.75 () () West face Spail 0.75 1.5 () () () West face, at time span Unsound Patched Ares 1 1 () () South face, at time span Unsound Patched Ares 1.5 1.5 () () At random throughout (AS) Gracking (RG and Other) 8.55 1.5 () () South face, at time span 1.4 Unsound Patched Area 1.5 1.5 () () South face, at time throughout (AS) Gracking (RG and Other) 8.5 1.5 () () South face, at</td><td>Vest Isce(-2) Spalls10.75//////17at end of beam, at Bent1.40.98m1.51.51.51.717South face, at Bent1.40.98m0.751.751.751.751.751.75Bottom face, 3t Fom Bent1.4Spall0.750.751.751.751.751.77Bottom face, 3t Fom Bent1.4Spall0.750.750.751.771.771.77Noth face, at Bent1.3Spall0.750.750.751.77</td><td>West free 1 0.75 0 17 0 inder 1 ist ord of Dama at Bast 14 5pail 1.5 1.5 1.7 0 inder 1 Sk from Bert 1.4 5pail 1.15 2.8 1.7 0 inder 2 South face, at Bart 1.24 6pail 0.75 1.75 1.7 0 inder 2 Bottom face, 1f from Bert 1.3 5pail 0.75 0.75 1.7 0 inder 2 Bottom face, 1f from Bert 1.4 5pail 1.5 1.7 0 inder 3 South face, at Bert 1.3 5pail 1.5 1.7 0 inder 4 South face, at Bent 1.4 1 1.7 0 inder 4 South face, At Bent 1.4 1.5 1.5 1.7 0 inder 4 South face, At Bent 1.4 0 inder 4 1.7 0 inder 4 South face, At Bent 1.4 0 inder 4 1.5 1.5 1.7 0 inder 5 South face, At Bent 1.4 0 inder 5 1.5</td><td>Wate of each of the set of t</td><td>Vertices
and end scaleDisplayDisplayIDD<</td><td>MemiM</td><td>Network Nome A No No No No <t< td=""><td>PictorPict</td><td>Network Network <</td><td>Index Image Image <</td></t<></td></td<> | West face(x2) Spalls1at end of beam, at Bent14Delam1.532. from Bent14Spall1South face, at Bent14Delam1.25West faceSpall0.75Bottom face, at Irom Bent14Spall1.25North face, at Bent13Spall0.75South face, at mid spanUnsound Patched Area1near end of beam, at Bent14Delam1.75at random throughout(x8) Cracking (RC and Other)8.5South face, at random throughout(x8) Cracking (RC and Other)8.5North face, at random throughout(x9) Spalls1.5Bottom face, 37 from Bent14Unsound Patched Area4.5Bottom face, 37 from Bent14Unsound Patched Area4.5Bottom face, 37 from Bent14Delam1.75Bottom face, 38 from Bent14Delam2.5Bottom face, 37 from Bent14Delam2.5Bottom face, 38 from Bent14Delam2.5Bottom face, 38 from Bent15Spall1Southeast corner, at Bent15Spall1Southeast corner, at Bent15Spall1Southeast corner, at Bent15Spall1Southeast corner, at Bent15Spall1.25North face, at end hold down locationsSpall1Southeast corner, at Bent15Spall1.25North face, at end hold down locationsSpa | West face (x2) Spalls 1 0.75 at end of beam, at Bent 14 Delam 1.5 1.5 31 from Bent 14 Spall 1 1 South face, at Bent 14 Spall 1.25 2.25 West face Spall 0.75 1.75 1.75 Bottom face, 1'rom Bent 14 Spall 0.75 0.75 North face, at Bent 13 Spall 0.75 0.75 South face, at Indiagan Unsound Patched Area 1 1 near end of beam, at Bent 14 Delam 1.75 1.5 South face, efform Bent 14 Delam 1.75 1.5 at random throughout (x8) Gracking (R C and Other) 8.5 1.5 South face, at Bent 13 Spall 1.5 1 at aradom throughout (x9) Spalls 1.5 1 1.5 South face, at Bent 13 Spall 1.5 1.2 Bottom face, 37 form Bent 1.4 < | West face (x2) Spalls 1 0.75 at end of beam, at Bent 144 Delam 1.5 1.5 Suff fore Bent 144 Spall 1.5 1.5 West face Spall 0.75 1.75 West face Spall 0.75 1.75 West face Spall 0.75 0.75 West face Spall 0.75 0.75 West face Spall 0.75 0.75 West face Spall 0.75 1.5 South face, at mid span 14 Delam 1.5 1 Rer end of beam, at Bent 144 Delam 1.5 1 At random throughout (x3) Cracking (RC and Other) 8.5 1.5 South face, 6' from Bent 144 Unsound Patched Area 4.5 1.25 Bottom face, 23' from Bent 144 Unsound Patched Area 4.5 1.25 Bottom face, 3' from Bent 144 Delam 1.5 2 Bottom face, 3' strand hold dwn location | West face10.7510.75at end of learn, at Bent14Delarn1.51.5South face, at Eent14Spail1.51.5Wost face, at Eent14Spail0.751.76West face13Spail0.751.761.6North face, at Bent13Spail0.750.761.6North face, at Bent13Spail1.521South face, at mid spain14Delarn1.751.51.5North face, at mid spain14Delarn1.751.51.5South face, for moment14Delarn1.751.51.5South face, for moment14Delarn1.751.51.5South face, for moment14Delarn1.51.51.5South face, for moment14Delarn1.51.51.5North face, at random throughout128O.753.51.51.5Bottom face, 20 from Bent1.4Delarn1.51.51.5Bottom face, 20 from Bent1.4Delarn2.51.251.5Bottom face, 20 from Bent1.4Delarn2.51.251.5Bottom face, 20 from Bent1.4Delarn2.51.251.5Bottom face, 20 from Bent1.5Spail1.40.751.761.5Bottom face, 20 from Bent1.5Spail1.51.51.51.51.5Bo | West face (x2) Spuils 1 0.75 () () at rand or beam, at Bent 1.4 Delam 1.5 1.5 () () Surf trans, at Bent 1.4 Delam 1.25 2.25 () () South face, at Bent 1.4 Delam 1.26 2.75 () () Bottom face, at Bent 1.4 Spail 0.75 1.75 () () West face Spail 0.75 1.5 () () () West face, at time span Unsound Patched Ares 1 1 () () South face, at time span Unsound Patched Ares 1.5 1.5 () () At random throughout (AS) Gracking (RG and Other) 8.55 1.5 () () South face, at time span 1.4 Unsound Patched Area 1.5 1.5 () () South face, at time throughout (AS) Gracking (RG and Other) 8.5 1.5 () () South face, at | Vest Isce(-2) Spalls10.75//////17at end of beam, at Bent1.40.98m1.51.51.51.717South face, at Bent1.40.98m0.751.751.751.751.751.75Bottom face, 3t Fom Bent1.4Spall0.750.751.751.751.751.77Bottom face, 3t Fom Bent1.4Spall0.750.750.751.771.771.77Noth face, at Bent1.3Spall0.750.750.751.77 | West free 1 0.75 0 17 0 inder 1 ist ord of Dama at Bast 14 5pail 1.5 1.5 1.7 0 inder 1 Sk from Bert 1.4 5pail 1.15 2.8 1.7 0 inder 2 South face, at Bart 1.24 6pail 0.75 1.75 1.7 0 inder 2 Bottom face, 1f from Bert 1.3 5pail 0.75 0.75 1.7 0 inder 2 Bottom face, 1f from Bert 1.4 5pail 1.5 1.7 0 inder 3 South face, at Bert 1.3 5pail 1.5 1.7 0 inder 4 South face, at Bent 1.4 1 1.7 0 inder 4 South face, At Bent 1.4 1.5 1.5 1.7 0 inder 4 South face, At Bent 1.4 0 inder 4 1.7 0 inder 4 South face, At Bent 1.4 0 inder 4 1.5 1.5 1.7 0 inder 5 South face, At Bent 1.4 0 inder 5 1.5 | Wate of each of the set of t | Vertices
and end scaleDisplayDisplayIDD< | MemiM | Network Nome A No No No No <t< td=""><td>PictorPict</td><td>Network Network <</td><td>Index Image Image <</td></t<> | PictorPict | Network < | Index Image Image < |

+

4800 SIX FORKS ROAD SUITE 120 RALEIGH, NC 27609 (919) 882-7839

DRAWN BY :	AARON J. MCMILLAN	DATE : 03-2018	
CHECKED BY :	DIEGO A.AGUIRRE	DATE : 03-2018	
DESIGN ENGINEER	OF RECORD : SAMUEL L.CULLUM	DATE : <u>03-2018</u>	
		5/9/2018	


5/9/2018 G:\4201720.03-Brunswick-71\Structures\401_325_15BPR.16_SMU_DEF03_S-62_090071.dgn User:jduke

			REVI	SION	IS		SHEET NO.
DOCUMENT NOT CONSIDERED	N0.	BY:	DATE:	NO.	BY:	DATE:	S-62
FINAL UNLESS ALL	1			3			TOTAL SHEETS
SIGNATURES COMPLETED	2			4			73

		Brunswick	< #71			As-Built Quantities			Brunswick #71		As-Built Quantities
Span #	Component	Location (ft. from nearest bent, etc) Bent #		Length(ft.)	Width(ft.) Depth(ft.) Actua	al (C.F.) Actual Depth (ft.) Span #	Component	Location (ft. from nearest bent, etc)	Bent # Defect Description	Length(ft.)	Width(ft.)Depth(ft.)Actual (C.F.)ActualDepth (ft.)Depth (ft.)Depth (ft.)
19	Girder 2	North face, at end of beam, at Bent19	Exposed Prestressing	0.75	1.5 1	23	Rt. Bridge Rail	at random throughout	(x6) Cracking (RC and Other)	6.5	1.5 Deptil (11.)
19 19		North face, 1' from beam, at Bent18North face, 3" from end of beam, at Bent19	Delam Cracking (PSC)	1.25 2.25	1.25 1.5						
19		South face, 3" from end of beam, at Bent19	Cracking (PSC)	1.75	1.5						
19 19	Girder 4	North face, 5" from end of beam, at Bent18North face, 2" from end of beam, at Bent18	Spall Spall	1	1						
19 19		North face, 2" from end of beam, at Bent18North face, at Bent19	Delam	1.25	1.25						
19	Lt. Bridge Rail	at Bent 18	Spall	1	1.5 1						
19 20	Lt. Bridge Rail Girder 2	at random throughoutBottom face, at Bent19	(x3) Cracking (RC and Other) Spall	3.5 1	1.5 1.75						
20		North face, 10" from end of beam , at Bent 19	Delam	1.5	1.5						
20 20	Girder 2 Girder 3	North face, 2" from end of beam, at Bent19Bottom & South faces, near Bent19	Spall Unsound Patched Area	1	1 5.5						
20		North face, at Bent20	Cracking (PSC)	2.75	1.5						
20 20		South face, 3" from end of beam, at Bent19North face, 3" from end of beam, at Bent20	Cracking (PSC) Cracking (PSC)	1.75	1.5 1.5						
20	Girder 5	North face, at Bent2020	Cracking (PSC)	1.5	1.5						
20		at random throughout	(x8) Cracking (RC and Other)	8.5	1.5						
20 21 C	-	at random throughout8' from left bridge rail, 14' from Bent21	(x2) Cracking (RC and Other) Spall	2.5 1	1.5 1						
21	Girder 1	North face, at beam end, at Bent 20	Delam	1	1						
21 21	Girder 2 Girder 2	Bottom of beam, 12' from Cap 1Bottom face, 14' from Bent20	Unsound Patched Area Delam	2.5 1.5	1.5 1.5						
21		East face, at Bent2021	Delam	1.5	2.25						
21 21		North face, at Bent20Bottom face, 22' from Bent20	Delam Delam	1.25 8.5	1.25 1.5						
21		North face, 6" from end of beam, at Bent20	Spall	1.5	1.5						
21		North & Bottom faces, 1.5' from beam end at Ber 20	Unsound Patched Area	7	1 1.25						
21 21		North face, 4" from end of beam, at Bent20North face, at Bent20	Spall Cracking (PSC)	1 2.5	0.75 1.5						
21	Girder 5	Bottom face, at Bent 20	Spall	1	1.25						
21 21	Lt. Bridge Rail Rt. Bridge Rail	at random throughout at random throughout	(x7) Cracking (RC and Other) (x13) Cracking (RC and Other)	7.5 13.5	1.5 1.5						
22	_	Bottom face, 23' from Bent21	Spall	1	1						
22 22		North face, 2" from end of beam, at Bent22Bottom face, 23' from Bent22	Cracking (PSC) Spall	2.5	1.5						
22		North face, at Bent21	Delam	2.5	1 0.75						
22 22		South face, at Bent22Beam end, at Bent22	Cracking (PSC) Cracking (PSC)	2.5 0.75	1.5 2.75 0.75						
22	Girder 5	Bottom face, 22' from Bent21	Spall	1	1						
22		at random throughout	(x4) Cracking (RC and Other)	4.5	1.5						
22 23	6	at random throughoutBottom face, 23' from EB 2EB2	(x2) Cracking (RC and Other) Spall	2.5 1	1.5 1						
23		North & Bottom faces, at Bent 22	Delam	3	0.75 0.75						
23 23		North corner, Bottom flange, at Bent22Bottom face, 23' from EB 2EB2	Delam Spall	3.5 1	1.25 0.75 1						
23		Bottom face, 22' from EB 2 EB2	Spall	1	1						
23 23		Bottom face, 22' from Bent223' from Bent22	Spall Spall	<u> </u>							
23	0	at random throughout	(x5) Cracking (RC and Other)	5.5	1.5						
KISINGER CA & ASSOCIA		FORKS ROAD SUITE 120 , NC 27609 2-7839		 2. REPAI BEST 3. THE E EACH 4. COORD 5. IF AD NECES SHEET AND W 	EFECTS WERE TAKEN FROM R LOCATIONS AND ESTIM INFORMATION AVAILABLE NGINEER SHALL FILL OUT LISTED DEFICIENCY. INATE THIS SHEET WITH OITIONAL REPAIRS, NOT SARY BY THE ENGINEER, THE APPROXIMATE LOCA VILL ADJUST THE ACTUAL R QUANTITIES TABLE.	ATED QUANTITIES ARE THE AS-BUILT REPAIR SHEETS S-32 THRU S-5 SHOWN ON SHEETS S-35 THE ENGINEER WILL NOT TIONS AND THE DESCRIF	GIVEN WITH THE QUANTITY FOR 7. THRU S-57, ARE E ON THE CORRE PTION OF THE R	DEEMED SPONDING EPAIRS,	DocuSigned by: Samuel L Column SEAL 19C97095C75A467 SEAL 043571 5/9/2018 2:14	BRI SHEET	JECT NO. <u>15BPR.16</u> BRUNSWICK COUNTY DGE NO. <u>71</u> 4 OF 4 STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH SUPERSTRUCTURE DEFICIENCIES
DRAWN BY : CHECKED BY : DESIGN ENGIN			\401_330_15BPR.16_SMU_DEF04_S-63_090071.dgn						DOCUMENT NOT CONS FINAL UNLESS A SIGNATURES COMPL	IDERED LL 1 ETED 2	BY: DATE: NO. BY: DATE: S-63 3 3 TOTAL SHEETS 4 73



G:\4201720.03-Brunswick-71\Structures\401_330_15BPR.16_SMU_DEF04_S-63_090071.dgn User:jduke




User:jduke


NOTES:

- FOR NAVIGATIONAL LIGHT SYSTEM, SEE SPECIAL PROVISIONS FOR "NAVIGATIONAL LIGHT SYSTEM".
- THE POWER SUPPLY SHALL BE TURNED OFF WHILE ANY CHANGES ARE 2. MADE TO THE NAVIGATIONAL LIGHT SYSTEM.
- THE CONTRACTOR IS RESPONSIBLE TO MAINTAIN AND ENSURE ALL 3. NAVIGATIONAL LIGHTS ARE OPERATIONAL FOR THE DURATION OF THE PROJECT IN ACCORDANCE WITH THE CODE OF FEDERAL GUIDELINES. THIS INCLUDES BUT IS NOT LIMITED TO INSTALLING (6) SIX TEMPORARY BATTERY OPERATED RED LIGHTS DURING THE CONSTRUCTION OF THE PROPOSED FENDER SYSTEM.
- THE CONTRACTOR'S ATTENTION IS BROUGHT TO NOTICE THAT THE 4. TOP GREEN NAVIGATIONAL LIGHTS ATTACHED TO THE BRIDGE RAIL ARE CURRENTLY POWERED BY THE SOLAR ARRAY ALSO ATTACHED TO THE BRIDGE RAIL. IF THE CONTRACTOR OR ENGINEER NOTICES ANY MALFUNCTION WITH THESE LIGHTS AND NO REPAIRS CAN BE MADE CONTACT THE NCDOT IMMEDIATELY (SEE NOTE 8 FOR CONTACT INFORMATION).
- 5. ALL CONNECTIONS SHALL BE MADE PER NFPA 70 ELECTRIC CODE (NEC) BY A CURRENT LICENSED ELECTRICIAN.
- 6. ALL ITEMS REQUIRED TO INSTALL ANY TEMPORARY NAVIGATIONAL LIGHTS OR POWER SOURCES SHALL BE CONSIDERED INCIDENTAL TO VARIOUS PAY ITEM FOR THE PROJECT.
- 7. DECOMMISIONING AND RECOMMISSIONING OF THE FENDER SYSTEM'S PERMANENT NAVIGATIONAL LIGHTS SHALL BE PERFORMED BY THE NCDOT AFTER THE COMPLETION OF THE PROPOSED FENDER SYSTEM.
- THE CONTRACTOR SHALL NOTIFY THE NCDOT JOHN LANGE AT 8. (910) 262-6319 (2) TWO WEEKS PRIOR TO THE COMPLETION OF THE PROPOSED FENDER SYSTEM TO CORRODINATE THE INSTALLATION OF THE PROPOSED NAVIGATIONAL LIGHTS.

		RUNSI		BPR.1 CC 71	6 UNTY
DocuSigned by: Samuel L Colom 19C97095C75A467 5/9/2018 2:14 SEAL 043571 5/9/2018 2:14		rtment 'IGAT	RALEIGH	NSPORTA	
		REVIS	SIONS		SHEET NO.
DOCUMENT NOT CONSIDERED	NO. BY:	DATE:	NO. BY:	DATE:	S-64
FINAL UNLESS ALL	1		3		TOTAL SHEETS
SIGNATURES COMPLETED	2		4		73

+






PRELIMINARY JACKING LOADS FACTORED LIVE LOAD FACTORED DEAD LOAD NO IMPACT (KIPS) 105 105 105 105 105 FACTORED FACTORED LIVE LOAD DEAD LOAD NO IMPACT (KIPS) 65 65 65 65 65


			REVIS	SION	1S		SHEET NO.
DOCUMENT NOT CONSIDERED	N0.	BY:	DATE:	NO.	BY:	DATE:	S-65
FINAL UNLESS ALL	1			3			TOTAL SHEETS
SIGNATURES COMPLETED	2			4			73

+




MAXIMUM ALLOWABLE SERVICE LOADS						
D.L.+L.L. (NO IMPACT)						
TYPE IV	225 k					

BEARING REPLACEMENT TABLE								
SPAN BENT BEARING TYPE "T" ELASTOMER VOLUME								
21	21	4	E3	27⁄16″	0.25 CF			
22	22	1	E3	2 ³ ⁄16″	0.24 CF			
23	22	1	E3	2 ³ ⁄16″	0.24 CF			




ION
32,-0,
EXISTING DOLPHIN
PROJECT NO. 15BPR.16 REPLACE BRUNSWICK COUNTY
NAVIGATION LIGHT BRIDGE NO. 71
CLUSTER JACKET (TYP.) DEPARTMENT OF TRANSPORTATION RALEIGH
FENDER SYSTEM
DocuSigned by TELL CULTURE Samuel L Culture 19C97095C75A467 5/10/2018 10:06:10 AM PDT
REVISIONS SHEET NO. DOCUMENT NOT CONSTDERED NO. BY: DATE: NO. BY: DATE: S-67
DOCUMENT NOT CONSIDERED FINAL UNLESS ALLNO.BY:DATE:NO.BY:DATE:DATE:SIGNATURESSIGNATURESSIGNATURESCOMPLETED2III<



G:\4201720.03-Brunswick-71\Structures\401_355_15BPR.16_SMU_FEN02_S-68_090071.dgn User:jduke

+

+




	BILL FENDER	OF MATERIALS SYSTEM CATW	S ALK
	DESCRIPTION PLASTIC LUMBER POS PLASTIC LUMBER RAI PLASTIC LUMBER DECI	LING 2" × 6"	LENGTH (FT.) 468'-0" 1868'-0" 1424'-6"
32:-0			
J J J J J J J J J J J J J J J J J J J	, , ,		

5-01/1"

B


	PROJECT BRI BRIDGE	UNSW	ICK		<u>6</u> UNTY
	SHEET 1 OF	4			
DocuSigned bys HELL CULTURE Samuel L Collem 19097095C75A467	depar F	TMENT ENDE CATW/	RALEIGH RSY ALK LA &	SPORTA	
		REVIS	IONS		SHEET NO.
DOCUMENT NOT CONSIDERED	NO. BY:	DATE: I	NO. BY:	DATE:	S-69
FINAL UNLESS ALL	1		3		TOTAL SHEETS
SIGNATURES COMPLETED	2		4		73



5/15/2018 G:\4201720.03-Brunswick-71\Structures\401_365_15BPR.16_SMU_FEN04_S-70_090071.dgn User:jduke

+

+




—

			B	AR TY	PES	
				2'-4" 2'-2" 2'-5"	J4	
		ر د ا 4 ا	12			
MPOSITE LUMBER "× 10"WALES (P.)		15'-2" 15'-1"	2'-0"	1		
		ALL BA	R DIME	NSIONS	ARE OUT	ΤΟ ΟυΤ
		BILL C 15'-6')F MA ⁻ ′ THRE	TERIAI E-PILI	L FOR O E JACKE	NE T
SITE LUMBER ″WALES	BAR	NUMBER	SIZE	TYPE	LENGTH	WEIGHT
MALLS	<u>* T2</u>	32	#4	1	6′-5″	140
	* J3	4	# 5	1	32'-8"	140
	₩ J4	2	# 5	1	32'-4"	70
	SHEAR	STUDS			EA.	72
	* EP0	XY COATE				
		NFORCINC RETE OR E		ROUT	LBS. CU. YDS.	<u>350</u> 2 . 5

—(X6) 2¹/2″ -∛₄Ø SHEAR STUDS @ 1'-0"

1"Ø STAINLESS STEEL THREADED BARS, LOCKING NUTS AND WASHERS (TYP.)

	PROJECT NO. <u>15BPR.16</u> <u>BRUNSWICK</u> COUNTY BRIDGE NO. <u>71</u>
	SHEET 3 OF 4
D SPLICED GRADE B8M. JRNISH EE FROM DocuSigned by: DocuSigned by:	STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH FENDER SYSTEM THREE-PILE JACKET DETAILS
5/15/2018 12:35:57 PM PDT	REVISIONS SHEET NO.
DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED	NO. BY: DATE: NO. BY: DATE: S-71 1 3 3 5 5 73 2 4 73 73 73



^{5/15/2018} G:\4201720.03-Brunswick-71\Structures\401_375_15BPR.16_SMU_FEN06_S-72_090071.dgn

—

+

User:jduke

	BAR TYPES
	$\begin{array}{c ccccccccccccccccccccccccccccccccccc$
	ALL BAR DIMENSIONS ARE OUT TO OUT
P_)	BILL OF MATERIAL FOR ONE 15'-6"SEVEN-PILE JACKET
)	BAR NUMBER SIZE TYPE LENGTH WEIGHT * T3 32 *4 1 8'-6" 185
	* J5 3 *5 1 33'-3" 105 * J6 4 *5 1 33'-4" 140
	SHEAR STUDS EA. 144
	* EPOXY COATED REINFORCING STEEL LBS. 430 CONCRETE OR EPOXY GROUT CU.YDS. 3.7
3)"	
-¾"Ø UDS @ 1'-0″	
INLESS HREADED OCKING NUTS SHERS (TYP.)	
	PROJECT NO. <u>15BPR.16</u> <u>BRUNSWICK</u> county BRIDGE NO. <u>71</u>
	SHEET 4 OF 4

STATE OF NORTH CAROLINA								
DEPARTMENT OF TRANSPORTATION								
RALEIGH								



SEVEN-PILE JACKET DETAILS

5/15/2018 12:35:57 PM PDT							
			REVI	SION	S		SHEET NO.
DOCUMENT NOT CONSIDERED	NO.	BY:	DATE:	NO.	BY:	DATE:	S-72
FINAL UNLESS ALL	1			3			TOTAL SHEETS
SIGNATURES COMPLETED	2			4			73

A CAR FESS/0

SEAL

043571

, TVGINEER

Samuel Cullur

- 190970950754467

SPECIFICATIONS	A.A.S.H.T.O. (CURRENT)
LIVE LOAD	SEE PLANS
IMPACT ALLOWANCE	SEE A.A.S.H.T.O.
STRESS IN EXTREME FIBER OF STRUCTURAL STEEL - AASHTO M270 GRADE 36	20,000 LBS.PER SQ.IN.
- AASHTO M270 GRADE 50W	27,000 LBS.PER SQ.IN.
- AASHTO M270 GRADE 50	27,000 LBS.PER SQ.IN.
REINFORCING STEEL IN TENSION - GRADE 60	24,000 LBS.PER SO.IN.
CONCRETE IN COMPRESSION	1,200 LBS.PER SQ.IN.
CONCRETE IN SHEAR	SEE A.A.S.H.T.O.
STRUCTURAL TIMBER - TREATED OR UNTREATED EXTREME FIBER STRESS	1,800 LBS.PER SQ.IN.
COMPRESSION PERPENDICULAR TO GRAIN OF TIMBER	375 LBS.PER SQ.IN.
EQUIVALENT FLUID PRESSURE OF EARTH	30 LBS.PER CU.FT. (MINIMUM)

MATERIAL AND WORKMANSHIP:

EXCEPT AS MAY OTHERWISE BE SPECIFIED ON PLANS OR IN THE SPECIAL PROVISIONS. ALL MATERIAL AND WORKMANSHIP SHALL BE IN ACCORDANCE WITH THE 2018 "STANDARD SPECIFICATIONS FOR ROADS AND STRUCTURES" OF THE N. C. DEPARTMENT OF TRANSPORTATION.

STEEL SHEET PILING FOR PERMANENT OR TEMPORARY APPLICATIONS SHALL BE HOT ROLLED.

CONCRETE:

UNLESS OTHERWISE REQUIRED ON PLANS, CLASS A CONCRETE SHALL BE USED FOR ALL PORTIONS OF ALL STRUCTURES WITH THE EXCEPTION THAT: CLASS AA CONCRETE SHALL BE USED IN BRIDGE SUPERSTRUCTURES, ABUTMENT BACKWALLS, AND APPROACH SLABS; AND CLASS B CONCRETE SHALL BE USED FOR SLOPE PROTECTION AND RIP RAP.

CONCRETE CHAMFERS:

UNLESS OTHERWISE NOTED ON THE PLANS, ALL EXPOSED CORNERS ON STRUCTURES SHALL BE CHAMFERED 3/4" WITH THE FOLLOWING EXCEPTIONS: TOP CORNERS OF CURBS MAY BE ROUNDED TO $1\frac{1}{2}$ RADIUS WHICH IS BUILT INTO CURB FORMS; CORNERS OF TRANSVERSE FLOOR EXPANSION JOINTS SHALL BE ROUNDED WITH A 1/4" FINISHING TOOL UNLESS OTHERWISE REQUIRED ON PLANS; AND CORNERS OF EXPANSION JOINTS IN THE ROADWAY FACES AND TOPS OF CURBS AND SIDEWALKS SHALL BE ROUNDED TO A $\frac{1}{4}$ RADIUS WITH A FINISHING STONE OR TOOL UNLESS OTHERWISE REQUIRED ON PLANS.

DOWELS:

DOWELS WHEN INDICATED ON PLANS AS FOR CULVERT EXTENSIONS, SHALL BE EMBEDDED AT LEAST 12" INTO THE OLD CONCRETE AND GROUTED INTO PLACE WITH 1:2 CEMENT MORTAR.

STANDARD NOTES

ALLOWANCE FOR DEAD LOAD DEFLECTION, SETTLEMENT, ETC. IN CASTING SUPERSTRUCTURES:

BRIDGES SHALL BE BUILT ON THE GRADE OR VERTICAL CURVE SHOWN ON PLANS. SLABS, CURBS AND PARAPETS SHALL CONFORM TO THE GRADE OR CURVE.

ALL DIMENSIONS WHICH ARE GIVEN IN SECTION AND ARE AFFECTED BY DEAD LOAD DEFLECTIONS ARE DIMENSIONS AT CENTER LINE OF BEARING UNLESS OTHERWISE NOTED ON PLANS. IN SETTING FORMS FOR STEEL BEAM BRIDGES AND PRESTRESSED CONCRETE GIRDER BRIDGES, ADJUSTMENTS SHALL BE MADE DUE TO THE DEAD LOAD DEFLECTIONS FOR THE ELEVATIONS SHOWN. WHERE BLOCKS ARE SHOWN OVER BEAMS FOR BUILDING UP TO THE SLAB, THE VERTICAL DIMENSIONS OF THE BLOCKS SHALL BE ADJUSTED BETWEEN BEARINGS TO COMPENSATE FOR DEAD LOAD DEFLECTIONS, VERTICAL CURVE ORDINATE, AND ACTUAL BEAM CAMBER. WHERE BOTTOM OF SLAB IS IN LINE WITH BOTTOM OF TOP FLANGES, DEPTH OF SLAB BETWEEN BEARINGS SHALL BE ADJUSTED TO COMPENSATE FOR DEAD LOAD DEFLECTION, VERTICAL CURVE ORDINATE, AND ACTUAL BEAM CAMBER.

IN SETTING FALSEWORK AND FORMS FOR REINFORCED CONCRETE SPANS, AN ALLOWANCE SHALL BE MADE FOR DEAD LOAD DEFLECTIONS, SETTLEMENT OF FALSEWORK, AND PERMANENT CAMBER WHICH SHALL BE PROVIDED FOR IN ADDITION TO THE ELEVATIONS SHOWN. AFTER REMOVAL OF THE FALSEWORK, THE FINISHED STRUCTURES SHALL CONFORM TO THE PROFILE AND ELEVATIONS SHOWN ON THE PLANS AND CONSTRUCTION ELEVATIONS FURNISHED BY THE ENGINEER.

DETAILED DRAWINGS FOR FALSEWORK OR FORMS FOR BRIDGE SUPERSTRUCTURE AND ANY STRUCTURE OR PARTS OF A STRUCTURE AS NOTED ON THE PLANS SHALL BE SUBMITTED TO THE ENGINEER FOR APPROVAL BEFORE CONSTRUCTION OF THE FALSEWORK OR FORMS IS STARTED.

REINFORCING STEEL:

ALL REINFORCING STEEL SHALL BE DEFORMED. DIMENSIONS RELATIVE TO PLACEMENT OF REINFORCING ARE TO CENTERS OF BARS UNLESS OTHERWISE INDICATED IN THE PLANS. DIMENSIONS ON BAR DETAILS ARE TO CENTERS OF BARS OR ARE OUT TO OUT AS INDICATED ON PLANS.

WIRE BAR SUPPORTS SHALL BE PROVIDED FOR REINFORCING STEEL WHERE INDICATED ON THE PLANS. WHEN BAR SUPPORT PIECES ARE PLACED IN CONTINUOUS LINES, THEY SHALL BE SO PLACED THAT THE ENDS OF THE SUPPORTING WIRES SHALL BE LAPPED TO LOCK LEGS ON ADJOINING PIECES.

STRUCTURAL STEEL:

AT THE CONTRACTOR'S OPTION, HE MAY SUBSTITUTE $\frac{7}{8}$ " Ø SHEAR STUDS FOR THE ¾″Ø STUDS SPECIFIED ON THE PLANS. THIS SUBSTITUTION SHALL BE MADE AT THE RATE OF 3 - $\frac{1}{8}$ " Ø STUDS FOR 4 - $\frac{3}{4}$ " Ø STUDS, AND STUD SPACING CHANGES SHALL BE MADE AS NECESSARY TO PROVIDE THE SAME EQUIVALENT NUMBER OF $\frac{7}{8}$ " Ø STUDS ALONG THE BEAM AS SHOWN FOR $\frac{3}{4}$ " Ø STUDS BASED ON THE RATIO OF 3 - $\frac{7}{8}$ " Ø STUDS FOR 4 - $\frac{3}{4}$ " Ø STUDS. STUDS OF THE LENGTH SPECIFIED ON THE PLANS MUST BE PROVIDED. THE MAXIMUM SPACING SHALL BE 2'-O".

EXCEPT AT THE INTERIOR SUPPORTS OF CONTINUOUS BEAMS WHERE THE COVER PLATE IS IN CONTACT WITH BEARING PLATE. THE CONTRACTOR MAY, AT HIS OPTION. SUBSTITUTE FOR THE COVER PLATES DESIGNATED ON THE PLANS COVER PLATES OF THE EQUIVALENT AREA PROVIDED THESE PLATES ARE AT LEAST 5/16" IN THICKNESS AND DO NOT EXCEED A WIDTH EQUAL TO THE FLANGE WIDTH LESS 2"OR A THICKNESS EQUAL TO 2 TIMES THE FLANGE THICKNESS. THE SIZE OF FILLET WELDS SHALL CONFORM TO THE REQUIREMENTS OF THE CURRENT ANSI/AASHTO/AWS "BRIDGE WELDING CODE". ELECTROSLAG WELDING WILL NOT BE PERMITTED.

WITH THE SOLE EXCEPTION OF EDGES AT SURFACES WHICH BEAR ON OTHER SURFACES.ALL SHARP EDGES AND ENDS OF SHAPES AND PLATES SHALL BE SLIGHTLY ROUNDED BY SUITABLE MEANS TO A RADIUS OF APPROXIMATELY VIGINCH OR EQUIVALENT FLAT SURFACE AT A SUITABLE ANGLE PRIOR TO PAINTING, GALVANIZING, OR METALLIZING.

HANDRAILS AND POSTS:

METAL STANDARDS AND FACES OF THE CONCRETE END POSTS FOR THE METAL RAIL SHALL BE SET NORMAL TO THE GRADE OF THE CURB, UNLESS OTHERWISE SHOWN ON PLANS. THE METAL RAIL AND TOPS OF CONCRETE POSTS USED WITH THE ALUMINUM RAIL SHALL BE BUILT PARALLEL TO THE GRADE OF THE CURB.

METAL HANDRAILS SHALL BE IN ACCORDANCE WITH THE PLANS. RAILS SHALL BE AS MANUFACTURED FOR BRIDGE RAILING. CASTINGS SHALL BE OF A UNIFORM APPEARANCE. FINS AND OTHER DEFORMATIONS RESULTING FROM CASTING OR OTHERWISE SHALL BE REMOVED IN A MANNER SO THAT A UNIFORM COLORING OF THE COMPLETED CASTING SHALL BE OBTAINED. CASTINGS WITH DISCOLORATIONS OR OF NON-UNIFORM COLORING WILL NOT BE ACCEPTED. CERTIFIED MILL REPORTS ARE REQUIRED FOR METAL RAILS AND POSTS.

SPECIAL NOTES:

GENERALLY, IN CASE OF DISCREPANCY, THIS STANDARD SHEET OF NOTES SHALL GOVERN OVER THE SPECIFICATIONS, BUT THE REMAINDER OF THE PLANS SHALL GOVERN OVER NOTES HEREON, AND SPECIAL PROVISIONS SHALL GOVERN OVER ALL. SEE SPECIFICATIONS ARTICLE 105-4.

ENGLISH JANUARY, 1990