

ANTICIPATED STEEL REPAIR LOCATIONS						
SPAN	BEAM	LOCATION	DIM "A"	DIM "B"	DIM "E"	DIM "F"
Α	9	BENT 1	* 13"	80″		
С	9	BENT 2	-	6 ¹ /2"	22″	

_ DATE : <u>03/2019</u>

DATE : 03/2019


R.L.PUTEK


A.M.LEE

DRAWN BY : _

CHECKED BY : .

(* SEE DETAIL "A")





BEAM REPAIR QUANTITY TABLE						
STEEL F	PLATES	BRIDGE	JACKING	STIFFENER		
LB	S .	EA.		LBS.		
ESTIMATE	ACTUAL	ESTIMATE	ACTUAL	ESTIMATE	ACTUAL	
23.0		2		0.0		
STEEL LATERAL BRACING		HARDWARE REPAIR		BEAM END REPAIR		
LB	BS.	LBS.		LBS.		
ESTIMATE	ACTUAL	ESTIMATE	ACTUAL	ESTIMATE	ACTUAL	
0.0		0.9		273.6		

1 BEAM NUMBER

(B) BEAM END REPAIR

P PLATING REPAIR

S STIFFENER REPAIR

(F) BOTTOM FLANGE REPAIR

H HARDWARE REPAIR

G GUSSET PLATE REPAIR

L LATERAL BRACE REPAIR

SHOTCRETE REPAIR AREA

ERI - EPOXY RESIN INJECTION

AS-BUILT REPAIR QUANTITY TABLE				
UNDERSIDE OF DECK REPAIRS - SPAN A				
	ESTI	MATE	ACT	UAL
SHOTCRETE REPAIRS	AREA SQ.FT.	VOLUME CU.FT.	AREA SQ.FT.	VOLUME CU.FT.
UNDERSIDE OF DECK	0.0	0.0		
BENT DIAPHRAGM	23.6	11.8		
OVERHANG	46.5	15 . 5		
CONCRETE REPAIRS	AREA SQ.FT.	VOLUME CU.FT.	AREA SQ.FT.	VOLUME CU.FT.
UNDERSIDE OF DECK	0.0	0.0		
BENT DIAPHRAGM	0.0	0.0		
OVERHANG	0.0	0.0		
EPOXY RESIN INJECTIO	LIN.FT.	LIN.FT.		
UNDERSIDE OF DECK		0.0		
BENT DIAPHRAGM		0.0		
OVERHANG		0.0		
AS-BUILT REPAIR QUANTITY TABLE				
LINDEDSTOR OF DECK DEDATES SOAN C				

UNDERSIDE OF DECK REPAIRS - SPAN C ESTIMATE ACTUAL VOLUME VOLUME SHOTCRETE REPAIRS SQ.FT. CU.FT. SQ.FT. CU.FT. UNDERSIDE OF DECK 0.0 0.0 BENT DIAPHRAGM 3.7 1.9 3.2 OVERHANG 1.1 VOLUME CU.FT. VOLUME CU.FT. CONCRETE REPAIRS SQ.FT. SQ.FT. UNDERSIDE OF DECK 0.0 0.0 BENT DIAPHRAGM 0.0 0.0 OVERHANG 0.0 0.0 EPOXY RESIN INJECTION LIN.FT. LIN.FT. UNDERSIDE OF DECK 0.0 BENT DIAPHRAGM 0.0

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2"CLEARANCE TO SAWCUT. SEE "OVERHANG, DIAPHRAGM AND BRIDGE RAIL REPAIR DETAILS" SHEET.

NOTES

OVERHANG

FOR UNDERSIDE OF DECK REPAIRS. SEE "OVERHANG, DIAPHRAGM AND BRIDGE RAIL REPAIR DETAILS" SHEET.

FOR OVERHANG REPAIRS. SEE "OVERHANG, DIAPHRAGM AND BRIDGE RAIL REPAIR DETAILS" SHEET.

FOR GUSSET PLATE REPAIR, CONTRACTOR IS TO FIELD VERIFY DIMENSIONS OF EXISTING GUSSET PLATE AND REPLACE WITH LIKE KIND.

FOR BEAM PLATING REPAIR. SEE "BEAM PLATING REPAIR DETAILS" SHEETS. FOR BRIDGE JACKING. SEE "JACKING DETAILS" SHEET.

> PROJECT NO. 15BPR.40 BUNCOMBE __ COUNTY BRIDGE NO. 100495

0.0

SHEET 1 OF 2

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION DECK UNDERSIDE REPAIR SPANS A & C

1 Ambur Mike — B04B5A4F2FAD484. 5/29/2019

SEAL 031021

MCINES!

SHEET NO **REVISIONS** NO. BY: S2-06 DATE: DATE: DOCUMENT NOT CONSIDERED -FINAL UNLESS ALL SIGNATURES COMPLETED TOTAL SHEETS

BEAM REPAIR QUANTITY TABLE						
STEEL F	PLATES	BRIDGE JACKING		STIFFENER		
LB	S .	EA.		LBS.		
ESTIMATE	ACTUAL	ESTIMATE	ACTUAL	ESTIMATE	ACTUAL	
23.0		2		0.0		
STEEL LATERAL BRACING		HARDWARE REPAIR		BEAM END REPAIR		
LE	SS.	LBS.		LBS.		
ESTIMATE	ACTUAL	ESTIMATE	ACTUAL	ESTIMATE	ACTUAL	
0.0		0.9		273.6		