

AS-BUILT REPAIR QUANTITY TABLE

BENT 2 REPAIRS

GUANTITIES

FSTIMATE

ACTUAL

BENT 2 REPAIRS	QUANTITIES				
DENI Z KEFAIKS	ESTIMATE		ACTUAL		
SHOTCRETE REPAIRS	AREA SF	VOLUME CF	AREA SF	DEPTH IN.	VOLUME CF
COLUMN	8.2	3.3			
EPOXY RESIN INJECT	LENGTH LF	LENGTH LF			
COLUMN		0.0			

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MINIMUM OF 1"BEHIND REBAR AND MINIMUM OF 2"CLEARANCE TO SAWCUT. FOR REPAIR DETAILS, SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.

NOTES:

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE BASED ON THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ENTER THE ACTUAL QUANTITIES INTO THE AS-BUILT REPAIR QUANTITY TABLE.

FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR EPOXY RESIN INJECTION, SEE SPECIAL PROVISIONS.

WHEN COLUMN REPAIRS ARE INDICATED TO GROUND LINE, EXTEND REPAIR MININUM OF 1'BELOW GROUND LINE.

FOR PROPOSED BENT CAP REPLACEMENT DETAILS, SEE SUBSTRUCTURE BENT SHEETS.

- SHOTCRETE REPAIR

ERI - EPOXY RESIN INJECTION

- DEMOLITION (SEE "CAP DEMOLITION DETAILS" SHEET)

PROJECT NO. B-4626

STANLY, ROWAN

AND DAVIDSON county

STATION: 45+22.65 -EBL-

SHEET 1 OF 2

STATE OF NORTH CAROLINA

DEPARTMENT OF TRANSPORTATION

RALEIGH

SUBSTRUCTURE REPAIR
BENT 2
SPAN "B" FACE

SEAL 020208 MGNEER Docusigned by: Six BML G 9/2/2021 ACB8082119D74CD...

Ein BML (p 9/2/2021	
ACB8082119D74CD	NC
OCUMENT NOT CONSIDERED	-
FINAL UNLESS ALL	Ш
SIGNATURES COMPLETED	2

					_	
	SHEET NO					
NO.	BY:	DATE:	NO.	BY:	DATE:	S1-78
1			₩			TOTAL SHEETS
2			4			125

PLANS PREPARED BY:

Suite 900
Raleigh, NC 27603
(919) 420-7660
Excellence Delivered As Promised

NC Lic. No. F-0270