

AS-BUILT REPAIR	QUAN	ITITY	ΤΑΒ	LE				
UNDERSIDE OF DECK REPAIRS								
	ESTIMATE		ACTUAL					
SHOTCRETE REPAIRS	AREA SQ.FT.	VOLUME CU.FT.	AREA SQ.FT.	VOLUME CU.FT.				
UNDERSIDE OF DECK	0.0	0.0						
UNDERSIDE OF OVERHANG	2.50	0.9						
	ESTIMATE		ACTUAL					
UNDERSIDE EPOXY RESIN INJECTION	0.0 LIN.FT.							


UNDERSIDE OF DECK REPAIR QUANTITIES REPRESENT ESTIMATED VALUES OF DECK REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MINIMUM OF 1"BEHIND REBAR AND MINIMUM OF 2"CLEAR TO SAWCUT. SEE REPAIR DETAILS.

## NOTES:

REPAIR LOCATIONS AND ESTIMATED QUANTITIES ARE BASED ON THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ENTER THE ACTUAL QUANTITIES INTO THE AS-BUILT REPAIR QUANTITY TABLE.

AT LOCATIONS INDICATED, CONCRETE, REINFORCING STEEL AND OTHER COMPONENTS OF EXTERIOR END DIAPHRAGMS SHALL BE REMOVED FLUSH TO THE BOTTOM OF THE DECK AND THE SIDE OF THE BEAMS/GIRDERS. AFTER REMOVAL, ENDS OF EXPOSED STEEL COMPONENTS SHALL BE COATED WITH EPOXY.NO SEPARATE PAYMENT WILL BE MADE FOR THIS WORK. COSTS FOR THIS WORK SHALL BE INCLUDED IN OTHER PAY ITEMS.

\*FOR UNDERSIDE OF DECK AND DIAPHRAGM REPAIRS, SEE ``OVERHANG, DIAPHRAGM AND BRIDGE RAIL REPAIR DETAILS'' SHEET.



UNDERSIDE REPAIR

	PROJEC <u>ME(</u> BRIDGE	CKLEN E NO	NBUF			C UNTY		
DZEE038FAB674C5 02EE038FAB674C5 02EE038FAB674C5 07 07 07 07 07 07 07 07 07 07	STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH DECK UNDERSIDE REPAIRS SPAN A							
	REVISIONS SHEET NO.							
DOCUMENT NOT CONSIDERED	NO. BY:	DATE:	NO. BY:		DATE:	S1-4		
FINAL UNLESS ALL	1		3			TOTAL SHEETS		
SIGNATURES COMPLETED	2		4			274		