

+

+

-3.0 SF SHOTCRETE REPAIR UNDERSIDE OF OVERHANG

€ JOINT @ BENT 5	
BRIDGE	£ BRIDGE

AS-BUILT REPAIR	QUAN	ITITY	ΤΑΒ	LE					
UNDERSIDE OF DECK REPAIRS									
	ESTIMATE		ACTUAL						
SHOTCRETE REPAIRS	AREA SQ.FT.	VOLUME CU.FT.	AREA SQ.FT.	VOLUME CU.FT.					
UNDERSIDE OF DECK	0.0	0.0							
UNDERSIDE OF OVERHANG	6.0	2.0							
INTERIOR DIAPHRAGMS	0.0	0.0							
	ESTIMATE		ACTUAL						
UNDERSIDE EPOXY RESIN INJECTION	0.0 LIN.FT.								

UNDERSIDE OF DECK REPAIR QUANTITIES REPRESENT ESTIMATED VALUES OF DECK REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MINIMUM OF 1"BEHIND REBAR AND MINIMUM OF 2"CLEAR TO SAWCUT. SEE REPAIR DETAILS.


NOTES:

Г

REPAIR LOCATIONS AND ESTIMATED QUANTITIES ARE BASED ON THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ENTER THE ACTUAL QUANTITIES INTO THE AS-BUILT REPAIR QUANTITY TABLE.

AT LOCATIONS INDICATED, CONCRETE, REINFORCING STEEL AND OTHER COMPONENTS OF EXTERIOR END DIAPHRAGMS SHALL BE REMOVED FLUSH TO THE BOTTOM OF THE DECK AND THE SIDE OF THE BEAMS/GIRDERS. AFTER REMOVAL, ENDS OF EXPOSED STEEL COMPONENTS SHALL BE COATED WITH EPOXY.NO SEPARATE PAYMENT WILL BE MADE FOR THIS WORK. COSTS FOR THIS WORK SHALL BE INCLUDED IN OTHER PAY ITEMS.

FOR UNDERSIDE OF DECK AND DIAPHRAGM REPAIRS, SEE ``OVERHANG, DIAPHRAGM AND BRIDGE RAIL REPAIR DETAILS'' SHEET.



UNDERSIDE REPAIR

	PROJEC <u>ME</u> BRIDGE	CKLEN		BURC	•	<u>C</u> UNTY	
CDocuSigned by: SHEET 5 OF 6							
DZEE938FAB674CS DZE	STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH						
	REVISIONS SHEET NO.						
OCUMENT NOT CONSIDERED	NO. BY:	DATE:	NO.	BY:	DATE:	S1-8	
FINAL UNLESS ALL SIGNATURES COMPLETED	1		3			TOTAL SHEETS	
STONATORES COMPLETED	2		ቆ			274	