

NOTES:

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE BASED ON THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ENTER THE ACTUAL QUANTITIES INTO THE AS-BUILT REPAIR QUANTITY TABLE.

FOR UNDERSIDE OF DECK AND DIAPHRAGM REPAIRS, SEE "OVERHANG, DIAPHRAGM AND BRIDGE RAIL REPAIR DETAILS" SHEET.

- FOR BEAM REPAIR DETAILS, SEE "BEAM SECTION REPAIR DETAILS" SHEET.
- FOR BEAM PLATING DETAILS, SEE "BEAM PLATING REPAIR DETAILS" SHEET.
- FOR BRIDGE JACKING DETAILS, SEE "JACKING DETAILS" SHEET.
- THE LOCATIONS AND DIMENSIONS OF THE AREAS FOR REPAIR ARE BASED ON THE BEST INFORMATION AVAILABLE. THE CONTRACTOR, IN CONJUNCTION WITH THE ENGINEER, SHALL VERIFY THE LOCATION AND EXTENT OF REPAIR AREAS PRIOR TO STEEL FABRICATION.

| BEAM REPAIR QUANTITY TABLE | | | | | | | |
|----------------------------|--------|----------------|--------|------------------|--------|------------------|--------|
| BEAM END REPAIR | | PLATING REPAIR | | STIFFENER REPAIR | | DIAPHRAGM REPAIR | |
| LBS. | | LBS. | | LBS. | | LBS. | |
| ESTIMATE | ACTUAL | ESTIMATE | ACTUAL | ESTIMATE | ACTUAL | ESTIMATE | ACTUAL |
| 0 | | 0 | | 0 | | 0 | |

DRAWN BY: R.L.PUTEK/E. BAYISSA DATE: 07/2021
CHECKED BY: H.A. LOCKLEAR DATE: 07/2021

UNDERSIDE EPOXY COATING
UNDERSIDE REPAIR

DIAPHRAGM REPAIR

- 1) BEAM NUMBER
- B BEAM END REPAIR
- P PLATING REPAIR
- S) STIFFENER REPAIR
- (D) STEEL DIAPHRAGM REPAIR

| AS-BUILT REPAI | R QU | ANTI | TY T | ABLE | |
|---------------------------------|----------------|------------------|----------------|------------------|--|
| UNDERSIDE OF DECK REPAIRS | | | | | |
| | ESTI | MATE | ACTUAL | | |
| SHOTCRETE REPAIRS | AREA SQ.FT. | VOLUME CU.FT. | AREA SQ.FT. | VOLUME CU.FT. | |
| UNDERSIDE OF DECK | 3.8 | 1.3 | | | |
| UNDERSIDE OF OVERHANG | 50 . 5 | 17.0 | | | |
| INTERIOR DIAPHRAGMS | 0.0 | 0.0 | | | |
| | | | | | |
| | ESTIMATE | | ACTUAL | | |
| UNDERSIDE EPOXY RESIN INJECTION | O.O LIN.FT. | | | | |
| UNDERSIDE EPOXY COATING | 75 SQ.FT. | | | | |
| | | | | | |

VALUES REPRESENT ESTIMATED UNDERSIDE OF DECK REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MINIMUM OF 1"BEHIND REBAR AND MINIMUM OF 2"CLEAR TO SAWCUT. SEE REPAIR DETAILS.

| ANTICIPATED BEAM REPAIR LOCATIONS | | | | | | | | |
|-----------------------------------|------|----------|---------|---------|---------|---------|--|--|
| SPAN | BEAM | LOCATION | DIM "A" | DIM "B" | DIM "C" | DIM "D" | | |
| - | - | - | - | - | - | - | | |

PROJECT NO. I-5746C

MECKLENBURG COUNTY

BRIDGE NO. 590320

SHEET 2 OF 3



8/23/2021

DEPARTMENT OF TRANSPORTATION
RALEIGH

UNDERSIDE DECK REPAIR

SPAN B

REVISIONSSHEET NODOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETEDNO. BY: DATE: NO. BY: DATE: SHEETSDATE: SHEETS