

ANTICIPATED BEAM REPAIR LOCATIONS							
SPAN	BEAM	LOCATION	DIM ``A''	DIM ``B''	DIM ``C''	DIM ``D''	
В	3	BENT 1	6″	-	-	_	
В	3	BENT 1	6″	-	-	-	
В	6	BENT 1	8″	-	-	-	
В	7	BENT 1	6″	-	-	-	
В	7	BENT 1	6″	-	-	-	
В	8	BENT 2	8″	-	-	-	
В	8	BENT 2	9″	-	-	-	
В	14	BENT 2	9″	6″	-	_	
В	18	BENT 2	9″	2'-10"	-	-	

BEAM REPAIR QUANTITY TABLE								
BEAM END REPAIR PLATING REPAIR STIFFENER					R REPAIR	PAIR DIAPHRAGM REPAIR		
	LBS.		LE	S.	LE	3S .	L	BS.
ESTIM	ΔTE	ACTUAL	ESTIMATE	ACTUAL	ESTIMATE	ACTUAL	ESTIMATE	ACTUAL
0			100		45		0	

URAWN DI :	(L.PUIEK/E. BATISSA	DATE :	07/2021
CHECKED BY :	H.A. LOCKLEAR	DATE :	07/2021

23-AUG-2021 11:58 R:\Structures\FINAL PLANS\Bridge 326\406_017_I5746C_SMU_SSR2_S6-09_590326.dgn aacole

+

PLAN

AS-BUILT REPAIR QUANTITY TABLE							
UNDERSIDE OF DECK REPAIRS							
	ESTIMATE		ACTUAL				
SHOTCRETE REPAIRS	AREA SQ.FT.	VOLUME CU.FT.	AREA SQ.FT.	VOLUME CU.FT.			
UNDERSIDE OF DECK	0.0	0.0					
UNDERSIDE OF OVERHANG	28.1	9.4					
INTERIOR DIAPHRAGMS	0.0	0.0					
	ESTIMATE ACTUA		UAL				
UNDERSIDE EPOXY RESIN INJECTION	0.0 L	IN.FT.					

UNDERSIDE OF DECK REPAIR QUANTITIES REPRESENT ESTIMATED VALUES OF DECK REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MINIMUM OF 1"BEHIND REBAR AND MINIMUM OF 2"CLEAR TO SAWCUT. SEE REPAIR DETAILS.

NOTES

FOR BEAM REPAIR DETAILS, SEE "BEAM SECTION REPAIR DETAILS" SHEET.

FOR BEAM PLATING DETAILS, SEE "BEAM PLATING REPAIR DETAILS" SHEET.

FOR BRIDGE JACKING DETAILS, SEE "JACKING DETAILS" SHEET.

THE LOCATIONS AND DIMENSIONS OF THE AREAS FOR REPAIR ARE BASED ON THE BEST INFORMATION AVAILABLE. THE CONTRACTOR, IN CONJUNCTION WITH THE ENGINEER, SHALL VERIFY THE LOCATION AND EXTENT OF REPAIR AREAS PRIOR TO STEEL FABRICATION. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ENTER THE ACTUAL QUANTITIES INTO THE AS-BUILT REPAIR QUANTITY TABLE.

FOR UNDERSIDE OF DECK AND DIAPHRAGM REPAIRS, SEE ``OVERHANG, DIAPHRAGM AND BRIDGE RAIL REPAIR DETAILS'' SHEET.

UNDERSIDE REPAIR

---- EPOXY RESIN INJECTION (ERI)

- (1) BEAM NUMBER
- (B) BEAM END REPAIR
- P PLATING REPAIR
- S STIFFENER REPAIR
- D STEEL DIAPHRAGM REPAIR

	PROJEC <u>ME(</u> BRIDGE	CT NO CKLENE E NO	<u>I-5</u> BURG 590	5746 co 326	<u>C</u> UNTY
DocuSigned by: 02EE938FAB674C5 02E938FAB674C5 02E93	depa UNDEI	RTMENT O RSIDE SF	F NORTH CAROLE F TRANS RALEIGH DEC	Sporta K RE	TION PAIR
8/23/2021 DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED	№. вү: 1 2	REVISIO DATE: NO 3 4	NS BY:	DATE:	SHEET NO. S6-9 TOTAL SHEETS 274