

- 1) BEAM NUMBER
- B BEAM END REPAIR
- P PLATING REPAIR
- S STIFFENER REPAIR
- (D) STEEL DIAPHRAGM REPAIR

NOTES

FOR BEAM REPAIR DETAILS, SEE "BEAM SECTION REPAIR DETAILS" SHEET.

FOR BEAM PLATING DETAILS, SEE "BEAM PLATING REPAIR DETAILS" SHEET.

FOR BRIDGE JACKING DETAILS, SEE "JACKING DETAILS" SHEET.

FOR UNDERSIDE OF DECK AND DIAPHRAGM REPAIRS, SEE "OVERHANG, DIAPHRAGM AND BRIDGE RAIL REPAIR DETAILS" SHEET.

THE LOCATIONS AND DIMENSIONS OF THE AREAS FOR REPAIR ARE BASED ON THE BEST INFORMATION AVAILABLE. THE CONTRACTOR, IN CONJUNCTION WITH THE ENGINEER, SHALL VERIFY THE LOCATION AND EXTENT OF REPAIR AREAS PRIOR TO STEEL FABRICATION. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ENTER THE ACTUAL QUANTITIES INTO THE AS-BUILT REPAIR QUANTITY TABLE.

_ DATE : <u>07/2021</u>

· UNDERSIDE EPOXY COATING
UNDERSIDE REPAIR

DIAPHRAGM REPAIR

DRAWN BY: REZA KOUCHEKI/ R.L. PUTEK DATE: 07/2021

H.A. LOCKLEAR

CHECKED BY : _

EPOXY RESIN INJECTION (ERI)

PLAN

AS-BUILT REPAI	IR QL	JANTI	TY T	ABLE					
UNDERSIDE OF DECK REPAIRS									
CHOTODETE DEDATOS	ESTIMATE		ACTUAL						
SHOTCRETE REPAIRS	AREA SQ.FT.	VOLUME CU.FT.	AREA SQ.FT.	VOLUME CU.FT.					
UNDERSIDE OF DECK	0.0	0.0							
UNDERSIDE OF OVERHANG	0.0	0.0							
INTERIOR DIAPHRAGMS	0.0	0.0							
	ESTIMATE		ACTUAL						
UNDERSIDE EPOXY RESIN INJECTION	O.O LIN.FT.								
UNDERSIDE EPOXY COATING	O SQ.FT.								

UNDERSIDE OF DECK REPAIR QUANTITIES REPRESENT ESTIMATED VALUES OF DECK REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MINIMUM OF 1"BEHIND REBAR AND MINIMUM OF 2"CLEAR TO SAWCUT. SEE REPAIR DETAILS.

(OTHER LOCATIONS MAY EXIST, SEE NOTES)

BEAM REPAIR QUANTITY TABLE								
BEAM END REPAIR PLATING REPAIR			STIFFENER REPAIR		DIAPHRAGM REPAIR			
LBS.		LB	S.	LE	LBS.		LBS.	
ESTIMATE	ACTUAL	ESTIMATE	ACTUAL	ESTIMATE	ACTUAL	ESTIMATE	ACTUAL	
0		0		0		0		

PROJECT NO. I-5746C

MECKLENBURG county

BRIDGE NO. 590327

DocuSigned by:

02EE938FAB674C5...

OZEE938FAB674C5...

OZEE938FAB

8/23/2021

DEPARTMENT OF TRANSPORTATION
RALEIGH
UNDERSIDE DECK
REPAIR

SPAN A

REVISIONS SHEET NO STORM NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED 2 4 274

SHEET 1 OF 3

BEAM REPAIR LOCATIONS

23-AUG-2021 11:59
R:\Structures\FINAL PLANS\Bridge 327\407_015_I5746C_SMU_SSR1_S7-08_590327.dgn
agcole