

BENT 1 SOUTHBOUND	AS-BUILT REPAIR QUANTITY TABLE					
SHOTCRETE REPAIRS AREA SO. FT. CAP COLUMNS CONCRETE REPAIRS AREA SO. FT. CAP CONCRETE REPAIRS AREA SO. FT. CAP CONCRETE REPAIRS AREA SO. FT. CAP COLUMNS CONCRETE REPAIRS AREA SO. FT. CAP COLUMNS COLUMN	BENT 1 SOUTHBOUND					
SHOTCRETE REPAIRS SO.FT. CU.FT. SO.FT. CU.FT. CAP 12.3 6.2 COLUMNS 3.9 2.0 CONCRETE REPAIRS AREA SO.FT. CU.FT. SO.FT. CU.FT. CAP 0.0 0.0 CO.FT. CU.FT. SO.FT. CU.FT. SO.FT. CU.FT. CAP 1.0 CAP 1.0 COLUMNS 0.0 CO.FT. CAP COLUMNS SO.FT. SO.FT. SO.FT.		ESTIMATE		ACTUAL		
CONCRETE REPAIRS AREA SO.FT. CAP CONCRETE REPAIRS O.O O.O LIN.FT. CAP COLUMNS COLUMNS COLUMNS SO.FT.	SHOTCRETE REPAIRS	_				
CONCRETE REPAIRS AREA SO.FT. CAP O.O O.O EPOXY RESIN INJECTION CAP COLUMNS COLUMNS COLUMNS SO.FT. VOLUME CU. FT. SO. FT. LIN. FT. LIN. FT. SO. FT.	CAP	12.3	6.2			
CONCRETE REPAIRS SO.FT. CU.FT. SO.FT. CU.FT. CAP 0.0 0.0 EPOXY RESIN INJECTION LIN.FT. LIN.FT. CAP 1.0 COLUMNS 0.0 EPOXY COATING SO.FT. SO.FT.	COLUMNS	3 . 9	2.0			
CONCRETE REPAIRS SO.FT. CU.FT. SO.FT. CU.FT. CAP 0.0 0.0 EPOXY RESIN INJECTION LIN.FT. LIN.FT. CAP 1.0 COLUMNS 0.0 EPOXY COATING SO.FT. SO.FT.						
EPOXY RESIN INJECTION LIN.FT. LIN.FT. CAP 1.0 COLUMNS 0.0 EPOXY COATING SQ.FT. SQ.FT.	CONCRETE REPAIRS					
CAP COLUMNS O.O EPOXY COATING SO.FT. SO.FT.	CAP	0.0	0.0			
CAP COLUMNS O.O EPOXY COATING SO.FT. SO.FT.						
CAP COLUMNS O.O EPOXY COATING SO.FT. SO.FT.						
COLUMNS 0.0 EPOXY COATING SQ.FT. SQ.FT.	EPOXY RESIN INJECTION		LIN.FT.		LIN.FT.	
EPOXY COATING SO.FT. SO.FT.	CAP		1.0			
	COLUMNS		0.0			
TOP OF BENT CAP 173	EPOXY COATING		SO.FT.		SQ.FT.	
	TOP OF BENT CAP		173			

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2"CLEARANCE TO SAWCUT. FOR REPAIR DETAISL, SEE "TYPICAL CAP AND COLUMNREPAIR DETAILS" SHEET.

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE BASED ON THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ENTER THE ACTUAL QUANTITIES INTO THE AS-BUILT REPAIR QUANTITY TABLE.

CONCRETE REPAIRS MAYBE SUBSTITUTED IN LIEU OF SHOTCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

FOR SHOTCRETE REPAIR SEE SPECIAL PROVISIONS.

FOR CONCRETE REPAIR SEE SPECIAL PROVISIONS.

FOR EPOXY RESIN NIJECTION, SEE SPECIAL PROVISIONS.

CLEAN AND REMOVE DEBRIS FROM THE TOP OF THE CAP AND APPLY EPOXY PROTECTIVE COATING. EPOXY COATING SHALL BE APPLIED TO THE TOP SURFACE OF THE CAP. THE CONTRACTOR SHALL NOT COAT THE AREA OF THE CAP BENEATH THE MASONRY PLATES. FOR EPOXY COATING, SEE SPECIAL PROVISIONS.

SHOTCRETE REPAIR AREA

CONCRETE REPAIR AREA

EPOXY RESIN INJECTION (ERI)

PROJ. NO. <u>I-5746C</u> MECKLENBURG COUNTY BRIDGE NO. 590327

SHEET 1 OF 2

8/23/2021

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION
RALEIGH

SHEET NO

S7-14

TOTAL SHEETS

274

REVISIONS NO. BY: DATE: DATE: DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

R.L. PUTEK

H.A. LOCKLEAR

DRAWN BY : _

CHECKED BY : _

DATE : <u>05/2021</u>

DATE : 07/2021