



AS-BUILT REPAIR QUANTITY TABLE QUANTITIES END BENT 1 ESTIMATE ACTUAL VOLUME VOLUME SHOTCRETE REPAIRS SQ.FT. CU.FT. SQ.FT. CU.FT. CAP & CURTAIN WALL 0.0 0.0 AREA VOLUME VOLUME CONCRETE REPAIRS SQ.FT. CU.FT. SQ.FT. CU.FT. CAP 0.0 0.0 EPOXY RESIN INJECTION FΤ. FT. 20.0 CAP & CURTAIN WALL SQ. FT. EPOXY COATING FT. TOP OF BENT CAP 150

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2"CLEARANCE TO SAWCUT. FOR REPAIR DETAILS, SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.

NOTES

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE BASED ON THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ENTER THE ACTUAL QUANTITIES INTO THE AS-BUILT REPAIR QUANTITY TABLE.

CONCRETE REPAIRS MAY BE SUBSTITUTED IN LIEU OF SHOTCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

FOR ANCHOR BOLT NUT REPLACEMENT, SEE SPECIAL PROVISIONS.

FOR SHOTCRETE REPAIR, SEE SPECIAL PROVISION.

FOR CONCRETE REPAIR, SEE SPECIAL PROVISION.

FOR EPOXY RESIN INJECTION, SEE SPECIAL PROVISION.

CLEAN AND REMOVE DEBRIS FROM THE TOP OF THE CAP. EPOXY COATING SHALL BE APPLIED TO THE TOP SURFACE OF THE CAP. THE CONTRACTOR SHALL NOT COAT THE AREA OF THE CAP BENEATH THE MASONRY PLATES. FOR EPOXY COATING, SEE SPECIAL PROVISIONS.

CONCRETE REPAIR AREA

SHOTCRETE REPAIR AREA

---- EPOXY RESIN INJECTION (ERI)

* REPLACE MISSING ANCHOR BOLT NUT

PROJECT NO. <u>I-5746C</u>

<u>MECKLENBURG</u> county

BRIDGE NO.: <u>328590</u>

SHEET 2 OF 2

DocuSigned by:

02EE938FAB674C5...

10 CAROLLAND

SEAL

35647

10 CAROLLAND

SEAL

35647

DEPARTMENT OF TRANSPORTATION
RALEIGH

END BENT 1 NORTHBOUND

8/23/2021

REVISIONSSHEET NODOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETEDNo.BY:DATE:No.BY:DATE:S8-1033TOTAL SHEETS24274

 DRAWN BY :
 R.L.PUTEK
 DATE :
 05/2021

 CHECKED BY :
 H. A. LOCKLEAR
 DATE :
 05/2021