

+

+

AS-BUILT REPAIR QUANTITY TABLE				
UNDERSIDE OF DECK REPAIRS				
	ESTIMATE		ACTUAL	
SHOTCRETE REPAIRS	AREA SQ.FT.	VOLUME CU.FT.	AREA SQ.FT.	VOLUME CU.FT.
UNDERSIDE OF DECK	0.0	0.0		
OVERHANG DIAPHRAGMS	2.0	0.7		
UNDERSIDE OF OVERHANG	16.2	5.4		
INTERIOR DIAPHRAGMS	2.1	0.7		
	ESTIMATE		ACTUAL	
UNDERSIDE EPOXY RESIN INJECTION	0.0 LIN.FT.			
UNDERSIDE EPOXY COATING	0 SQ.FT.			

UNDERSIDE OF DECK REPAIR QUANTITIES REPRESENT ESTIMATED VALUES OF DECK REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MINIMUM OF 1"BEHIND REBAR AND MINIMUM OF 2"CLEAR TO SAWCUT. SEE REPAIR DETAILS.

IR QUANTITY TABLE							
PAIR	STIFFENE	R REPAIR	DIAPHRAG	M REPAIR	STEEL KEEPER ANGLE ASSEMBLY		
	LBS.		LBS.		EA.		
TUAL	ESTIMATE	ACTUAL	ESTIMATE	ACTUAL	ESTIMATE	ACTUAL	
	6		0		1		

TED BEAM	REPAIR L	OCATIONS	
DIM ``A''	DIM ``B''	DIM ``C''	DIM ``D''
5″	-	_	_

	PROJEC <u>MEC</u> BRIDGE	CKLEN	<u>IBUR(</u>	<u>;</u> co	<u>SC</u> UNTY
SHEET 1 OF 11					
DocuSigned by: 02EE938FAB674C5	STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH				
PROFESSION SEAL 35647 MCINEER. CONTINUER	DECK	UNDE	ERSI	DE RE	PAIR
8/23/2021		SPA	ΝΑ	& B	
	REVISIONS SHEET NO.				
OCUMENT NOT CONSIDERED	NO. BY:	DATE:	NO. BY:	DATE:	S10-17
FINAL UNLESS ALL SIGNATURES COMPLETED	1 2		<u>3</u> 4		TOTAL SHEETS 274