





VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE.MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2"CLEARANCE TO SAWCUT.FOR REPAIR DETAILS,SEE "CONCRETE RESTORATION DETAILS" SHEETS.

NOTES:

REPAIR LOCATIONS AND ESTIMATED QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE.IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE TABLE ABOVE.

CRACKING LOCATIONS AND QUANTITIES FOR LOCATIONS DESCRIBED AS ``SCATTERED THROUGHOUT'' IN THE INSPECTION REPORT ARE BASED ON THE BEST INFORMATION AVAILABLE. THE ENGINEER AND CONTRACTOR SHALL IDENTIFY AND REPAIR ALL CRACKS >=1/16" AS DESCRIBED IN THE SPECIAL PROVISIONS AT EACH BENT.

AVERAGE CONCRETE COVER IS EXPECTED TO BE FROM 2"TO 3" ON THE CAP AND FROM $1\frac{1}{2}$ "TO 2" ON THE PILES.ACTUAL CONCRETE COVER SHALL BE DETERMINED BY THE CONTRACTOR AND PRESENTED TO THE ENGINEER PRIOR TO BEGINNING EXCAVATION/ DEMOLITION.

FOR CONCRETE AND SHOTCRETE REPAIRS, SEE "CONCRETE RESTORATION DETAILS" SHEETS.

SHOTCRETE REPAIRS MAY BE REPLACED WITH CONCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

REPAIRS TO THE BENT CAP MAY REQUIRE BRIDGE JACKING.FOR BRIDGE JACKING, SEE SPECIAL PROVISIONS.

PERFORM ALL CONCRETE REPAIRS PRIOR TO APPLYING THE EPOXY COATINGS.

TOP OF THE CAPS SHOULD BE CLEAN AND CLEAR OF ALL DEBRIS PRIOR TO THE APPLICATION OF THE EPOXY COATING.

BEARING AREAS.

FOR EPOXY COATING, SEE SPECIAL PROVISION AND STANDARD SPECIFICATIONS SECTION 420-18. SEE ``CONCRETE RESTORATION SHEETS'' FOR CFRP PEDESTAL REPAIRS & BEARING RETROFIT DETAILS.

AS-BUILT REPAIR QUANTITY TABLE									
	QUANTITIES								
	ESTIMATE		ACTUAL						
HOTCRETE REPAIRS	AREA SQ.FT.	VOLUME CU.FT.	AREA SQ.FT.	VOLUME CU.FT.					
CAP/BACKWALL	1.0	0.5							
COLUMN/PILE									
ONCRETE REPAIRS	AREA SQ.FT.	VOLUME CU.FT.	AREA SQ.FT.	VOLUME CU.FT.					
CAP	9.2	4.6							
POXY RESIN INJECTION	LIN.FT.		LIN.FT.						
САР	13.0								
COLUMN/PILE									
POXY COATING	AREA SQ.FT.		AREA SQ.FT.						
САР	136.3								
FRP PEDESTAL REPAIRS &	EA.								
EARING RETROFIT	4								

COAT ALL THE FREE SURFACE AREA ON THE TOP OF CAPS, INCLUDING CHAMFERS, WITH EPOXY COATINGS.DO NOT COAT UNDER

		PROJE 	CT NO. <u>Robes</u> e no.	SON	<u>I-593</u> C 7001(OUNTY	
	DocuSigned by: Jacober CARO/ -2000 Set	STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH SUBSTRUCTURE REPAIRS					
	KCA	BENT 1					
I	KISINGER CAMPO	REVISIONS				SHEET NO.	
CONSIDERED 3	ASSOCIATES 01 FAYETTEVILLE ST., SUITE 1500	NO. BY:	DATE:	NO. BY:	DATE:	S1-12	
ESS ALL R	ALEIGH, NC 27601 (919) 882-7839	1		3 A		TOTAL SHEETS	
COMPLETED N	IC FIRM LICENSE: C-1506	1 22		<u>///</u> L		II 14 I	