


SPAN D SPAN E



END VIEW

AS-BUILT REPAIR QUANTITY TABLE								
BENT 4 SPAN D FACE	QUANTITIES							
	ESTI	MATE	ACTUAL					
SHOTCRETE REPAIRS	AREA SQ.FT.	VOLUME CU.FT.	AREA SQ.FT.	VOLUME CU.FT.				
САР	0.0	0.0						
COLUMN	0.0	0.0						
CONCRETE REPAIRS	AREA SQ.FT.	VOLUME CU.FT.	AREA SQ.FT.	VOLUME CU.FT.				
САР	0.0	0.0						
COLUMN	0.0	0.0						
EPOXY RESIN INJECTION		LIN.FT.	LIN.FT.					
САР	19.5							
COLUMN	0.0							
EPOXY COATING	SQ.FT.	SQ.FT.						
TOP OF BENT CAP	143.3							
VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER								


VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2"CLEARANCE TO SAWCUT. SEE ``TYPICAL CAP AND COLUMN REPAIR DETAILS'' SHEET.

NOTES:

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN BASED ON THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ENTER THE ACTUAL QUANTITIES INTO THE AS-BUILT REPAIR QUANTITY TABLE.

CLEAN AND REMOVE DEBRIS FROM THE TOP OF THE CAP AND APPLY EPOXY PROTECTIVE COATING. EPOXY COATING SHALL BE APPLIED TO THE TOP SURFACE OF THE CAP. THE CONTRACTOR SHALL NOT COAT THE AREA OF THE CAP BENEATH THE MASONRY PLATES. FOR EPOXY COATING, SEE SPECIAL PROVISIONS.

CONCRETE REPAIRS MAYBE SUBSTITUTED IN LIEU OF SHOTCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.



SHOTCRETE REPAIR AREA

CONCRETE REPAIR AREA



ERI - EPOXY RESIN INJECTION

PROJECT NO. <u>15BPR.21</u> <u>MONTGOMERY</u> COUNTY BRIDGE NO. <u>610006</u>

DocuSigned by: Krishma P. Sedai EAGF7941500 WWW PTH CAROUTING SEAL 031583 WCINETR PRASAD	STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH BENT 4 SPAN D FACE								
	REVISIONS SHEET NO.								
DOCUMENT NOT CONSIDERED	NO. BY:	DATE:	NO.	BY:	DATE:	S1-19			
FINAL UNLESS ALL	1		3			TOTAL SHEETS			
SIGNATURES COMPLETED	2		4			34			