

AS-BUILT REPAIR QUANTITY TABLE QUANTITIES BENT 8 SPAN H FACE ESTIMATE ACTUAL VOLUME VOLUME SHOTCRETE REPAIRS SQ.FT. CU.FT. SQ.FT. CU.FT. CAP 0.0 0.0 0.0 COLUMN 0.0 AREA SQ.FT. VOLUME CU.FT. VOLUME CONCRETE REPAIRS SQ.FT. CU.FT. CAP 0.0 0.0 COLUMN 0.0 0.0 EPOXY RESIN INJECTION LIN.FT. LIN.FT. CAP 23.0 COLUMN 0.0 EPOXY COATING SQ.FT. SQ.FT. TOP OF BENT CAP 143.3

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2"CLEARANCE TO SAWCUT. SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.

NOTES:

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN BASED ON THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ENTER THE ACTUAL QUANTITIES INTO THE AS-BUILT REPAIR QUANTITY TABLE.

CLEAN AND REMOVE DEBRIS FROM THE TOP OF THE CAP AND APPLY EPOXY PROTECTIVE COATING. EPOXY COATING SHALL BE APPLIED TO THE TOP SURFACE OF THE CAP. THE CONTRACTOR SHALL NOT COAT THE AREA OF THE CAP BENEATH THE MASONRY PLATES. FOR EPOXY COATING, SEE SPECIAL PROVISIONS.


CONCRETE REPAIRS MAYBE SUBSTITUTED IN LIEU OF SHOTCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

SHOTCRETE REPAIR AREA

CONCRETE REPAIR AREA

ERI - EPOXY RESIN INJECTION

PROJECT NO. 15BPR.21 MONTGOMERY COUNTY BRIDGE NO. 610006



STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION

BENT 8 SPAN H FACE

SHEET NO **REVISIONS** NO. BY: DATE: S1-27 DATE: DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED TOTAL SHEETS 34