




**-L- CURVE DATA**


PI Sta 48+37.98	PI Sta 62+27.11
$\Delta = 7^{\circ} 01' 28.2''$ (RT)	$\Delta = 13^{\circ} 43' 19.0''$ (LT)
$D = 0^{\circ} 40' 26.6''$	$D = 0^{\circ} 47' 36.9''$
$L = 1,042.10'$	$L = 1,729.14'$
$T = 521.71'$	$T = 868.73'$
$R = 8,500.00'$	$R = 7,220.00'$
SE = NC	SE = NC



**NOTE:**  
 THE EXISTING DRAINAGE DITCHES WERE DRY AND APPEARED STABLE AT THE DATE OF THE FIELD INVESTIGATION. THE 24" RCP AT -L- STA. 28+73 WAS IN GOOD CONDITION, CONTAINED 1"-2" OF SILT AND WAS NOT CONVEYING ANY WATER. THE 2 @ 36" RCP AT -L- STA. 59+90 WAS IN GOOD CONDITION, CONTAINED NO SILT AND WAS NOT CONVEYING ANY WATER. THE EXISTING BRIDGE OVER LITTLE ROCKFISH CREEK WAS IN GOOD STRUCTURAL CONDITION, HOWEVER, EVIDENCE OF SCOURING AGAINST THE PILES AND ABUTMENT OF THE BRIDGE WAS NOTED. THE CREEK WAS FLOWING AT A LOW VELOCITY AT THE DATE OF THE FIELD INVESTIGATION.

JOHN MCNATT GILLIS, MARY ALMA GILLIS  
 MALCOLM D GILLIS HEIRS ET AL  
 MALCOLM GILLIS HEIRS  
 JUDY GILLIS MCKETHAN  
 DB 4093 PG 287 (TRACT 6C)


U-5798B -L- PRC Sta. 43+16.28



U-5798B FUTURE WORK TO BE DONE BY OTHERS

JOHN MCNATT GILLIS, MARY ALMA GILLIS  
 MALCOLM D GILLIS HEIRS ET AL  
 MALCOLM GILLIS HEIRS  
 JUDY GILLIS MCKETHAN  
 DB 4093 PG 287 (TRACT 6C)

BEGIN PROJECT U-5798A  
 END PROJECT U-5798B  
 -L- Sta. 50+00.00



**NOTE:**  
 UTILIZE FABRIC INSERT INLET PROTECTION DEVICES IN LIEU OF ROCK INLET SEDIMENT TRAPS, TYPE-C AS DIRECTED TO AVOID IMPOUNDMENT OF RUNOFF IN ROADWAY OPEN TO TRAFFIC.

**NOTES:** ANY DEVIATION FROM OPTIONS GIVEN WILL REQUIRE PRIOR APPROVAL BY ENGINEER.  
  
 ADDITIONAL EROSION CONTROL DEVICES MAY NEED TO BE INSTALLED AS DIRECTED BY THE ENGINEER.

8/17/99  
 24-NOV-2001 11:55  
 R:\E:\M\Projects\10\Design\Plan Sheets\U-5798A\_psh\_EC-10.dgn  
 \$\$\$\$  
 \$\$\$\$  
 \$\$\$\$