

AS-BUILT REPAIR QUANTITY TABLE

DECK UNDERSIDE REPAIR - SPAN B

	ESTIMATE		ACTUAL	
SHOTCRETE REPAIRS	AREA SQ.FT.	VOLUME CU.FT.	AREA SQ.FT.	VOLUME CU.FT.
UNDERSIDE OF DECK	0.0	0.0		
UNDERSIDE OF OVERHANG	11.5	3.8		
DIAPHRAGMS	63 . 5	21.2		
OTHER REPAIRS	ESTIMATE		ACTUAL	

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2" CLEARANCE TO SAWCUT. SEE REPAIR DETAILS.

FOR STEEL BEARING KEEPER ANGLE ASSEMBLY, SEE SPECIAL RPOVISIONS.

FOR STEEL BEARING KEEPER ANGLE ASSEMBLY DETAILS, SEE "STEEL KEEPER

STEEL KEEPER ANGLE ASSEMBLY

DIAPHRAGM REPAIR

SHOTCRETE REPAIR

ANTICIPATED BEAM REPAIR LOCATIONS 9" 8"

9"

BEAM REPAIR QUANTITY TABLE									
PLATING	REPAIR	STIFFENER	R REPAIR	DIAPHRAGM REPAIR		STEEL BEARING KEEPER ANGLE ASSMEBLY			
LBS. LBS.		LBS.		EA.					
ESTIMATE	ACTUAL	ESTIMATE	ACTUAL	ESTIMATE	ACTUAL	ESTIMATE	ACTUAL		
39.9		0		0		0			

PROJECT NO. 15BPR.55 FORSYTH __ COUNTY BRIDGE NO. 330078

SHEET 2 OF 4

SEAL 031583

Krishna P. Sedai

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION UNDERSIDE DECK REPAIR

9"

SPAN B

SHEET NO **REVISIONS** S1-11 DATE: DATE: BY: DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED TOTAL SHEETS 79