

NOTES:

REPAIR LOCATIONS AND ESTIMATED QUANTITIES ARE BASED ON THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ENTER THE ACTUAL QUANTITIES INTO THE AS-BUILT REPAIR QUANTITY TABLE.

CONTRACTOR SHALL SAW CUT TO A NOMINAL DEPTH OF 1/2" BUT REINFORCING STEEL SHALL NOT BE DAMAGED.

CONTRACTOR SHALL REMOVE SURFACE CONCRETE TO VERIFY THAT SAW CUT DEPTH WILL NOT DAMAGE EXISTING REINFORCING STEEL.

SHOTCRETE REPAIRS MAY BE REPLACED WITH CONCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

FOR UNDERSIDE OF DECK REPAIRS, SEE "OVERHANG, DIAPHRAGM AND BRIDGE RAIL REPAIR DETAILS" SHEET.

FOR OVERHANG REPAIRS, SEE "OVERHANG, DIAPHRAGM AND BRIDGE RAIL REPAIR DETAILS" SHEET.

FOR GIRDER REPAIRS, SEE "PRESTRESSED CONCRETE GIRDER REPAIR DETAILS" SHEET.

FOR SHOTCRETE REPAIRS, SEE SPECIL PROVISIONS.

FOR CONCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR BEARING REPLACEMENT, SEE "ELASTOMERIC BEARING DETAILS"


FOR BRIDGE JACKIING DETAILS, SEE "JACKING DETAILS" SHEET.

CLASS III SURFACE PREPARATION AREA **
ON TOP SURFACE OF BRIDGE DECK

BEARING REPLACEMENT



GIRDER REPAIR



DIAPHRAGM REPAIR



ERI - EPOXY RESIN INJECTION

BEAM REPAIR QUANTITY TABLE

BEARING REPLACEMENT				
EA.				
ESTIMATE	ACTUAL			
4				

DECK UNDERSIDE REPAIR - SPAN E ESTIMATE ACTUAL

AS-BUILT REPAIR QUANTITY TABLE

SHOTCRETE REPAIRS	AREA SQ.FT.	VOLUME CU.FT.	AREA SQ.FT.	VOLUME CU.FT.
UNDERSIDE OF DECK	0.0	0.0		
UNDERSIDE OF OVERHANG	0.0	0.0		
DIAPHRAGMS	6.5	2.2		
GIRDER REPAIRS	AREA SQ.FT.	VOLUME CU.FT.	AREA SQ.FT.	VOLUME CU.FT.
GIRDER	4.0	1.3		
EPOXY COATING CONCRETE GIRDER ENDS	602.0			

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2"CLEARANCE TO SAWCUT. SEE "OVERHANG, DIAPHRAGM AND BRIDGE RAIL REPAIR DETAILS" SHEET.

AFTER CLASS III SURFACE PREPARATION AND LMC-VES PLACEMENT, CONTRACTOR SHALL EXAMINE THE BOTTOM OF THE BRIDGE DECK TO IDENTIFY AREAS THAT MIGHT NOT HAVE BEEN ADDRESSED BY CLASS III SURFACE PREPARATION. REPAIR IDENTIFIED AREAS WITH SHOTCRETE REPAIRS.

> PROJECT NO. 15BPR.55 FORSYTH BRIDGE NO. 330227

SHEET 5 OF 5

01/26/2022 SEAL 031583 Krishna P. Sedai

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH

DECK_UNDERSIDE REPAIR SPAN E

SHEET NO **REVISIONS** S2-15 DATE: DATE: BY: DOCUMENT NOT CONSIDERED FINAL UNLESS ALL TOTAL SHEETS SIGNATURES COMPLETED

<u>SPAN E</u>

A. SORSENGINH

M.G.SHAIKH

DRAWN BY :

CHECKED BY : .

_ DATE : <u>11/2019</u>