

1/25/2022 P:\15BPR55\Structures\FinalPlans\402_037_15BPR.55_SMU_ B2B_S19_330227.dgn ksedai

+

+

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE BASED ON THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ENTER THE ACTUAL QUANTITIES ENTERED INTO THE AS-BUILT

FOR SHOTCRETE REPAIR, SEE SPECIAL PROVISIONS.

FOR CONCRETE REPAIRS, SEE SPECIAL PROVISIONS.

SHOTCRETE REPAIRS MAY BE SUBSTITUTED IN LIEU OF CONCRETE REPAIRS WITH THE APPROVAL

FOR EPOXY RESIN INJECTION, SEE SPECIAL PROVISIONS.

CLEAN AND REMOVE DEBBRIS FROM THE TOP OF THE CAP AND APPLY EPOXY PROTECTIVE COATING TO THE TOP SURFACE OF THE CAP. THE CONTRACTOR SHALL NOT COAT THE AREA OF THE CAP BENEATH THE MASONRY PLATES. FOR EPOXY COATING,SEE SPECIAL PROVISIONS.

JILT REPAIR QUANTITY TABLE				
NT 2 (B FACE)	QUANTITIES			
	ESTIMATE		ACTUAL	
CRETE REPAIRS	AREA SF	VOLUME CF	AREA SF	VOLUME CF
	0.0	0.0		
	0.0	0.0		
RETE REPAIRS	AREA SF	VOLUME CF	AREA SF	VOLUME CF
	7.7	3.9		
Y RESIN INJECTION		LN.FT.		LN.FT.
		0.0		
		0.0		
Y COATING		SQ.FT.		SQ.FT.
BENT CAP		249.8		

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2"CLEARANCE TO SAWCUT. FOR REPAIR DETAILS, SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.

SHOTCRETE AREA

CONCRETE AREA

✓ ERI - EPOXY RESIN INJECTION

PROJECT NO. 15BPR.55 FORSYTH ____ COUNTY BRIDGE NO. 330227 SHEET 1 OF 2 STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION 01/26/2022 RALEIGH TH CAR ~ ~ GEESSION SEAL 031583 BENT 2 SPAN B FACE Krishna P. Sedai -EA6F794150BF4B7... REVISIONS SHEET NO. NO. BY: S2-19 DATE: DATE: BY: DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED total sheets 79