
ANTICIPATED STEEL REPAIR LOCATIONS										
SPAN	BEAM	LOCATION	DIM "A"	DIM "B"	DIM "C"	DIM "D"	DIM "E"			
В	2	BENT 1	6″	31"						
В	2	BENT 1	6″	31"						
В	4	BENT 1	4"	33"						
В	4	BENT 1	4"	33"						
В	4	BENT 2		4"			5"			

BEAM REPAIR QUANTITY TABLE										
STEEL	PLATES	BRIDGE JACKING		STIFFENER						
LBS.		EA.		LBS.						
ESTIMATE	ACTUAL	ESTIMATE	ACTUAL	ESTIMATE	ACTUAL					
60.0		0		0.0						
STEEL LATER	RAL BRACING	HARDWARE REPAIR		BEAM END REPAIR						
LE	BS.	LBS.		LBS.						
ESTIMATE	ACTUAL	ESTIMATE	ACTUAL	ESTIMATE	ACTUAL					
0.0		0.0		0.0						
			·	_						



VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2"CLEARANCE TO SAWCUT. SEE "OVERHANG, DIAPHRAGM AND BRIDGE RAIL REPAIR DETAILS" SHEET.

## NOTES

FOR UNDERSIDE OF DECK REPAIRS. SEE "OVERHANG, DIAPHRAGM AND BRIDGE RAIL REPAIR DETAILS" SHEET.

FOR OVERHANG REPAIRS. SEE "OVERHANG, DIAPHRAGM AND BRIDGE RAIL REPAIR DETAILS" SHEET.


FOR BEAM PLATING REPAIR. SEE "BEAM PLATING REPAIR DETAILS" SHEETS.

FOR SHOTCRETE REPAIR, SEE SPECIAL PROVISIONS.

FOR CONCRETE REPAIR, SEE SPECIAL PROVISIONS.

SHOTCRETE REPAIRS MAY BE REPLACED WITH CONCRETE REPAIR WITH APPROVAL OF THE ENGINEER.

FOR EPOXY RESIN INJECTION, SEE SPECIAL PROVISIONS.



1 BEAM NUMBER

B BEAM END REPAIR

P PLATING REPAIR

S STIFFENER REPAIR

F BOTTOM FLANGE REPAIR

H HARDWARE REPAIR

G GUSSET PLATE REPAIR

LATERAL BRACE REPAIR

J TYPE I BRIDGE JACKING

SHOTCRETE REPAIR AREA

ERI - EPOXY RESIN INJECTION

PROJECT NO. 15BPR.51

GASTON COUNTY

BRIDGE NO. 350046

SHEET 2 OF 3

01/25/2022

DEPARTMENT OF TRANSPORTATION
RALEIGH

DECK\_UNDERSIDE REPAIR SPAN\_B

REVISIONSSHEET NO.DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETEDNO.BY:DATE:NO.BY:DATE:SI-1213TOTAL SHEETS2467

PLAN OF SPAN B

DRAWN BY: GHOLAMREZA KOUCHEKI DATE: 11/2021
CHECKED BY: H.A. LOCKLEAR DATE: 11/2021